


EWR D&I ANNOTATION



FAN-000001L103001DP136-6034

Artemis # : 000001L103001DP136**Record Created Date :** 03/28/2011**Printed Date :** 03/29/2011**Description :**

DI11-005. SEQ ID 136. 2010 Q3. WE RECEIVED A POLICE REPORT AND CALL LOG FOR A 2006 CHEVY COBALT. THE DRIVER WAS TRAVELLING ON A US HWY GOING ABOUT 55MPH WHEN ANOTHER VEHICLE IN ONCOMING TRAFFIC TURNED LEFT IN FRONT OF HER. THE DRIVER STATES SHE DID NOT HAVE TIME TO APPLY THE BRAKES AND HIT THE CAR ON THE SIDE WITH THE FRONT OF HER VEHICLE. THE VEHICLE HAD FRONT END DAMAGE AND IT IS UNKNOWN TO WHAT EXTENT. THE DRIVER WAS INJURED AND IS WONDERING WHY THE AIR BAGS DID NOT DEPLOY. IT IS UNKNOWN WHETHER SHE WAS WEARING SEAT BELTS. GM HAS DENIED THAT THERE WAS A PROBLEM WITH THE SYSTEM. FRONTAL COLLISION AIR BAG HISTORY FOR THE 2006 COBALT: VOQ-18. FR-100 (TOTAL AIRBAGS). PURSUIT-1 (FRONTAL AIRBAGS). RECALL-0. TSB-0. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

February 15, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DII11-005

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 7, 8, 19, 20, 21, 23, 24, 50, 51, 68, 73, 83, 94, 113, 124, 136, 138, 147, 170, 172, 175, 177, 181, 183, 187, 191, 195, 197, 205, 225, 227, 274, 321, 323, 324, 327, 329, 369, 374, 375, 376, 377, 378, 379, 401, 418, 419, 437, 454, 455, 461, 468, 473, 474, 481, 483, 484, 487, 504, 511, 541, 560, 565, 570, 618, 619, 633	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly

identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CRF 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **March 18, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in cursive script that reads "Christina Morgan".

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

March 17, 2011

MAR 18 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-005

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated February 15, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2010.

GM's response is comprised of 68 disks for the incidents that are the subject of DI11-005.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 7 316869715-696125 and 2010 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 7 316869715-696125_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-005
7 316869715-696125
2010 BUICK ENCLAVE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.



Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

7 316869715-696125_01_001- is the first document responsive to Inquiry no.1.

7 316869715-696125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(67 Vehicles from the Light Vehicle Template)			
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)		TYPE
7	5GALRBED2AJ		NISM
8	5GALRAEDXAJ		NISM
19	1G4HD572X7U		NISM
20	1G4HD57257U		NISM
21	1G4HR57Y77U		NISM
23	1G4HA5EM8AU		NISM
24	1G4HC5EM3AU		NISM
50	1G6DE5EG6A0		NISM
51	1G6DE5EY7B0		NISM
68	3GYFNFY9AS		NISM
73	3GNEC12097G		LIT
83	KL1TD66638B2		NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
94	2G1FB1EV5A9	NISM
113	1G1AK15F567	NISM
124	1G1AK55F267	NISM
136	1G1AK15F967	NISM
138	1G1AL55F767	NISM
147	1G1AL15F277	PAR
170	1G1AL18F087	NISM
172	1G1AL58F887	NISM
175	1G1AK18F087	NISM
177	1G1AK18F987	NISM
181	1G1AK18H197	PAR
183	1G1AS18H397	NISM
187	1G1AT58H697	NISM
191	1G1AS58H297	NISM
195	1G1AB5F59A7	NISM
197	1G1AB5F57A7	NISM
205	1GTJTCDE1A8	NISM
225	2CNALDEW3A6	PAR
227	2CNALBEC0B6	NISM
274	2G1WA5EN4A1	NISM
321	1G1ZC5E05AF	NISM
323	1G1ZD5E7XAF	NISM
324	1G1ZA5E08AF	NISM
327	1G1ZE5EB4AF	NISM
329	1G1ZC5EU2BF	NISM
369	1GCEC290X9Z	RMR
374	1GCEK290X9Z	NISM
375	3GCRKSE31AG	NISM
376	3GCRKSE39AG	NISM
377	3GCXKTE29AG	NISM
378	1GCSKREA0AZ	NISM
379	1GCSKSEA2AZ	NISM
401	1GNUKKE32AR	NISM
418	1GNFK13017R	NISM
419	1GNFC13J97R	NISM
437	1GNDS13S052	LIT
454	1GNLRFEDXAS	PAR
455	1GNLVGED3AS	NISM
461	1GNDV33178D	LIT
468	1GNDV23E45D	NISM
473	1GKEV23738J	NISM
474	1GKEV23798J	NISM
481	1GKDS13SX52	NISM
483	1GKDT13S652	NISM
484	1GKDS13S652	NISM
487	1GKET63M672	NISM
504	1GTPKVE02AZ	PAR
511	1GKEC13T75R	LIT
541	1G2AL15F677	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
560	1G2ZH36N874 [REDACTED]	NISM
565	1G2ZM177984 [REDACTED]	NISM
570	1G2ZG57N494 [REDACTED]	NISM
618	1G8AJ55F47Z [REDACTED]	NISM
619	1G8AN15F17Z [REDACTED]	NISM
633	3GSCL33P58S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,



M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 68 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a 'CIVIL CASE COVER SHEET' form for the case 'CARDONA V. CHEVROLET'. The form includes sections for case information, case type, and case details. Annotations point to specific features:

- Step 7: Next File (Image)**: Points to the 'Next Image' button in the right-hand menu.
- Step 7: Next Page**: Points to the 'Next page' button in the right-hand menu.
- Step 8: Scale Image**: Points to the 'Scale' section in the right-hand menu, which includes options for 'Fit Scale to fit', '1:2 Scale 50%', '1:1 Scale 100%', and '2:1 Scale 200%'.
- Step 7: Image Properties**: Points to the 'Image Properties' button at the bottom of the right-hand menu.

The form itself contains the following information:

ATTORNEY OR PARTY WITHOUT ATTORNEY (Print name, title, address and telephone number)
 ERIC D. PARIS, ESQ., 8/58 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 FONDRIA, CALIFORNIA 91766
 TELEPHONE NO. 909-469-5127 FAX NO. 909-469-5126

FOR COURT USE ONLY
 982.2(b)(1)

ATTORNEY FOR: PLAINTIFF'S
 DEPT. NAME OF COURT, JUDICIAL DISTRICT AND BRANCH COURT, IF ANY
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COUNTY

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited

Complex Case Designation
☐ Counter ☐ Joinder
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)

SPSE NUMBER
 ASSIGNED JUDGE:

1. Check one box below for the case type that best describes this case. Please complete all five (5) items below.

Auto Tort
☒ Auto (22)
☐ Other PIP/DWD (Personal Injury/Property Damage/Wrongful Death) Tort
☐ Annuities (34)
☐ Product liability (24)
☐ Medical malpractice (45)
☐ Other PIP/DWD (23)
☐ Non-PIP/DWD (Other) Tort
☐ Business tortious business practice (27)
☐ Civil rights (e.g., discrimination, false arrest) (33)
☐ Defamation (e.g., slander, libel) (13)
☐ Fraud (16)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PIP/DWD tort (30)
☐ Employment
☐ Wrongful termination (36)

Other employment (15)
☐ Contract
☐ Breach of contract/warranty (26)
☐ Collection (e.g., money owed, open real accounts) (28)
☐ Insurance coverage (18)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/inverse condemnation (14)
☐ Wrongful eviction (33)
☐ Other real property (e.g., quiet title) (20)
☐ Unlawful Detainer
☐ Commercial (21)
☐ Residential (22)
☐ Drugs (38)
☐ Judicial Review
☐ Asset forfeiture (35)
☐ Pattern re. arbitration award (11)

2. The case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management.

a. ☒ Large number of separately represented parties d. ☒ Large number of coordination in other courts

b. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve e. ☐ Substantial post

c. ☒ Substantial amount of documentary evidence f. ☐ Substantial post

3. Type of remedies sought (check all that apply)
 a. ☒ monetary ☐ nonmonetary, declaratory or injunctive relief c. ☐

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., 8/58 147836
 (TYPE OR PRINT NAME)

NOTICE
 • Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (ex. under the Probate, Family, or Welfare and Institutions Code) (Cal. Rules of Court, rule 1800).
 • File this cover sheet in addition to any cover sheet required by local court rule.
 • If this case is complex under rule 1800 et seq. of the California Rules of Court, you must file other parties to the action or proceeding.
 • Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

Form Approved for Mandatory Use
 Superior Courts of California
 982-281 (Rev. January 1, 2003)

CIVIL CASE COVER SHEET

DI11-005
136 316869752 – 696205
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No.	(b) (6)	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR - Collision
Address		City	Norman	Involved Dir		Safety	Yes
State	OK ZipCd	Con Acct		Source	Phone	Updated	7/23/2010 02:02:17 PM
Serial #/VIN	1G1AK15F967	Model Year	2006	Priority	Medium License #	Owner	FABIANBR
Make	Chevrolet	Warr. Start	07/05/2006	Status	Open	Opened	7/23/2010 01:12:26 PM
Model	Cobalt	Mileage	135000	Sub-Status	Dissatisfied	Closed	
Abstract	Non-deployment - 06 Chevrolet Cobalt						
Customer Description	This is a BRC - PAR case /do not assume /Forward all inquiries to Brandy ext. 31065						

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	Other Veh	People in Veh	Road Surface	Road Cond	Fire Report	Police Report
Owner	3/9/2010 05:00:00 PM	Y	1	1	Asphalt	Dry	n/a	G000146-10
Driver Last Name	Driver First Name	Height	Weight	DOB	Disabilities			
		5'6"						
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
unknown	unknown		Farmers Insurance					
Incident Loc	Hwy 62 and Hwy 39 in Chickasha, OK			Incident Desc	-Driving home from Work on The 9th of March East on Hwy 62 @ about 55 mph in Chickasha, OK - on 62 was approaching a T Intersection with Hwy 39 and guy was traveling west on 62, was almost coming to intersection a guy pulled in frt of me and hit him in his passenger rear end by			
Component	Airbag			Damage Desc	-frt end damage all the way across -			
Vehicle Loc	Unknown - Insurance company took vehicle			Addl Info	Non-deployment			
Empoy Svc Names	Oklahoma Police Dept			Main Loc	Independent - Last Svc Date unknown			

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	n/a
Vehicle Speed	55		Weather Condition	Dry			Prop Owner	Joseph Traggi
Last Service Date			Loc Last Service				Property Location	n/a
Veh Est Repair Cost	\$0.00		Spec Equip Installer	n/a			Prop Damage Description	Passenger side in the Rear Damage
Primary Veh Use	Personal		Inspection Type	Restraint System SIR/Seat Belt			Inspected By	Inspection Not Performed
Veh Damage Description	-frt end damage all the way across -						Inspection Date/Time	
							Explain Other	Independent - Last Svc Date unknown

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seatbelt
Injury Description			Medical Rpt		Treatment Location	Treated By
-broke bone in hand			unknown		Norman Regional Hospital in Norman OK	Dr. Matthew Bonner
					-Physical Therapy	
Street Address			City	State	Zip Code	
			Norman	OK		

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 03:18:10 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
broke bone in hand, went to Norman Regional Hospital in Norman OK and was seen by Dr. Matthew Bonner							
-Physical Therapy							
Joe G/PAR/ATX							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 02:51:32 PM	FABIANBR	FABIANBR	Scheduled Follow-up		Scheduled Alarm		
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Check esis pick up							
brandyfabian.par.atx							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 02:51:19 PM	FABIANBR	GARCIAJR	Notify CRM		Done	7/23/2010 03:20:11 PM	ESIS- Injuries
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
ESIS- Injuries

Escalating to central claims dept due to medical attn sought

brandyfabian.par.abx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 02:50:37 PM	FABIANBR	FABIANBR	BRC PAR	ESIS- Injuries	Done	7/23/2010 02:51:18 PM	ESIS- Injuries
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
ESIS- Injuries

Escalating to central claims dept due to medical attn sought

brandyfabian.par.abx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 02:00:06 PM	FABIANBR	FABIANBR	Ownership Changed	Ownership Escalated to BRC	Done	7/23/2010 02:00:08 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:40:13 PM	FABIANBR	FABIANBR	Ownership Changed		Done	7/23/2010 01:40:13 PM	Service Request Ownership has changed FROM: HOBSONTA TO: FABIANBR
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:39:47 PM	FABIANBR	FABIANBR	BRC PAR	Initial Contact- AVM	Done	7/23/2010 02:48:54 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							

My name is Brandy with the Product Allegation Dept with GM. My Service Request number is 71-852086117. The Customer's name is [REDACTED] Their telephone number is [REDACTED] The Vehicle involved is a Year, Make and Model. -The customer is alleging that she was traveling and was involved in a collision and alleges the airbag should have deployed, due to medical attn sought will be escalating to esis. You do not need to respond to this message unless you have any comments concerns or questions. pls contact me at 866-790-5600 x 31065

brandyfabian.par.abc

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:39:36 PM	FABIANBR	FABIANBR	BRC PAR	Initial Contact- Dealer	Done	7/23/2010 02:38:17 PM	Called No Initial Contact required. Vehicle has not been to dealer in two years.
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							

No Initial Contact required. Vehicle has not been to dealer in two years.

brandyfabian.par.abc

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:39:28 PM	FABIANBR	FABIANBR	BRC PAR	Initial Contact- Phone	Done	7/23/2010 02:12:30 PM	Called Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

-cust had airbag that didn't deploy in a collision
71-852065117
-fractured hand
-calling to find out if there was a recall on vehicle
-Driving home from Work on The 9th of March East on Hwy 62 @ about 55 mph in Chickashea, OK - on 62 was approaching a T intersection with Hwy 39 and
guy was traveling west on 62, was almost coming to intersection a guy pulled in frt of me and hit him in his passenger rear end by the tire, my tire was totalled,
my frt end was bashed in
-frt end damage all the way across -
-broke bone in hand, and the airbags didn't deploy -
-traveling at hwy speed
-process to get medical damages with atty to his insurance this isn't going to affect anything is it?
Norman OK

CRS SLA:

-adv cust escalating case to esls due to medical attn sought 7-10 business days

brandyfabian.par.abx

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:39:17 PM	FABIANBR	FABIANBR	BRC PAR	Acknowledgement	Done	7/23/2010 02:12:19 PM	Called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

-cust had airbag that didn't deploy in a collision
71-852086117
-fractured hand
-calling to find out if there was a recall on vehicle
-Driving home from Work on The 9th of March East on Hwy 62 @ about 55 mph in Chickashea, OK - on 62 was approaching a T intersection with Hwy 39 and
guy was traveling west on 62, was almost coming to intersection a guy pulled in frt of me and hit him in his passenger rear end by the tire, my tire was totalled,
my frt end was bashed in
-frt end damage all the way across -
-broke bone in hand, and the airbags didn't deploy -
-traveling at hwy speed
-process to get medical damages with atty to his insurance this isn't going to affect anything is it?
[redacted]orman OK [redacted]

CRS sts:

-adv cust escalating case to esls due to medical attn sought 7-10 business days

brandyfabian.par.abx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:39:07 PM	FABIANBR	FABIANBR	Research		Done	7/23/2010 02:05:05 PM	Research

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS researched VIN:

no related claim history

no previous related SR's

Open Recalls:

Product Safety Recall N100023 10023 LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR 03/18/2010 Open

brandyfabian.par.abx

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:38:47 PM	FABIANBR	FABIANBR	BRC PAR	Case Assigned	Done	7/23/2010 01:39:04 PM	FABIANBR @ 31065

Contact Last Name	Contact First Name	Account	BAC Code

Comments

FABIANBR @ 31065

brandyfabian.par.sbx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
7/23/2010 01:12:45 PM	HOBSONTA	HOBSONTA	Inbound Call Customer	Complex Request	Done	7/23/2010 01:27:49 PM	veh accident why didn't air bag go off

Contact Last Name	Contact First Name	Account	BAC Code

Comments

accident
cust sts talked to dir
Was owner 06
*Kripplemeyer
Blancher ok
7/06 purchased
Acc In early march someone turned
Air bag didn't go off answer to her

cust sks: why didn't air bag go off
no longer owns veh was totaled by insurance co
fractured hand
wreck happened what date? MAR 9th, 2010
hit the other veh passenger rear side.

Crs sts:

there is a recall on this veh
10023 LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR

Tanya Hobson/CAC T1/ATX L

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front



Mr. GMVIS 2

Logout

July 26, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary

②

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

Vehicle Information

VIN: 1G1AK15F987

Model: 1AK37-2008 COBALT 2-DOOR LS COUPE

Service Contract: No

Branded Title: Yes

Warranty Block: Yes

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: 1 Open

For this vehicle:

• View Vehicle Summary

• Service Contract

• Branded Title

• Warranty Block

• View Vehicle Build

• View Vehicle Component Summary

• View Vehicle

• Transaction History Detail

• View Vehicle Delivery Information

Required Field Actions

Open field actions are highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N100023	10023	LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR	03/18/2010	Open

Branded Title

The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Brand Description: SALVAGED

Date Branded: 04/01/2010

Title Number: 142206

Reporting Source Code:

Reported By: OK

Effective Date: 05/01/2010

Warranty Block

Code	Description	Effective Date
BT	BRANDED TITLE	04/30/2010
Block Transaction Types:		Blocked Labour Ops:
ZPDI		
ZPTI		
ZREG		
ZSCT		

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
-------	-------------	-------------------	------------	--------------------	----------	--------------

Bumper to Bumper Limited Warranty	05/01/2010	07/05/2006	20 MI	07/05/2009	36,020 MI
Corrosion Limited Warranty	05/01/2010	07/05/2006	20 MI	07/05/2012	100,020 MI
Emission Select Component Ltd Wty	05/01/2010	07/05/2006	20 MI	07/05/2014	80,020 MI
Powertrain Limited Warranty	05/01/2010	07/05/2006	20 MI	07/05/2011	60,020 MI
Special Coverage 09275	05/01/2010	07/05/2006	20 MI	07/05/2016	120,020 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History

[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
04/19/2006	A [REDACTED]	ZPDI—Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved

Warranty

Mr. GMVIS 2
 July 26, 2010

[Logout](#)

Global Warranty Management: [Main](#) > [Interface With Customer](#) > [View Vehicle Build](#)

INTERFACE WITH CUSTOMER

View Vehicle Build

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN: 1G1AK15F967
 Service Contract: No Branded Title: Yes Model: 1AK37-2008 COBALT 2-DOOR LS COUPE
 Order Type: 70 - RETAIL - STOCK Warranty Block: Yes PDI Status: No
 Field Actions: 1. Open

Vehicle Build

Model: 1AK37-2008 COBALT 2-DOOR LS COUPE Order Number: JZQM03
 Gross Vehicle Weight: 1,651 Build Date: 04/19/2008
 Build Plant: 7

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

14B - GRAY	14I - GRAY
1LS - 1LS BASE PACKAGE	1SZ - OPTION PACKAGE DISCOUNT
48U - BLUE GRANITE METALLIC	6AR - FRONT SPRING
7AR - FRONT SPRING	8AA - REAR SPRING
9AA - REAR SPRING	AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS
AR9 - DELUXE FRONT BUCKET SEAT	B34 - FLOOR MATS
B35 - REAR FLOOR MATS	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	FE1 - SUSPENSION SYSTEM-SOFT RIDE
FE9 - FEDERAL EMISSIONS	FR6 - 3.84 FINAL DRIVE TRANSAXLE RATIO
IP8 - INTERIOR TRIM DESIGN	J41 - POWER DISC FRONT BRAKES
K64 - 115 AMP GENERATOR	L61 - 2.2L DOHC 4 CYL ENGINE
LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO	M86 - MANUAL 5 SPEED TRANSMISSION
MM5 - 5-SPEED MANUAL TRANSMISSION	N46 - 4 SPOKE STEERING WHEEL
NT7 - FEDERAL EMISSION TIER 2	PG1 - 15" STEEL WHEEL
OTU - P195/60R15 TOURING BW TIRES	R6P - PREMIUM PAINT
R8K - *****	R9U - GM ACCESS - AUTOBOOK IDENTIFIER
SLM - STOCK ORDERS	UN0 - AM/FM STEREO W/CD & RDS
UO4 - BASE SPEAKER SYSTEM	V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA
VX3 - FRONT LICENSE PLATE MOUNT	

Added Option Codes

-AS - SPECIAL COVERAGE APPLIED

For this vehicle:

- [View Vehicle Summary](#)
 - [Service Contract](#)
 - [Branded Title](#)
 - [Warranty Block](#)
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Global Warranty Management: [Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary

| ②

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build

Vehicle Information

VIN: 1G1AK15F967
 Service Contract: No Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [1 Open](#)

For this vehicle:

- View Vehicle Summary
 - Service Contract
 - Branded Title
 - Warranty Block
- View Vehicle Build
- View Vehicle Component Summary
- View Vehicle Transaction History Detail
- View Vehicle Delivery Information

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY Source Plant: T-CPC TONAWANDA, NEW YORK Date Scanned: 04/19/2006	Traceability: 604111235 Part / Number Broadcast: TAX Time Scanned: 06:56:00 Scan Station: 04
Component Code: 61-TRANSMISSION Source Plant: 0- Date Scanned: 04/19/2006	Traceability: 6029042 Part / Number Broadcast: DCY Time Scanned: 06:56:00 Scan Station: 04
Component Code: 86-ELECTRONIC CONTROL MODULE (ECM) Source Plant: T- Date Scanned: N/A	Traceability: 00000Y6Z5 Part / Number Broadcast: YMZD Time Scanned: N/A Scan Station: 06
Component Code: 87-BODY CONTROL MODULE Source Plant: R- Date Scanned: 04/19/2006	Traceability: A60950442 Part / Number Broadcast: 7055 Time Scanned: 03:29:00 Scan Station: 04
Component Code: AB-IR-MODULE ASM-INFLATOR Source Plant: INLAND Date Scanned: 04/19/2006	Traceability: H103D1290 Part / Number Broadcast: 4416 Time Scanned: 08:10:00 Scan Station: 04
Component Code: AL-IR-MODULE ASM-UP Source Plant: INLAND Date Scanned: 04/19/2006	Traceability: G103D1442 Part / Number Broadcast: 4446 Time Scanned: 03:43:00 Scan Station: 04
Component Code: CB-SEQ NUM (FLEX) BODY ASM Source Plant: - Date Scanned: 04/13/2006	Traceability: 2100618 Part / Number Broadcast: 1ZZ Time Scanned: 05:17:00 Scan Station:

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved

Global

Warranty

Mr. GMVIS 2
 July 26, 2010

[Logout](#)

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

 INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail

17

This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN: 1G1AK15F967 [REDACTED] Model: 1AK37-2006 COBALT 2-DOOR LS COUPE
 Service Contract: No Branded Title: Yes Warranty Block: Yes PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [1_Open](#) [REDACTED]

For this vehicle:

- [View Vehicle Summary](#)
 - [Service Contract](#)
 - [Branded Title](#)
 - [Warranty Block](#)
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Job Card Date: 04/19/2006

Job Card Number: A48257

 Repair Service Agent: 112367
 KNIPPELMIER CHEVROLET, INC.
 1811 E US 62 HIGHWAY
 BLANCHARD OK 73010-9202
 4054853333

 Odometer Reading: 0 MI
 Authorization Code:

 Process Date:
 04/25/2006

 Transaction Type:
 ZPDI—Pre-Delivery Inspection

Transaction Expense Category:

 Customer Complaint Code:
 0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time


Causal Part Number

Line Total: USD 89.56

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved



Mr. GMVIS 2

[Logout](#)

July 26, 2010

Global Warranty Management: [Main](#) > [Interface With Customer](#) > [View Vehicle Delivery Information](#)INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN: 1G1AK15F967

Model: 1AK37-2006 COBALT 2-DOOR LS COUPE

Service Contract: No

Branded Title: Yes

Warranty Block: Yes

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: 1_Open

For this vehicle:

- View Vehicle Summary
 - Service Contract
 - Branded Title
 - Warranty Block
- View Vehicle Build
- View Vehicle Component Summary
- View Vehicle Transaction History Detail
- View Vehicle Delivery Information

Invoice Information

Invoicing Service Agent: 112367
KNIPPELMIER CHEVROLET, INC.
1811 E US 62 HIGHWAY
BLANCHARD OK 73010-9202 4054853333

Invoice Date: 04/19/2006

Ship to Information

Invoicing Service Agent: 112367
KNIPPELMIER CHEVROLET, INC.
1811 E US 62 HIGHWAY
BLANCHARD OK 73010-9202 4054853333

Ship to Date: N/A

Delivery Information

Delivery Service Agent: 112367
KNIPPELMIER CHEVROLET, INC.
1811 E US 62 HIGHWAY
BLANCHARD OK 73010-9202 4054853333

Delivery Date: 07/05/2006
Delivery Type: D10—INDIVIDUAL
Delivery Odometer: 20

In Service Information

Invoicing Service Agent:

In Service Date: N/A
In Service Type: 0000
In Service Odometer: 0

[Global Warranty Management: Site Map](#)[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved

Pg 1 of 4

DO NOT WRITE IN THIS SPACE

OFFICIAL OKLAHOMA TRAFFIC COLLISION REPORT

Incident Report
Investigation Completed ☒ Revised ☒
Investigation Made at Scene ☒ Fatality ☒
Photographs ☒ Hit and Run ☒

(1) Reporting Agency: OKLAHOMA HIGHWAY PATROL Case Number (Agency Use): (b) (6) Motor Vehicle Involved: 02 Number Injured: 00 Number Killed: 00

(2) Date of Collision (mm/dd/yyyy): 03/09/2010 Time: 1706 County Number and Name: 26 GRADY Nearest City or Town Number and Name: 00 CHICKASHA

(3) Distance from Nearest City or Town Limits: 0000 Coated # Int ID Location East Grid North Grid Administrative: 0074 04 16 00 00 029 5 050 0 300051535

(4) Street, Road or Highway: US HWY 62 Distance from (Nearest) Intersecting Street, Road or Highway: ST HWY 39

(5) Unit: 01 Occupants Type: 01 Last Name: First: Address: City: LINDSAY State: OK Zip: Telephone (Use Area Code):

(6) Driver License Number: OK D 1 0 01 04

(7) Insurance Company Name: CASUALTY CORP OF AMERICA Policy Number: 8 Insurance Telephone (Use Area Code):

(8) Vehicle Year: 1994 Color: WHI Make: DODG Model: SHA Vch. Cont: 02 License of Damage: 4

(9) Station: F027816 Motorist/Driver Number: 11-402 Station Number: 02 01 D City: NORMAN State: OK Zip: Telephone (Use Area Code):

(10) Driver License Number: OK D 1 0 01 04

(11) Vehicle Year: 2009 Color: GRY Make: CHEV Model: BLS Vch. Cont: 01 License of Damage: 4

(12) Station: QUALITY TOWING Motorist/Driver Number: 00 Station Number: 02 00 City: State: Zip: Telephone (Use Area Code):

(13) Station: PARRISH Motorist/Driver Number: 373 G Station Number: 137 JH Date of Report (mm/dd/yyyy): 03/09/2010

WARNING - STATE LAW Use of contents for commercial solicitation is unlawful

CPS: 0192-01 REV 01/07

Report Number: 306031535; Date: 2010-03-17; Last Name: JOSEPH; First Name: JOSEPH; US Do 1: X082982136; Last Name: MEYER; First Name: SUZ; US Do 2: X080273329; County Code: 26; Collision Date: 2010-03-09; Operator: 01

Case Number		G060146-10		Pg 2 of 4	
(24) Unit		Pos in Veh.		Last Name	
☐ Injured ☐ Witness ☐ Passenger ☐ Prop. Owner		☐ First ☐ Middle ☐ Suffix		DOB (mm/dd/yyyy)	
(25) Address		City		State	
Zip		Telephone (Use Area Code)			
(26) Injury Severity / Type		OP Use		Air Bag	
Ejected		Exhausted		Transported by	
To Medical Facility		Property Type			
(27) Unit		Pos in Veh.		Last Name	
☐ Injured ☐ Witness ☐ Passenger ☐ Prop. Owner		☐ First ☐ Middle ☐ Suffix		DOB (mm/dd/yyyy)	
(28) Address		City		State	
Zip		Telephone (Use Area Code)			
(29) Injury Severity / Type		OP Use		Air Bag	
Ejected		Exhausted		Transported by	
To Medical Facility		Property Type			
(30) Unit		Pos in Veh.		Last Name	
☐ Injured ☐ Witness ☐ Passenger ☐ Prop. Owner		☐ First ☐ Middle ☐ Suffix		DOB (mm/dd/yyyy)	
(31) Address		City		State	
Zip		Telephone (Use Area Code)			
(32) Injury Severity / Type		OP Use		Air Bag	
Ejected		Exhausted		Transported by	
To Medical Facility		Property Type			
(33) Unit		Pos in Veh.		Last Name	
☐ Injured ☐ Witness ☐ Passenger ☐ Prop. Owner		☐ First ☐ Middle ☐ Suffix		DOB (mm/dd/yyyy)	
(34) Address		City		State	
Zip		Telephone (Use Area Code)			
(35) Injury Severity / Type		OP Use		Air Bag	
Ejected		Exhausted		Transported by	
To Medical Facility		Property Type			
(36) Unit		Carrier Name		Address	
(37) Car		State		Zip	
(38) J.R. DOT Number		M&B Report Number		Plaint Number	
OK					
(39) L&L		Carrier phone		Address	
(40) City		State		Zip	
(41) U.S. DOT Number		R&B Region Number		Fleet Number	
OK					
Position in Vehicle		Vehicle Configuration		Cargo Body Type	
01. Not Applicable 02. Front Row - Other 03. Second Row - Other 04. Third Row - Other 05. Fourth Row - Other 06. Other Seating in Truck Cab		07. Not Applicable 08. Front Row - Other 09. Second Row - Other 10. Third Row - Other 11. Fourth Row - Other 12. Other Seating in Truck Cab		13. Not Applicable 14. Front Row - Other 15. Second Row - Other 16. Third Row - Other 17. Fourth Row - Other 18. Other Seating in Truck Cab	

Case Number		G000146-10		OFFICIAL OKLAHOMA TRAFFIC COLLISION REPORT		Pg 3 of 4											
Unit		Total Lanes in Roadway		Legal Speed		Actions Prior to Collision		Location at Time of Collision		Safety Equip.		Unit Number of Vehicle Struck		Was the collision in or near a construction, maintenance or utility work zone? (If yes, complete this section)		Yes ☐ No ☒	
01		02		65													
02		02		65													
This unit will correspond to Unit 1		This unit will correspond to Unit 2															
Light		1		What Vehicle Was Going to Do		Unit 1 Unit 2		Under/Over		Unit 1 Unit 2				Type of Work Zone		Location of the Work Zone	
1 Daylight		02		01										1 Lane Closure		1 Before the First Work Zone Warning Sign	
2 Dark-Not Lighted														2 Lane Shift/Crossover		2 Advance Warning Area	
3 Dark-Lighted														3 Work on Shoulder or Median		3 Transition Area	
4 Dawn														4 Intersecting or Moving Work		4 Activity Area	
5 Dusk														5 Unknown		5 Termination Area	
6 Dark-Unknown																6 Unknown	
7 Lighting																	
8 Other																	
9 Unknown																	
Weather		01												Workers Present		Yes ☐ No ☐ Unknown ☐	
01 Clear																	
02 Fog/Smog/Smoke																	
03 Cloudy																	
04 Rain																	
05 Snow																	
06 Sleet/Hail (Freezing Rain/Unfrozen)																	
07 Sleet/Hail (Freezing Rain/Unfrozen)																	
08 Steady Snow																	
09 Steady Snow, Grad. Wind																	
10 Other																	
11 Unknown																	
Locality		6															
1 Residential																	
2 Business																	
3 Industrial																	
4 School																	
5 Not 3rd-4th																	
6 Mixed Use																	
7 Other																	
8 Unknown																	
Type of Intersection		3															
1 Not an Intersection																	
2 Y-Intersection																	
3 T-Intersection																	
4 Four-Way Intersection																	
5 Five-Way or More Intersection on Part of Interchange																	
6 Traffic Circle																	
7 Roundabout																	
8 Unknown																	
Incident Type		00															
00 Not an Incident																	
01 Private Property																	
02 Deliberate Injury																	
03 Medical Condition																	
04 Legal Intervention																	
05 Suicide																	
06 Domestic																	
07 Other																	
Location of First Handoff Event		01															
01 On Roadway																	
02 Shoulder																	
03 Median																	
04 Roadside																	
05 Core																	
06 Separator																	
07 Parking Lot/Zone																	
08 Off Roadway																	
09 Outside Right-of-Way																	
10 Other																	
11 Unknown																	
Driver Distracted by		0															
0 Not Applicable/None																	
1 Electronic Communication Device																	
2 Other Electronic Device																	
3 Other Vehicle																	
4 Other Outside Vehicle																	
5 Unknown																	
Road Surface		2															
1 Concrete																	
2 Asphalt																	
3 Gravel																	
4 Dirt																	
5 Other																	
6 Unknown																	
Emergency Vehicle Responding to an Emergency		0															
0 No																	
1 Yes																	
Point of First Contact on Vehicle		03															
0 Not Applicable																	
1 Unknown																	
Most Damaged Area		06															
0 Not Applicable																	
1 Unknown																	
DPS: 0162-03 REV 0107																	

Report Number: 300051535; Scan Date: 2010-03-17; Last Name 1: IRAGGI; First Name 1: JOSEPH; DL No: 1-K02982334; Last Name 2: MCKEN; First Name 2: SUM; DL No 2: K029823329; County Code: 26; Collision Date: 2010-03-09; Operator: *

Case Number G000146-10

Latitude

Longitude

Railroad Crossing Number

Roadway Orientation

Pg 4 of 4

Unit Number

N

W

Unit Number

01

NE

SW

W

Unit Number

02

NE


SW

E

US HWY 62



Indicate North by Arrow



CCH LOCUS EVENTS

Unit	Unit	Unit	Unit	Unit	Unit	Unit
01	34	00	00	00	34	34
Unit	Unit	Unit	Unit	Unit	Unit	Unit
02	34	00	00	00	34	34

- 01 Not Applicable
- 02 Overlap/Overlap
- 03 First Collision
- 04 Intersection
- 05 Jurisdiction
- 06 Cargo/Equipment Load or Shift
- 07 Equipment Failure (Blow Tire, Brake Failure, etc.)
- 08 Recombination of Units
- 09 Separated Road Right
- 10 Separated Road Left
- 11 Cross Median/Overline
- 12 Overlap/Overlap

- 21 Half-Jumped From Motor Vehicle
- 22 Thrown Or Falling Object
- 23 Other Non-Fixed Object
- 24 PERSON, MOTOR VEHICLE, OR NON-FIXED OBJECT
- 25 Pedestrian
- 26 Postal Cycle
- 27 Railway Vehicle (Truck, engine)
- 28 Aircraft
- 29 Motor Vehicle - Transport
- 30 Pushed Motor Vehicle
- 31 Struck by Falling, Chilling Cargo or Anything Not in Motion by Motor Vehicle

- 37 Work Zone/Obstruction
- 38 Equipment
- 39 Other Non-Fixed Object
- 40 Fixed Object
- 41 Barrier (Concrete)
- 42 Barrier (Other)
- 43 Fence Pole
- 44 Pole
- 45 Traffic Signal Support
- 46 Traffic Sign Support
- 47 Utility Pole/Light Support
- 48 Other Post/Pole Support
- 49 Guardrail/Retardant Face
- 50 Guardrail End
- 51 Cable
- 52 Comb
- 53 Island
- 54 Sand Barrels
- 55 Impact Alterations/Obstruction
- 56 Collision

- 58 Frequent Drop-Off
- 59 Catch
- 60 Embankment
- 61 Tree (Standing)
- 62 Fencing Strip
- 63 Rubbing Wall
- 64 Bridge Abutment
- 65 Bridge Pier or Support
- 66 Bridge Wall
- 67 Bridge Post
- 68 Bridge Curb
- 69 Bridge Super Structure (Beams)
- 70 Bridge Overhead Structure
- 71 Mailbox
- 72 Other Fixed Object
- 73 Other Highway Structure
- 74 Guardrail
- 75 Unknown

Remarks

UNIT 1 WAS WESTBOUND ON US 62, SLOWING TO MAKE A LEFT TURN ONTO SH 30. UNIT 2 WAS EASTBOUND ON US 62. UNIT 1 ATTEMPTED THE LEFT TURN IN FRONT OF UNIT 2. DRIVER OF UNIT 2 STATED SHE DID NOT EXPECT UNIT 1 TO ATTEMPT THE TURN AND THEREFORE DID NOT HAVE TIME TO APPLY THE BRAKES PRIOR TO IMPACT. AOI WAS APPROX. 4' NORTH OF SOUTH EDGE OF US 62 AND APPROX. 7' EAST OF WEST EDGE OF SH 30. AOR FOR UNIT 1 WAS APPROX. 24' SOUTH OF SOUTH EDGE OF US 62 AND APPROX. 42' EAST OF AOI. AOR FOR UNIT 2 WAS APPROX. 7' SOUTH OF SOUTH EDGE OF US 62 AND APPROX. 57' EAST OF AOI. THERE WERE NO APPARENT SKIDMARKS PRIOR TO AOI FROM EITHER UNIT.

This report is based on the officer's investigation of this collision. This report may contain the opinion of the officer.

DPS: 0192-04 REV-0107

Report Number: '300031535', Scene Date: '2010-03-17', Last Name 1: 'KIRKBY', First Name 1: 'JOSAM', DL No 1: '50829921394', Last Name 2: 'MYER', First Name 2: 'BOB', DL No 2: 'E081223529', County Code: '26', Collision Date: '2010-03-09', Operator: ''

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Bryan Schwartz
Claims Administrator

October 13, 2010

[REDACTED]
Norman, OK [REDACTED]

RE: Claimant: [REDACTED]
 Our File No.: 696205
 Our Client: General Motors LLC
 Date/Event: 3/19/10
 Vehicle: 2006 Chevrolet Cobalt
 VIN: 1G1AK15F967 [REDACTED]

Dear [REDACTED]

This will confirm that we have completed our review of your claim regarding your 2006 Chevrolet Cobalt. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Bryan Schwartz
Claims Administrator