

EWR D&I ANNOTATION

FAN-000001L104001DP132-5595

Artemis # : 000001L104001DP132**Record Created Date :** 06/03/2011**Printed Date :** 06/03/2011**Description :**

DI11-045 SEQ#132: 1 DEATH. 2007 CHEVROLET COBALT. CUSTOMER'S DAUGHTER WAS DRIVING AND AT A CURVE, THE VEHICLE WENT STRAIGHT INSTEAD OF TURNING AND RAN INTO A BOULDER. NONE OF THE AIRBAGS DEPLOYED. CUSTOMER ALLEGES THAT THE STEERING MALFUNCTION CAUSED THE COLLISION AND THE AIRBAG NON-DEPLOYMENT CAUSED THE FATALITY. CUSTOMER STATES THAT THEY RECEIVED A 'RECALL 10023' LETTER IN REGARDS TO POWER STEERING ASSIST FAILURE. ACCORDING TO THE POLICE REPORT PROVIDED, THE DRIVER OF THE VEHICLE SUSTAINED BLUNT IMPACT TRAUMA TO THE HEAD AND SUCCUMBING TO HER INJURIES PRIOR TO THE ARRIVAL OF EMERGENCY SERVICES PERSONNEL. THE POLICE REPORT FURTHER STATES THAT DUE TO THE FACT THAT THE DRIVER HAD A BAC OF 0.219% AND WAS ALSO USING A HAND HELD CELLULAR PHONE DEVICE, SHE FAILED TO MAINTAIN PROPER LANE USE CAUSING HER TO LEAVE THE PAVED ROAD AND ENTER A GRASSY AREA. THIS CAUSED HER TO LOSE CONTROL OF HER VEHICLE. THE VEHICLE OVERTURNED SEVERAL TIMES AFTER STRIKING A ROCK OUTCROP COMING TO REST UPRIGHT IN THE CENTER MEDIAN. ACCORDING TO THE EDR PROVIDED THE VEHICLE SPEED BEFORE IMPACT WAS INVALID, THE STEERING WHEEL ANGLE WAS MAINTAINED AT 0 DEGREES, AND THE MAXIMUM SDM RECORDED VELOCITY CHANGE WAS 6.39MPH. A DISCREPANCY WAS FOUND BETWEEN THE DOCUMENTS PROVIDED AS WELL AS ARTEMIS. THE VEHICLE'S MODEL YEAR IS REPORTED AS 2005 IN THE SERVICE REQUEST DETAIL AND IN THE WARRANTY VEHICLE INFORMATION. HOWEVER, IN ARTEMIS, THE POLICE REPORT AND IN THE EDR IT IS LISTED AS 2007. TWO VIN'S WERE FOUND WHERE THE LAST 6 DIGITS WERE THE SAME BUT THE MODEL YEAR DIGIT DIFFERED. A SEARCH IN ARTEMIS YIELDED RECALL #10V073000, POWER STEERING ASSIST, WAS FOUND AND IS RELATED TO THIS INCIDENT. PLANNED OWNER AND DEALER NOTIFICATION DATE FOR THE ELECTRIC POWER STEERING RECALL #10V073000 WAS ON THE DATE OF THIS INCIDENT. BOTH VIN'S FOUND WERE IN THE RANGE OF THE RECALL. GM'S ASSESSMENT WAS NOT PROVIDED. SERVICE REQUEST DETAIL, VEHICLE WARRANTY INFORMATION, POLICE REPORT AND THE EDR DATA WERE PROVIDED.

*LA

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

April 14, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-045

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 4th quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 9, 12, 35, 41, 50, 51, 61, 62, 64, 74, 75, 102, 104, 105, 106, 132, 138, 142, 155, 158, 163, 167, 168, 177, 187, 198, 199, 231, 235, 236, 238, 260, 265, 268, 292, 294, 306, 315, 324, 325, 339, 341, 343, 358, 359, 380, 383, 401, 402, 403, 418, 454, 504, 517, 523, 525, 531, 543, 556	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **May 13, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

May 12, 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

MAY 13 2011

NVS-217kb
DI11-045

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated April 14, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 4th quarter of 2010.

GM's response is comprised of 59 disks for the incidents that are the subject of DI11-045.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 9 327100506-71-877948747 and 2011 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 9 327100506-71-877948747_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-045
9 327100506-71-877948747
2011 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

9 327100506-71-877948747_01_001- is the first document responsive to Inquiry no.1.
 9 327100506-71-877948747_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI11-045, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(59 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
9	5GAKRBED9BJ [REDACTED]	PAR
12	1G4GE5GDxBF [REDACTED]	PAR
35	1G6DP567150 [REDACTED]	NISM
41	1G6DM57T170 [REDACTED]	NISM
50	1G6DA5EY4B0 [REDACTED]	NISM
51	1G6DG8EG2A0 [REDACTED]	NISM
61	1G6KA5EY8AU [REDACTED]	NISM
62	1G6KD5EY2AU [REDACTED]	NISM
64	1GYUKBEF6AR [REDACTED]	NISM
74	3GYFNAEYXAS [REDACTED]	NISM
75	3GYFNDEY9BS [REDACTED]	NISM
102	KL1TD5DE4AB [REDACTED]	NISM
104	KL1TD5DE1AB [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
105	UNKNOWN	NISM
106	2G1FB1EV2A9	NISM
132	1G1AP18P577	NISM
138	1G1AL58F487	NISM
142	1G1AL58F987	NISM
155	1G1AS58H897	NISM
158	1G1AK18H197	NISM
163	1G1AB1F59A7	NISM
167	1G1AB5F5XA7	NISM
168	1G1AB5F53A7	NISM
177	1G1PG5S97B7	NISM
187	2CNALDECXB6	NISM
198	3GNBABDB8AS	NISM
199	3GNBABDV7AS	PAR
231	2G1WT57N191	NISM
235	2G1WC5EM4A1	NISM
236	2G1WB5EK2A1	NISM
238	2G1WB5EK6A1	NISM
260	1G1ZK57758F	NISM
265	1G1ZE5EB8AF	NISM
268	1G1ZD5EU9BF	RUMOR
292	1GCEC19Z87Z	RUMOR
294	2GCEK13M771	NISM
306	1GCEC19CX9Z	PAR
315	1GCNCPEX1BZ	NISM
324	1GBHK29K87E	NISM
325	1GCHK24K97E	NISM
339	1GNFC16037J	PAR
341	1GNFK36349R	NISM
343	1GNSCJE07BR	NISM
358	1GNFC13088R	NISM
359	1GNUKCE08AR	NISM
380	1GNDT13S652	NISM
383	1GNDS13SX52	PAR
401	UNKNOWN	NISM
402	1GNKRLED3BJ	NISM
403	UNKNOWN	NISM
418	1GKLRLED0AJ	PAR
454	1GT120EG1BF	PAR
504	1G2ZG57B594	NISM
517	1G2MB35B68Y	PAR
523	5Y2SL63885Z	PAR
525	5Y2SL65888Z	PAR
531	1G8ZX57789F	NISM
543	UNKNOWN	NISM
556	3GSDL537X9S	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 59 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer


1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI11-045
132 325749803 – 699460
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document and Police Photos.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No.	71-880150175	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Steering - Power Steering Pump /	Sub-Area	Initiate PAR- Injury
Address		City	Fishkill	Involved Dir		Safety	Yes
State	NY	Con Acct		Source	Phone	Updated	10/14/2010 12:54:22 PM
Serial #/VIN	1G1JC12F457	Model Year	2005	Priority	Medium	Owner	STEWARDE
Make	Chevrolet	Warr. Start		Status	Open	Opened	10/14/2010 11:33:05 AM
Model	Cavalier	Mileage		Sub-Status	Dissatisfied	Closed	
Abstract	(ESIS)Steering - Power Steering Pump / Brackets						
Customer Description	This is a BRC PAR File. Please do not Assume. Forward all Inquiries to Debbie Stewart @ ext 31117						

Pre-PAR

PAR Notifier	3/21/2010 03:00:00 AM	Injuries	Y	Other Veh's	0	People in Veh	1	Road Surface	Asphalt	Road Cond	Dry	Fire Report	N/A	Police Report	unknown
Driver Last Name		Driver First Name		Height	5'5"	DOB		Disabilities	None						
Insurance Agent Last Name	unknown	Insurance Agent First Name	unknown	Phone #		Insurance Agency	Geico Insurance								
Incident Loc	Interstate 84 near Exit 12 eastbound in Fishkill, NY 12524							Incident Desc	Daughter was driving and at a curve her veh went straight instead of turning and ran into a boulder. None of the air bags deployed. I received a recall 10023 after the incident.						
Component	steering							Damage Desc	totaled						
Vehicle Loc	Fast Eddie's, Monticello, NY 845-784-5089							Add'l Info	No repair estimate, cust is unsure of last date veh was serviced or speed of veh, veh may be moved, mother did not have mileage of veh						
Emgcy Svc Names	Fishkill Police, Fire Dept and EMS							Maint Loc	Independent shops						

PAR Detail

Collision	Y	Non Collision		Property Damage	N	Thermal/Evt	N	Spec Equip	None	Property Type	N/A
Vehicle Speed		Weather Condition	clear	Prop Owner		Prop Damage Description	N/A	Prop Est Repair Cost	\$0.00		
Last Service Date		Loc Last Service		Property Location		Inspected By	Inspection Not Performed	Inspection Date/Time			
Veh Est Repair Cost		Spec Equip Installer	N/A	Inspection Type	Steering and Suspension Sys	Explains Other	Forwarding to ESIS				
Primary Veh Use	Personal										
Veh Damage Description	totaled										

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seatbelt
Injury Description			Medical Role		Treatment Location	Treated By
deceased			autopsy		Dutchess county, poughkeepsie, NY	karl reiber, md
Street Address			City	State	Zip Code	
			Fishkill	NY		

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/15/2010 10:37:34 AM	GARCIAJR	ESISBIQU	Escalation	ESIS - Fatalities	In Progress		Fatality - ESIS
Contact Last Name	Contact First Name	Account		BAC Code			
Comments							
							fatality - autopsy - Dutchess county, poughkeepsie, NY - Dr. Karl Reiber, MD
Joe G/PAR/ATX							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:53:06 PM	STEWARDE	STEWARDE	Scheduled Follow-up		Scheduled Alarm		ESIS
Contact Last Name	Contact First Name	Account		BAC Code			
Comments							
							Check to see if ESIS picked up file
Debbie Stewart/PAR/ATX							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:52:39 PM	STEWARDE	GARCIAJR	Notify CRM		Done	10/15/2010 10:37:04 AM	Forwarding to ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Cust alleges a steering malfunction caused a collision and the air bags did not deploy.

Fatality

Insurance Involvement

Forwarding to ESIS

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:49:57 PM	STEWARDE	STEWARDE	BRC PAR	Business Case	Done	10/14/2010 12:52:36 PM	Business Case

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Cust alleges a steering malfunction caused a collision and the air bags did not deploy.

Fatality

Insurance Involvement

Forwarding to ESIS

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:43:25 PM	STEWARDE	STEWARDE	Research		Done	10/14/2010 12:44:44 PM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code

Comments

VIN and CUST scan-no files

No recalls

DRIVER & RIGHT FRONT PASSENGER AIR BAGS

Research completed

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:40:57 PM	STEWARDE	STEWARDE	BRC PAR	Initial Contact- AVM	Done	10/14/2010 12:48:17 PM	Called FFOM Rose Chris @ 914055 8455

Contact Last Name	Contact First Name	Account	BAC Code

Comments

FFOM Name: Chris Rose

Node/Mailbox: 914055 8455

This is Debbie calling from the GM Product Allegaon Dept to make you aware of a file that was received in your area.

The request number is: 71-880150175

The Customer's name is: [REDACTED]

The dealer involved is: none

The vehicle is a: 2005 Chevrolet Cavalier

With current mileage: unknown

The last 8 digits of the VIN# are: 57 [REDACTED]

This involves: Cust alleges steering malfunction caused a collision and the air bags did not deploy causing a fatality.

I will be forwarding the file to our central Claims office, ESIS for further handling. This message is for informational purposes only, however if you do have any questions please feel free to give me a call at 866-790-5600 x31117.

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:40:03 PM	STEWARDE	STEWARDE	BRC PAR	Initial Contact-Dealer	Done	10/14/2010 12:40:55 PM	No call made

Contact Last Name	Contact First Name	Account	BAC Code

Comments

No Initial Contact required. Vehicle has not been to dealer in two years.

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:32:45 PM	STEWARDE	STEWARDE	BRC PAR	Initial Contact-Phone	Done	10/14/2010 12:39:41 PM	Cust transferred from CAC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Spoke to mother confirmed contact info and allegation
CRS adv: Completed PAR questions
Cust sts: Daughter was driving and at a curve her veh went straight instead of turning and ran into a boulder. She was fatally injured. None of the air bags deployed. I received a recall 10023 letter after the incident. The veh may be moved from where it is now or I will have to start paying for storage.
CRS adv: CRS advised customer of required verbiage as stated in d_1075834
Cust sts: continue
CRS adv: Thank you. Gave contact info and SR#
Cust sts: Thank you

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:32:18 PM	STEWARDE	STEWARDE	BRC PAR	Acknowledgement	Done	10/14/2010 12:32:41 PM	Cust transferred from CAC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

See INI

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:31:57 PM	STEWARDE	STEWARDE	BRC PAR	Case Assigned	Done	10/14/2010 12:32:17 PM	STEWARDE x 31117

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:05:52 PM	STEWARDE	STEWARDE	Ownership Changed	Ownership Escalated to BRC	Done	10/14/2010 12:05:52 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 12:02:32 PM	STEWARDE	STEWARDE	Ownership Changed		Done	10/14/2010 12:02:32 PM	Service Request Ownership has changed FROM: FUENTEAM TO: STEWARDE

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
10/14/2010 11:48:39 AM	FUENTEAM	FUENTEAM	Inbound Call Customer	Complex Request	Done	10/14/2010 11:51:10 AM	pre par
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts:
-daughter died of power steering failure validated by letter recall she received today
Cust sks:
-Investigation of the accident by gm
CSR adv:
-I'll be happy to assist you

Amelia/CAC/MNL/T1/Lvl0

Confidential Comments

UCC Information

UCC Code	Symptom	Description
M30 C48	No Symptom Indicated SIR - Did Not Deploy	Steering - Power Steering Pump / Brackets Restraints - (SIR) - Driver Front



Mr. GMVIS 2

October 15, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

**INTERFACE WITH
CUSTOMER****View Vehicle Summary**

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

For this

View V

Vehicle Information

VIN: 1G1JC12F457

Model: 1JC37-2005 CAVALIER 2-DOOR COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: 0_Open

VIEW MORE ACTIONS

View V

View V

Comp

View V

Transa

Detail

View V

Inform

Required Field Actions

Open field actions are highlighted

Vehicle has no current record of required field actions.

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Corrosion Limited Warranty	02/21/2010	09/28/2004	6 MI	09/28/2010	100,006 MI

Emission Select Component Ltd Wty	02/21/2010	09/28/2004	6 MI	09/28/2012	80,006 MI
Bumper to Bumper Limited Warranty	02/21/2010	09/28/2004	8 MI	09/28/2007	36,006 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History


[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
08/27/2004	A [REDACTED]	ZPDI----Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available)

For this
- View v

Vehicle Information

VIN: 1G1JC12F457

Model: 1JC37-2005 CAVALIER 2-DOOR COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: [Q Open](#)

REQUEST ANOTHER VIN

- View v
- View v
- Comp
- View v
- Trans
- Detail
- View v
- Inform

Vehicle Build

Model: 1JC37-2005 CAVALIER 2-DOOR COUPE

Gross Vehicle Weight: 1,595

Order Number: HMXGJQ

Build Date: 08/27/2004

Build Plant: 7-

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker

12C - GRAPHITE

1SA - CAVALIER BASE VEHICLE

6MA - COMPONENT FRT LH

8DH - REAR SPRING

9DH - REAR SPRING

AR9 - CLOTH BUCKET SEATS

C60 - AIR CONDITIONING

DL5 - ROADSIDE SERVICE INFORMATION DECAL

FE9 - 50-STATE EMISSIONS

IPC - INTERIOR TRIM DESIGN

K62 - 105 AMP GENERATOR

LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO

MM5 - 5-SPEED MANUAL TRANSMISSION

NT9 - FED EMIS SYS, TIER 2 PHASE-OUT

QFB - P195/70 R-14 ALS S/B RADIAL BW TIRES

SLM - STOCK ORDERS

UM7 - RADIO, AM/FM STEREO

UX7 - EXTENDED RANGE SPEAKER SYSTEM

V73 - STATEMENT OF VEHICLE CERT.-
U.S./CANADA

VK3 - FRONT LICENSE PLATE BRACKET

12I - GRAPHITE INTERIOR TRIM

1SZ - EQUIPMENT SAVINGS

7MA - 010 COMPONENT FRT LH

91U - ARRIVAL BLUE METALLIC

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR
BAGS

C49 - ELECTRIC REAR WINDOW DEFOGGER

D35 - LH REM, RH MAN SPORT MIRRORS

FE1 - SUSPENSION SYSTEM-SOFT RIDE

FX1 - TRANS/AXLE 3.94 RATIO

J41 - BRAKES, POWER FRT DISC/RR DRUM

L61 - 2.2L DOHC 4 CYL ECOTEC ENGINE

M86 - 5-SPEED MANUAL TRANSMISSION

N46 - STEERING WHEEL 4 SPOKES

PC1 - BOLT-ON FULL WHEEL COVERS

R9U - IDENTIFIER

UH8 - INSTRUMENT CLUSTER W/TACHOMETER

US6 - FIXED MAST ANTENNA-BLACK

V1H - HOOD BLANKET

VH9 - ENVELOPE OWNER INFO MANUAL

VM3 - CONSUMER INFORMATION LABEL

Added Option Codes

Vehicle has no current record of SAIO codes.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



Mr. GMVIS 2

October 15, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build.

For this:

View v

Vehicle Information

VIN 1G1JC12F457

Model: 1JC37-2005 CAVALIER 2-DOOR COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: Q, Open

REQUEST ANOTHER VIN

View v

View v

Compr

View v

Transa

Detail

View v

Inform

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY

Traceability: 408100032

Source Plant: T-CPC TONAWANDA, NEW YORK

Part / Number Broadcast: UZZ

Date Scanned: 08/27/2004

Time Scanned: 08:14:00

Scan Station: 04

Component Code: 35-STEERING COLUMN - SIR SYSTEM

Traceability: 5S1912334

Source Plant: S-SAGINAW DIVISION SAGINAW, MI

Part / Number Broadcast: ZFS

Date Scanned: 08/27/2004

Time Scanned: 07:08:00

Scan Station: 04

Component Code: 61-TRANSMISSION

Traceability: 4157446

Source Plant: 0-

Part / Number Broadcast: UBT

Date Scanned: 08/27/2004

Time Scanned: 08:14:00

Scan Station: 04

Component Code: 86-ELECTRONIC CONTROL MODULE (ECM)

Traceability: 34232SYCN

Source Plant: M-DELCO ELECTRONICS MILWAUKEE, WISCONSIN

Part / Number Broadcast: YJHJ

Date Scanned: 08/27/2004

Time Scanned: 12:29:00

Scan Station: 06

Component Code: AB-IR-MODULE ASM-INFLATOR

Traceability: 3YUJYPN

Source Plant: I-INLAND

Part / Number Broadcast: 0741

Date Scanned: 08/27/2004

Time Scanned: 10:20:00

Scan Station: 04

Component Code: AD-IR-SENSOR-FORWARD

Traceability: C310LM

Source Plant: H-HAMLIN INC, LAKE MILLS WISCONSIN

Part / Number Broadcast: 7309

Date Scanned: 08/27/2004

Time Scanned: 10:38:00

Scan Station: 04

Component Code: AL-IR-MODULE ASM-I/P

Traceability: 3YUJJPJ0

Source Plant: I-INLAND

Part / Number Broadcast: 4591

Date Scanned: 08/27/2004

Time Scanned: 07:29:00

Scan Station: 04

Component Code: CB-SEQ NUM (FLEX) BODY ASM

Traceability: 0670906

Source Plant: -

Part / Number Broadcast: 1ZZ

Date Scanned: 08/21/2004

Time Scanned: 06:06:00

Scan Station:

Component Code: CP-SEQ NUM (FLEX) GEN ASM

Traceability: 5078128

Source Plant: -

Part / Number Broadcast: 1XX

Date Scanned: 08/21/2004

Time Scanned: 10:13:00 Scan Station:

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.



Warranty

Mr. GMVIS 2

October 15, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail



This screen allows GMVIS users to view the available information on individual transaction for the VIN selected

Vehicle Information

VIN 1G1JC12F457

Model: 1JC37-2005 CAVALIER 2-DOOR COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: [Q Open](#)

For this:

[View V](#)[View V](#)[View V](#)[View V](#)[View V](#)[View V](#)[View V](#)[View V](#)[View V](#)[View V](#)

Job Card Date: 08/27/2004

Job Card Number: A77905

Repair Service Agent: 112035

Odometer Reading: 0 MI

H & H CHEVROLET LLC

Authorization Code:

4645 SOUTH 84TH ST

OMAHA NE 68127-1792

4023392222

Process Date:

08/31/2004

Transaction Type:

ZPDI---Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code

0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

Line Total: USD 75.70

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.

**Warranty**

Mr. GMVIS 2

October 15, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

**INTERFACE WITH
CUSTOMER****View Vehicle Delivery Information**

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

For this:

View V

Vehicle Information

VIN: 1G1JC12F457

Model: 1JC37-2005 CAVALIER 2-DOOR COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: [Open](#)

View V

View V

Comp

View V

Transa

Detail

View V

Inform:

Invoice Information

Invoicing Service Agent: 112035

Invoice Date: 08/27/2004

H & H CHEVROLET LLC

4645 SOUTH 84TH ST

OMAHA NE 68127-1792 4023392222

Ship to Information

Invoicing Service Agent: 112035

Ship to Date: N/A

H & H CHEVROLET LLC

4645 SOUTH 84TH ST

OMAHA NE 68127-1792 4023392222

Delivery Information

Delivery Service Agent: 112035

Delivery Date: 09/28/2004

H & H CHEVROLET LLC

Delivery Type: 010--INDIVIDUAL

4645 SOUTH 84TH ST

Delivery Odometer: 6

OMAHA NE 68127-1792 4023392222

In Service Information

Invoicing Service Agent

In Service Date: N/A

In Service Type: 0000

In Service Odometer: 0

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors



New York State Department of Motor Vehicles

POLICE REPORT FOR FATAL MOTOR VEHICLE ACCIDENTS



MV-104D (3/02)

Page 1 of 1 Pages

Local Code (b) (6)	Accident Date Month Day Yr. 3 21 2010	Military Time 02:55	County DUTCHESS	City/Town/Village FISHKILL, TOWN OF	No. Killed 1	No. Vehicles 1	Work Related ☐ Yes ☒ No
Name and Address of Deceased 1: BEACON NY							

ACCIDENT DATA

Speed Limit (MPH) 65	Location (Route or Street Name) I 84 E/B
Estimated Speed: Vehicle 1 _____ MPH ☒ Unknown Vehicle _____ MPH ☐ Unknown Vehicle _____ MPH ☐ Unknown	
Vehicle Model (for example, Mustang or Corvette): Vehicle 1 COBALT Vehicle _____ Vehicle _____	
Roadway Surface: ☐ Concrete ☒ Blacktop ☐ Brick or Block ☐ Dirt ☐ Slag ☐ Gravel ☐ Stone ☐ Other	
No. of Lanes 2	Roadway Flow: ☐ One Way Traffic ☐ DMded highway, other barrier or barrier type unknown ☒ Divided highway, median strip ☐ Divided highway, guard rail ☐ Not physically divided
EMERGENCY MEDICAL SERVICES * Time (Military): Notified _____ 03:06 Arrived at Scene _____ 03:16 Arrived at Hospital _____ 05:24	
HOSPITAL INFORMATION If the victim was taken to a hospital outside of NYS, give name, county and state of that hospital: 1: DUTCHESS - VASSAR BROTHERS HOSPITAL If the victim was transferred to another hospital (after initial transportation), give the name, county and state of that hospital:	

OCCUPANT DATA

Name	Deceased Yes/No	Time of Death	Extricated Yes/No**	Type of Extrication Equip. Used	Air Bags Deployed Yes/No	Not In Vehicle	Initial Point of Impact to Vehicle***
V E H I C L E 1 Driver	YES	04:15	NO		NO	NO	01 - FRONT LEFT
Passenger							
Passenger							
V E H I C L E Passenger							
Passenger							
V E H I C L E Passenger							
Passenger							

* This includes any type of EMS service (for example, fire, police, private). If you are unable to furnish the EMS data, please give the name, address and plate number of the ambulances so we can contact them:

** To be "extricated", the victim must be pried from the wreckage. Unfastening the seat belt is not considered "extricated".

*** Indicate the first area of the vehicle that was impacted, for example, right front, undercarriage.

Additional Information

SIGN HERE	Officer's Rank and Signature TPR <i>[Signature]</i>	Badge/ID No 705	Department 11308	Precinct/Post Troop/Zone T5	Station/Beat/ Sector 21	Reviewing Officer <i>[Signature]</i>	Date/Time Reviewed 5/25/10
Print Name A PIACQUADIO							

TA000112488

New York State Department of Motor Vehicles
POLICE ACCIDENT REPORT
 MV-104A (3/04)

Local Codes

(b) (6)

AMENDED REPORT

1	Accident Date Month 3 Day 21 Year 2010		Day of Week Sunday	Military Time 02:55	No. of Vehicles 1	No. Injured 0	No. Killed 1	Not Investigated at Scene ☐	Left Scene ☐	Police Photos ☒ Yes ☐ No	20	
2	Vehicle 1 - Driver License ID Number [REDACTED]		State of Lic. NY									21
3	Driver Name - exactly as printed on license [REDACTED]											22
4	Address (Include Number and Street) [REDACTED]		Apt. No. [REDACTED]									23
5	City or Town BEACON		State NY									24
6	Date of Birth Month 7 Day 11 Year 1986		Sex F	Unlicensed ☐	No. of Occupants 01	Public Property Damaged ☒						25
7	Name - exactly as printed on registration [REDACTED]		Sex F	Date of Birth Month [REDACTED] Day [REDACTED] Year [REDACTED]								26
8	Address (Include Number and Street) [REDACTED]		Apt. No. [REDACTED]	Reg. Mat. Code [REDACTED]	Released ☐							27
9	City or Town BEACON		State NY									28
10	Plate Number [REDACTED]	State of Reg. NY	Vehicle Year & Make 2007 CHEV	Vehicle Type 2DSD	Ins. Code 100							29
11	Ticket/Arrest Number(s) [REDACTED]											30
12	Violation Section(s) [REDACTED]											31
13	Check if involved vehicle is: ☐ more than 95 inches wide; ☐ more than 34 feet long; ☐ operated with an overweight permit; ☐ operated with an overdimension permit.		Check if involved vehicle is: ☐ more than 95 inches wide; ☐ more than 34 feet long; ☐ operated with an overweight permit; ☐ operated with an overdimension permit.									32
14	VEHICLE 1 DAMAGE CODES Box 1 - Point of Impact Box 2 - Most Damage Enter up to three more damage codes		VEHICLE 2 DAMAGE CODES Box 1 - Point of Impact Box 2 - Most Damage Enter up to three more damage codes									33
15	Vehicle Bv: MANNS TOWING Towed To: MANNS TOWING		Vehicle Bv: [REDACTED] Towed To: [REDACTED]									34
16	VEHICLE DAMAGE CODING: 1-13 SEE DIAGRAM ON RIGHT. 14. UNDERCARRIAGE 17. DEMOLISHED 15. TRAILER 18. NO DAMAGE 16. OVERTURNED 19. OTHER		See the last page of the MV-104A for the accident diagram. Cost of repairs to any one vehicle will be more than \$1000. ☐ Unknown/Unable to determine ☒ Yes ☐ No									35
17	Reference Marker 8 4 I T W Y E 4 4 4		Coordinates (if available) Latitude/Northing: 4598091 Longitude/Easting: 589919		Place Where Accident Occurred: County DUTCHESS ☐ City ☐ Village ☒ Town of FISHKILL Road on which accident occurred I 84 E/B at 1) Intersecting street MPM 44.4 or 2) ☐ N ☐ S of ☐ E ☐ W feet miles (Milepost, Nearest Intersecting Route Number or Street Name)							36
18	Accident Description/Officer's notes OP-V1 TRAVELING EASTBOUND ON INTERSTATE 84 AT MILE POST MARKER 44.4 IN THE LEFT LANE WHILE INTOXICATED AND USING A CELLULAR PHONE DEVICE. V1 LEFT THE ROADWAY FROM THE NORTHERN SHOULDER AND STRUCK A ROCK CUT OUT. V-1 THEN OVERTURNS SEVERAL TIMES AND COMES TO REST IN THE CENTER MEDIAN. OP-V1 SUSTAINED BLUNT IMPACT TRAUMA TO THE HEAD, WITH COMPOUND SKULL FRACTURES AND BRAIN INJURIES DURING THE COLLISION WHICH CAUSED HER DEATH. THRUWAY PROPERTY DAMAGE REPORT NUMBER 5-06228 ASSIGNED.											37

ALL INVOLVED

8	9	10	11	12	13	14	15	16	17 BY	TO 18	Names of all Involved	Date of Death Only
A	1	1	4	1	23	F	12	05	1	9996	1306	3/21/2010
B												
C												
D												
E												
F												
Officer's Rank and Signature TPR [Signature] Print Name A PIACQUADIO In Full												
Badge/ID No.		NCIC No.		Precinct/Post Troop/Zone		Station/Beat Sector		Reviewing Officer		Date/Time Reviewed		
705		11308		T5		21		[Signature] 1497		5/25/10		

New York State Department of Motor Vehicles
POLICE ACCIDENT REPORT
MV-104A (3/04)

Local Codes

(b) (6)

☐ AMENDED REPORT

19

[illegible]

**USE
COVER
SHEET**

N

		8	9	10	11	12	13	14	15	16	17 BY	TO 18	Names of all involved	Date of Death Only
ALL INVOLVED	A													
	B													
	C													
	D													
	E													
	F													
Officer's Rank and Signature TPR <i>[Signature]</i>		Badger ID No.		NCIC No.		Precinct/Post Troop/Zone		Station/Beat Sector		Reviewing Officer		Date/Time Reviewed		
Print Name in Full A PIACQUADIO		705		11308		T5		21						


New York State Department of Motor Vehicles
POLICE ACCIDENT REPORT
 MV-104A (3/04)

Local Codes
(b) (6)

☐ AMENDED REPORT

Accident Date			Day of Week	Military Time	No. of Vehicles	No. Injured	No. Killed	Not Investigated at Scene ☐	Left Scene ☐	Police Photos ☒ Yes ☐ No
Month 3	Day 21	Year 2010	Sunday	02:55	1	0	1	Accident Reconstructed ☐	☐	

INTERSTATE 84 WESTBOUND



INTERSTATE 84 EASTBOUND



NOT TO SCALE

PEDESTRIAN/BICYCLIST/OTHER PEDESTRIAN LOCATION 1. Pedestrian/Bicyclist/Other Pedestrian at Intersection 2. Pedestrian/Bicyclist/Other Pedestrian Not at Intersection PEDESTRIAN/BICYCLIST/OTHER PEDESTRIAN ACTION 1. Crossing, With Signal 2. Crossing, Against Signal 3. Crossing, No Signal, Marked Crosswalk 4. Crossing, No Signal or Crosswalk 5. Riding/Walking/Skating Along Highway With Traffic 6. Riding/Walking/Skating Along Highway Against Traffic 7. Emerging from in Front of/Behind Parked Vehicle 8. Going to/From Stopped School Bus 9. Getting On/Off Vehicle Other Than School Bus 10. Working in Roadway 11. Playing in Roadway 12. Other Actions in Roadway* 13. Not in Roadway (Indicate)* TRAFFIC CONTROL 1. None 2. Traffic Signal 3. Stop Sign 4. Flashing Light 5. Yield Sign 6. Officer/Guard 7. No Passing Zone 8. RR Crossing Sign 9. RR Crossing Flashing Light 10. RR Crossing Gates 11. Stopped School Bus-Red Lights Flashing 12. Construction Work Area 13. Maintenance Work Area 14. Utility Work Area 15. Police/Fire Emergency 16. School Zone 17. Other* LIGHT CONDITIONS 1. Daylight 2. Dawn 3. Dusk 4. Dark-Road Lighted 5. Dark-Road Unlighted ROADWAY CHARACTER 1. Straight and Level 2. Straight and Grade 3. Straight at Milecrest 4. Curve and Level 5. Curve and Grade 6. Curve at Hillcrest ROADWAY SURFACE CONDITION 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 6. Flooded 7. Other* WEATHER 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Freezing Rain 6. Fog/Smog/Smoke 7. Other*	APPARENT CONTRIBUTING FACTORS Human 1. Alcohol Involvement 2. Backing Unsafely 3. Driver Inattention/Distracted* 4. Driver Inexperience* 5. Drugs (Illegal) 6. Failure to Yield Right-of-Way 7. Failure to Keep Right 8. Fatigued/Drowsy 9. Fell Asleep 10. Following Too Closely 11. Illness 12. Lost Consciousness 13. Passenger Distraction 14. Passing or Lane Usage Improper 15. Pedestrian/Bicyclist/Other Pedestrian Error/Confusion 16. Physical Disability 17. Prescription Medication 18. Traffic Control Disregarded 19. Turning Improperly 20. Unsafe Speed 21. Unsafe Lane Changing 22. Cell Phone (hand-held) 23. Cell Phone (hands-free) 24. Other Electronic Device* 25. Outside-Car Distraction* 26. Reaction to Other Uninvolved Vehicle 27. Aggressive Driving/Road Rage Vehicular 41. Accelerator Defective 42. Brakes Defective 43. Headlights Defective 44. Other Lighting Defects 45. Oversized Vehicle 46. Steering Failure 47. Tire Failure/Inadequate 48. Tow Hitch Defective 49. Windshield Inadequate 50. Driverless/Runaway Vehicle 51. Other Vehicular* Environmental 61. Animal's Action 62. Glare 63. Lane Marking Improper/Inadequate 64. Obstruction/Debris 65. Pavement Defective 66. Pavement Slippery 67. Shoulders Defective/Improper 68. Traffic Control Device Improper/Non-Working 69. View Obstructed/Limited	DIRECTION OF VEHICLE: Vehicle 19 Vehicle 20 Vehicle 21 Vehicle 22 Vehicle 23 Vehicle 24 Vehicle 25 Vehicle 26 Vehicle 27 Vehicle 28 Vehicle 29 Vehicle 30
New York State Department of Motor Vehicles POLICE ACCIDENT REPORT MV-104A (7/01) *EXPLAIN IN ACCIDENT DESCRIPTION If a question DOES NOT APPLY, enter a dash (-). If an answer is UNKNOWN, enter an "X".		
WHICH VEHICLE OCCURRED 1. Vehicle No. 1 A. All-Terrain Vehicle (ATV) O. Other* 2. Vehicle No. 2 B. Bicyclist P. Pedestrian 3. In-Line Skater S. Snowmobiler POSITION IN ON VEHICLE 1. Driver 2-7. Passenger 8. Riding/Hanging on Outside SAFETY EQUIPMENT USED 1. None 2. Lap Belt 3. Harness 4. Lap Belt/Harness 5. Child Restraint Only 6. Helmet (Motorcycle Only) 7. Air Bag Deployed 8. Air Bag Deployed/Lap Belt 9. Air Bag Deployed/Harness A. Air Bag Deployed/Lap Belt/Harness B. Air Bag Deployed/Child Restraint EJECTION FROM VEHICLE 1. Not Ejected 2. Partially Ejected 3. Ejected AGE SEX W F	LOCATION OF MOST SEVERE PHYSICAL COMPLAINT 1. Head 2. Face 3. Eye 4. Neck 5. Chest 6. Back 7. Shoulder-Upper Arm 8. Elbow-Lower Arm-Hand 9. Abdomen - Pelvis 10. Hip-Upper Leg 11. Knee-Lower Leg-Foot 12. Entire Body TYPE OF PHYSICAL COMPLAINT 1. Amputation 2. Concussion 3. Internal 4. Minor Bleeding 5. Severe Bleeding 6. Minor Burn 7. Moderate Burn 8. Severe Burn 9. Fracture - Dislocation 10. Contusion - Bruise 11. Abrasion 12. Complaint of Pain 13. None Visible 14. Whiplash VICTIM'S PHYSICAL AND EMOTIONAL STATUS 1. Apparent Death 2. Unconscious 3. Semiconscious 4. Incoherent 5. Shock 6. Conscious	PRE-ACCIDENT VEHICLE ACTION 1. Going Straight Ahead 2. Making Right Turn 3. Making Left Turn 4. Making U Turn 5. Starting from Parking 6. Starting in Traffic 7. Stopping or Stopping 8. Stopped in Traffic 9. Entering Parked Position 10. Parked 11. Avoiding Object in Roadway 12. Changing Lanes 13. Passing 14. Merging 15. Backing 16. Police Pursuit 17. Other* LOCATION OF FIRST EVENT 1. On Roadway 2. Off Roadway TYPE OF ACCIDENT - COLLISION WITH 1. Other Motor Vehicle 6. In-Line Skater 2. Pedestrian 7. Deer 3. Bicyclist 8. Other Pedestrian 4. Animal 10. Other Object (Not Fixed) 5. Railroad Train COLLISION WITH FIXED OBJECT 11. Light Support/Utility Pole 12. Guide Rail-Not At End 13. Guide Rail-End 14. Crash Cushion 15. Sign Post 16. Tree 17. Building/Wall 18. Curbing 19. Fence 20. Bridge Structure 21. Culvert/Head-Wall 22. Median-Not At End 23. Median-End 24. Barrier 25. Snow Embankment 26. Earth Embankment/Rock Cut/Ditch 27. Fire Hydrant 28. Other Fixed Object* NO COLLISION 31. Overturned 32. Fire/Explosion 33. Submersion 34. Ran Off Roadway Only 40. Other*
INJURED TAKEN BY TO 18		

JUN 28 2010

NEW YORK STATE THRUWAY AUTHORITY

INTER OFFICE MEMO

TO: Mr. W. Behrens DATE: June 21, 2010
FROM: Mr. C. Richards SUBJECT: 1 vehicle PIAA involving a Fatal
DATE: March 21, 2010
TIME: 0303 hours
LOCATION: I-84 Eastbound Milepost 44.4
COMPLAINT: (b) (6)
WEATHER: Clear ROAD: Dry

On March 21, 2010, at 0324 hours, I was advised of a personal injury auto accident involving a fatality. The accident occurred on I-84 eastbound, in the vicinity of mile post 44.4.

Upon arrival at the scene at 0427 hours, I located vehicle #1, a 2007 Chevrolet 2 door sedan, bearing New York registration [REDACTED] registered to and operated by [REDACTED] (deceased), DOB: [REDACTED], residing at [REDACTED] Beacon, NY. Vehicle #1 was insured by Geico Indemnity Company (Code 100). There were no other occupants in vehicle #1.


Investigation revealed that vehicle #1 was being operated on I-84 eastbound, in the left lane of the two lane roadway. In this area I-84 exists as a four lane roadway divided into two lanes for eastbound traffic and two lanes for westbound traffic separated by a grassy median with an average width of approximately 90 feet. A gradual slope runs from the eastbound roadway down to the center point of the median, with a resulting decrease in elevation of approximately 5 feet. On approach to the accident scene, the eastbound roadway characteristic is horizontally level with a slight upward vertical inclination as it begins to curve to the right. The pavement is smooth and devoid of any irregularities that would cause a vehicle to unintentionally change course. In the vicinity of milepost 44.35 eastbound, vehicle #1 veered left onto the left shoulder and continued onto the grassy center median, traveling in a straight forward direction for approximately 202 feet, where the driver's side front of vehicle #1 struck a rock outcrop located 17.5 feet from the outside edge of the eastbound roadway's yellow fog line. Vehicle #1 continued to travel forward in a generally liner direction, overturning several times and coming to rest upright, in the center median, approximately 61.5 feet (measured perpendicularly) from the outside edge of the eastbound roadway's yellow fog line. [REDACTED] sustained blunt impact trauma to her head and succumbed to her injuries prior to the arrival of emergency services personnel. She was pronounced dead at 0415 hours by Investigator Eric Benjamin, of the Dutchess County Coroner's Office, and was

transported from the scene by personnel from the Atchmoody Funeral Home to Vasser Brothers Medical Center located in Poughkeepsie, New York.

The cause of the accident was the direct result of [REDACTED] failing to maintain proper lane use. Her vehicle left the paved roadway and entered onto a grassy area, causing her to lose control of her vehicle. Her actions may have been due to the fact that she was operating her vehicle while under the influence of alcohol, in combination with the use of a hand held cellular phone device. Responding/investigating New York State Trooper A. Piacquadio generated a Police Accident Report indicating the apparent contributing factors as alcohol involvement and cell phone use (hand held). New York State Police Sergeant S. Garrison advised me that the toxicology report indicated that [REDACTED] blood alcohol content was measured at .219%.

Photos taken CJR-D2072 thru CJR-D2082, CJR-D2107, and CJR-D2108.

Attached are the MV-104 A, MV-104D, and CAD report.


Christopher Richards
Assistant Traffic Supervisor
New York Division

CR/cr
Attach.
Cc: Mr. Nadratowski
Daybook
File

INCIDENT HISTORY DETAIL: T100800044

INITIATE: 03:03:46 03/21/10 CALL NUMBER: T0044
 ENTRY: 03:06:34 CURRENT STATUS: CLOSED
 DISPATCH: 03:10:08 PRIMARY UNIT: 7539
 ONSCENE: 03:11:28 CASE NUMBER: (b) (6)
 CLOSE: 06:19:09 DISPOSITION: TA

LOCATION: 44.5 E I84 TH (8412ED RA & 8412EA)

LOCATION COMMENTS:

DAREA: MH

BEAT: 36

RD: 8454451E

OLD TYPE: AA FINAL: FAT Fatality
 PRIORITY: 1

03:06:34 DNY1 ENTRY TEXT: FISHKILL PD STATED AA IN MEDIAN ONE CAR POSSIBLE
 EJECTION? UNKNOWN E OR W UNKNOWN BEFORE OR AFTER
 COMP: DUTCHESS-

03:09:08 DNY1 HOLD

03:10:08 DNY1 DISP-ENR 7539 7505

03:10:25 DNY1 BACKUP 7539 758

03:10:28 DNY1 ENROUTE 758

03:11:06 DNY1 MISC .44, AS PER PD THEY HAVE A UNIT OUT THERE AS WELL,
 THEY ONLY HAVE A PASSENGER OF THE CAR, THEY CAN'T FIND
 THE DRIVER SO FAR, AS PER OUR SP START EMS POSSIBLE
 SERIOUS STANDING BY FOR FURTHER

03:11:16 DNY1 MISC .44, EMS IS ENROUTE CONFIRMED BY DUTCHESS.

03:11:25 DNY1 NEWLOC LOCATION: 44.77 E I84 TH-->44.5 E I84 TH

03:11:28 DNY1 ONSCENE 7505

03:11:28 DNY1 ONSCENE 7539

03:13:28 DNY1 MISC .44, NO LANE BLOCKAGE THAT I KNOW OF

03:13:49 DNY1 ONSCENE 758

03:16:04 DNY1 QUERY 7539 RVOS MIS/SAME LIC/DTX3651

03:16:34 DNY1 MISC 7539, DNY1JGOODE0001 NYMV RALL TTHR 0316 NPLDTX3651
 HDR: [REDACTED] LIC/ [REDACTED] LIY/2011.
 LIT/PC. VIN/1G1AP18P577 [REDACTED] VYR/2007. VMA/CHEV.
 VMO/CBT. VST/2D. VCO/BLK 2007 CHEVROLET CBT, BLACK
 TWO-DOOR SEDAN, 2898 POUNDS ** REGISTERED TO **
 [REDACTED] DOB/ [REDACTED] SEX/FEMALE. [REDACTED]
 [REDACTED] BEACON, NY [REDACTED] LICENSE PLATE: [REDACTED] DMV
 REGISTRATION CLASS: PAS (016) INSURANCE: GEICO
 INDEMNITY COMPANY (100) REGISTRATION EXPIRATION DATE:
 2011-01-02 STATUS: VALID[03/21/[REDACTED]]

03:19:06 DNY1 MISC .44, AS PER 758 BRING A CAMERA 7528 ENRT

03:19:11 DNY1 BACKUP 758 7528

03:19:14 DNY1 ENROUTE 7528

03:20:31 DSP1 SUPP TEXT: APPEARS TO BE SINGLE OCCUPANT FATAL

03:20:58 DNY1 FNU/TYPE FINALTYPE: AA-->FAT

03:24:57 DSR1 MISC .44, MR RICHARDS (TRAFFIC) ADVISED

03:25:10 DSR1 BACK-ER 758 1162

03:26:40 DNY1 MISC .44, LEFT LANE EB AND WB ARE NOW BLOCKED WITH
 INVESTIGATION

03:27:47 DSR1 MISC .44, MS GARRISON (DUTY) ADVISED

03:28:47 DSR1 MISC .44, MS GRAHAM (PUBLIC INFO) ADVISED

03:30:06 DSP1 SUPP TEXT: FL 28 SENT AND DUTCHESS COUNTY CORONER'S OFFICE
 ADVISED

03:31:00 DSR1 MISC .44, MR STAHL (OPS/MIANT) ADVISED // PER OPS/MAINT

ADVISED EXECUTIVE AT 06:00
03:43:29 DSP1 SUPP TEXT: INV BENJAMIN FROM CORONER'S OFFICE ENROUTE-ETA
APPROX 60 MINUTES
04:01:41 DSR2 MISC .44, DSR2LGAMBL0010 NYMV DGRP TTHR 0400 GRPKOSILLA, NE-
IL M TODAYS DATE: 2010-03-21 04:00:30 CLIENT ID:
DOB: SEX: MALE
HEIGHT: 5 FEET 08 EYES: BROWN FISHKILL NY
COUNTY: DUTCHESS MOTORIST ID #:
LICENSE CLASS: CDL *A* EXPIRATION:
2015-06-19 STATUS: VALID RESTRICTIONS: TYPE: CLASS
CHANGE DATE: 1992-06-18 IMAGE CAPTURE DATE: 2007-04-27
IMAGE: KEPT[03/21]
04:04:10 DSR2 QUERY 7528 RVOS MIS/X LIC/
04:04:59 DSR2 MISC .44, DSR2LGAMBL0010 NYMV RALL TTHR 0404 NPLBPC6127
HEDR/ LIC/ LIY/2010.
LIT/PC. VIN/1GCCS339588 VYR/2008. VMA/CHEV.
VMO/CLD. VST/PK. VCO/ONG 2008 CHEVROLET COLORADO,
ORANGE PICK-UP TRUCK, 3658 POUNDS ** REGISTERED TO **
DOB/ SEX/MALE.
FISHKILL, NY LICENSE PLATE: DMV
REGISTRATION CLASS: PAS (016) INSURANCE: STATE FARM
MUT AUTO CO (328) REGISTRATION EXPIRATION DATE:
2010-07-09 STATUS: VALID[03/21]
04:27:25 DSR2 ONSCENE 1162
04:38:31 DNY1 INSRVICE 7528
04:49:13 DSP1 SUPP TEXT: ROBERT AUCHMOODY FUNERAL HOME CONTACTED AND THEY
WILL RESPOND ASAP
04:50:35 DNY1 CASE 7539 MHL000000558 Assigned
04:51:46 DNY1 CASE-INF #44, TFR/PIACQUADIO 7539: CMPT-NO/MHL0000558:
TYPE/FAT: TIME/0306: LOC/44.5 E I84: MIS/CBI:
04:53:31 DSR1 MISC .44, NO TRAFFIC DELAYS AT THIS TIME
04:57:20 DSP1 SUPP TEXT: FUNERAL HOME ETA 0530
05:02:35 DSR2 QUERY 7539 RVOS MIS/X LIC/
05:03:54 DSR2 MISC .44, DSR2LGAMBL0010 NYMV DLIC TTHR 0502 LIC/
TODAYS DATE: 2010-03-21 05:02:41 CLIENT ID:
DOB: SEX: FEMALE
HEIGHT: 5 FEET 07 EYES: BROWN BEACON NY
12508 COUNTY: DUTCHESS MOTORIST ID #:
LICENSE CLASS: *DM* EXPIRATION:
2015-07-11 STATUS: VALID RESTRICTIONS: TYPE: CLASS
CHANGE DATE: 2003-04-30 IMAGE CAPTURE DATE: 2007-06-27
IMAGE: KEPT[03/21]
05:25:26 DNY1 BACKUP 7539 520
05:26:47 DNY1 ENROUTE 520
05:57:48 DSR1 MISC .44, MR BELL (EXECUTIVE) ADVISED
06:03:40 DNY1 MISC .44, ALL LANES CLEAR BOTH DIRECTIONS
06:03:52 DNY1 ONSCENOK 1162
06:03:52 DNY1 ONSCENOK 7505
06:03:52 DNY1 ONSCENOK 7539
06:03:52 DNY1 ONSCENOK 758
06:10:12 DSR1 MISC .44, 1162 CLEAR
06:10:15 DSR1 INSRVICE 1162
06:11:36 DNY1 ONSCENOK 520
06:11:51 DNY1 INSRVICE 758
06:11:51 DNY1 INSRVICE 7505
06:11:51 DNY1 INSRVICE 520
06:13:38 DNY1 PROP-DMG .44, 5-06228 2 DELINATORS
06:19:09 DNY1 CLEAR 7539 TA, ALL UNITS CLEAR
06:19:09 DNY1 CLOSE 7539 TA, ALL UNITS CLEAR
06:21:57 DNY1 MISC .44, IN 15257 NY

OPERATOR ASSIGNMENTS: DNY1 JGOODE JILLIAN GOODENOUGH
DSP1 MKOPP MICHAEL KOPP
DSR1 PSABAT PAUL SABATINO
DSR2 LGABEL
AS OF 06:10:12: DSR1 WDORPF BILL DORPFELD



163099 - 163138
[REDACTED] # 699460

DISC 2 OF 2

F10 - 0298
MH10-0558

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G1AP18P577
User	r.h.schottler
Case Number	699460
EDR Data Imaging Date	11/08/2010
Crash Date	03/21/2010
Filename	1G1AP18P577.ACM.CDRX
Saved on	Monday, November 8 2010 at 12:04:55
Collected with CDR version	Crash Data Retrieval Tool 3.5.1
Reported with CDR version	Crash Data Retrieval Tool 3.5.1
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

Comments

Just this investigator
at fast eddies salvage yard
plugged directly into sdm

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM. The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record up to 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data

-Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.

-The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-The ignition cycle counter relies upon the transitions through OFF→RUN→CRANK power-modifying messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.

-Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMEps_r002

Multiple Event Data

Associated Events Not Recorded	7
An Event(s) Preceded the Recorded Event(s)	Yes
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	Yes
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	Yes

System Status At AE

Vehicle Identification Number	**1AP18P*Z
Low Tire Pressure Warning Lamp (If Equipped)	OFF
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Invalid
Transmission Selector Position (If Equipped)	Invalid
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	52
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	No	No
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	Invalid	Invalid	Invalid	Invalid	Invalid
Engine Speed (RPM)	3456	3456	3456	3264	2816
Percent Throttle Accelerator Pedal Position (percent)	38	38	38	36	12
Antilock Brake System Active (If Equipped)	18	18	18	15	0
Lateral Acceleration (feet/s²) (If Equipped)	No	No	No	Yes	Yes
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
	Invalid	Invalid	Invalid	Invalid	Invalid


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	7002
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	6990
Ignition Cycles At Event	6991
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Invalid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	6.39
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	70
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Vehicle Event Data (Pre-Crash) Associated With This Event	No
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-0.68	-1.36	-2.71	-3.39	-4.07	-4.74	-5.42	-5.42	-5.42	0.00	0.00	0.00	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.68	1.36	2.03	2.71	2.71	3.39	3.39	3.39	0.00	0.00	0.00	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```

$01 08 00 00 00 00 00 00
$02 30 00 00 00 00 00 00
$03 00 00 00 00 00 00 00
$04 00 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 0A 00 03 0A 00 00
$07 00 20 00 00 00 00 00
$08 00 00 00 00 00 00 00
$09 00 00 00 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 0F 0F 03 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F 00 00 00 00 00 00 00
$10 00 00 00 00 00 C0 00
$11 00 00 00 00 00 C0 00
$12 00 00 00 00 00 C0 00
$13 00 00 00 00 00 C0 00
$14 00 00 00 00 00 C0 00
$15 00 00 00 00 00 C0 00
$16 03 06 0C 16 34 C0 00
$17 00 00 00 00 00 C0 00
$18 00 00 00 00 00 C0 00
$19 00 00 00 00 00 00 00
$1B 3F 30 00 67 00 7A 00
$1C 3F 30 00 62 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 00 00 00 00 00 00 00
$1F 28 00 00 00 00 00 00
$20 40 00 00 00 00 00 00
$21 00 00 00 00 F0 00 00
$22 00 8A 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 1B 4E 00 00
$2F 00 FE 1B 5A 0B 00 00
$30 9D 00 00 00 00 00 00
$31 00 27 2F 2F 2F 00 00
$32 00 00 00 00 00 00 00
$33 1F 5B 60 60 60 00 00
$34 2C 33 36 36 36 00 00
$35 78 90 95 96 97 80 00
$36 00 00 00 00 00 00 00
$37 C0 00 00 09 0A 00 78
$38 66 00 40 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00

```

```

$3C 00 00 00 00 00 00 C0
$3D 31 41 50 31 38 50 00
$3E 37 17 79 05 00 00 00
$3F AF 00 90 00 00 00 00
$40 00 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 1B 4E 00 00
$43 FE 1B 4F 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 FF 01 FE 02 FC 00
$48 03 FB 04 FA 04 F9 00
$49 05 F8 05 F8 05 F8 00
$4A 00 00 00 00 00 00 00
$4B 00 00 00 00 00 00 00
$4C 00 00 00 00 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 D0 00 00 00 00 00 00
$52 80 00 00 00 00 00 00
$53 07 00 59 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 32 39 34 39 52 36 31 34 33 32 34 46 36 43
$02 41 0A 99 B3
$03 41 54 32 39 34 39 52 36 31 35 31 33 34 47 42 32
$04 41 0A 99 B3
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 36 31 39 31 32 44 34 54 56
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 06 32 35 35 38 32 4A 33
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 37 35 E1 72 6A 74 91 9A

```

```

$22 39 14
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA
$26 32 41 FA FA FA FA FA
$40 00 00
$41 3F 30 00 62 00 1A
$42 D0 C4
$43 00 00 8E 80
$44 C6 00 00 FC C0 C0
$45 07 01 07 01 05 01
$46 FF 1B 1B 64 28
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 33 39 31 34 32 32 30 35 32 56 20 20 20 20
$B7 50 AA 04 0F 07
$B8 43 48 70 02 09
$C1 30 46 30 37
$CA 30 46 30 37
$CB 01 89 6E 6A
$CC 01 89 6E 6A
$D1 00 00
$DB 00 00
$DC 00 00

```

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.

CDR File Information

User Entered VIN	1G1AP18P577
User	r.h.schottler
Case Number	699460
EDR Data Imaging Date	11/08/2010
Crash Date	03/21/2010
Filename	1G1AP18P577.ACM.CDRX
Saved on	Monday, November 8 2010 at 12:04:55
Collected with CDR version	Crash Data Retrieval Tool 3.5.1
Reported with CDR version	Crash Data Retrieval Tool 3.5.1
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non-Deployment Event cannot be overwritten or cleared by the SDM. The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record up to 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data

-Driver's and Passenger's Belt Switch Circuit Status Indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.

-The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.

-Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMEps_r002

Ignition Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$2F Bytes 3-4	\$1B5A	Ignition Cycles at Investigation	7002	cycles

Vehicle Status Data (Pre-Crash)

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID Pack \$31 Byte 1	\$00	Accelerator Pedal Position (-1 sec)	0	% full throttle
DPID Pack \$31 Byte 2	\$27	Accelerator Pedal Position (-2 sec)	15	% full throttle
DPID Pack \$31 Byte 3	\$2F	Accelerator Pedal Position (-3 sec)	18	% full throttle
DPID Pack \$31 Byte 4	\$2F	Accelerator Pedal Position (-4 sec)	18	% full throttle
DPID Pack \$31 Byte 5	\$2F	Accelerator Pedal Position (-5 sec)	18	% full throttle
DPID \$31 Byte 6 bit 7	\$00	Accelerator Pedal Position Validity Status	Valid	
DPID \$32 Byte 1 bit 7	\$00	Brake Switch Circuit State (-1 sec)	OFF	
DPID \$32 Byte 1 bit 6	\$00	Brake Switch Circuit State (-2 sec)	OFF	
DPID \$32 Byte 1 bit 5	\$00	Brake Switch Circuit State (-3 sec)	OFF	
DPID \$32 Byte 1 bit 4	\$00	Brake Switch Circuit State (-4 sec)	OFF	
DPID \$32 Byte 1 bit 3	\$00	Brake Switch Circuit State (-5 sec)	OFF	
DPID \$32 Byte 2 bit 7	\$00	Brake Switch Circuit State Validity Status	Valid	
DPID \$32 Byte 3 bit 7	\$00	Cruise Control Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 6	\$00	Cruise Control Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 5	\$00	Cruise Control Resume Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 4	\$00	Cruise Control Resume Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 3	\$00	Cruise Control Set Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 2	\$00	Cruise Control Set Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 1	\$00	Reduced Engine Power Mode (-1sec)	OFF	
DPID \$32 Byte 3 bit 0	\$00	Reduced Engine Power Mode (-2sec)	OFF	
DPID \$32 Byte 4 bit 7	\$00	Cruise Control Active Validity Status If Equipped	Valid	
DPID \$33 Byte 1	\$1F	Throttle Position (-1 sec)	12	% full throttle
DPID \$33 Byte 2	\$5B	Throttle Position (-2 sec)	36	% full throttle
DPID \$33 Byte 3	\$60	Throttle Position (-3 sec)	38	% full throttle
DPID \$33 Byte 4	\$60	Throttle Position (-4 sec)	38	% full throttle
DPID \$33 Byte 5	\$60	Throttle Position (-5 sec)	38	% full throttle
DPID \$33 Byte 6 bit 7	\$00	Throttle Position Validity Status	Valid	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$34 Byte 1	\$2C	Engine Speed (-1 sec)	2816	RPM
DPID \$34 Byte 2	\$33	Engine Speed (-2 sec)	3264	RPM
DPID \$34 Byte 3	\$36	Engine Speed (-3 sec)	3456	RPM
DPID \$34 Byte 4	\$36	Engine Speed (-4 sec)	3456	RPM
DPID \$34 Byte 5	\$36	Engine Speed (-5 sec)	3456	RPM
DPID \$34 Byte 6 bit 7	\$00	Engine Speed Validity Status	Valid	
DPID \$35 Byte 1	\$78	Vehicle Speed (-1 sec)	75	MPH
DPID \$35 Byte 2	\$90	Vehicle Speed (-2 sec)	89	MPH
DPID \$35 Byte 3	\$95	Vehicle Speed (-3 sec)	93	MPH
DPID \$35 Byte 4	\$96	Vehicle Speed (-4 sec)	93	MPH
DPID \$35 Byte 5	\$97	Vehicle Speed (-5 sec)	94	MPH
DPID \$35 Byte 6 bit 7	\$80	Vehicle Speed Validity Status	Invalid	
DPID \$36 Byte 1	\$00	Steering Wheel Angle (-1 sec) If Equipped	0	degrees
DPID \$36 Byte 2	\$00	Steering Wheel Angle (-2 sec) If Equipped	0	degrees
DPID \$36 Byte 3	\$00	Steering Wheel Angle (-3 sec) If Equipped	0	degrees
DPID \$36 Byte 4	\$00	Steering Wheel Angle (-4 sec) If Equipped	0	degrees
DPID \$36 Byte 5	\$00	Steering Wheel Angle (-5 sec) If Equipped	0	degrees
DPID \$36 Byte 6 bit 7	\$00	Steering Wheel Angle Validity Status If Equipped	Valid	
DPID \$37 Byte 1 bit 7	\$C0	Antilock Brake System Active (-1 sec) If Equipped	Yes	
DPID \$37 Byte 1 bit 6	\$C0	Antilock Brake System Active (-2 sec) If Equipped	Yes	
DPID \$37 Byte 1 bit 5	\$C0	Antilock Brake System Active (-3 sec) If Equipped	No	
DPID \$37 Byte 1 bit 4	\$C0	Antilock Brake System Active (-4 sec) If Equipped	No	
DPID \$37 Byte 1 bit 3	\$C0	Antilock Brake System Active (-5 sec) If Equipped	No	
DPID \$37 Byte 2 bit 7	\$00	Traction Control System Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 7	\$00	Vehicle Dynamics Control Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 6	\$00	Vehicle Dynamics Control Active (-2 sec) If Equipped	No	
DPID \$37 Byte 3 bit 5	\$00	Vehicle Dynamics Control Active (-3 sec) If Equipped	No	
DPID \$37 Byte 3 bit 4	\$00	Vehicle Dynamics Control Active (-4 sec) If Equipped	No	
DPID \$37 Byte 3 bit 3	\$00	Vehicle Dynamics Control Active (-5 sec) If Equipped	No	
DPID \$37 Byte 4 bits 3-0	\$09	Transmission Range (-1 sec) If Equipped	Neutral	
DPID \$37 Byte 5 bits 3-0	\$0A	Transmission Selector Position (-1 sec) If Equipped	Park	
DPID \$37 Byte 6 bit 7	\$00	Service Engine Soon (Non-Emission Related) Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 6	\$00	Service Vehicle Soon Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 3	\$00	Brake System Warning Lamp If Equipped	OFF	
DPID \$37 Byte 6 bit 1	\$00	Low Tire Pressure Warning Lamp If Equipped	OFF	
DPID \$37 Byte 7 bit 7	\$78	Antilock Brake System Active Validity Status If Equipped	Valid	
DPID \$37 Byte 7 bit 6	\$78	Traction Control System Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 5	\$78	Vehicle Dynamics Control Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 4	\$78	Transmission Range Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 3	\$78	Transmission Selector Position Validity Status If Equipped	Invalid	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$37 Byte 7 bit 2	\$78	Service Engine Soon (Non-Emission Related) / Service Vehicle Soon Lamp Validity Status	Valid	
DPID \$37 Byte 7 bit 1	\$78	Low Tire Pressure Warning Lamp Validity Status If Equipped	Valid	
DPID \$38 Byte 1	\$86	Outside Air Temperature (-1 sec) If Equipped	52	
DPID \$38 Byte 2 bit 7	\$00	Outside Air Temperature Validity Status (-1 sec) If Equipped	Valid	
DPID \$38 Byte 5 bits 7-6	\$03	Left Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 5-4	\$03	Right Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 3-2	\$03	Rear Door(s) Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 1-0	\$03	Left Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 6 bits 7-6	\$C0	Right Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 7 bit 7	\$00	Left Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 6	\$00	Right Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 5	\$00	Rear Door(s) Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 4	\$00	Left Rear Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 3	\$00	Right Rear Door Validity Status If Equipped	Valid	
DPID \$39 Byte 1	\$00	Lateral Acceleration (-1 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 2	\$00	Lateral Acceleration (-2 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 3	\$00	Lateral Acceleration (-3 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 4	\$00	Lateral Acceleration (-4 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 5	\$00	Lateral Acceleration (-5 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 6 bit 7	\$80	Lateral Acceleration Validity Status If Equipped	Invalid	
DPID \$3A Byte 1	\$00	Yaw Rate (-1 sec) If Equipped	0	
DPID \$3A Byte 2	\$00	Yaw Rate (-2 sec) If Equipped	0	
DPID \$3A Byte 3	\$00	Yaw Rate (-3 sec) If Equipped	0	
DPID \$3A Byte 4	\$00	Yaw Rate (-4 sec) If Equipped	0	
DPID \$3A Byte 5	\$00	Yaw Rate (-5 sec) If Equipped	0	
DPID \$3A Byte 6 bit 7	\$80	Yaw Rate Validity Status If Equipped	Invalid	

VIN Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3D Byte 1	\$31	Vehicle Identification Number (VIN) Digit 3	1	
DPID \$3D Byte 2	\$41	Vehicle Identification Number (VIN) Digit 4	A	
DPID \$3D Byte 3	\$50	Vehicle Identification Number (VIN) Digit 5	P	
DPID \$3D Byte 4	\$31	Vehicle Identification Number (VIN) Digit 6	1	
DPID \$3D Byte 5	\$38	Vehicle Identification Number (VIN) Digit 7	8	
DPID \$3D Byte 6	\$50	Vehicle Identification Number (VIN) Digit 8	P	
DPID \$3E Byte 1	\$37	Vehicle Identification Number (VIN) Digit 10	7	
DPID \$3E Byte 2 bits 7-4	\$17	Vehicle Identification Number (VIN) Digit 12	1	
DPID \$3E Byte 2 bits 3-0	\$17	Vehicle Identification Number (VIN) Digit 13	7	
DPID \$3E Byte 3 bits 7-4	\$79	Vehicle Identification Number (VIN) Digit 14	7	
DPID \$3E Byte 3 bits 3-0	\$79	Vehicle Identification Number (VIN) Digit 15	9	
DPID \$3E Byte 4 bits 7-4	\$05	Vehicle Identification Number (VIN) Digit 16	0	
DPID \$3E Byte 4 bits 3-0	\$05	Vehicle Identification Number (VIN) Digit 17	5	

Multiple Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 1 bit 7	\$AF	An Event(s) Preceded the Recorded Event(s)	Yes	
DPID \$3F Byte 1 bit 6	\$AF	An Event(s) was in Between the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 5	\$AF	An Event(s) Followed the Recorded Event(s)	Yes	
DPID \$3F Byte 1 bit 4	\$AF	The Event(s) Not Recorded was a Deployment Event(s)	No	
DPID \$3F Byte 1 bit 3	\$AF	The Event(s) Not Recorded was a Non-Deployment Event(s)	Yes	
DPID \$3F Byte 1 bits 2-0	\$AF	Associated Events Not Recorded	7	

Power Mode Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 3 bits 7-6	\$90	Vehicle Power Mode Status	Run	
DPID \$3F Byte 3 bit 5	\$90	Remote Start Status If Equipped	Inactive	
DPID \$3F Byte 3 bit 4	\$90	Run/Crank Ignition Switch Logic Level	Active	

Non-Deployment Or Deployment #2 Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$40 Byte 1 bit 7	\$00	Crash Record Locked	No	
DPID \$40 Byte 1 bit 6	\$00	Deployment Event Recorded in the Non-Deployment Record	No	
DPID \$40 Byte 1 bit 5	\$00	Vehicle Event Data (Pre-Crash) Associated With This Event	No	
DPID \$40 Byte 2	\$A5	Event Recording Complete	Yes	
DPID \$41 Byte 1 bit 7	\$00	Driver 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 6	\$00	Driver 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 5	\$00	Driver Side Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 4	\$00	Driver Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 3	\$00	Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 2	\$00	Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 1	\$00	Driver Knee Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 7	\$00	Passenger 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 6	\$00	Passenger 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 5	\$00	Passenger Side Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 4	\$00	Passenger Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 3	\$00	Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 2	\$00	Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 1	\$00	Passenger Knee Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 7	\$00	Driver Anchor Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 6	\$00	Second Row Left Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 5	\$00	Third Row Left Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 4	\$00	Second Row Right Side Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 3	\$00	Second Row Right Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 2	\$00	Third Row Right Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 1	\$00	Center Rear Pretensioner Deployment Loop Commanded	No	
DPID \$42 Byte 1 bit 7	\$00	SIR Warning Lamp Status	OFF	
DPID \$42 Bytes 2-3	\$FFF0	SIR Warning Lamp ON/OFF Time Continuously	655200	seconds
DPID \$42 Bytes 4-5	\$1B4E	Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	6990	cycles
DPID \$43 Byte 1	\$FE	Ignition Cycles Since DTCs Were Last Cleared	254	cycles
DPID \$43 Bytes 2-3	\$1B4F	Ignition Cycles at Event	6991	cycles
DPID \$44 Bytes 1-2	\$0000	DTC number for fault #1	N/A	
DPID \$44 Byte 3	\$00	DTC fault type for fault #1	\$00	
DPID \$44 Bytes 4-5	\$0000	DTC number for fault #2	N/A	
DPID \$44 Byte 6	\$00	DTC fault type for fault #2	\$00	
DPID \$45 Bytes 1-2	\$0000	DTC number for fault #3	N/A	
DPID \$45 Byte 3	\$00	DTC fault type for fault #3	\$00	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$45 Bytes 4-5	\$0000	DTC number for fault #4	N/A	
DPID \$45 Byte 6	\$00	DTC fault type for fault #4	\$00	
DPID \$46 Bytes 1-2	\$0000	DTC number for fault #5	N/A	
DPID \$46 Byte 3	\$00	DTC fault type for fault #5	\$00	
DPID \$46 Bytes 4-5	\$0000	DTC number for fault #6	N/A	
DPID \$46 Byte 6	\$00	DTC fault type for fault #6	\$00	
DPID \$47 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (10 ms after event enable or 70 ms before deployment)	0.00	MPH
DPID \$47 Byte 2	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (10 ms after event enable or 70 ms before deployment)	-0.68	MPH
DPID \$47 Byte 3	\$01	SDM Recorded Vehicle Velocity Change for Axis #1 (20 ms after event enable or 60 ms before deployment)	0.68	MPH
DPID \$47 Byte 4	\$FE	SDM Recorded Vehicle Velocity Change for Axis #2 (20 ms after event enable or 60 ms before deployment)	-1.36	MPH
DPID \$47 Byte 5	\$02	SDM Recorded Vehicle Velocity Change for Axis #1 (30 ms after event enable or 50 ms before deployment)	1.36	MPH
DPID \$47 Byte 6	\$FC	SDM Recorded Vehicle Velocity Change for Axis #2 (30 ms after event enable or 50 ms before deployment)	-2.71	MPH
DPID \$48 Byte 1	\$03	SDM Recorded Vehicle Velocity Change for Axis #1 (40 ms after event enable or 40 ms before deployment)	2.03	MPH
DPID \$48 Byte 2	\$FB	SDM Recorded Vehicle Velocity Change for Axis #2 (40 ms after event enable or 40 ms before deployment)	-3.39	MPH
DPID \$48 Byte 3	\$04	SDM Recorded Vehicle Velocity Change for Axis #1 (50 ms after event enable or 30 ms before deployment)	2.71	MPH
DPID \$48 Byte 4	\$FA	SDM Recorded Vehicle Velocity Change for Axis #2 (50 ms after event enable or 30 ms before deployment)	-4.07	MPH
DPID \$48 Byte 5	\$04	SDM Recorded Vehicle Velocity Change for Axis #1 (60 ms after event enable or 20 ms before deployment)	2.71	MPH
DPID \$48 Byte 6	\$F9	SDM Recorded Vehicle Velocity Change for Axis #2 (60 ms after event enable or 20 ms before deployment)	-4.74	MPH
DPID \$49 Byte 1	\$05	SDM Recorded Vehicle Velocity Change for Axis #1 (70 ms after event enable or 10 ms before deployment)	3.39	MPH
DPID \$49 Byte 2	\$F8	SDM Recorded Vehicle Velocity Change for Axis #2 (70 ms after event enable or 10 ms before deployment)	-5.42	MPH
DPID \$49 Byte 3	\$05	SDM Recorded Vehicle Velocity Change for Axis #1 (80 ms after event enable or at deployment)	3.39	MPH
DPID \$49 Byte 4	\$F8	SDM Recorded Vehicle Velocity Change for Axis #2 (80 ms after event enable or at deployment)	-5.42	MPH
DPID \$49 Byte 5	\$05	SDM Recorded Vehicle Velocity Change for Axis #1 (90 ms after event enable or 10 ms after deployment)	3.39	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$49 Byte 6	SF8	SDM Recorded Vehicle Velocity Change for Axis #2 (90 ms after event enable or 10 ms after deployment)	-5.42	MPH
DPID \$4A Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (100 ms after event enable or 20 ms after deployment)	0.00	MPH
DPID \$4A Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (100 ms after event enable or 20 ms after deployment)	0.00	MPH
DPID \$4A Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (110 ms after event enable or 30 ms after deployment)	0.00	MPH
DPID \$4A Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (110 ms after event enable or 30 ms after deployment)	0.00	MPH
DPID \$4A Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (120 ms after event enable or 40 ms after deployment)	0.00	MPH
DPID \$4A Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (120 ms after event enable or 40 ms after deployment)	0.00	MPH
DPID \$4B Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (130 ms after event enable or 50 ms after deployment)	0.00	MPH
DPID \$4B Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (130 ms after event enable or 50 ms after deployment)	0.00	MPH
DPID \$4B Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (140 ms after event enable or 60 ms after deployment)	0.00	MPH
DPID \$4B Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (140 ms after event enable or 60 ms after deployment)	0.00	MPH
DPID \$4B Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4B Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4C Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (170 ms after event enable or 90 ms after deployment)	0.00	MPH
DPID \$4C Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (170 ms after event enable or 90 ms after deployment)	0.00	MPH
DPID \$4C Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (180 ms after event enable or 100 ms after deployment)	0.00	MPH
DPID \$4C Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (180 ms after event enable or 100 ms after deployment)	0.00	MPH
DPID \$4D Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (190 ms after event enable or 110 ms after deployment)	0.00	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$4D Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (190 ms after event enable or 110 ms after deployment)	0.00	MPH
DPID \$4D Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4D Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4E Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4E Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4F Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (270 ms after event enable or 190 ms after deployment)	0.00	MPH
DPID \$4F Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (270 ms after event enable or 190 ms after deployment)	0.00	MPH
DPID \$50 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (280 ms after event enable or 200 ms after deployment)	0.00	MPH
DPID \$50 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (280 ms after event enable or 200 ms after deployment)	0.00	MPH
DPID \$50 Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (290 ms after event enable or 210 ms after deployment)	0.00	MPH

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$50 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (290 ms after event enable or 210 ms after deployment)	0.00	MPH
DPID \$50 Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$50 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$51 Byte 1 bit 7	\$D0	Driver Belt Switch Circuit Status	BUCKLED	
DPID \$51 Byte 1 bit 6	\$D0	Driver Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 5	\$D0	Passenger Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 4	\$D0	Passenger Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 3	\$D0	Front Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 2	\$D0	Front Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 7	\$00	Second Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 6	\$00	Second Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 5	\$00	Second Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 4	\$00	Second Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 3	\$00	Second Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 2	\$00	Second Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 7	\$00	Third Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 6	\$00	Third Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 5	\$00	Third Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 4	\$00	Third Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 3	\$00	Third Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 2	\$00	Third Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 4 bit 7	\$00	Driver Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 6	\$00	Driver Seat Position Status Monitored	No	
DPID \$51 Byte 4 bit 5	\$00	Passenger Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 4	\$00	Passenger Seat Position Status Monitored	No	
DPID \$52 Byte 1 bit 7	\$80	Automatic Passenger SIR Suppression System Validity Status	Invalid	
DPID \$52 Byte 1 bit 0	\$80	Automatic Passenger SIR Suppression System Status	Air Bag Suppressed	
DPID \$52 Bytes 2-3	\$0000	SDM Synchronization Counter	0	
DPID \$52 Byte 4 bits 7-6	\$00	Rollover Sensor Message Status	No Rollover Event	
DPID \$52 Byte 4 bit 5	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Side Impact Event	No	
DPID \$52 Byte 4 bit 4	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Rollover Event	No	

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$52 Byte 4 bits 3-0	\$00	Rollover Sensor Status	Last message received contained errors	
DPID \$53 Byte 1	\$07	Time From Algorithm Enable to Maximum SDM Recorded Vehicle Velocity Change	70	msec
DPID \$53 Bytes 2-3	\$0059	Maximum SDM Recorded Vehicle Velocity Change	6.39	MPH
DPID \$54 Byte 1 bit 7	\$00	Automatic Passenger SIR Suppression System Validity Status / Passenger SIR Suppression Switch Circuit Validity Status	Valid	
DPID \$54 Byte 1 bit 1	\$00	Automatic Passenger SIR Suppression System Status / Passenger SIR Suppression Switch Circuit Status	Air Bag Suppressed	
DPID \$54 Byte 2	\$00	Rollover Sensor - Time Between Successive Side Deploys	0	msec
DPID \$54 Byte 3	\$00	Rollover Sensor - Time From Rollover Enable to Deploy	0	msec
DPID \$55 Byte 1	\$00	Driver 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 2	\$00	Driver 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 3	\$00	Passenger 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 4	\$00	Passenger 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 5	\$00	Driver Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 6	\$00	Passenger Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec

























































NEW YORK



01/02/17

1G1AP18P577

2477 - CLEVELAND - 205D

PAID - 8 -



VEHICLE REGISTRATION





