


EWR D&I ANNOTATION



FAN-000001L123001DP492-9895

Artemis # : 000001L123001DP492**Record Created Date :** 06/19/2013**Printed Date :** 06/19/2013**Description :**

DI12-108. SEQUENCE ID 492. QUARTER 3. 2006 SATURN ION. 1 INJURY. THIS RESPONSE INCLUDES SERVICE REQUEST DETAIL DOCUMENTS AND CRASH DATA RETRIEVAL DOCUMENTS. ACCORDING TO THE SERVICE REQUEST DOCUMENTS, THE DRIVER OF THE SUBJECT VEHICLE TURNED THE CORNER AT AN INTERSECTION GOING ABOUT 40 MPH AND THERE WAS A VEHICLE IN FRONT OF THE SUBJECT VEHICLE GOING ABOUT 20 MPH. THE SUBJECT VEHICLE MOVED INTO THE LEFT LANE TO GO AROUND THE OTHER VEHICLE. THE DRIVER OF THE OTHER VEHICLE (A TRUCK) STOPPED ABRUPTLY. WHEN THE DRIVER OF THE OTHER VEHICLE STOPPED, THE SUBJECT VEHICLE RAN INTO IT. THE SUBJECT VEHICLE'S AIRBAG DID NOT DEPLOY. THE WEATHER WAS NOTED AS WARM. THE ROAD CONDITION WAS NOTED AS DRY. THE DRIVER REPORTED A NECK AND SHOULDER SPRAIN. THERE ARE SEVERAL FIELD REPORTS IN ARTEMIS RELATED TO AIRBAG NON DEPLOYMENT IN THIS MODEL YEAR VEHICLE. THE FOLLOWING COMPLAINTS CAN BE FOUND IN ARTEMIS RELATED AIRBAG NON DEPLOYMENT IN THIS MODEL YEAR VEHICLE: 10497828, 10349343, 10286648, 10266873, 10253290, 10229360, 10184279. *TGW

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

December 19, 2012

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI12-108

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2012. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 1, 2, 36, 39, 47, 64, 66, 87, 92, 93, 106, 143, 148, 149, 153, 157, 158, 163, 166, 168, 169, 189, 192, 229, 231, 232, 284, 290, 305, 317, 323, 328, 329, 333, 334, 371, 372, 374, 381, 389, 392, 394, 418, 423, 428, 439, 446, 460, 492, 497	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of any related Police Accident Report that is in your possession.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION”

must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **January 25, 2013**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-7028, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink, appearing to read "Leo Yon". The signature is fluid and cursive, with the first name "Leo" and last name "Yon" clearly distinguishable.

Leo Yon, Acting Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Vehicle Safety and Crashworthiness

January 31, 2013

FEB 22 2013

Leo Yon, Acting Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave, SE
Washington, DC 20590

NVS-217kb
DI12-108

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated December 19, 2012, regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2012.

GM's response is comprised of 50 disks for the incidents that are the subject of DI12-108.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 1 384415629-746629 and 2010 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 1 384415629-746629_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in
the index for the disk are as follows:

DI12-108
1 384415629-746629
2010 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 1 384415629-746629_01_001- is the first document responsive to Inquiry no.1.
- 1 384415629-746629_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI12-108, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(65 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
1	5GALRCED8A	NISM
2	5GAKVCED9C	NISM
36	1G6DK5EG0A	NISM
39	1G6DE5EY7B	NISM
47	1GYS4BEF9B	LIT
64	1G6DW67756	NISM
66	2G61R5S34D	NISM
87	KL1TD5DE5B	NISM
92	2G1FA1E39C	NISM
93	2G1FT1EW2C	NISM
106	1G1AK55F46	NISM
143	1GCHTDFP5C	NISM
148	1G1PH5S94B	NISM
149	1G1PC5SH5B	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
153	1G1PF5S94B7 [REDACTED]	LIT
157	UNKNOWN	NISM
158	UNKNOWN	NISM
163	1G1PC5SH3C7 [REDACTED]	NISM
166	1G1PC5SH9C7 [REDACTED]	NISM
168	UNKNOWN	NISM
169	1G1PE5SC2C7 [REDACTED]	NISM
189	2GNALBEK8C1 [REDACTED]	NISM
192	2GNFLNEK2C6 [REDACTED]	LIT
229	2G1WF5EK3B1 [REDACTED]	NISM
231	2G1WG5E38C1 [REDACTED]	NISM
232	2G1WF5E35C1 [REDACTED]	NISM
284	1G1ZD5EU6CF [REDACTED]	PAR
290	1G1ZC5E01CF [REDACTED]	NISM
305	2GCEC13C181 [REDACTED]	NISM
317	1GCRKSE75CZ [REDACTED]	RUMOR
323	1GCHK23D06F [REDACTED]	NISM
328	1G1JC5SBXC4 [REDACTED]	NISM
329	1G1JC5SH3C4 [REDACTED]	NISM
333	UNKNOWN	NISM
334	UNKNOWN	NISM
371	1GNKRGED1CJ [REDACTED]	NISM
372	1GNKVGED1CJ [REDACTED]	NISM
374	1GNKVJED7CJ [REDACTED]	NISM
381	1G1RD6E48CU [REDACTED]	NISM
389	1GKLRLED6AJ [REDACTED]	NISM
392	1GKKRRED7CJ [REDACTED]	NISM
394	1GKKRSED8CJ [REDACTED]	NISM
418	1GTR1VE03BZ [REDACTED]	NISM
423	2GKFLUE54C6 [REDACTED]	NISM
428	1GKS2CE05CR [REDACTED]	NISM
439	5GTDN136X68 [REDACTED]	NISM
446	1G2AL18FX87 [REDACTED]	NISM
460	1G2ZH17NX84 [REDACTED]	NISM
492	1G8AJ55F36Z [REDACTED]	RUMOR
497	1G8MF35XX8Y [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, photographs, reports and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read "M. Carmen Benavides". The signature is fluid and cursive, with the first name "M." followed by "Carmen" and "Benavides" in a stylized script.

M. Carmen Benavides, Director
Product Investigations and Safety Regulations

Enclosures: 50 Disks
Attachment A



Attachment A

Instructions for using Disk Viewer

1. Insert the encrypted disk into the disk ROM drive and click on your DVD drive.
2. Double-click on the **.zip file** file.

Name	Date modified	Type	Size
Files Currently on the Disc (1)			
200689_001.zip	2/19/2013 11:53 AM	WinZip File	3,448 KB
Files Ready to Be Written to the Disc (1)			
desktop.ini	2/21/2013 7:57 AM	Configuration sett...	1 KB

3. Double-click the **images file....** Insert encryption password



4. Double-click on any of the files and view



DI12-108
492 384415923-747261
2006 SATURN ION

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Documents.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Documents. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	ESIS Escalation
Address	City Grand Rapids	Involved Dir	Todd Wenzel Buick GMC, Inc.	Safety	Yes
State MI ZipCd	Con Acct	Source	Email	Updated	9/6/2012 04:32:42 PM
Serial #/VIN 1G8AJ55F302	Model Year 2006	Priority	Medium License # SATURN -	Owner	BABBSKE
Make Saturn - GM	Warr. Start 05/08/2006	Status	Open	Opened	9/6/2012 09:29:47 AM
Model ION 2	Mileage 87600	Sub-Status	Satisfied	Closed	
Abstract	airbags non-deployment				
Customer Description	This is a BRC PAR File. Please do not Assume. Forward all Inquiries to Kellin Bobbs @ ext. 41026				

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	8/29/2012 04:30:00 PM	Y	1	1	Asphalt	Dry	na	
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'6"		Injured/ glasses				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
unk	unk	(888) 244-6163	21st Century					
Incident Loc	Grand Rapids MI	Incident Desc	Customer ended up hitting another vehicle from behind when they were making a right turn through an intersection					
Component	airbags	Damage Desc	whole front end is crunched on the driver side.					
Vehicle Loc	Star Collision - 1560 Plainfield Ave NE Grand Rapids MI 49505	Add'l info	loc last svc date: unk inspec date time: unk					
Emgcy Svc Names	unk	Metnl Loc	GM dealerships					

PAR Detail

Collision	Y	Non Collision	Property Damage	Y	Thermal Evt	N	Spec Equip	none
Vehicle Speed	40	Weather Condition	83 degrees	Prop Owner		Property Type	2004 Chevrolet Avalanche K1500	
Last Service Date	9/9/2011	Loc Last Service		Property Location	Rupius MI	Prop Est Repair Cost	\$0.00	
Veh Est Repair Cost	\$4,638.00	Spec Equip Installer	na	Prop Damage Description	no damage	Inspected By	Inspection Not Performed	Inspection Date/Time
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Explain Other	case is being sent to esis for medical			
Veh Damage Description	whole front end is crunched on the driver side.							

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
		11/27/52	Occupant of Owner's Vehicle		Driver	SIR
Injury Description		Medical Rpt#		Treatment Location		Treated By
neck and shoulder sprain		unk		Spectrum Health		Dr. Koolstra
Street Address		City	State	Zip Code		
		Grand Rapids	MI			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/7/2012 09:20:21 AM	KINZERTH	ESISBIQU	Escalation	ESIS - Injuries	In Progress		ESIS - Injuries
Contact Last Name		Contact First Name	Account		BAC Code		
Comments							
airbag non-deployment with injuries							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/6/2012 04:43:50 PM	BABBSKE	BABBSKE	Scheduled Follow-up		Scheduled Alarm		esis - medical
Contact Last Name		Contact First Name	Account		BAC Code		
Comments							
Customer is alleging that they were making a right turn into an intersection when another vehicle stopped causing them to hit them from behind and having their airbags not deploy.							
esis - medical							
kellinbabbs/par/alx							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/6/2012 04:43:19 PM	BABBEKE	KINZERTH	Notify CRM		Done	9/7/2012 09:20:43 AM	esis - medical
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Customer is alleging that they were making a right turn into an intersection when another vehicle stopped causing them to hit them from behind and having their airbags not deploy.

esis - medical

kellinbabbs/pa/abx

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 04:42:05 PM	BABBSKE	BABBSKE	Outbound Email	DVM/CAMField	Done	9/8/2012 04:42:28 PM	christine.price@gm.com
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

A product allegation claim has been made in your region. The customer is alleging that they were making a right turn into an intersection when another vehicle stopped causing them to hit them from behind and having their airbags not deploy. This case is being escalated to ESIS because of medical treatment.

2006 Saturn Ion 2

1G8AJ55F36Z

Todd Wenzel Buick GMC, Inc. Grand Rapids MI 183998

(616) 949-7700

This is only a notification. No action is required on your part at this time.

Respectfully,
Kellin Babbs | CRS

Aditya Birla Minacs | Inspired every day
7401 E. Ben White Blvd, Bldg. F, Austin, TX 78741
Phone: 866-790-5700 | Fax: 866-311-2784 | www.minacs.adityabirla.com Follow us on Twitter

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 04:32:43 PM	BABBSKE	BABBSKE	Ownership Changed	Ownership Escalated to BRC	Done	9/8/2012 04:32:43 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Report Generated for toporowm

on 9/10/2012

Page 4 of 13

TA000129918

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 01:47:39 PM	BABBSKE	BABBSKE	BRC PAR	Business Case	Done	9/8/2012 04:38:33 PM	business case
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Customer is alleging that they were making a right turn into an intersection when another vehicle stopped causing them to hit them from behind and having their airbags not deploy.

esis - medical

kellinbabbs/parfabx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 01:47:32 PM	BABBSKE	BABBSKE	Other		Done	9/8/2012 04:35:44 PM	vehicle incident location
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Grand Rapids M

kellinbabbs/parfabx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 01:23:13 PM	MERCADTO	KINZERTH	Inbound Call Third Party	Voice Mail Received	Done	9/8/2012 01:23:27 PM	PAR V/M
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

71-1104558928

customer

airbag non-deployment

Sep 8 9:41am

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 10:20:12 AM	MERCADTO	BABBSKE	Ownership Changed		Done	9/8/2012 10:20:12 AM	Service Request Ownership has changed FROM: PAGATPPE TO: BABBSKE
Contact Last Name	Contact First Name	Account	UAC Code				
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 10:18:57 AM	MERCADTO	BABBSKE	BRC PAR	Initial Contact - Field	Done	9/8/2012 04:42:03 PM	christine.price@gm.com
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

A product allegation claim has been made in your region. The customer is alleging that they were making a right turn into an intersection when another vehicle stopped causing them to hit them from behind and having their airbags not deploy. This case is being escalated to ESIS because of medical treatment.

2006 Saturn ION 2

1G8AJ55F36Z

Todd Wenzel Buick GMC, Inc. Grand Rapids MI 49508

(616) 949-7700

This is only a notification. No action is required on your part at this time.

Respectfully,
Kellin Babbs | CRS

Aditya Birla Minacs | Inspired every day
7401 E. Ben White Blvd, Bldg. F, Austin, TX 78741
Phone: 866-750-5700 | Fax: 866-311-2784 | www.minacs.adityabirla.com Follow us on Twitter

Confidential Comments

Report Generated for toporowm

on 9/10/2012

Page 6 of 13

TA000129920

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 10:18:48 AM	MERCADTO	BABBSKE	BRC PAR	Initial Contact- Dealer	Done	9/8/2012 04:40:58 PM	Todd Wenzel Buick GMC, Inc. (616) 948-7700
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS spoke with Tim Cumigan

divided of cust product allegation.

dir sts: have not seen them since september of 2011.

sept 28th 2011 76,264 clunk noise in the front and they recommended us replading the sway bar links. That is the last thing I see.

Maint:n

Evidence of abuse misuse or lack of maint: n

Known product concerns relating to customer's allegation: n

kellinbabbs/pa/raix

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/6/2012 10:19:38 AM	MERCADTO	BABBSKE	BRC PAR	Initial Contact Phone	Done	9/6/2012 04:35:09 PM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

crs spoke w

crs verified address

crs verified customer contact information.

crs verified email

Grand Rapids MI

Cust. states: turned corner at intersection going slow about 40 mph and there was a car in front of me going about 20 mph so I moved into the left lane to go around them. The driver in a truck next to me on a cell phone stopped abruptly. When he stopped I was behind him and my car slid over a yard. I slid right in front of him on the driver's side. The impact I think should have had the airbags deploy.

Original owner? yes

rental? n

medical attn?

neck and shoulder sprain.

spectrum health

Koolstra

par form notes:

loc last svc date: unk

inspec date time: unk

Crs gathered prePAR and PAR Detail Info.

CRS advised customer of required verbiage as stated in d_1075834

Cust requested the file to be referred to the Central Claims dept.

Crs advised cust someone from our Central Claims department will follow up with you within 7-10 business days.

Crs provided contact information and the case number

kel@babbs/par/atx

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 10:19:30 AM	MERCADTO	BABBSKE	BRC PAR	Acknowledgement	Done	9/8/2012 04:11:08 PM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

crs adv: This is Kellin calling from the GM Product Allegation Dept. I have received your file and do require further information. Do you have a moment to speak to me?

Cust sta: Yes

(Continued in Initial)

kellinbabbs/par/atx

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 10:19:21 AM	MERCADTO	BABBSKE	Research		Done	9/8/2012 01:53:53 PM	Research VIN
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

S/R's:
ST-1-24068932- saturn salute goodwill items
068932-EBVPM - parent sr number
068932-EBVPN - parent sr number
71-970559573 - dlr issue
71-981896091 - power steering

Recalls:
Special Coverage 09014 06/07/2012 05/06/2006 11 MI 05/06/2011 150,011 MI
Special Coverage 10187 06/07/2012 05/06/2006 11 MI 05/06/2010 150,011 MI

Branded: n

Warranty Block: n

Repairs: 0

research complete

kellinbabbs/par/atx

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/6/2012 10:18:08 AM	MERCADTO	BABBSKE	Notify CRM		Done	9/6/2012 05:32:30 PM	File assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments
file received

kellinbabbs/parfax

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/6/2012 10:18:35 AM	MERCADTO	BABBSKE	BRC PAR	Case Assigned	Done	9/6/2012 05:32:33 PM	Assigned to Kellin x31460

Contact Last Name	Contact First Name	Account	BAC Code

Comments
file received

kellinbabbs/parfax

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/6/2012 10:18:26 AM	MERCADTO	PAGATPPE	SR Opened		Done	9/6/2012 10:18:28 AM	SR In Status of Closed has been Re-Opened by MERCADTO

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/6/2012 10:18:25 AM	MERCADTO	PAGATPPE	SR Closed - Satisfied		Done	9/6/2012 10:18:25 AM	Service Request has been Closed Satisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 08:41:57 AM	PAGATPPE	KINZERTH	Notify CRM		Done	9/8/2012 10:16:21 AM	PAR-airbags did not deploy

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
9/8/2012 09:33:37 AM	PAGATPPE	PAGATPPE	Outbound Call Customer	Made Contact	Done	9/8/2012 09:41:54 AM	Spoke with

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Crs sts:
-introduced myself
-advised that I am calling to verify some info

Cust sts:
-62203300 with 87600 miles
-original owner
-veh is in Star Collision at this time
-they are the one who provided the estimate of the damage
-veh is not driveable so I took it to the Collision place instead
-airbags did not deploy at the time of the accident that's why I was into an accident
-august 29, 2012
-no related repairs in the past, front right tire was repaired before when I got into a pot hole last time

Crs sts:
-provided the s#
-advised that I will forward the info to one of our PAR rep for further assistance
-advised that someone will get back to her within 24-48 hours

Pearl-RR-Survey-WM-Email-CAC-T1-MLA-L1

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/5/2012 03:10:53 PM		PAGATPPE	Email - Inbound		Done	9/8/2012 09:33:35 AM	FW: Thank you for your Buick question
Contact Last Name		Contact First Name		Account		UAC Code	
Comments							
[THREAD ID:149CVKQ]							

—Original Message—

From: feq@buick.com
Sent: 8/5/2012 12:21:35 AM
To: feq@buick.com
Subject: Thank you for your Buick question

<html>
<head>
<meta http-equiv="Content-Type" content="text/html; charset=iso-8859-1" />
<title></title>
</head>
<body>

<p>Name:

Email Address:

Address:

Grand Rapids, MI

Day Phone: ex

Evening Phone: ()- ex
</p>

<p>Comments: My name is I have a 2008-Saturn Ion 2, I have owned this car for 6yr.Never had a Accident until now. I LOVE this Car. Aug 29,2012. I had a Run-In to a Person on a Cellphone in front of me. The Impact Really messed up my Front,But For some Reason My Air-Bags did not Deploy. I suffered a Neck and Shoulder Sprain,I feel my Car was somehow (Defective),I have pictures also. There is \$4600.00,of damage to my car. Please have someone contact me on this issue.</p>

<p>Website Concern Info:

Website: buick

Operating System: windows

Browser: eol
</p>

</body>
</html>

Confidential Comments

Service Request Detail

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C47	SIR - Did Not Deploy	Restraints - (SIR) - Driver Side - Side Impact
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front
C49	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Side -Side Impact

[Logout](#)

September 10, 2012

Global Warranty Management: Mah > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMERView Vehicle Summary ?

This screen allows IVH users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable)

Vehicle Information

VIN 1G8AJ55F36Z XXXXXXXXXX Model: ZAJ69-2006 ION.2 BASE SEDAN
 Service Contract No XXXXXXXXXX Branded Title No XXXXXXXXXX Warranty Block No XXXXXXXXXX PDI Status Yes
 Order Type T - DEALER STOCK
 Field Actions [Open](#) XXXXXXXXXX

For this vehicle:

[View Vehicle Summary](#)

- [Service Contract](#)
- [Branded Title](#)
- [Warranty Block](#)

- [View Vehicle Build](#)
- [View Vehicle](#)
- [Component Summary](#)
- [View Vehicle](#)
- [Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Required Field Actions

Open field actions are highlighted

Vehicle has no current record of required field actions.

Branded Title

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Refer to Help page for details. For OnStar contact 888.ON.STAR1 (888.667.8271) and for XM Radio contact 877.GET.XMST (877.438.9877 Canada) and in the USA: 800-356-3690.

OnStar Equipped Y	OnStar Status: Active
XM Equipped N	XM Status: NA
OnStar Vehicle Diagnostics N	DMN Enabled: N

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Saturn 96/80M Emission select components	06/07/2012	05/06/2006	11 MI	05/06/2014	80,011 MI
	Saturn 36/36K Bumper to Bumper	06/07/2012	05/06/2006	11 MI	05/06/2009	36,011 MI
	Saturn 72/100K Corrosion	06/07/2012	05/06/2006	11 MI	05/06/2012	100,011 MI
	Special Coverage 09014	06/07/2012	05/06/2006	11 MI	05/06/2021	150,011 MI
	Special Coverage 10187	06/07/2012	05/06/2006	11 MI	05/06/2018	150,011 MI

https://gmvis2.gotd.gm.com/gmvis2/showVehicleHistorySummary.do?_SEC_TOKEN_=6... 9/10/2012

Service Contract

Vehicle has no current record of service contracts.

Transaction History[View Details](#)


Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
09/01/2011	16044672	ZREG—Regular Vehicle Transaction		T5783 - 10187 - Replace Power Steering Motor Control Module	75,092 MI
08/19/2011	16043775	ZREG—Regular Vehicle Transaction		E3851 - Strut, Front - Left - Replace	74,469 MI
08/19/2011	16043775	ZREG—Regular Vehicle Transaction		E3551 - Bushings And/Or Shaft, Front Control Arm - Lower - Left - Replace	74,469 MI
07/01/2011	16040206	ZREG—Regular Vehicle Transaction		T6721 - 09014 - Engine Control Module - Emission Related Reprogramming	72,383 MI
03/15/2010	2302903	ZPTI—Part Transaction - Service Agent Installed		L1020 - Fuel Tank Filler Cap Replacement	58,821 MI
11/20/2008	Z17877	ZREG—Regular Vehicle Transaction		Z8025 - ONSTAR - FLAT TIRE	0 MI
11/11/2008	2281897	ZSET—Service Event		M5005 - TOP OFF ALL FLUIDS	40,356 MI
11/11/2008	2281897	ZSET—Service Event		M5105 - BRAKE INSPECTION (FLUID CHECK)	40,356 MI
05/29/2008	2273830	ZSET—Service Event		M5005 - TOP OFF ALL FLUIDS	32,174 MI
05/01/2008	2272507	ZREG—Regular Vehicle Transaction		J6354 - Powertrain Control Module Engine Reprogramming with SPS	30,360 MI
04/07/2008	0271333	ZREG—Regular Vehicle Transaction		C0180 - Regulator, Front Door Window - Right Manual - R&R Or Replace	28,526 MI
12/28/2007	0266933	ZSET—Service Event		M5005 - TOP OFF ALL FLUIDS	23,873 MI
10/05/2007	P91834	ZREG—Regular Vehicle Transaction		Z4535 - ROADSIDE SERVICE (FLAT TIRE) - SATURN U.S.	20,223 MI
10/05/2007	0232795	ZSET—Service Event		M5120 -	20,227 MI
08/21/2007	0258489	ZSET—Service Event		M5005 -	14,808 MI
06/21/2007	0258489	ZREG—Regular Vehicle Transaction		B7611 - Molding, Windshield Side Roof Rail Drip - Left - R&R Or Replace	14,808 MI
05/14/2007	0256696	ZREG—Regular Vehicle Transaction		C0183 - Front Side Door Window Regulator Replacement - Left Side	11,680 MI
02/05/2007	0252233	ZSET—Service Event		M5005 -	7,021 MI
02/05/2007	0252233	ZSET—Service Event		M5025 -	7,021 MI
02/05/2007	0252233	ZREG—Regular Vehicle Transaction		Z4632 - 2-DAY CAR RENTAL - SATURN U.S.	7,021 MI
02/05/2007	0252233	ZREG—Regular Vehicle Transaction		J6354 - Powertrain Control Module Engine Reprogramming with SPS	7,021 MI
01/15/2007	0251366	ZREG—Regular Vehicle Transaction		J3010 - Cooling System Leak-Analyze	6,439 MI
05/04/2006	0123070	ZSET—Service Event		M5090 -	10 MI
04/27/2006	0122833	ZPDI—Pre-Delivery Inspection		Z7000 -	1 MI

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved

https://gmvis2.gotd.gm.com/gmvis2/showVehicleHistorySummary.do?_SEC_TOKEN_=6... 9/10/2012

[Logout](#)

September 10, 2012

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build

This screen allows IVH users to view the initial build information on the selected VIN including option codes with descriptions (where available)

Vehicle Information

VIN 1G8AJ55F36Z Model ZAJ69-2006 ION.2 BASE SEDAN
 Service Contract No Branded Title No Warranty Block No PDI Status: Yes
 Order Type T - DEALER STOCK
 Field Actions [Open](#)

Vehicle Build

Model ZAJ69-2006 ION.2 BASE SEDAN Order Number GFL865
 Gross Vehicle Weight 0 Build Date 04/12/2006
 Build Plant 2

For this vehicle:

- [View Vehicle Summary](#)
 - Service Contract
 - Branded Title
 - Warranty Block
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Option Codes

*IVH is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker

17C - GREY CLOTH	171 - GRAY
41L - BLACK	41U - BLACK ONYX
6AB - SUSPENSION	7AB - SUSPENSION
8AF - SUSPENSION	9AF - SUSPENSION
A31 - POWER WINDOWS	AG4 - DRIVER SEAT MANUAL HEIGHT ADJ.
AK5 - DR & PASS SEAT RESTRAINT SYSTEM	AR9 - DLXE FRT BKT SEAT
AU0 - REMOTE KEYLESS ENTRY W/ALARM	B37 - FLOOR MATS FRONT & REAR
BBC - BODY COLOR APPLIQUES	C60 - AIR CONDITIONING W/DUST & POLLEN FILTER
DG7 - PWR. REMOTE EXTERIOR MIRRORS	FE1 - SOFT RIDE SUSPENSION SYSTEM
FE9 - FEDERAL EMISSIONS	FY1 - RATIO - 3.63
HAA - PREFERRED PACKAGE: * POWER WINDOWS * REMOTE KEYLESS ENTRY W/ALARM * PWR. REMOTE EXTERIOR MIRRORS * CRUISE CONTROL * DRIVER SEAT MANUAL HEIGHT ADJ	IPC - TRIM INTERIOR DESIGN
J41 - POWER BRAKE SYSTEM	K34 - CRUISE CONTROL
K62 - 105 AMP GENERATOR	L61 - 2.2L 4CYL GAS ENGINE
MN5 - 4 SPEED AUTO TRANS	MX0 - MERCHANDISED TRANS AUTO PROVIS
NK5 - STANDARD STEERING WHEEL	NT7 - EMISSION SYSTEM FEDERAL
P2W - WHEEL COVER, FLUSH SPORT	PG1 - STEEL WHEEL 15 X 6
QTU - TIRE P195/60R16	R6H - SDS CHARGE
R7Y - COMMUNICATIONS PLUS	RF3 - MERCHANDISED PKG SATURN
U1C - AM/FM STEREO W/CD & INPUT JACK	UE1 - ONSTAR SERVICE: INCLUDES 1 YEAR SAFE AND SOUND PLAN
UH8 - CLUSTER INST, COOL TEMP, TRIP ODOM, TACH	U58 - FIXED ANTENNA, PAINTED, RADIO
UX7 - SPEAKER SYSTEM 4	V73 - VEHICLE STATEMENT USA/CANADA

https://gmvis2.gotd.gm.com/gmvis2/showVehicleBuild.do?_SEC_TOKEN_=6776573468... 9/10/2012

TA000129930

Added Option Codes

-BA -

-CC -

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

Global Warranty

September 10, 2012

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMERView Vehicle Component Summary ?

This screen allows IVH users to view the information on various major components added to the VIN selected during vehicle build

Vehicle Information

VIN: 1G8AJ55F38Z XXXXXXXXXX Model: ZAJ69-2006 ION.2 BASE SEDAN
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
 Order Type: T - DEALER STOCK
 Field Actions: [0 Open](#) XXXXXXXXXX

For this vehicle:

- [View Vehicle Summary](#)
 - Service Contract
 - Branded Title
 - Warranty Block
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY	Traceability: 604100198	
Source Plant: S-	Part / Number Broadcast: TYD	
Date Scanned: 04/12/2006	Time Scanned: 16:17:00	Scan Station:
Component Code: 61-TRANSMISSION	Traceability: AFFM TN81	
Source Plant: J-HYDRAMATIC WINDSOR, ONTARIO	Part / Number Broadcast: 6EHJ	
Date Scanned: 04/12/2006	Time Scanned: 16:17:00	Scan Station:
Component Code: 85-ELECTRONIC CONTROL MODULE (ECM)	Traceability: 0Y7MR	
Source Plant: T-	Part / Number Broadcast: YMZK	
Date Scanned: 04/12/2006	Time Scanned: 16:17:00	Scan Station:
Component Code: 87-BODY CONTROL MODULE	Traceability: 813118093	
Source Plant: 6-	Part / Number Broadcast: 8901	
Date Scanned: 04/12/2006	Time Scanned: 16:17:00	Scan Station:
Component Code: AB-IR-MODULE ASM-INFLATOR	Traceability: H098D1303	
Source Plant: H-LAND	Part / Number Broadcast: 2528	
Date Scanned: 04/12/2006	Time Scanned: 09:57:00	Scan Station:
Component Code: AL-JR-MODULE ASM-I/P	Traceability: 302096080	
Source Plant: H-LAND	Part / Number Broadcast: 1596	
Date Scanned: 04/11/2006	Time Scanned: 19:14:00	Scan Station:
Component Code: AS-SENSING DIAGNOSTIC MODULE	Traceability: 260944WBP	
Source Plant: K-DELCO ELECTRONICS KOKOMO, IN	Part / Number Broadcast: 5728	
Date Scanned: 04/12/2006	Time Scanned: 16:17:00	Scan Station:
Component Code: BK-INTERNATIONAL TRANS. CONTROL MODULE	Traceability: 060940186	
Source Plant: K-	Part / Number Broadcast: YLXP	
Date Scanned: 04/12/2006	Time Scanned: 16:17:00	Scan Station:
Component Code: CA-SEQ NUM (FLEX) BODY ASM	Traceability: 875561	
Source Plant: S-	Part / Number Broadcast: Z696	
Date Scanned: 04/12/2006	Time Scanned: 06:48:00	Scan Station:
Component Code: DU---	Traceability: 64061062	
Source Plant: 2-	Part / Number Broadcast: 9677	
Date Scanned: 04/11/2006	Time Scanned: 19:14:00	Scan Station:

https://gmvis2.gotd.gm.com/gmvis2/showVehicleComponent.do?_SEC_TOKEN_=67765... 9/10/2012

TA000129932


Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management. Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved


[Logout](#)

September 10, 2012

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail

②

This screen allows IVH users to view the available information on individual transaction for the VIN selected

Vehicle Information

VIN 1G8AJ55F362 Model ZAJ69-2008 ION.2 BASE SEDAN
 Service Contract No Branded Title No Warranty Block No PDI Status Yes
 Order Type T - DEALER STOCK
 Field Actions [Open](#)

For this vehicle:

[View Vehicle Summary](#)

- Service Contract
- Branded Title
- Warranty Block

[View Vehicle Build](#)
[View Vehicle](#)
[Component Summary](#)
[View Vehicle](#)
[Transaction History Detail](#)
[View Vehicle Delivery Information](#)

Job Card Date: 09/01/2011

Job Card Number: 16044672

Repair Service Agent 163988
 TODD WENZEL BUICK GMC
 2727 28TH ST SE
 GRAND RAPIDS MI 49512-1610
 6169497700

Odometer Reading 75,092 MI
 Authorization Code

Process Date
 09/02/2011

Transaction Type:
 ZREG—Regular Vehicle
 Transaction

Transaction Expense Category:
 Special Policy

Customer Complaint Code
 0190-Drivability - Other Issues

Job Card Line # 1 Transaction Adjustment Cause Code: 9090-Other - Field Action / Tech Bulletin

Labour Op T5783-10187 - Replace Power Steering Motor Control Module

Causal Part Number 000000000019257879-MOTORKIT,P/SASST(REMANUFACT

[See other Parts and/or Net Items](#)

Job Card Date: 08/19/2011

Job Card Number: 16043775

Repair Service Agent 163988
 TODD WENZEL BUICK GMC
 2727 28TH ST SE
 GRAND RAPIDS MI 49512-1610
 6169497700

Odometer Reading 74,469 MI
 Authorization Code: A

Process Date
 08/24/2011

Transaction Type:
 ZREG—Regular Vehicle Transaction
 Transaction Expense Category:
 Policy

Customer Complaint Code
 0126-Drivability - Noise

Job Card Line # 4 Transaction Adjustment Cause Code: 6051-Module/Component - Leaks

Labour Op E3851-Strut, Front - Left - Replace

Causal Part Number 000000000022707167-STRUTKIT,FRTSUSP

[See other Parts and/or Net Items](#)

Job Card Date: 08/19/2011

Job Card Number: 16043775

Repair Service Agent 183998
TODD WENZEL BUICK GMC
2727 28TH ST SE
GRAND RAPIDS MI 49512-1610
6169497700

Odometer Reading 74,469 MI
Authorization Code A

Process Date
08/24/2011

Transaction Type
ZREG—Regular Vehicle Transaction
Transaction Expense Category
Policy

Customer Complaint Code
0126-Drivability - Noise

Job Card Line #: 3 Transaction Adjustment Cause Code: 6025-Module/Component - Loose

Labour Op E3551-Bushings And/Or Shaft, Front Control Arm - Lower - Left - Replace

Causal Part Number 000000000025984679-BUSHING-FRTLWRCONTARM

--See other Parts and/or Net Items

Job Card Date: 07/01/2011

Job Card Number: 16040206

Repair Service Agent 183998
TODD WENZEL BUICK GMC
2727 28TH ST SE
GRAND RAPIDS MI 49512-1610
6169497700

Odometer Reading 72,383 MI
Authorization Code

Process Date
07/01/2011

Transaction Type
ZREG—Regular Vehicle
Transaction
Transaction Expense Category
Special Policy

Customer Complaint Code
0190-Drivability - Other Issues

Job Card Line #: 1 Transaction Adjustment Cause Code: 9090-Other - Field Action / Tech Bulletin

Labour Op T5721-09014 - Engine Control Module - Emission Related Reprogramming

Causal Part Number

--See other Parts and/or Net Items

Job Card Date: 03/15/2010

Job Card Number: 2302803

Repair Service Agent 164999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1621
6169496550000

Odometer Reading 56,821 MI
Authorization Code

Process Date
03/15/2010

Transaction Type
ZPTI—Part Transaction - Service Agent
Installed

Transaction Expense Category
Service Agent Installed Parts Warranty

Customer Complaint Code
0321-Engine/Fuel/Exhaust - "Check
Engine" Light

Job Card Line #: 2 Transaction Adjustment Cause Code: 6031-Module/Component - Poor Fits

Labour Op L1020-Fuel Tank Filter Cap Replacement

https://gmvis2.gotd.gm.com/gmvis2/showClaimHistoryDetail.do?_SEC_TOKEN_=67765... 9/10/2012

Causal Part Number 00000000010372248-CAPASM-F/TNKFIL

--See other Parts and/or Net Items

Job Card Date: 11/20/2008

Job Card Number: Z17877

Repair Service Agent 207631
GM SATURN ROADSIDE ASSISTANCE/CCAS
ONE CABOT RD
MEDFORD MA 02155-5117Odometer Reading: 0 MI
Authorization CodeProcess Date
12/26/2008Transaction Type
ZREG—Regular Vehicle TransactionTransaction Expense Category
Customer EnthusiasmCustomer Complaint Code
0000-Converted Claim

Job Card Line # 1 Transaction Adjustment Cause Code: 0000-Converted Claims

Labour Op Z8025-ONSTAR - FLAT TIRE

Causal Part Number

--See other Parts and/or Net Items

Job Card Date: 11/11/2008

Job Card Number: 2281897

Repair Service Agent 164999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1821
61694965550000Odometer Reading 40,356 MI
Authorization CodeProcess Date
11/11/2008Transaction Type
ZSET—Service EventTransaction Expense Category
Service Event

Customer Complaint Code:

-

Job Card Line # 2 Transaction Adjustment Cause Code: -

Labour Op M5005-TOP OFF ALL FLUIDS

Causal Part Number

--See other Parts and/or Net Items

Job Card Date: 11/11/2008

Job Card Number: 2281897

Repair Service Agent 164999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1821
61694965550000Odometer Reading 40,356 MI
Authorization CodeProcess Date
11/11/2008Transaction Type
ZSET—Service EventTransaction Expense Category
Service Event

Customer Complaint Code:

-

Job Card Line # 1 Transaction Adjustment Cause Code: -

Labour Op M5105-BRAKE INSPECTION (FLUID CHECK)

Causal Part Number

•See other Parts and/or Net Items

Job Card Date: 05/29/2008

Job Card Number: 2273830

Repair Service Agent 164999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1621
61694965550000

Odometer Reading 32,174 MI
Authorization Code

Process Date
05/29/2008

Transaction Type
ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code

-

Job Card Line # 1

Transaction Adjustment

Cause Code -

Labour Op M5005-TOP OFF ALL FLUIDS

Causal Part Number

•See other Parts and/or Net Items

Job Card Date: 05/01/2008

Job Card Number: 2272507

Repair Service Agent 164999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1621
61694965550000

Odometer Reading 30,360 MI
Authorization Code

Process Date
05/02/2008

Transaction Type
ZREG—Regular Vehicle Transaction
Transaction Expense Category
Warranty

Customer Complaint Code
0321-Engine/Fuel/Exhaust - "Check
Engine" Light

Job Card Line # 1

Transaction Adjustment: Cause Code: 3067-Rotating Part - Resonance /
from foreign part

Labour Op J6354-Powertrain Control Module Engine Reprogramming with SPS

Causal Part Number

Job Card Date: 04/07/2008

Job Card Number: 0271333

Repair Service Agent 164999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1621
61694965550000

Odometer Reading 28,528 MI
Authorization Code

Process Date
04/07/2008

Transaction Type
ZREG—Regular Vehicle
Transaction

Transaction Expense Category
Warranty

Customer Complaint Code

0421-Exterior - FIV/Finish

Job Card Line # 1

Transaction Adjustment

Cause Code: 1011-Surface (exterior) -
Alignment/Adjustment

Labour Op C0180-Regulator, Front Door Window - Right Manual - R&R Or Replace

Causal Part Number 00000000021008318-NUT

-See other Parts and/or Net Items

Job Card Date: 12/28/2007

Job Card Number: 0266933

Repair Service Agent 164999

Odometer Reading 23,873 MI

SATURN OF GRAND RAPIDS

Authorization Code

2120 28TH STREET SE

GRAND RAPIDS MI 49512-1621

61694865550000

Process Date

12/28/2007

Transaction Type:

ZSET---Service Event

Transaction Expense Category

Customer Complaint Code:

-

Job Card Line # 1

Transaction Adjustment

Cause Code -

Labour Op M5005-TOP OFF ALL FLUIDS

Causal Part Number

-See other Parts and/or Net Items

Job Card Date: 10/05/2007

Job Card Number: P91834

Repair Service Agent 207531

Odometer Reading 20,223 MI

GM SATURN ROADSIDE ASSISTANCE/CCAS

Authorization Code: C

ONE CABOT RD

MEDFORD MA 02155-5117

Process Date

10/12/2007

Transaction Type:

ZREG---Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line # 1

Transaction Adjustment

Cause Code 0000-Converted Claims

Labour Op Z4535-ROADSIDE SERVICE (FLAT TIRE) - SATURN U.S.

Causal Part Number

-See other Parts and/or Net Items

Job Card Date: 10/05/2007

Job Card Number: 0232795

Repair Service Agent 164180

Odometer Reading 20,227 MI

SATURN OF OKEMOS

Authorization Code

1728 GRAND RIVER AVE

OKEMOS MI 48864-5825

51734778900000

Process Date:

11/21/2007

Transaction Type:

ZSET---Service Event

Transaction Expense Category

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op M5120-

Causal Part Number

Job Card Date: 06/21/2007

Job Card Number: 0258489

Repair Service Agent: 164999

Odometer Reading: 14,808 MI

SATURN OF GRAND RAPIDS

Authorization Code:

2720 28TH STREET SE

GRAND RAPIDS MI 49512-1621

61694865550000

Process Date:

11/21/2007

Transaction Type:

ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 2

Transaction Adjustment:

Cause Code: -

Labour Op M5005-

Causal Part Number

--See other Parts and/or Not Items

Job Card Date: 06/21/2007

Job Card Number: 0258489

Repair Service Agent: 164889

Odometer Reading: 14,808 MI

SATURN OF GRAND RAPIDS

Authorization Code:

2720 28TH STREET SE

GRAND RAPIDS MI 49512-1621

61694865550000

Process Date:

06/21/2007

Transaction Type:

ZREG—Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op B7611-Molding, Windshield Side Roof Rail Drip - Left - R&R Or Replace

Causal Part Number

Job Card Date: 05/14/2007

Job Card Number: 0258696

Repair Service Agent: 164889

Odometer Reading: 11,880 MI

SATURN OF GRAND RAPIDS

Authorization Code:

2720 28TH STREET SE

GRAND RAPIDS MI 49512-1621

61694865550000

Process Date:

05/14/2007

Transaction Type:

ZREG—Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op C0183-Front Side Door Window Regulator Replacement - Left Side
Causal Part Number

Job Card Date: 02/05/2007

Job Card Number: 0252233

Repair Service Agent 184989
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1821
61694985550000

Odometer Reading 7,021 MI
Authorization Code

Process Date:
11/21/2007

Transaction Type:
ZSET---Service Event

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line # 5

Transaction Adjustment

Cause Code -

Labour Op M5005-

Causal Part Number

-See other Parts and/or Net Items

Job Card Date: 02/05/2007

Job Card Number: 0252233

Repair Service Agent 184989
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1821
61694985550000

Odometer Reading: 7,021 MI
Authorization Code

Process Date
11/21/2007

Transaction Type:
ZSET---Service Event

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 4

Transaction Adjustment

Cause Code: -

Labour Op M5025-

Causal Part Number

Job Card Date: 02/05/2007

Job Card Number: 0252233

Repair Service Agent 184989
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1821
61694985550000

Odometer Reading: 7,021 MI
Authorization Code

Process Date
02/08/2007

Transaction Type:
ZREG---Regular Vehicle Transaction

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 3

Transaction Adjustment

Cause Code: 0000-Converted Claims

Labour Op Z4632-2-DAY CAR RENTAL - SATURN U.S.

Causal Part Number

https://gmvis2.gotd.gm.com/gmvis2/showClaimHistoryDetail.do?_SEC_TOKEN_=67765... 9/10/2012

TA000129940

—See other Parts and/or Net Items

Job Card Date: 02/05/2007

Job Card Number: 0252233

Repair Service Agent: 184999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1621
61694965550000

Odometer Reading: 7,021 MI
Authorization Code:

Process Date
02/08/2007

Transaction Type
ZREG—Regular Vehicle Transaction

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 2

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op J6354-Powertrain Control Module Engine Reprogramming with SPS

Causal Part Number

Job Card Date: 01/15/2007

Job Card Number: 0251368

Repair Service Agent: 164999
SATURN OF GRAND RAPIDS
2720 28TH STREET SE
GRAND RAPIDS MI 49512-1621
61694965550000

Odometer Reading: 5,439 MI
Authorization Code:

Process Date
01/15/2007

Transaction Type
ZREG—Regular Vehicle Transaction

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 0000-Converted Claims

Labour Op J3010-Cooling System Leak-Analyze

Causal Part Number

Job Card Date: 05/04/2006

Job Card Number: 0123070

Repair Service Agent: 160723
SATURN OF FLINT
2430 DUTCHER ROAD
FLINT MI 48532-4421
81072088000000

Odometer Reading: 10 MI
Authorization Code:

Process Date
11/20/2007

Transaction Type
ZSET—Service Event

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op M5090-

Causal Part Number

Job Card Date: 04/27/2006

Job Card Number: 0122833

Repair Service Agent: 180723
SATURN OF FLINT
2430 DUTCHER ROAD
FLINT MI 48532-4421
81072088000000Odometer Reading: 1 MI
Authorization Code:

Process Date:
11/20/2007Transaction Type:
ZPDI—Pre-Delivery Inspection
Transaction Expense Category:Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -


Labour Op Z7000-

Causal Part Number

→ See other Parts and/or Net Items

Global Warranty Management Site Map[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

[Logout](#)

September 10, 2012

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMERView Vehicle Delivery Information ?

This screen allows IVH users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN 1G8AJ55F362
Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
Order Type: T - DEALER STOCK
Field Actions: [Open](#)

Model: ZAJ69-2006 ION.2 BASE SEDAN

Invoice Information

Invoicing Service Agent: 160723
SATURN OF FLINT
2430 DUTCHER ROAD
FLINT MI 48532-4421 81072088000000

Invoice Date: 05/06/2006

Ship to Information

Ship to Service Agent: 160723
SATURN OF FLINT
2430 DUTCHER ROAD
FLINT MI 48532-4421 81072088000000

Ship to Date: N/A

Delivery Information

Delivery Service Agent: 160723
SATURN OF FLINT
2430 DUTCHER ROAD
FLINT MI 48532-4421 81072088000000

Delivery Date: 05/06/2006
Delivery Type:
Delivery Odometer: 11

In Service Information

Invoicing Service Agent: 2211085

In Service Date: N/A
In Service Type: 0000
In Service Odometer: 0

Registration Information

Registration Service Agent: N/A

Registration Date: N/A
Registration Number: N/A
Registration Odometer: 0

For this vehicle:

[View Vehicle Summary](#)

- Service Contract
- Branded Title
- Warranty Block

[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History](#)[Detail](#)[View Vehicle Delivery](#)[Information](#)

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.



esis

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Lawrence Harrington
Claim Administrator

October 8, 2012

[REDACTED]
GRAND RAPIDS, MI [REDACTED]

RE: Claimant: [REDACTED]
Our File No.: 747261
Our Client: General Motors LLC
Date/Event: 8/29/2012
Vehicle: 2006 SATURN ION 2
VIN: 1G8AJ55F36Z [REDACTED]

Dear [REDACTED]:

This will confirm that we have completed our review of your claim regarding alleged defects to the 2006 SATURN ION 2. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Lawrence Harrington

Lawrence Harrington

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G8AJ55F36Z [REDACTED]
User	Bailey
Case Number	747261
EDR Data Imaging Date	09/17/2012
Crash Date	08/29/2012
Filename	GANT 1G8AJ55F36Z [REDACTED] ACM.CDRX
Saved on	Monday, September 17 2012 at 11:16:46
Collected with CDR version	Crash Data Retrieval Tool 6.0
Reported with CDR version	Crash Data Retrieval Tool 6.0
EDR Device Type	Airbag Control Module
Event(s) recovered	Non-Deployment

Comments

Method used to download: DLC
Powered by: Vehicle Battery
Location: [REDACTED] Grand Rapids, MI
Present: Self & Owner
Mileage: 87,932
Lamp test results: On at ignition, flashes, then off

Data Limitations

Recorded Crash Events:

There are two types of Recorded Crash Events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). It contains Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event may be overwritten by another Non-Deployment Event. This event will be cleared by the SDM, after approximately 250 ignition cycle. This event can be overwritten by a second Deployment Event, referred to as a Deployment Level Event, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds before a Deployment Event. A locked Non-Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also contains Pre-Crash and Crash data. The SDM can store up to two different Deployment Events, if they occur within five seconds of one another. If a Deployment Level Event occurs within five seconds after the Deployment Event, the Deployment Level Event will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Longitudinal Velocity Change reflects the change in longitudinal velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Longitudinal Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 100 milliseconds of data after Deployment criteria is met and up to 50 milliseconds before Deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 150 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- Significant changes in the tire's rolling radius
- Final drive axle ratio changes
- Wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- The SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- No data is received from the module sending the pre-crash data
- No module present to send the pre-crash data

-Driver's Belt Switch Circuit Status indicates the status of the driver's seat belt switch circuit. If the vehicle's electrical

system is compromised during a crash, the state of the Driver's Belt Switch Circuit may be reported other than the actual state.

-The Time between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-All data should be examined in conjunction with other available physical evidence from the vehicle and scene.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

-Vehicle Speed, Engine Speed, and Percent Throttle data are transmitted by the Powertrain Control Module (PCM), via the vehicle's communication network, to the SDM.

-Brake Switch Circuit Status data is transmitted by either the ABS module or the PCM, via the vehicle's communication network, to the SDM. Depending on vehicle option content, the Brake Switch Circuit Status data may not be available.

-The SDM may obtain Belt Switch Circuit Status data a number of different ways, depending on the vehicle architecture. Some switches are wired directly to the SDM, while others may obtain the data from various vehicle control modules, via the vehicle's communication network.


01014_SDMDW_r003

System Status At Non-Deployment

SIR Warning Lamp Status	OFF
Driver's Belt Switch Circuit Status	BUCKLED
Passenger Belt Switch Circuit Status (If Equipped)	UNBUCKLED
Driver Seat Position Status (If Equipped)	Forward
Passenger Seat Position Status (If Equipped)	Forward
Ignition Cycles At Non-Deployment	18211
Ignition Cycles At Investigation	18236
Maximum SDM Recorded Velocity Change (MPH)	-10.44
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	250
A Deployment was Commanded Prior to this Event	No
Event Recording Complete	Yes

Seconds Before AE	Vehicle Speed (MPH)	Engine Speed (RPM)	Percent Throttle
-5	50	1792	16
-4	50	1728	0
-3	47	1600	0
-2	37	1280	0
-1	22	704	0

Seconds Before AE	Brake Switch Circuit State
-8	OFF
-7	OFF
-6	OFF
-5	OFF
-4	ON
-3	ON
-2	ON
-1	ON



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Recorded Velocity Change	0.00	-0.44	-1.32	-1.32	-1.76	-2.19	-3.07	-3.51	-4.39	-4.83	-5.27	-5.70	-6.58	-7.46	-7.90

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 A0 3B 00 00 00 00
$02 AB C7 00 00 00 00
$03 41 53 36 30 39 34
$04 4B 34 57 42 50 32
$05 02 41 00 00 C3 00
$06 22 72 57 28 00 00
$10 F7 18 F0 00 00 00
$11 96 00 00 00 00 84
$12 60 40 FF FF 00 00
$13 0A 00 00 00 00 00
$14 F3 04 ED 05 50 00
$18 84 84 84 4A FF 00
$1C 38 FA 41 FA FA FA
$1D FA 38 FA 41 FA FA
$1E FA FA 00 00 00 00
$1F 00 05 00 00 00 00
$20 40 00 00 11 FE 00
$21 FF FF FF FF FF FF
$22 FF FF FF FF 00 00
$23 00 01 03 03 04 05
$24 07 08 0A 0B 0C 0D
$25 0F 11 12 00 00 00
$26 24 3B 4B 51 51 F0
$27 00 00 00 00 29 00
$28 0B 14 19 1B 1C 00
$29 F7 1B F8 00 00 00
$2A 00 00 00 00 00 00
$2B 00 00 00 00 00 00
$2C 00 00 FF 2A 02 FA
$2D 00 00 00 00 00 00
$2E 00 00 22 00 00 00
$30 FF FF FF FF FF 00
$31 FF FF FF FF FF FF
$32 FF FF FF FF 00 00
$33 FF FF FF FF FF FF
$34 FF FF FF FF FF FF
$35 FF FF FF FF FF FF
$36 FF FF FF FF FF FF
$37 FF FF FF FF FF FF
$38 FF FF FF FF FF 00
$39 FF FF FF FF FF FF
$3A FF FF FF FF FF 00
$3B FF FF FF FF 00 00
$3C FF FF FF FF FF FF
$3D FF FF FF FF 00 00
$3E FF FF FF 00 00 00
$40 FF FF FF FF FF 00
$41 FF FF FF FF FF FF
$42 FF FF FF FF 00 00
$43 FF FF FF 00 00 00
$44 FF 00 00 00 00 00
$50 00 00 00 00 6C 43
$51 64 AA 00 00 00 00
```

\$60 FF FF FF FF FF FF
\$61 FF 00 00 00 00 00

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.

Tech2

32 Megabyte

CANdi Module Attached

Press [ENTER] to continue.
Software Version: 32.006
North American Operations

Main Menu

F0: Diagnostics

F1: Service Programming System

F2: View Captured Data

F3: GM Performance Parts Diagnostics

F4: Tool Options

F5: Getting Started

Vehicle Identification

Select one of the following
Model Year(s)

(D) 2013

(C) 2012

(B) 2011

(A) 2010

(9) 2009

(8) 2008

(7) 2007

(6) 2006

(5) 2005

8 / 23 —

(6) 2006

Vehicle Identification

Select one of the following
Vehicle Type(s)

Passenger Car

LD Trk, MPV, Incomplete

Medium Duty Truck

Workhorse

1 / 4 —

Passenger Car

Vehicle Identification

Select one of the following
Product Make(s)

- (S) Daewoo
- (K) Daewoo
- (1) Chevrolet
- (2) Pontiac
- (4) Buick
- (6) Cadillac
- (8) Saturn

7 / 7

- (8) Saturn

Diagnostics

- (6) 2006 Passenger Car
- (8) Saturn

F0: Powertrain

F1: Body

F2: Chassis

F3: Diagnostic Circuit Check

Body

F0: Body Control Module
F1: Digital Radio Receiver
F2: Instrument Panel Cluster
F3: Passenger Presence System
F4: Radio
F5: Supplemental Inflatable Restraint
F6: Vehicle Comm. Interface Module

Supplemental Inflatable Restraint

F0: Diagnostic Trouble Codes (DTC)
F1: Data Display
F2: Snapshot
F3: Module ID Information
F4: Module Setup

Diagnostic Trouble Codes (DTC)

F0: DTC Information

F1: Clear DTC Information

DTC Information

F0: History Diagnostic Trouble Code(s)

F1: Test not Pass Since Code Cleared

F2: Current Diagnostic Trouble Code(s)

Diagnostic Trouble Codes History

No Diagnostic Trouble Codes.

DTC Information

F0: History Diagnostic Trouble Code(s)

F1: Test not Pass Since Code Cleared

F2: Current Diagnostic Trouble Code(s)

Diagnostic Trouble Codes

Current

No Diagnostic Trouble Codes.

Supplemental Inflatable Restraint

F0: Diagnostic Trouble Codes (DTC)

F1: Data Display

F2: Snapshot

F3: Module ID Information

F4: Module Setup

Data Display

F0: Data

F1: System Configuration

Data

Battery Voltage Signal	12.00 Volts
ADS A/D	10.38 Volts
Driver Seat Belt Switch	Unbuckled

1 / 3

Battery Voltage Signal

Select
Items

Quick
Snapshot

More

Data

Battery Voltage Signal	12.00 Volts
IDS A/D	10.38 Volts
Driver Seat Belt Switch Buckled	

1 / 3

Battery Voltage Signal

Select
Items

Quick
Snapshot

More