


EWR D&I ANNOTATION

FAN-000001L091001DP159-6853

Artemis # : 000001L091001DP159**Record Created Date :** 04/15/2010**Printed Date :** 04/16/2010

Description : DI09-066 SEQUENCE ID 159 GM INJURY A CUSTOMER CONTACTED GM CUSTOMER SERVICE TO DESCRIBE AN ACCIDENT THAT SHE WAS IN. SHE WAS THE FRONT SEAT PASSENGER OF A 2006 CHEVROLET HHR THAT WAS HIT IN THE PASSENGER DOOR AREA. THE PASSENGER RECEIVED NON-LIFE-THREATENING INJURIES. SHE CONTACTED GM BECAUSE THE FRONTAL AIRBAGS DID NOT DEPLOY AND SHE BELIEVES THAT THEY SHOULD HAVE. IN DISCUSSING THE ACCIDENT WITH A GM REP, THE PASSENGER STATED THAT THERE WAS NO DAMAGE TO THE FRONT OF THE VEHICLE AND THAT THE VEHICLE WAS NOT EQUIPPED WITH SIDE IMPACT AIRBAGS. SHE THOUGHT THAT SINCE THE IMPACT SENT HER FLYING TOWARDS THE CENTER FRONT OF THE VEHICLE, THE AIRBAG SHOULD HAVE DEPLOYED. THE GM REP EXPLAINED TO HER THAT THERE MUST BE A FRONTAL IMPACT FOR THEM TO DEPLOY AND THAT THEY FUNCTIONED CORRECTLY. *JN

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

September 4, 2009

Ms. Gay P. Kent
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI09-066

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2009. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 2, 17, 20, 75, 76, 79, 87, 98, 103, 122, 124, 126, 133, 139, 147, 150, 157, 159, 160, 164, 179, 186, 196, 203, 204, 205, 209, 216, 254, 257, 266, 268, 282, 283, 296, 325, 331, 339, 354, 355, 357, 358, 374, 380, 396, 407, 432, 435, 436, 439, 440, 456, 457, 462, 469, 471, 504, 507, 511	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new

requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **October 2, 2009**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Josh Neff at (202) 366-0698 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name and last name clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS COMPANY
Global Interior and Safety Center

14 October 2009

OCT 15 2009

OCT 15 2009

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI09-066

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated September 4th, 2009 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2009.

GM's response is comprised of 65 disks for the incidents that are the subject of DI09-066. Sequence ID number 457, is a NISM (Not In Suit Matters) that originated in China and will be submitted as soon as the documents are located.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 2 274020230 - 671278 and 2008 BUICK LACROSSE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 2 274020230 - 671278_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index for the disk are as follows:

DI09-066
2 274020230-671278
2008 BUICK LACROSSE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining document listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

- 2 274020230 - 671278_01_001 - is the first document responsive to Inquiry no. 1.
 2 274020230 - 671278_02_001 - is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.

The table below lists the incident that is the subject of DI09-066, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(1 Vehicle from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
2	UNKNOWN	NISM
17	3G5DA03E25S	NISM
20	3G5DA03L97S	NISM
75	KL1TG52655B	NISM
76	KL1TD52685B	NISM
79	KL1TD56677B	NISM
87	KL1TD56EX9B	NISM
98	1G1AZ55F267	PAR
103	1G1AK55F067	NISM
122	1G1AL58F887	NISM
124	1G1AL58F887	NISM
126	1G1AM18BX87	NISM
133	1G1AT58H497	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
139	1GCDS49E288	NISM
147	2CNDL73F866	NISM
150	2CNDL63F166	PAR
157	1GBJG316481	RUMOR
159	3GNDA23D96S	NISM
160	3GNDA23DX7S	NISM
164	3GNDA13D18S	NISM
179	2G1WF52E359	NISM
186	2G1WT58K879	NISM
196	2G1WB57K291	NISM
203	1G1ZU57NX7F	NISM
204	1G1ZU57N77F	NISM
205	1G1ZT58F57F	NISM
209	1G1ZG57BX8F	NISM
216	2G1WM15K069	NISM
254	2GCEK133971	NISM
257	2GCEK19J071	PAR
266	2GCEK19JX81	NISM
268	2GCEK13C181	NISM
282	1GCHK29D87E	NISM
283	1GCHK53679F	LIT
296	1GNFK16358R	NISM
325	1GNDT13S552	NISM
331	1GNDT13S772	NISM
339	1GNDT13S882	PAR
354	1GKEV33798J	NISM
355	1GKER23738J	NISM
357	1GKEV33748J	NISM
358	1GKEV33748J	NISM
374	1GKDT13S862	NISM
380	1GKDT13S772	NISM
396	3GTEC13047G	NISM
407	1GTHK23668F	NISM
432	1G2ZH57N284	NISM
435	1G2ZF57B084	NISM
436	1G2ZH57NX84	NISM
439	1G2ZH57N394	NISM
440	1G2ZH57N094	NISM
456	2G2WP552281	NISM
457	UNKNOWN	NISM
462	1G2MB33B76Y	NISM
469	YS3FD79Y856	NISM
471	YS3FD79Y376	NISM
504	5GZCZ53466S	NISM
507	5GZCZ33D36S	PAR
511	3GSDL73768S	NISM

2. **Provide a copy of the Police Accident Report.**

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. **At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read 'G. Kent', with a long, sweeping horizontal line extending to the right.


Gay P. Kent,
Director, Product Investigations
and Safety Regulations

Enclosures: 65 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl +PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl +PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl +PgDn** or **Ctrl +PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5, F6, F7, and F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

982.2(b)(1)

FOR COURT USE ONLY

ATTESTED BY PARTY/WEBSITE ATTORNEY/PLAINTIFF, with the number and address
 ERIC D. PARIS, ESQ., S/88 147836
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 281 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91766
 TELEPHONE NO: 909-469-5127 FAX NO: 909-469-5126
 ATTORNEY FOR: PLAINTIFF'S
 SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 INDIO COURT

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET

Complex Case Designation
☐ Counter ☐ Joinder
 Filed with first appearance by defendant
 (Cal. Rules of Court, rule 1811)

CASE NUMBER: _____
 ASSIGNED JUDGE: _____

1. Check one box below for the case type that best describes this case:

☒ Auto Tort (22)
☐ Other PFDWD (Personal Injury/Property Damage/Willful Death) Tort
☐ Asbestos (04)
☐ Product Liability (24)
☐ Medical malpractice (45)
☐ Other PFDWD (23)
☐ Non-PFDWD (Other) Tort
☐ Business tortious business practice (07)
☐ Claims (e.g., discrimination, false arrest) (00)
☐ Detention (e.g., slander, libel) (13)
☐ Fraud (16)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (20)
☐ Other non-PFDWD tort (26)
☐ Employment
☐ Wrongful termination (36)

☐ Other employee (15)
☐ Breach of contract/warranty (06)
☐ Collection (e.g., money owed, debt 8000 accounts) (09)
☐ Insurance coverage (18)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/taxwise condemnation (14)
☐ Wrongful eviction (30)
☐ Other real property (e.g., quiet title) (28)
☐ Unlawful Detainer
☐ Commercial (31)
☐ Residential (32)
☐ Drugs (38)
☐ Medical Review
☐ Asset forfeiture (56)
☐ Pollution or arbitration award (11)

☐ Will of decedent (02)
☐ Other judicial review (39)
☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 1809 - 1812)
☐ Antitrust/Trade regulation (03)
☐ Construction defect (10)
☐ Claims limitation means first page

2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring conceptual/judicial management.

a. ☒ Large number of separately represented parties b. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve c. ☒ Substantial amount of documentary evidence d. ☐ Large number of coordination and in other counties

3. Type of remedies sought (check all that apply):
 a. ☒ Monetary b. ☐ Injunctive, declaratory or injunctive relief c. ☐ Substantial post

4. Number of causes of action (specify): FIVE

5. This case ☐ is ☒ is not a class action suit.

Date: JULY 3, 2003

ERIC D. PARIS, ESQ., S/88 147836
 (Print or next name)

NOTICE
 • Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (except under the Probate, Family, or Welfare and Institutions Code) (Cal. Rules of Court, rule 1809).
 • File this cover sheet in addition to any cover sheet required by local court rule.
 • If this case is complex under rule 1800 et seq. of the California Rules of Court, you must also file a complex case cover sheet.
 • Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

CIVIL CASE COVER SHEET

EXIF Image Information...
 Preferences...

Step 7: Next File
(Image)

Step 7: Next page

Step 8: Scale
Image

Step 7: Image Properties

DI09-066
159 272742644 – 668809
2006 CHEVROLET HHR

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No. (b) (6)	Ref No. 71-704849047	Goodwill No Goodwill Offered	BRC Type PAR
Account	Site	GW SubType	Bus. Unit BRC
Last Name	First Name	Approval Not Initiated	Area PAR
Daytime #	Evening #	UCC Restraints - (SIR) - Driver Side - Side	Sub-Area Initiate PAR- Injury
Address	City Evergreen	Involved Dir Stevenson Chevrolet West, Inc.	Safety Yes
State CO ZipCd	Con Acct	Source Email	Updated 3/23/2009 05:58:44 PM
Serial #VIN 3GNDA23D96S	Model Year 2006	Priority Medium License # CHEVROL	Owner RODRIGOS
Make Chevrolet	Warr. Start 07/05/2006	Status Open	Opened 2/25/2009 12:07:00 PM
Model HHR	Mileage 30560	Sub-Status Dissatisfied	Closed
Abstract (CO) Airbags Did Not Deploy			
Customer Description *** BRC PAR CASE. DO NOT ASSUME. FORWARD ALL INQUIRIES TO JOSE RODRIGUEZ EXT 31103 ***			

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Firo Report#	Police Report#
GM Personnel	2/21/2009 10:55:00 AM	Y	1	2	Concrete	Dry	na	Unknown
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'9"		n/a				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Holdcroft	Sharon	(720) 497-9461	Safeco Insurance					
Incident Loc	On entrance ramp to I-70 Eastbound, Evergreen, CO. at Hwy 74 junction.				Incident Desc	Cust sts that on 2/21/2009, her husband was driving the vehicle. She was the front passenger. Cust sts that he was driving about 50-55 an exit ramp. Sts that they were T-Boned, by another vehicle on the passenger side door. Cust sts that the front airbags did not deploy. sts that there		
Component	Airbags Did Not Deploy				Damage Desc	passanger door		
Vehicle Loc	at home				Addt Info	All of Cust's claims of injury due to accident Cervical strain. Concussion.		
Emgcy Svc Namas	State Police				Maint Loc	unknown		

PAR Detail

Collision Y	Non Collision	Property Damage N	Thermal Evt N	Spec Equip unknown				
Vehicle Speed	Weather Condition	unknown	Prop Owner	n/a	Property Type	n/a		
Last Service Date	Loc Last Service		Property Location	n/a	Prop Est Repair Cost			
Veh Est Repair Cost	Spec Equip Installer	unknown	Prop Damage Description	n/a				
Primary Veh Use	Personal	Inspection Type	Inspected By	Inspection Not Performed	Inspection Date/Time			
Veh Damage Description	passenger front damages		Explain Other	n/a				

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
Occupant of Owner's Vehicle					Front Passenger	seatbelt
Injury Description			Medical Rpt#	Treatment Location		Treated By
Door hit her head hard, Cust went flying towards middle front of veh, and caused concussion and whiplash, hyper-extended tandon, a neuropathy problem (cust does not have feeling in right hand fingers) Neck hurts down bottom of neck into shoulders.			unknown	Saint Anthonys in lakewood Colorado		unknown
Street Address			City	State	Zip Code	
			Evergreen	CO		

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/23/2009 05:55:10 PM	RODRIGOS	RODRIGOS	BRC PAR	ESIS - Injuries	Done	3/23/2009 05:55:31 PM	esis case
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Case was sent to ESIS, due to injuries

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/23/2009 05:54:51 PM	RODRIGOS	RODRIGOS	Scheduled Follow-up		Scheduled Alarm		71-705216688 Check on ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/23/2009 05:54:29 PM	RODRIGOS	ESIS81QU	Escalation	ESIS - Injuries	In Progress		Assigned to ESIS
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Injuries

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/23/2009 04:39:42 PM	RODRIGOS	RODRIGOS	Outbound Call Customer	Made Contact	Done	3/23/2009 05:16:06 PM	Called customer
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust sts that on 2/21/2009, her husband was driving the vehicle. She was the front passenger. Cust sts that he was driving about 50-55 on exit ramp. Sts that they were T-Boned, by another vehicle on the passenger side door. Cust sts that the front airbags did not deploy, sts that there was no front impact. Cust sts that she was injured, she hit her head on the door. Cust believes that the airbags should have deployed.

Cust sts that she does not believe that her veh has side airbags. Sts that he wants to know why she was never notified that there was a recall on her vehicle for 08157 INSTRUMENT PANEL STORAGE BIN DOOR COMPLIANCE - ADD REINFORCEMENT BRACKET

Crs advised that the front airbags do not deploy unless there is a frontal collision.

Cust believes that they still should have deployed. sts that she went forward.

Crs advised that the case will go to ESIS. Advised that they will be in contact in the next 7-10 business days.

Cust understood.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/21/2009 11:14:29 AM	RODRIGOS	RODRIGOS	Scheduled Follow-up		Done	3/23/2009 04:33:21 PM	71-705216588 3rd Attempt
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Closed

Call made early

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:38:12 PM	KINZERTH	RODRIGOS	Ownership Changed		Done	3/20/2009 02:38:12 PM	Service Request Ownership has changed FROM: MCFADDUA TO: RODRIGOS
Contact Last Name	Contact First Name	Account			BAC Code		
Comments							

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:37:53 PM	KINZERTH	RODRIGOS	BRC PAR	Initial Contact- AVM	Done	3/23/2009 05:54:26 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							

DVM Dan Kelley 80509 58775

Crs advised that Cust sts that on 2/21/2009, her husband was driving the vehicle. She was the front passenger. Cust sts that he was driving about 50-55 an exit ramp. Sts that they were T-Boned, by another vehicle on the passenger side door. Cust sts that the front airbags did not deploy, sts that there was no front impact. Cust sts that she was injured, she hit her head on the door. Cust believes that the airbags should have deployed.

Crs advised case is going to ESIS.

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:37:44 PM	KINZERTH	RODRIGOS	BRC PAR	Initial Contact- Dealer	Done	3/23/2009 05:42:42 PM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

BAC # 113032
STEVINSON CHEVROLET WEST, INC.
15000 W COLFAX AVE
LAKEWOOD CO 80401-4023
303-279-3311

Svc Mgr Elliot Cox

Crs advised that on 2-21-09, cust was T-Boned, on the passengers side door, by another vehicle. The customer is upset that the front airbags did not deploy.

Cust seeks info on allegation.

Dir sts: 1-08, the veh was at the dir for a radio reprogrammed, and a shifter, fuse for the power steering.

no information on the accident.

call ended.

Jose Rodriguez ATX PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:37:35 PM	KINZERTH	RODRIGOS	BRC PAR	Initial Contact- Phone	Done	3/21/2009 11:14:01 AM	Called
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

left vm

Crs advised that received case in PAR. Crs seeks call back.
Provided contact information.

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:37:28 PM	KINZERTH	RODRUOS	BRC PAR	Acknowledgement	Done	3/20/2009 04:01:43 PM	
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
Left message

CRS adv. This message is for [REDACTED] - this is Monica Marquez calling from gm par dept for the 06 Chevrolet HHR - advised that Jose Rodriguez is working on your file and wanted to give info to contact - he should be in contact with customer as well. Provided number and ext to call OCRS.

Monica Marquez/BRCPAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:37:18 PM	KINZERTH	RODRUOS	Notify CRM		Done	3/21/2009 10:08:12 AM	File Assigned
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:37:11 PM	KINZERTH	RODRUOS	Research		Done	3/21/2009 11:07:42 AM	Research VIN
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
3GNDA23D96S

no open recalls

Found Duplicate ADR case about same issue.
71-704849047

Jose Rodriguez ATX PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:36:52 PM	KINZERTH	RODRIGOS	BRC PAR	Case Assigned	Done	3/21/2009 10:59:30 AM	Assigned to Jose Rodriguez x31103
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:00:36 PM	KINZERTH	MCFADDJA	SR Opened		Done	3/20/2009 02:00:36 PM	SR in Status of Closed has been Re-Opened by KINZERTH
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 02:00:35 PM	KINZERTH	MCFADDJA	SR Closed - Satisfied		Done	3/20/2009 02:00:35 PM	Service Request has been Closed Satisfied.
Contact Last Name		Contact First Name		Account		BAC Code	

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 01:04:02 PM	MCFADDJA	MCFADDJA	Other		Done	3/20/2009 01:06:58 PM	(cont'd from prev activity)
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs sts: I do apol that you have experienced this accident, and will fully document your concerns for further review by a special division within GM. You can expect to hear from an agent of this division within 2 business days.

Cust sts: I imagine that GM will want to diagnose the vehicle, but again, I am hesitant to repair the veh, pending what we are doing with our attorney in this matter.

Crs sts: I will involve our PAR division, and we can continue from there.

Cust sts: Thanks very much! And thank-you for being so patient with me while I was sick.

Jason McFadden/BRC/Chatham/21861

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 01:01:26 PM	MCFADDJA	KINZERTH	Escalation	Initiate PAR	Done	3/20/2009 02:00:15 PM	Assigning activity to PAR QUEUE.
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS advised that a person from the PAR Department will contact the customer within 2 business days.

Jason McFadden/BRC/Chatham/21861

Received and assigned in PAR
Thaddeus Kinzan/PAR Workflow/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/20/2009 12:33:40 PM	MCFADDJA	MCFADDJA	Inbound Call Customer	Complex Request	Done	3/20/2009 01:07:38 PM	Cust calls in
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust st: We were driving up the entrance ramp, when we were t-boned by another veh (a Chrysler Sebring). I then learnt that there was a related recall last September which I was not advised of. This accident occured at approx. 55 mph. Veh not yet repaired, bc demages are a couple thousand dollars over my deductible. We have to wait until our attorney. We are disputing the details that were so loosely reported by both the other party, and the state police. I believe that the other driver caused the accident on purpose. And the witness for the other driver (who showed up 15 minutes later) claimed that we caused the accident. This is all pending our attorney's investigation. GM has nothing to do with the accident itself. I don't believe that the veh caused the accident. But the airbags did not deploy, and I think the blindspots in the veh may have contributed to the circumstances. The other driver's veh was already being repaired two days after the accident. I am going to hold off on repairing my vehicle until we have our day in court with the other driver anyways. Our insurance investigator was trying to acquire a police report, but thus far, we have not been able to receive one. I had a previous back surgery last March. I keep the seat as erect and only slightly reclined. We have not brought our vehicle to a GM dealer just yet, bc I am hesitant to have it repaired.

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/18/2009 09:11:29 AM	MCFADDJA	MCFADDJA	Scheduled Follow-up		Done	3/20/2009 02:00:31 PM	6 Days
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Jason McFadden/BRC/Chatham/21861

Cancelled activity

**Case will be assigned to PAR agent

**No further action required from CAC

Thaddeus Kinzer/PAR Workflow/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/13/2009 09:08:49 AM	MCFADDJA	MCFADDJA	Scheduled Follow-up		Done	3/18/2009 09:11:24 AM	- 6 Days
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Jason McFadden/BRC/Chatham/21861

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/9/2009 10:09:25 AM	MCFADDJA	MCFADDJA	Scheduled Follow-up		Done	3/13/2009 09:08:48 AM	6 Days
Contact Last Name	Contact First Name	Account			BAC Code		
Comments							
Jason McFadden/BRC/Chatham/21861							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/5/2009 12:47:02 PM	MCFADDJA	MCFADDJA	Other		Done	3/5/2009 12:48:08 PM	Refer to SR # 71-704849047 for case progression.
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
PAR SR is pending Customer contact.							
Refer to SR # 71-704849047 for case progression information.							
Jason McFadden/BRC/Chatham/21861							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/4/2009 11:25:20 AM	MCFADDJA	MCFADDJA	Inbound Email	Customer	Done	3/4/2009 11:25:34 AM	From Customer
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
I am sorry I was unable to speak with you the other day. I've been down with bronchitis / flu, and I'm still not so good to talk long but I'm feeling ok to start handling this. I understand that you can't handle my continuing claim via email, but at this point I think I would still like to handle everything in writing. The need for complete documentation is greater than the need for speed at this point. So, I'd prefer doing this the old fashioned way, that also gives me time to pull my thoughts together and respond to your needs more thoroughly. Would you please send correspondence to [REDACTED] Evergreen, CO 80439.							
Sincerely,							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
3/3/2009 09:08:40 AM	MCFADDJA	MCFADDJA	Scheduled Follow-up		Done	3/9/2009 10:09:17 AM	6 Days
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Jason McFadden/BRC/Chatham/21861							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/25/2009 12:15:24 PM	MCFADDJA	MCFADDJA	Scheduled Follow-up		Done	3/3/2009 09:08:37 AM	6 Days
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
Jason McFadden/BRC/Chatham/21861							
Confidential Comments							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/25/2009 12:15:59 PM	MCFADDJA	MCFADDJA	Outbound Call Customer	Left Message	Done	2/25/2009 12:15:22 PM	Attempt to contact re: PAR
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
Crs attempted to contact Cust re: BBB claim, and the potential PAR allegation.

Crs left message on Cust voicemail.

2/26/2009 betw 11am - 1pm, EST.
Daytime #
Evening/C

Re: BBB claim, and potential PAR allegation.

Note: SOCC is scheduled within the SR# 71-704849047, which is the file created and attached to the Cust's BBB claim.

Jason McFadden/BRC/Chatham/21861

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
2/25/2009 12:07:01 PM	MCFADDJA	MCFADDJA	Ownership Changed	Ownership Escalated to BRC	Done	2/25/2009 12:07:01 PM	Ownership Escalated to BRC
Contact Last Name							
Contact First Name							
Account							
BAC Code							
Comments							
Confidential Comments							

UCC Information

UCC Code	Symptom	Description
C47	SIR - Did Not Deploy	Restraints - (SIR) - Driver Side - Side Impact

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

[Help](#)

VIN :	3GNDA23D96S
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	1AS46 -2006 CHEVROLET HHR LT SEDAN		Warranty Start Date :		07/05/2006		
BARS Order Type :	70 - RETAIL - STOCK						
Delivering Dealer :	FRANK GALOS CHEVROLET-CADILLAC PO BOX 1510 SACO, ME 04072-7510 (207) 284-5986			Selling Source :		13 - CHEVROLET	
				Site Code :		32250	
				Business Associate Code :		115033	
Service Contract :	Yes	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Type	Number	Description	Posted Date	Status
RC	08016	HEAD IMPACT PROTECTION - INCREASED PROTECTION	N/A	Closed
RC	08157	INSTRUMENT PANEL STORAGE BIN DOOR COMPLIANCE - ADD REINFORCEMENT BRACKET	N/A	Closed

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.

APPLICABLE WARRANTIES

	Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY		07/05/2006	9 miles	07/05/2009	36009 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY		07/05/2006	9 miles	07/05/2012	100009 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM		07/05/2006	9 miles	07/05/2014	80009 miles
36/50000 CALIFORNIA EMISSIONS		07/05/2006	9 miles	07/05/2009	50009 miles
84/70000 CALIFORNIA SELECT COMPONENT		07/05/2006	9 miles	07/05/2013	70009 miles

<http://198.208.187.167/gmvis/main/Summary?languageSelected=EN&VIN=3GNDA23D9...> 3/24/2009

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
09/22/2008	Y03522	#	Z2080 - ROADSIDE SERVICE (TOWING)	30596 miles
09/22/2008	127355	#	N4800 - BODY CONTROL MODULE REPLACEMENT	30596 miles
09/22/2008	127355	#	Z7905 - 5-DAY COURTESY TRANSPORTATION	30596 miles
09/22/2008	127355	#	Z5000 - DEALER/RETAILER TRADE(PART OBTAINED LOCALLY)	30596 miles
04/25/2008	121302	#	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE	25594 miles
04/25/2008	121302	G	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE	25599 miles
04/25/2008	121302	#	L1195 - SEAL, FUEL SENDER/PUMP ASSEMBLY (TANK UNIT) - REPLACE	25599 miles
04/25/2008	121302	#	V1786 - 08016 - INSTALL ENERGY ABSORBING DEVICES	25594 miles
04/25/2008	121302	#	N0850 - FRONT FOG LAMP BULB REPLACEMENT	25594 miles
04/25/2008	121302	#	Z5000 - DEALER/RETAILER TRADE(PART OBTAINED LOCALLY)	25594 miles
01/02/2008	S37860	#	Z2080 - ROADSIDE SERVICE (TOWING)	22000 miles
01/02/2008	249003	#	K5225 - CONTROL ASSEMBLY, FLOOR SHIFT - REPLACE	23001 miles
01/02/2008	249003	#	R0759 - RADIO REPROGRAMMING WITH SPS	23001 miles
01/02/2008	249003	D	K5225 - CONTROL ASSEMBLY, FLOOR SHIFT - REPLACE	23001 miles
01/02/2008	249003	#	Z7901 - 1-DAY COURTESY TRANSPORTATION	23001 miles
01/02/2008	249003	#	N1720 - FUSE REPLACEMENT	23001 miles
05/30/2007	087358	#	E2320 - FRONT WHEEL BEARING AND HUB REPLACEMENT	14982 miles
05/17/2007	087057	#	J6354 - POWERTRAIN CONTROL MODULE ENGINE REPROGRAMMING WITH SPS	14447 miles
03/26/2007	085759	#	N6608 - EMISSIONS SYSTEM WIRING AND/OR CONNECTOR REPAIR OR REPLACE	13167 miles
07/13/2006	079026	#	N1720 - FUSE REPLACEMENT	431 miles
07/13/2006	079026	#	T2020 - TOWING	431 miles
02/13/2006	A15857	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Claim History

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information - Service Contract - Warranty Block - Branded Title

[Help](#)

VIN :	3GNDA23D96S
-------	-------------

CLAIM HISTORY

Repair Order Date :		09/22/2008		Repair Order Number :		Y03522		Odometer Reading :		30596 miles	
Serviced By :		GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117				Selling Source :			13 - CHEVROLET		
						Site Code :			34415		
						Business Associate Code :			207453		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
11/04/2008	949	01	#	Z2080 - ROADSIDE SERVICE (TOWING)		N/A		C	N/A	\$ 69.68	N

Repair Order Date :		09/22/2008		Repair Order Number :		127355		Odometer Reading :		30596 miles	
Serviced By :		EMICH CHEVROLET 2033 S WADSWORTH BLVD LAKEWOOD, CO 80227-2481 (303) 986-2233				Selling Source :		13 - CHEVROLET			
						Site Code :		10533			
						Business Associate Code :		224441			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
11/11/2008	951	01	#	Z7905 - 5-DAY COURTESY TRANSPORTATION		N/A	BWG	N/A	\$ 210.00	Y	
10/17/2008	944	01	#	N4800 - BODY CONTROL MODULE REPLACEMENT		15910666 - MODULE	E	N/A	\$ 579.97	Y	
10/10/2008	942	03	#	Z5000 - DEALER/RETAILER TRADE(PART OBTAINED LOCALLY)		15910666 - MODULE	N/A	N/A	\$ 18.14	Y	

Repair Order Date :	04/25/2008	Repair Order Number :	121302	Odometer Reading :	25599 miles
Serviced By :	EMICH CHEVROLET			Selling Source :	13 - CHEVROLET

<http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=3GNDA2...> 3/24/2009

By :		2033 S WADSWORTH BLVD LAKEWOOD, CO 80227-2481 (303) 986-2233			Site Code :		10533		
					Business Associate Code :		224441		
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
07/15/2008	917	01	G	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE	N/A	G	N/A	\$ 42.44	N
07/11/2008	916	01	#	L1195 - SEAL, FUEL SENDER/PUMP ASSEMBLY (TANK UNIT) - REPLACE	15850486 - MODULE KI	N/A	N/A	\$ 360.92	N
06/20/2008	910	01	#	H0042 - PADS, DISC BRAKE - FRONT - R&R OR REPLACE	22728988 - ROTOR	N/A	N/A	\$ 491.44	N
06/20/2008	910	02	#	V1786 - 08016 - INSTALL ENERGY ABSORBING DEVICES	19206742 - ABSORBER	N/A	N/A	\$ 53.54	N
06/20/2008	910	03	#	N0850 - FRONT FOG LAMP BULB REPLACEMENT	N/A	N/A	N/A	\$ 27.38	N
06/20/2008	910	04	#	Z5000 - DEALER/RETAILER TRADE(PART OBTAINED LOCALLY)	22728988 - ROTOR	N/A	N/A	\$ 30.48	N

Repair Order Date :		01/02/2008		Repair Order Number :		S37860		Odometer Reading :		22000 miles	
Serviced By :	GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117					Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
01/11/2008	864	01	#	Z2080 - ROADSIDE SERVICE (TOWING)		N/A		C	N/A	\$ 58.94	N

Repair Order Date :		01/02/2008		Repair Order Number :		249003		Odometer Reading :		23001 miles	
Serviced By :		STEVINSON CHEVROLET WEST, INC. 15000 W COLFAX AVE LAKEWOOD, CO 80401-4023 (303) 279-3311				Selling Source :		13 - CHEVROLET			
						Site Code :		10822			
						Business Associate Code :		113032			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
				K5225 - CONTROL							

03/07/2008	880	01	D	ASSEMBLY, FLOOR SHIFT - REPLACE	N/A	N/A	N/A	\$ 15.16	Y
03/07/2008	880	02	#	Z7901 - 1-DAY COURTESY TRANSPORTATION	N/A	G	N/A	\$ 37.00	N
02/22/2008	876	01	#	R0759 - RADIO REPROGRAMMING WITH SPS	N/A	N/A	N/A	\$ 36.02	N
02/01/2008	870	01	#	K5225 - CONTROL ASSEMBLY, FLOOR SHIFT - REPLACE	25864102 - CONTROL	N/A	N/A	\$ 231.59	N
02/01/2008	870	03	#	N1720 - FUSE REPLACEMENT	15319480 - FUSE	N/A	N/A	\$ 21.50	N

Repair Order Date :		05/30/2007		Repair Order Number :		087368		Odometer Reading :		14982 miles	
Serviced By :	FRANK GALOS CHEVROLET-CADILLAC PO BOX 1510 SACO, ME 04072-7510 (207) 284-5986					Selling Source :		13 - CHEVROLET			
						Site Code :		32250			
						Business Associate Code :		115033			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
06/01/2007	800	01	#	E2320 - FRONT WHEEL BEARING AND HUB REPLACEMENT		22728987 - HUB	N/A	N/A	\$ 199.95	Y	

Repair Order Date :		05/17/2007		Repair Order Number :		087057		Odometer Reading :		14447 miles	
Serviced By :	FRANK GALOS CHEVROLET-CADILLAC PO BOX 1510 SACO, ME 04072-7510 (207) 284-5986					Selling Source :		13 - CHEVROLET			
						Site Code :		32250			
						Business Associate Code :		115033			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
05/29/2007	799	01	#	J6354 - POWERTRAIN CONTROL MODULE ENGINE REPROGRAMMING WITH SPS		N/A	B	N/A	\$ 53.23	Y	

Repair Order Date :		03/26/2007	Repair Order Number :		085759	Odometer Reading :		13167 miles	
Serviced By :	FRANK GALOS CHEVROLET-CADILLAC PO BOX 1510 SACO, ME 04072-7510				Selling Source :		13 - CHEVROLET		
					Site Code :		32250		

<http://198.208.187.167/gmvis/main/ClaimHistory?languageSelected=EN&VIN=3GNDA2...> 3/24/2009

(207) 284-5986					Business Associate Code : 115033				
Cycle Date	Cycle Nbr	Case	Type	Labor Operation	Part	Auth Code	Person Code	Line Total	Comments
03/30/2007	782	01	#	N6608 - EMISSIONS SYSTEM WIRING AND/OR CONNECTOR REPAIR OR REPLACE	N/A	E	N/A	\$ 190.10	Y

Repair Order Date :		07/13/2006		Repair Order Number :		079026		Odometer Reading :		431 miles	
Serviced By :	FRANK GALOS CHEVROLET-CADILLAC PO BOX 1510 SACO, ME 04072-7510 (207) 284-5986					Selling Source :		13 - CHEVROLET			
						Site Code :		32250			
						Business Associate Code :		115033			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
08/11/2006	716	01	#	N1720 - FUSE REPLACEMENT		88914568 - FUSE		N/A	N/A	\$ 17.96	Y
08/11/2006	716	02	#	T2020 - TOWING		N/A		N/A	N/A	\$ 70.00	Y

Repair Order Date :		02/13/2006		Repair Order Number :		A15857		Odometer Reading :		0 miles	
Serviced By :		FRANK GALOS CHEVROLET-CADILLAC PO BOX 1510 SACO, ME 04072-7510 (207) 284-5986				Selling Source :		13 - CHEVROLET			
						Site Code :		32250			
						Business Associate Code :		115033			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
02/17/2006	666	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 95.30	N

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 1998-2005 General Motors Corporation. All Rights Reserved.

GM Vehicle Inquiry System

Vehicle Build

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN	3GNDA23D96S
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AS46 -2006 CHEVROLET HHR LT SEDAN		
Gross Vehicle Weight Rating :	1925 kg (4245 lb)	Order Number :	JVBKBF
Build Date :	02/13/2006	Build Plant :	36SA

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AP3 - REMOTE STARTER SYSTEM	AR9 - FRONT BUCKET SEATS,DELUXE
AXP - MPV VIN IDENT POSITION	BVE - RUNNING BOARDS, COLOR KEYED ***DEALER INSTALLED***
B57 - BRIGHT CHROME APPEARANCE PKG: *BRIGHT CHROME GRILLE *BRIGHT CHROME O/S MIRRORS *BRT CHROME LIFTGATE APPLIQUE *BRIGHT CHROME DOOR HANDLE *ROOF RAILS WHEN PURCHASED	CF5 - POWER SUNROOF W/EXPRESS CLOSE
C2Y - GVW RATING 4,240 LBS	C67 - AIR CONDITIONING
DG7 - MIRROR,O/S ELECT REMOTE CNTRL	DNR - DEALER INSTALLED EQUIPMENT
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FX2 - 3.91 AXLE RATIO
G63 - ROOF LUGGAGE ROOF RAILS	IPB - TRIM INTERIOR DESIGN (PB)
J41 - PWR BRAKE SYSTEM	L61 - 2.2L DOHC 4V ECOTEC
MN5 - 4 SPD AUTO TRANSMISSION, HMD	MX0 - AUTOMATIC TRANS W/REMOTE START
NE1 - 50-STATE EMISSIONS	NU1 - CA EMISSION SYSTEM LEV 2
N24 - STEERING WHEEL, 3 SPOKE	QDB - TIRE, P215/55R16-91S BW ST AL2
QG9 - 16" MACHINED FACE ALLOY WHEELS	R6P - PREMIUM PAINT
R8K - ***** (NOT LISTED FOR THIS POSS OVERAL?)	SAL - RAMOS ARIZPE, MEXICO PLANT CODE
SLM - STOCK ORDERS	T37 - FOG LAMPS
US8 - AM/FM STEREO W/CD & MP3, RDS & AUXILIARY INPUT JACK (REPLACES STD/OPT RADIO)	UW5 - 6 SPEAKER SYSTEM

<http://198.208.187.167/gmvis/main/VehicleBuild?languageSelected=EN&VIN=3GNDA2...> 3/24/2009

VK3 - FRONT LICENSE PLATE MOUNT	V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA
1LT - LT PACKAGE	1SZ - OPTION PKG DISCOUNT
14B - GRAY CLOTH	14I - GRAY INTERIOR TRIM
41U - BLACK	6AE - FRONT SPRING
7AE - FRONT SPRING	

© 1998-2005 General Motors Corporation. All Rights Reserved.