


EWR D&I ANNOTATION



FAN-000001L101001DP114-4600

Artemis # : 000001L101001DP114**Record Created Date :** 01/05/2011**Printed Date :** 01/05/2011

Description : DI10-062 SEQUENCE 114 GENERAL MOTORS 1 INJURY 2006 CHEVROLET COBALT A VEHICLE CRASH OCCURRED DURING ICY ROAD CONDITIONS ON A NEW YORK ROADWAY. THE CAR WAS TRAVELING WITH THE CRUISE CONTROL ON. THE DRIVER TAPPED ON THE BRAKES TO DISENGAGE THE CRUISE CONTROL; INSTEAD THE VEHICLE EXPERIENCED SUDDEN ACCELERATION. THE VEHICLE LOST CONTROL ON ICY SLUSH CAUSING THE CAR TO SLIP AND MOVE TOWARDS THE LEFT SIDE OF THE ROAD WHERE IT STRUCK ANOTHER VEHICLE HEAD-ON. THE DRIVER SUSTAINED MULTIPLE FRACTURES TO HER ARMS AND LEGS. THE INSURANCE COMPANY TOTALED THE VEHICLE. NO SIMILAR FIELD REPORTS, VOQS, OR TSBS.
*AA

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

September 16, 2010

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-G11
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI10-062

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 16, 34, 38, 53, 67, 77, 91, 94, 113, 114, 125, 151, 167, 172, 173, 183, 195, 196, 208, 217, 225, 231, 253, 261, 267, 268, 285, 286, 293, 320, 323, 357, 365, 409, 410, 451, 506, 516, 539, 540, 585	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.

Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the

information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **October 15, 2010**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name and last name clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

October 13, 2010

OCT 15 2010

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI10-062

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated September 16, 2010 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2010.

GM's response is comprised of 41 disks for the incidents that are the subject of DI10-062.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 16 298093428-690125 and 2005 BUICK RAINIER. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 16 298093428-690125_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI10-062
16 298093428-690125
2005 BUICK RAINIER

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

16 298093428-690125_01_001- is the first document responsive to Inquiry no.1.
 16 298093428-690125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-062, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(41 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
16	5GADT13S552 [REDACTED]	NISM
34	1G6DP577760 [REDACTED]	NISM
38	1G6DP57V680 [REDACTED]	NISM
53	1GYFK43569R [REDACTED]	NISM
67	1G6DK67V490 [REDACTED]	NISM
77	KL1TD52695B [REDACTED]	LIT
91	2G1FK1EJ3A9 [REDACTED]	NISM
94	2G1FB1EV4A9 [REDACTED]	NISM
113	1G1AM58B367 [REDACTED]	NISM
114	1G1AK55F667 [REDACTED]	NISM
125	1G1AK55F767 [REDACTED]	PAR
151	1G1AL55FX77 [REDACTED]	NISM
167	1G1AL58F787 [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
172	1G1AT58H497	NISM
173	1G1AT58H797	NISM
183	1G1AG1FX3A7	NISM
195	1GCDT19E898	NISM
196	1G1YY32G935	NISM
208	2CNDL13F576	PAR
217	1GCFG15X481	NISM
225	3GNCA33D28S	NISM
231	3GNBABDB4AS	NISM
253	2G1WB55K379	NISM
261	2G1WB58K789	NISM
267	2G1WT57K491	NISM
268	2G1WC57M091	NISM
285	1G1ZH57B384	NISM
286	1G1ZJ57B28F	LIT
293	1G1ZH57B39F	NISM
320	1GCEC19X17Z	NISM
323	3GCEC13J48G	NISM
357	1GNFK13J57J	NISM
365	1GNFK13559R	NISM
409	1GNEV23D19S	NISM
410	1GNLRHED5AS	NISM
451	1GTEK19047Z	NISM
506	1G2ZG57B994	NISM
516	1G2NW52EX2M	NISM
539	5Y2SP67019Z	NISM
540	5Y2SM67079Z	PAR
585	5GZCZ53477S	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing

responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,

A handwritten signature in black ink, appearing to read "M. Carmen Benavides". The signature is fluid and cursive, with a prominent initial "M" and a stylized "B" at the end.

M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 41 Disks
Attachment A

Attachment A


Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



Selected Death Incidents from the
3rd Quarter 2004
For Reporting Category: Light Vehicles

(c) Vallen-Systeme GmbH, www.vallen.de/freeware



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.

Vallen JPegger V4.43

File Edit View Image Tools Help

Step 5: Select Page Icon

Step 5: Previous Page Icon (Ctrl +PgUp)

Step 5: Next Page Icon (Ctrl + PgDn)

Step 8: Scale Image Icons (F6, F7, & F8)

Step 4: Image List

1997 CHEVROLET VENTURE
335 62588861-466779

Request for Information:

1. Provide a copy of the claim or notice that notified General Motors of the incident, including any amendments and supplements thereto, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
Response: See Attached Documents
2. Provide a copy of all documents received from the claimant(s) or the claimant's representative that identify and/or support or purport to support any allegation of a defect in the vehicle, regardless of whether the General Motors disputes the assertion therein.
Response: See Attached Documents
3. Provide a copy of all investigative documents prepared by any local, state or Federal governmental agency or personnel related to the incident, including but not limited to police accident report(s).
Response: See Attached Documents
4. Provide a copy of all diagrams and drawings that relate to the incident, including post-incident reconstruction.
Response: See #3
5. Provide a copy of all documents, photographs or videos that relate to the incident, or the vehicles involved in the incident, excluding materials related to the progression, cure, or rehabilitation of any injury.
Response: See Attached Photographs and Attached Documents

Filename	Size	Modified	Associated
335 62588861-4667...	62 KB	4/23/2004 2:42 PM	D:\Images
335 62588861-4667...	597 KB	4/23/2004 5:23 PM	D:\Images
335 62588861-4667...	420 KB	4/23/2004 5:23 PM	D:\Images
335 62588861-4667...	1.0 MB	4/23/2004 5:25 PM	D:\Images
335 62588861-4667...	8.5 MB	4/23/2004 6:04 PM	D:\Images
335 62588861-4667...	714 KB	4/23/2004 6:03 PM	D:\Images
335 62588861-4667...	417 KB	4/23/2004 7:13 PM	D:\Images
335 62588861-4667...	9.1 MB	4/23/2004 6:09 PM	D:\Images
335 62588861-4667...	9.8 MB	4/23/2004 6:14 PM	D:\Images
335 62588861-4667...	690 KB	4/23/2004 6:16 PM	D:\Images
335 62588861-4667...	420 KB	4/23/2004 6:17 PM	D:\Images
335 62588861-4667...	1.0 MB	4/23/2004 6:21 PM	D:\Images
335 62588861-4667...	11.6 MB	4/23/2004 6:25 PM	D:\Images
335 62588861-4667...	695 KB	4/23/2004 6:31 PM	D:\Images
335 62588861-4667...	414 KB	4/23/2004 6:33 PM	D:\Images
335 62588861-4667...	1.0 MB	4/23/2004 6:35 PM	D:\Images
335 62588861-4667...	10.1 MB	4/23/2004 6:39 PM	D:\Images
335 62588861-4667...	8.6 MB	4/23/2004 6:43 PM	D:\Images
335 62588861-4667...	8.4 MB	4/23/2004 7:10 PM	D:\Images
335 62588861-4667...	8.4 MB	4/23/2004 7:13 PM	D:\Images
335 62588861-4667...	702 KB	4/23/2004 7:16 PM	D:\Images
335 62588861-4667...	495 KB	4/23/2004 7:17 PM	D:\Images
335 62588861-4667...	1.1 MB	4/23/2004 7:18 PM	D:\Images
335 62588861-4667...	4.9 MB	4/23/2004 7:23 PM	D:\Images
335 62588861-4667...	528 KB	4/23/2004 7:25 PM	D:\Images
335 62588861-4667...	2.7 MB	4/23/2004 7:26 PM	D:\Images
335 62588861-4667...	739 KB	4/23/2004 7:27 PM	D:\Images
335 62588861-4667...	421 KB	4/23/2004 7:28 PM	D:\Images
335 62588861-4667...	1.3 MB	4/23/2004 7:29 PM	D:\Images
335 62588861-4667...	746 KB	4/23/2004 7:38 PM	D:\Images
335 62588861-4667...	441 KB	4/23/2004 7:39 PM	D:\Images
335 62588861-4667...	1.2 MB	4/23/2004 7:40 PM	D:\Images

Image Explorer MP3 Music Explorer

D:\Images\335 62588861-466779_00_Request and Responses.tif 1/48 Scale: 18.1% 2553 x 3296 ptx, 62 KB

- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

The screenshot shows a 'CIVIL CASE COVER SHEET' form for the Superior Court of California, County of San Diego. The case name is 'CARDONA V. CHEVROLET'. The form includes sections for case designation, case number, and a list of case types. Annotations with arrows point to specific parts of the form:

- Step 7: Next File (Image)**: Points to the 'Next Image' button in the right-hand menu.
- Step 7: Next Page**: Points to the 'Next page' button in the right-hand menu.
- Step 8: Scale Image**: Points to the 'Scale' section in the right-hand menu, which includes options for 'fit', '50%', '100%', and '200%'.
- Step 7: Image Properties**: Points to the 'Image Properties' button at the bottom of the right-hand menu.

The form itself contains the following information:

ATTESTATION ON PARTIES WITHOUT ATTORNEY NAME, ADDRESS, AND PHONE NUMBER
 ERIC D. PARIS, ESQ., S/B# 147936
 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
 291 S. THOMAS STREET
 SUITE 403
 POMONA, CALIFORNIA 91765
 TELEPHONE NO: 909-469-5127 FAX NO: 909-469-5126
 ATTORNEY NAME: ERIC D. PARIS
 COUNTY AND COURT: SAN DIEGO COUNTY, SUPERIOR COURT FOR THE STATE OF CALIFORNIA
 JUDICIAL DISTRICT: 1
 CASE NAME: CARDONA V. CHEVROLET
 CIVIL CASE COVER SHEET
 Limited ☐ Unlimited ☒
 Complex Case Designation
☐ Counter ☐ Joinder
 Filed with first appearance by defendant (Cal. Rules of Court, rule 181)
 Please complete all five (5) items below
 1. Check one box below for the case type that best describes this case.
 Auto Tort ☒ Auto (22)
 Other PIP/NOV (Personal Injury/Property Damage/Wrongful Death) Tort
☐ Asbestos (24)
☐ Product liability (24)
☐ Medical malpractice (45)
☐ Other PIP/NOV (23)
 Non-PIP/NOV (Other) Tort
☐ Business tort/unfair business practice (27)
☐ Civil rights (e.g., discrimination, false arrest) (24)
☐ Defamation (e.g., slander, libel) (13)
☐ Fraud (18)
☐ Intellectual property (19)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PIP/NOV tort (30)
 Employment
☐ Wrongful termination (30)
☐ Other employment (15)
☐ Breach of contract/warranty (26)
☐ Collections (e.g., money owed, open credit accounts) (20)
☐ Insurance coverage (18)
☐ Other contract (37)
☐ Real Property
☐ Eminent domain/expropriation (14)
☐ Wrongful eviction (33)
☐ Other real property (e.g., quiet title) (20)
 Unlawful Detainer
☐ Commercial (21)
☐ Residential (22)
☐ Drugs (28)
 Judicial Review
☐ Appeal (34)
☐ Petition for writ of habeas corpus (11)
☐ Writ of mandamus (22)
☐ Other judicial review (34)
 Prejudicially Complex Civil Litigation (Cal. Rules of Court, rules 188 - 192)
☐ Arbitral/Trade regulation (29)
☐ Construction defect (10)
☐ Claims involving marine law (40)
 2. This case ☒ is ☐ is not complex under rule 180C of the California Rules requiring exceptional judicial management.
 a. ☒ Large number of separately represented parties d. ☒ Large number of parties
 b. ☒ Extensive motion practice raising difficult or novel issues that will be time-consuming to resolve e. ☐ Coordination and management of multiple parties in other counties
 c. ☐ Substantial amount of documentary evidence f. ☐ Substantial cost
 3. Type of remedies sought (check all that apply).
 a. ☒ Monetary b. ☐ Nonmonetary, declaratory or injunctive relief c. ☐ Other
 4. Number of causes of action (specify): FIVE
 5. This case ☒ is ☐ is not a class action suit.
 Date: JULY 3, 2003
 ERIC D. PARIS, ESQ., S/B# 147936
 (TYPE OR PRINT NAME)
 NOTICE
 Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (see under the Probate, Family, or Welfare and Institutions Code) (Cal. Rules of Court, rule 181).
 File this cover sheet in addition to any cover sheet required by local court rule.
 If this case is complex under rule 180C of the California Rules of Court, you must file this cover sheet with the first paper filed in the action or proceeding.
 Unless this is a complex case, this cover sheet shall be used for statistical purposes only.
 Form Number: 100-1000-001
 Judicial District: 1
 Adopted by the Judicial Branch of the Superior Court of California
 10/20/03 (Rev. January 1, 2003)
 CIVIL CASE COVER SHEET

DI10-062
114 298092244 – 683052
2006 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Documents. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Site	GW SubType		Bus. Unit	BRC
Last Name Tierno	First Name Claudine	Approval	Not Initiated	Area	PAR
Daytime # (607) 763-2257	Evening #	UCC	Electrical - Power Cruise Control	Sub-Area	Initiate PAR- Injury
Address 530 Columbia Dr Ste 101	City Johnson City	Involved Dir	Stafford Chevrolet Inc.	Safety	Yes
State NY ZipCd 13790-3300	Con Acct PROGRESSIVE	Source	Phone	Updated	1/11/2010 02:21:30 PM
Serial #/VIN 1G1AK55F667	Model Year 2006	Priority	Medium License #	Owner	MONTOYEL
Make Chevrolet	Warr. Start 07/21/2005	Status	Open	Opened	1/8/2010 01:27:02 PM
Model Cobalt	Mileage 69843	Sub-Status	Dissatisfied	Closed	
Abstract (E) 06 Cobalt - Cruise Control failure					
Customer Description This is a BRC PAR Case. Do not assume case. Forward any inquiries to Elizabeth @ ext. 31460.					

Pre-PAR

PAR Notifier	12/9/2009 09:27:00 AM	Injuries	Y	Other Veh	1	People In Veh	1	Road Surface	Asphalt	Road Cond	Icy	Fire Report	n/a	Police Report	09-11174
Insurance Agent	12/9/2009 09:27:00 AM	Driver First Name	Unknown	DOB	none	Disabilities		Insurance Agency	Progressive Insurance						
Incident Loc	Asbury and West Dryden Rd in Dryden, NY	Incident Desc	Tried tapping brakes to dis-engage cruise control and veh sped up, slipped on slush and went left of center line and collided with another vehicle, head on.												
Component	Cruise control	Damage Desc	Vehicle is totalled												
Vehicle Loc	Stafford Chevrolet	Add'l Info	Insurance Agent is the contact on SR as agent is seeking to possible file for subrogation.												
Emergency Svc Names	Tompkins County Sheriff	Main Loc	Unknown												

PAR Detail

Collision	Y	Non Collision	Property Damage	Y	Thermal Evt	N	Spec Equip	None		
Vehicle Speed	35	Weather Condition	Slushy	Prop Owner		Property Type	2002 Mitsubishi			
Last Service Date		Loc Last Service		Property Location	Brecht's Towing	Prop Est Repair Cost	\$0.00			
Veh Est Repair Cost		Spec Equip Installer	n/a	Prop Damage Description	We believe the veh is at a total loss.					
Primary Veh Use	Personal	Inspection Other Type		Inspected By	Inspection Not Performed	Inspection Date/Time				
Veh Damage Description	Total loss. Value was \$8812.80			Explain Other	Cruise Control					

Service Request Detail

PAR Injuries

Injury Description	Location	Occupant of Owner's Vehicle	Driver	Seating Position	Restraint Type	Treated By	Treatment Location
Broken bones, and fractures	unknown	unknown	unknown	unknown	Unknown	Emergency center in Cayuga, NY and then transferred to upstate Medical Hospital in Syracuse, NY	unknown

Activities

Created By	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2010 03:24:58 PM	MARTIRAM	ESISBIQU	Escalation	ESIS - Insurance Involvement	In Progress		ESIS - Insurance Involvement

Contact Last Name: Tierno Contact First Name: Claudine Account: BAC Code:

Comments: Insurance Involvement- Progressive Insurance, Claim # Claim Rep Claudine Tierno, Phone # (607) 763-2257, claim made and pending.

Property Damage/Owner Info - 2002 Mitsubishi, Brechts Towing, We believe the veh is at a total lost

Injuries - Broken bones, and fractures

Ramiro Martinez/PAR/ATX

Confidential Comments:

Created By	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 02:21:30 PM	MONTOYEL	MONTOYEL	Ownership Changed	Ownership Escalated to BRC	Done	1/11/2010 02:21:30 PM	Ownership Escalated to BRC

Contact Last Name: Tierno Contact First Name: Claudine Account: BAC Code:

Comments:

Confidential Comments:

Service Request Detail

Activities

Created By: MONTYOEL Assigned To: MONTYOEL Activity Type: Scheduled Follow-up Activity Sub-Type: Scheduled Alarm Status: Done Completed: 1/11/2010 02:15:30 PM Description: ESIS - Tierno

Contact Last Name: Tierno Contact First Name: Claudine Account: BAC Code: MONTYOEL

Comments: THIS IS NOT A SCHED CALL BACK, DO NOT ADV CUST OF THIS SCHED ACTIVITY, DIRECT ALL INQUIRIES TO OCRS ELIZABETH @ EXT 31460

Action Plan: review case for updates. Case pending ESIS escalation

Elizabeth Montoya/PAR/ATX

Confidential Comments:

Created By: MONTYOEL Assigned To: MARTIRAM Activity Type: Notify CRM Activity Sub-Type: Done Status: Done Completed: 1/12/2010 03:13:58 PM Description: Escalating to ESIS - third party damage, medical attention, and subrogation

Contact Last Name: Tierno Contact First Name: Claudine Account: BAC Code: MONTYOEL

Comments: Veh involved in head on collision, allegedly due to cruise control malfunction. Case to be escalated to ESIS due to third party damage, medical attention, and subrogation.

Elizabeth Montoya/PAR/ATX

Confidential Comments:

Created By: MARTIRAM Assigned To: MONTYOEL Activity Type: Ownership Changed Activity Sub-Type: Done Status: Done Completed: 1/11/2010 10:01:49 AM Description: Service Request Ownership has changed FROM: CANETEAL TO: MONTYOEL

Contact Last Name: MONTYOEL Contact First Name: MONTYOEL Account: BAC Code: MONTYOEL

Confidential Comments:

Service Request Detail

Activities

Created By	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:01:38 AM	MARTIRAM	MONTROYEL	BRC PAR	Initial Contact-Phone	Done	1/11/2010 01:00:15 PM	Agent Contact @ 607-763-2257

Contact Last Name : Contact First Name : Account : BAC Code :

Tiempo	Claudine	PROGRESSIVE INSURANCE AGENT
---------------	-----------------	------------------------------------

Comments: 1944-1945 - 1946-1947 - 1948-1949 - 1950-1951 - 1952-1953 - 1954-1955 - 1956-1957 - 1958-1959 - 1960-1961 - 1962-1963 - 1964-1965 - 1966-1967 - 1968-1969 - 1970-1971 - 1972-1973 - 1974-1975 - 1976-1977 - 1978-1979 - 1980-1981 - 1982-1983 - 1984-1985 - 1986-1987 - 1988-1989 - 1990-1991 - 1992-1993 - 1994-1995 - 1996-1997 - 1998-1999 - 2000-2001 - 2002-2003 - 2004-2005 - 2006-2007 - 2008-2009 - 2010-2011 - 2012-2013 - 2014-2015 - 2016-2017 - 2018-2019 - 2020-2021 - 2022-2023 - 2024-2025 - 2026-2027 - 2028-2029 - 2030-2031 - 2032-2033 - 2034-2035 - 2036-2037 - 2038-2039 - 2040-2041 - 2042-2043 - 2044-2045 - 2046-2047 - 2048-2049 - 2050-2051 - 2052-2053 - 2054-2055 - 2056-2057 - 2058-2059 - 2060-2061 - 2062-2063 - 2064-2065 - 2066-2067 - 2068-2069 - 2070-2071 - 2072-2073 - 2074-2075 - 2076-2077 - 2078-2079 - 2080-2081 - 2082-2083 - 2084-2085 - 2086-2087 - 2088-2089 - 2090-2091 - 2092-2093 - 2094-2095 - 2096-2097 - 2098-2099 - 2100-2101 - 2102-2103 - 2104-2105 - 2106-2107 - 2108-2109 - 2110-2111 - 2112-2113 - 2114-2115 - 2116-2117 - 2118-2119 - 2120-2121 - 2122-2123 - 2124-2125 - 2126-2127 - 2128-2129 - 2130-2131 - 2132-2133 - 2134-2135 - 2136-2137 - 2138-2139 - 2140-2141 - 2142-2143 - 2144-2145 - 2146-2147 - 2148-2149 - 2150-2151 - 2152-2153 - 2154-2155 - 2156-2157 - 2158-2159 - 2160-2161 - 2162-2163 - 2164-2165 - 2166-2167 - 2168-2169 - 2170-2171 - 2172-2173 - 2174-2175 - 2176-2177 - 2178-2179 - 2180-2181 - 2182-2183 - 2184-2185 - 2186-2187 - 2188-2189 - 2190-2191 - 2192-2193 - 2194-2195 - 2196-2197 - 2198-2199 - 2200-2201 - 2202-2203 - 2204-2205 - 2206-2207 - 2208-2209 - 2210-2211 - 2212-2213 - 2214-2215 - 2216-2217 - 2218-2219 - 2220-2221 - 2222-2223 - 2224-2225 - 2226-2227 - 2228-2229 - 2230-2231 - 2232-2233 - 2234-2235 - 2236-2237 - 2238-2239 - 2240-2241 - 2242-2243 - 2244-2245 - 2246-2247 - 2248-2249 - 2250-2251 - 2252-2253 - 2254-2255 - 2256-2257 - 2258-2259 - 2260-2261 - 2262-2263 - 2264-2265 - 2266-2267 - 2268-2269 - 2270-2271 - 2272-2273 - 2274-2275 - 2276-2277 - 2278-2279 - 2280-2281 - 2282-2283 - 2284-2285 - 2286-2287 - 2288-2289 - 2290-2291 - 2292-2293 - 2294-2295 - 2296-2297 - 2298-2299 - 2300-2301 - 2302-2303 - 2304-2305 - 2306-2307 - 2308-2309 - 2310-2311 - 2312-2313 - 2314-2315 - 2316-2317 - 2318-2319 - 2320-2321 - 2322-2323 - 2324-2325 - 2326-2327 - 2328-2329 - 2330-2331 - 2332-2333 - 2334-2335 - 2336-2337 - 2338-2339 - 2340-2341 - 2342-2343 - 2344-2345 - 2346-2347 - 2348-2349 - 2350-2351 - 2352-2353 - 2354-2355 - 2356-2357 - 2358-2359 - 2360-2361 - 2362-2363 - 2364-2365 - 2366-2367 - 2368-2369 - 2370-2371 - 2372-2373 - 2374-2375 - 2376-2377 - 2378-2379 - 2380-2381 - 2382-2383 - 2384-2385 - 2386-2387 - 2388-2389 - 2390-2391 - 2392-2393 - 2394-2395 - 2396-2397 - 2398-2399 - 2400-2401 - 2402-2403 - 2404-2405 - 2406-2407 - 2408-2409 - 2410-2411 - 2412-2413 - 2414-2415 - 2416-2417 - 2418-2419 - 2420-2421 - 2422-2423 - 2424-2425 - 2426-2427 - 2428-2429 - 2430-2431 - 2432-2433 - 2434-2435 - 2436-2437 - 2438-2439 - 2440-2441 - 2442-2443 - 2444-2445 - 2446-2447 - 2448-2449 - 2450-2451 - 2452-2453 - 2454-2455 - 2456-2457 - 2458-2459 - 2460-2461 - 2462-2463 - 2464-2465 - 2466-2467 - 2468-2469 - 2470-2471 - 2472-2473 - 2474-2475 - 2476-2477 - 2478-2479 - 2480-2481 - 2482-2483 - 2484-2485 - 2486-2487 - 2488-2489 - 2490-2491 - 2492-2493 - 2494-2495 - 2496-2497 - 2498-2499 - 2500-2501 - 2502-2503 - 2504-2505 - 2506-2507 - 2508-2509 - 2510-2511 - 2512-2513 - 2514-2515 - 2516-2517 - 2518-2519 - 2520-2521 - 2522-2523 - 2524-2525 - 2526-2527 - 2528-2529 - 2530-2531 - 2532-2533 - 2534-2535 - 2536-2537 - 2538-2539 - 2540-2541 - 2542-2543 - 2544-2545 - 2546-2547 - 2548-2549 - 2550-2551 - 2552-2553 - 2554-2555 - 2556-2557 - 2558-2559 - 2560-2561 - 2562-2563 - 2564-2565 - 2566-2567 - 2568-2569 - 2570-2571 - 2572-2573 - 2574-2575 - 2576-2577 - 2578-2579 - 2580-2581 - 2582-2583 - 2584-2585 - 2586-2587 - 2588-2589 - 2590-2591 - 2592-2593 - 2594-2595 - 2596-2597 - 2598-2599 - 2600-2601 - 2602-2603 - 2604-2605 - 2606-2607 - 2608-2609 - 2610-2611 - 2612-2613 - 2614-2615 - 2616-2617 - 2618-2619 - 2620-2621 - 2622-2623 - 2624-2625 - 2626-2627 - 2628-2629 - 2630-2631 - 2632-2633 - 2634-2635 - 2636-2637 - 2638-2639 - 2640-2641 - 2642-2643 - 2644-2645 - 2646-2647 - 2648-2649 - 2650-2651 - 2652-2653 - 2654-2655 - 2656-2657 - 2658-2659 - 2660-2661 - 2662-2663 - 2664-2665 - 2666-2667 - 2668-2669 - 2670-2671 - 2672-2673 - 2674-2675 - 2676-2677 - 2678-2679 - 2680-2681 - 2682-2683 - 2684-2685 - 2686-2687 -

Crs adv calling in response to notification received on your client's 2003 Cobalt. Are you contacting us to file for subrogation?

Agent sts/sks potentially yes. Veh is a total loss, probably be a looking into an inspection. There were damages to another party as well. Driver sts that while on cruise control, she tried tapping brakes to dis-engage cruise control and veh sped up, then slipped on icy slush causing it to swerve to the left of center line and collided with another vehicle, head on. Owner of veh is Mrs. Sarah Murray, who was not in the veh at the time of the incident.

Crs adv I will be escalating your case to our ESIS department for third party property damage, injuries and subrogation. Someone will be contacting you in 7-10 business days. If you do not received word from anyone by the 25 pls contact me at 868-760-5600 ext 31460 and I will provide you whatever information has been released to me.

Elizabeth Montoya/PA/ATX

Confidential Comments

Created **11/15/2011** Created By **228** Assigned To **228** Activity Type **110** Activity Sub-Type **1100** Status **1100** Completed **11/15/2011** Description **1100**

1/11/2010 10:01:35 AM	MARTIRAM	MONTOYEL	BRC PAR	Initial Contact- Dealer	Done	1/11/2010 02:11:26 PM	Dtr Contact
-----------------------	----------	----------	---------	-------------------------	------	-----------------------	-------------

Contact Last Name	JOHNSON, JIM	First Name	JIM	Account No.	10000000000000000000	BAC Code	000000
-------------------	--------------	------------	-----	-------------	----------------------	----------	--------

Downloaded from <http://www.jco.org/> on July 10, 2015. For personal use only; all rights reserved.

[illegible]

Stafford Chevrolet
1777 Old Hwy 100

(607) 844-8113
Bob Green *owner*

Bob Green svc mgr

Crs adv calling to see if you records show any prior repairs to the cruise control? At this time case will be forwarded to ESIS for further assistance.

Dirsts I don't see any record for any prev cruise control repairs/issues. Cust complaint of Cruise Control inop on 06/30/08 at 42,309 miles, couldnt duplicate, no repairs made. RO # 149040. Veh is at the bodyshop. They haven't done anything w/ it yet.

Elizabeth Montoya/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:01:32 AM	MARTIRAM	MONTOYEL	BRC PAR	Initial Contact-AVM	Done	1/11/2010 02:14:02 PM	FFOM Contact

Contact Last Name	Contact First Name	Account	BAC Code

Comments: CRM left a voice mail for FFOM: Daneelle Redwood

At node and mailbox #: 814244 6169

Involved dealership: Stafford Chevrolet

Location of dealership: Dryden, NY

VIN: 1G1AK55F667

SR: 71-792507810

Crs adv: This is regarding veh involved in head on collision, allegedly due to cruise control malfunction. Case will be escalated to ESIS due to third party damage, medical attention, and subrogation. Any questions I can be reached at 866-790-5600 ext 31460. This is an FYI and requires no fu.

Elizabeth Montoya/PA/ATX

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:01:26 AM	MARTIRAM	MONTOYEL	BRC PAR	Acknowledgement	Done	1/11/2010 12:55:50 PM	Agent Contact @ 607-763-2257

Contact Last Name	Contact First Name	Account	BAC Code

Tier	Claudine	PROGRESSIVE INSURANCE AGENT

Comments: Acknowledgement made with initial. Convo documented in initial activity.

Acknowledgement made with initial. Convo documented in initial activity.

Elizabeth Montoya/PA/ATX

Confidential Comments:

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:01:16 AM	MARTIRAM	MONTOYEL	Notify CRM		Done	1/11/2010 11:31:16 AM	file assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments:

Confidential Comments:

Service Request Detail

Activities

Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:01:08 AM	MARTIRAM	MONTOYEL	Research	Done	1/11/2010 11:45:16 AM	Research VIN

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments: [REDACTED]

Recalls: No open recalls

Related repairs: No related repairs

Previous SRs: No previous SRs

Elizabeth Montoya/PA/ATX

Confidential Comments: [REDACTED]

Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:00:38 AM	MARTIRAM	MONTOYEL	BRC PAR	Case Assigned	Done	1/11/2010 11:31:12 AM

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments: [REDACTED]

Confidential Comments: [REDACTED]

Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:00:30 AM	MARTIRAM	CANETEAL	SR Opened	Done	1/11/2010 10:00:30 AM	SR In Status of Closed has been Re-Opened by MARTIRAM

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments: [REDACTED]

Confidential Comments: [REDACTED]

Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/11/2010 10:00:29 AM	MARTIRAM	CANETEAL	SR Closed - Dissatisfied	Done	1/11/2010 10:00:29 AM	Service Request has been Closed Dissatisfied.

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments: [REDACTED]

Confidential Comments: [REDACTED]

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/8/2010 01:46:33 PM	CANETEAL	MARTIRAM	Escalation	Initiate PAR	Done	1/11/2010 10:00:24 AM	Assigning activity to PAR QUEUE
Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]							
Comments: [REDACTED]							
CRS advised that a person from the PAR Department will contact the customer within 2 business days							
Confidential Comments: [REDACTED]							

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/8/2010 01:40:10 PM	CANETEAL	CANETEAL	Inbound Call Customer	Complex Request	Done	1/8/2010 01:51:12 PM	Product allegation collision
Contact Last Name: [REDACTED] Contact First Name: [REDACTED] Account: [REDACTED] BAC Code: [REDACTED]							

Comments: [REDACTED]

Progressive Insurance Agent calling in behalf of customer
Insurance agent is Claudine Tierno / 6077632257
call Claudine Tierno regarding this concern.

agent sts:

- customer had a collision
- name of the driver that was involved in the accident is [REDACTED]
- cruise control engaged and dis engaged abnormally
- that caused the customer to an accident
- customer had a broken bones and now recovering in the hospital

agent sks:

- claim

Crs advsd:

- advised customer that their information will be forwarded to the Product Allegation Department within the SRC

Alvin Cafete/CAC/Tier1/MNL/LVL1-EMP
866-780-5700 ext 42905

Confidential Comments: [REDACTED]

UCC Information

UCC Code	Symptom	Description
N47	No Symptom Indicated	Electrical - Power Cruise Control Module / System

GM Vehicle Inquiry System Summary

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK55F667
-------	-------------

VEHICLE INFORMATION

Merchandising Model :	IAK69 -2006 COBALT 4-DOOR LS SEDAN	Warranty Start Date :	07/21/2005				
BARS Order Type :	50 - FLEET						
Delivering Dealer :	WALDEN FLEET GROUP, INC. 6 SYLVAN WAY PARSIPPANY, NJ 07054-3826	Selling Source :	13 - CHEVROLET				
		Site Code :	04681				
		Business Associate Code :	111571				
Service Contract :	No	Branded Title :	No	Warranty Block :	No	PDI Status :	Paid

REQUIRED FIELD ACTIONS

Vehicle Has No Current Record Of Outstanding Campaigns
--

SERVICE INFORMATIONAL ITEMS

Vehicle Has No Current Record Of Outstanding Service Information
--

ON STAR AND XM SATELLITE RADIO INFORMATION

Vehicle Has No Associated On Star or XM Radio Information.
--

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	07/21/2005	10 miles	07/21/2008	36010 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	07/21/2005	10 miles	07/21/2011	100010 miles
39/39000 GM CERTIFIED USED LIMITED WARRANTY	07/21/2005	10 miles	10/21/2008	39010 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	07/21/2005	10 miles	07/21/2013	80010 miles
96/100000 CALIFORNIA SELECT COMPONENT	07/21/2005	10 miles	07/21/2013	100010 miles
36/50000 CALIFORNIA EMISSIONS	07/21/2005	10 miles	07/21/2008	50010 miles
60/60000 POWERTRAIN - U.S. LIMITED WARRANTY	07/21/2005	10 miles	07/21/2010	60010 miles

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
07/11/2009	160863	#	E3550 - BUSHINGS AND/OR SHAFT, FRONT CONTROL ARM - LOWER - RIGHT -	55140 miles
01/21/2008	S82262	#	Z2080 - ROADSIDE SERVICE (TOWING)	35000 miles
01/23/2007	K61559	#	Z2080 - ROADSIDE SERVICE (TOWING)	9000 miles
09/05/2005	731329	#	Z2083 - ROADSIDE SERVICE (BATTERY/JUMP START)	2500 miles
07/20/2005	A15220	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles

CHECK HISTORY INFORMATION

Vehicle Has No Associated Check History Information.

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Claim History

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN :	1G1AK55F667
-------	-------------

CLAIM HISTORY

Repair Order Date :		07/11/2009		Repair Order Number :		160863		Odometer Reading :		55140 miles	
Serviced By :		STAFFORD CHEVROLET INC. PO BOX 68 DRYDEN, NY 13053-0068 (607) 844-8113				Selling Source :		13 - CHEVROLET			
						Site Code :		15058			
						Business Associate Code :		166292			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part	Auth Code	Person Code	Line Total	Comments	
08/07/2009	29	01	#	E3550 - BUSHINGS AND/OR SHAFT, FRONT CONTROL ARM - LOWER - RIGHT -		25984679 - BUSHING	A	N/A	\$ 89.76	Y	

Repair Order Date :		01/21/2008		Repair Order Number :		S82262		Odometer Reading :		35000 miles	
Serviced By :		GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117				Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
02/01/2008	870	01	#	Z2080 - ROADSIDE SERVICE (TOWING)		N/A		C	N/A	\$ 58.94	N

Repair Order Date :		01/23/2007		Repair Order Number :		K61559		Odometer Reading :		9000 miles	
Serviced By :		GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117				Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments

04/10/2007	785	01	#	Z2080 - ROADSIDE SERVICE (TOWING)	N/A	C	N/A	\$ 58.94	N
------------	-----	----	---	-----------------------------------	-----	---	-----	----------	---

Repair Order Date :		09/05/2005		Repair Order Number :		731329		Odometer Reading :		2500 miles	
Serviced By :		GM ROADSIDE ASSISTANCE/CCAS ONE CABOT RD MEDFORD, MA 02155-5117				Selling Source :		13 - CHEVROLET			
						Site Code :		34415			
						Business Associate Code :		207453			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
09/16/2005	622	01	#	Z2083 - ROADSIDE SERVICE (BATTERY/JUMP START)		N/A		C	N/A	\$ 45.88	N

Repair Order Date :		07/20/2005		Repair Order Number :		A15220		Odometer Reading :		0 miles	
Serviced By :		BUDGET RENT A CAR 6251 CHANCELLOR DRIVE ORLANDO, FL 32809-5501				Selling Source :		13 - CHEVROLET			
						Site Code :		99118			
						Business Associate Code :		126458			
Cycle Date	Cycle Nbr	Case	Type	Labor Operation		Part		Auth Code	Person Code	Line Total	Comments
07/26/2005	607	01	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME		N/A		N/A	N/A	\$ 73.03	N

CHECK HISTORY

Vehicle Has No Associated Check History.
--

© 2009 General Motors. All Rights Reserved.

GM Vehicle Inquiry System Vehicle Build

Home - Summary - Claim History - Vehicle Build - Vehicle Component - Delivery Information - Dealer Information -
Service Contract - Warranty Block - Branded Title

Help

VIN	1G1AK55F667
-----	-------------

VEHICLE BUILD

Merchandising Model :	1AK69 -2006 COBALT 4-DOOR LS SEDAN		
Gross Vehicle Weight Rating :	1715 kg (3782 lb)	Order Number :	JDXQPR
Build Date :	07/20/2005	Build Plant :	167A

GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

OPTION CODES

AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS	AR9 - DELUXE FRONT BUCKET SEAT
AU0 - REMOTE KEYLESS ENTRY	AU3 - POWER DOOR LOCKS W/REMOTE KEYLESS ENTRY
BQ2 - AVIS RENT A CAR	B0H - GM PRODUCTION WEEK #26
B34 - FLOOR MATS	B35 - REAR FLOOR MATS
B84 - BODY COLOR BODYSIDE MOLDINGS	C67 - ELECT. FRONT AIR CONDITIONER
DC8 - MIRROR, O/S MANUAL FLDG, BLK	DT4 - ASHTRAY AND LIGHTER
FE1 - SUSPENSION SYSTEM-SOFT RIDE	FLT - FLEET PROCESSING OPTION
FY1 - TRANS/AXLE 3.63 RATIO	IPB - INTERIOR TRIM DESIGN
J41 - POWER DISC FRONT BRAKES	K34 - CRUISE CONTROL
K64 - 115 AMP GENERATOR	LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO
L61 - 2.2L DOHC 4 CYL ENGINE	MN5 - 4 SPEED AUTO TRANSMISSION
MX0 - 4-SPD. AUTO. TRANS. W/OVERDRIVE	NE1 - MA/ME/NY/VT EMISSIONS
NU3 - EMISSIONS SYSTEM CALIFORNIA, SULEV	N46 - 4 SPOKE STEERING WHEEL
PG1 - 15" STEEL WHEEL	QTU - P195/60R15 TOURING BW TIRES
R6F - IDENTIFY B-CODE USERS	R6P - PREMIUM PAINT
T43 - REAR DECK-LID SPOILER	UN0 - AM/FM STEREO W/CD & RDS
UQ4 - BASE SPEAKER SYSTEM	VK3 - FRONT LICENSE PLATE MOUNT
VN9 - DAILY RENTAL REPURCHASE PROGRAM	V2G - FULL FUEL FILL CREDIT

<http://gmvis/gmvis/main/VehicleBuild?languageSelected=EN&VIN=1G1AK55F667>. 1/13/2010

V73 - STATEMENT OF VEHICLE CERT.- U.S. /CANADA	1LS - 1LS BASE PACKAGE
1SZ - OPTION PACKAGE DISCOUNT	15U - SANDSTONE METALLIC
52B - NEUTRAL	52I - GRAY
6AR - FRONT SPRING	7AR - FRONT SPRING
8AA - REAR SPRING	9AA - REAR SPRING

© 2009 General Motors. All Rights Reserved.

POLICE ACCIDENT REPORT
MV-104A (3/04)TCSO Records Division
COPY OF ORIGINAL

Local Codes
(b) (6)
(b) (6)

☐ AMENDED REPORT

Accident Date	Day of Week	Military Time	No. of Vehicles	No. Injured	No. Killed	Not Investigated at Scene	Left Scene	Police Photos
Month 12 Day 9 Year 2009	Wednesday	09:27	2	3	0	☐	☐	☒ Yes ☐ No
						Accident Reconstructed	☐	☐

VEHICLE 1	VEHICLE 2	BICYCLIST	PEDESTRIAN	OTHER PEDESTRIAN
-----------	-----------	-----------	------------	------------------

VEHICLE 1 - Driver License ID Number	State of Lic. NY	VEHICLE 2 - Driver License ID Number	State of Lic. NY
--------------------------------------	------------------	--------------------------------------	------------------

Driver Name - exactly as printed on license	Driver Name - exactly as printed on license
---	---

Address (Include Number and Street)	Apt. No.	Address (Include Number and Street)	Apt. No.
-------------------------------------	----------	-------------------------------------	----------

City or Town	State	Zip Code	City or Town	State	Zip Code
GRANTON	NY		FREEVILLE	NY	

Date of Birth	Sex	Unlicensed	No. of Occupants	Public Property Damaged	Date of Birth	Sex	Unlicensed	No. of Occupants	Public Property Damaged
Month 1 Day 1 Year 2009	M	☐	02	☐	Month 1 Day 1 Year 2009	F	☐	01	☐

Name - exactly as printed on registration	Sex	Date of Birth	Name - exactly as printed on registration	Sex	Date of Birth
---	-----	---------------	---	-----	---------------

Address (Include Number and Street)	Apt. No.	Address (Include Number and Street)	Apt. No.
-------------------------------------	----------	-------------------------------------	----------

City or Town	State	Zip Code	City or Town	State	Zip Code
GRANTON	NY		FREEVILLE	NY	

State of Reg. NY	Vehicle Year & Make 2002 MITS	Vehicle Type 4DSD	Ins. Code 219	State of Reg. NY	Vehicle Year & Make 2006 CHEV	Vehicle Type 4DSD	Ins. Code 607
------------------	-------------------------------	-------------------	---------------	------------------	-------------------------------	-------------------	---------------

Tickler/Arrest Number(s)	Tickler/Arrest Number(s)
	S112008BS8

Violation Section(s)	Violation Section(s)
	1120A

Check if involved vehicle is:	Check if involved vehicle is:	Circle the diagram below that describes the accident, or draw your own diagram in space #9. Number the vehicles.
☐ more than 95 inches wide;	☐ more than 65 inches wide;	Diagram 1: Front End
☐ more than 34 feet long;	☐ more than 34 feet long;	Diagram 2: Left Turn
☐ operated with an overweight permit;	☐ operated with an overweight permit;	Diagram 3: Right Angle
☐ operated with an overdimension permit.	☐ operated with an overdimension permit.	Diagram 4: Right Turn

VEHICLE 1 DAMAGE CODES	VEHICLE 2 DAMAGE CODES
Box 1 - Point of Impact	Box 1 - Point of Impact
Box 2 - Most Damage	Box 2 - Most Damage

Enter up to three more damage codes	Enter up to three more damage codes
-------------------------------------	-------------------------------------

Vehicle Bv. BRECHS	Vehicle Bv. BRECHS
Towed To: BRECHS	Towed To:

VEHICLE DAMAGE CODING:	Diagram of vehicle damage
------------------------	---------------------------

13 SEE DIAGRAM ON RIGHT.	14. UNDERCARRIAGE	17. DEMOLISHED
15. TRAILER	18. NO DAMAGE	
16. OVERTURNED	19. OTHER	

Cost of repairs to any one vehicle will be more than \$1000.
☐ Unknown/Unable to determine ☒ Yes ☐ No

Reference Marker	Coordinates (if available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☒ Town of DRYDEN
	Longitude/Easting:	Road on which accident occurred WEST DRYDEN RD (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) .10 N S of ASBURY RD (Milepost, Nearest Intersecting Route Number or Street Name)

Accident Description/Officer's notes
DRIVER OF VEHICLE ONE STATES HE AND HIS PASSENGER WERE TRAVELING EAST ON WEST DRYDEN ROAD WHEN V2 SPUN AROUND AND STRUCK THEM HEAD ON. HE ADVISES THAT HE HAS KNEE PAIN AND SO DOES HIS PASSENGER. I WENT AND SPOKE TO DRIVER OF VEHICLE TWO SHE STATES THAT THE CAR WAS ON CRUISE CONTROL AND SET AT 35 MPH AND WHEN SHE TRIED TO TURN IT OFF IT WOULD NOT SHUT OFF. SHE STATES SHE LOST CONTROL OF THE CAR DUE TO SNOW AND ICE AND SPUN AROUND STRIKING THE OTHER VEHICLE HEAD ON. DRIVER OF VEHICLE TWO APPEARED TO BE IN SEVERE PAIN IN HER LEG AND SHOULDER. I

8	9	10	11	12	13	14	15	16	17 BY	TO 18	Names of all involved	Date of Death Only
A	1	1	A	1	M	11	12	6	9995	5401		
B	1	3	A	1	M	11	12	6	552	5401		
C	2	1	A	1	F	12	12	6	551	5401		
D												
E												
F												

Officer's Rank and Signature	Badge/ID No.	NCIC No.	Precinct/Post Troop/Zone	Station/Beat Sector	Reviewing Officer	Date/Time Reviewed
DEPUTY <i>[Signature]</i>	1233	05400	TCSO	325S	LAMPAN, ROBERT	12/11/2009 15:38
Print Name	LEON ANDERSON					

New York State Department of Motor Vehicles POLICE ACCIDENT REPORT MV-104A (3/04)

Local Codes
(b) (6)
(b) (6)

☐ AMENDED REPORT

Accident Date	Day of Week	Military Time	No. of Vehicles	No. Injured	No. Killed	Not Investigated at Scene	Left Scene	Police Photos
Month 12 Day 9 Year 2009	Wednesday	09:27	2	3	0	☐	☐	☒ Yes ☐ No
						Accident Reconstructed	☐	

VEHICLE		☐ VEHICLE ☐ BICYCLIST ☐ PEDESTRIAN ☐ OTHER PEDESTRIAN	
---------	--	---	--

VEHICLE 1 - Driver	State of Lic.	VEHICLE 2 - Driver	State of Lic.
License ID Number		License ID Number	

Driver Name - exactly as printed on license	Driver Name - exactly as printed on license
---	---

Address (Include Number and Street)	Address (Include Number and Street)
-------------------------------------	-------------------------------------

City or Town	State	Zip Code	City or Town	State	Zip Code
--------------	-------	----------	--------------	-------	----------

Date of Birth	Sex	Unlicensed	No. of Occupants	Public Property Damaged	Date of Birth	Sex	Unlicensed	No. of Occupants	Public Property Damaged
Month Day Year		☐		☐	Month Day Year		☐		☐

Name - exactly as printed on registration	Sex	Date of Birth	Name - exactly as printed on registration	Sex	Date of Birth
Month Day Year		Month Day Year	Month Day Year		Month Day Year

Address (Include Number and Street)	Appt. No.	Address (Include Number and Street)	Appt. No.
-------------------------------------	-----------	-------------------------------------	-----------

City or Town	State	Zip Code	City or Town	State	Zip Code
--------------	-------	----------	--------------	-------	----------

Plate Number	State of Reg.	Vehicle Year & Make	Vehicle Type	Ins. Code	Plate Number	State of Reg.	Vehicle Year & Make	Vehicle Type	Ins. Code
--------------	---------------	---------------------	--------------	-----------	--------------	---------------	---------------------	--------------	-----------

Tick if Arrest Number(s)	Violation Section(s)	Tick if Arrest Number(s)	Violation Section(s)
--------------------------	----------------------	--------------------------	----------------------

Check if involved vehicle is:	Check if involved vehicle is:	Circle the diagram below that describes the accident, or draw your own diagram in space #9. Number the vehicles
☐ more than 95 inches wide;	☐ more than 95 inches wide;	
☐ more than 34 feet long;	☐ more than 34 feet long;	
☐ operated with an overweight permit;	☐ operated with an overweight permit;	
☐ operated with an overdimension permit;	☐ operated with an overdimension permit;	

VEHICLE 1 DAMAGE CODES	VEHICLE 2 DAMAGE CODES
------------------------	------------------------

Box 1 - Point of Impact	Box 2 - Most Damage
Enter up to three more damage codes	

Vehicle Box	Vehicle Box
Towed To	Towed To

VEHICLE DAMAGE CODING:	
------------------------	--

1. SEE DIAGRAM ON RIGHT.	
--------------------------	--

14. UNDERCARRIAGE	17. DEMOLISHED
15. TRAILER	18. NO DAMAGE
16. OVERTURNED	19. OTHER

1	2	3	4	5	6	7	8	9	10	11	12
---	---	---	---	---	---	---	---	---	----	----	----

Reference Marker	Coordinates (If available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☐ Town of
	Longitude/Easting	Road on which accident occurred (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) feet miles N S E W of (Milepost, Nearest intersecting Route Number or Street Name)

Accident Description/Officer's notes

ADVISED EMS UPON THERE ARRIVAL OF ALL INJURIES I HAD LEARNED ABOUT. DRIVER OF VEHICLE TWO WAS ISSUED A UTT FOR FAILURE TO KEEP RIGHT. ALL PERSONS WERE TAKEN TO CAYUGA MEDICAL CENTER AT ITHACA. DRIVER OF VEHICLE TWO WAS TRANSFERRED TO UPSTATE MEDICAL CENTER IN SYRACUSE BECAUSE OF MULTIPLE FRACTURES TO HER ARMS AND LEGS.
--

Cost of repairs to any one vehicle will be more than \$1000.
☐ Unknown/Unable to determine ☐ Yes ☐ No

Reference Marker	Coordinates (If available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☐ Town of
	Longitude/Easting	Road on which accident occurred (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) feet miles N S E W of (Milepost, Nearest intersecting Route Number or Street Name)

Accident Description/Officer's notes

ADVISED EMS UPON THERE ARRIVAL OF ALL INJURIES I HAD LEARNED ABOUT. DRIVER OF VEHICLE TWO WAS ISSUED A UTT FOR FAILURE TO KEEP RIGHT. ALL PERSONS WERE TAKEN TO CAYUGA MEDICAL CENTER AT ITHACA. DRIVER OF VEHICLE TWO WAS TRANSFERRED TO UPSTATE MEDICAL CENTER IN SYRACUSE BECAUSE OF MULTIPLE FRACTURES TO HER ARMS AND LEGS.
--

Cost of repairs to any one vehicle will be more than \$1000.
☐ Unknown/Unable to determine ☐ Yes ☐ No

Reference Marker	Coordinates (If available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☐ Town of
	Longitude/Easting	Road on which accident occurred (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) feet miles N S E W of (Milepost, Nearest intersecting Route Number or Street Name)

Accident Description/Officer's notes

ADVISED EMS UPON THERE ARRIVAL OF ALL INJURIES I HAD LEARNED ABOUT. DRIVER OF VEHICLE TWO WAS ISSUED A UTT FOR FAILURE TO KEEP RIGHT. ALL PERSONS WERE TAKEN TO CAYUGA MEDICAL CENTER AT ITHACA. DRIVER OF VEHICLE TWO WAS TRANSFERRED TO UPSTATE MEDICAL CENTER IN SYRACUSE BECAUSE OF MULTIPLE FRACTURES TO HER ARMS AND LEGS.
--

Cost of repairs to any one vehicle will be more than \$1000.
☐ Unknown/Unable to determine ☐ Yes ☐ No

Reference Marker	Coordinates (If available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☐ Town of
	Longitude/Easting	Road on which accident occurred (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) feet miles N S E W of (Milepost, Nearest intersecting Route Number or Street Name)

Accident Description/Officer's notes

ADVISED EMS UPON THERE ARRIVAL OF ALL INJURIES I HAD LEARNED ABOUT. DRIVER OF VEHICLE TWO WAS ISSUED A UTT FOR FAILURE TO KEEP RIGHT. ALL PERSONS WERE TAKEN TO CAYUGA MEDICAL CENTER AT ITHACA. DRIVER OF VEHICLE TWO WAS TRANSFERRED TO UPSTATE MEDICAL CENTER IN SYRACUSE BECAUSE OF MULTIPLE FRACTURES TO HER ARMS AND LEGS.
--

Cost of repairs to any one vehicle will be more than \$1000.
☐ Unknown/Unable to determine ☐ Yes ☐ No

Reference Marker	Coordinates (If available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☐ Town of
	Longitude/Easting	Road on which accident occurred (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) feet miles N S E W of (Milepost, Nearest intersecting Route Number or Street Name)

Accident Description/Officer's notes

ADVISED EMS UPON THERE ARRIVAL OF ALL INJURIES I HAD LEARNED ABOUT. DRIVER OF VEHICLE TWO WAS ISSUED A UTT FOR FAILURE TO KEEP RIGHT. ALL PERSONS WERE TAKEN TO CAYUGA MEDICAL CENTER AT ITHACA. DRIVER OF VEHICLE TWO WAS TRANSFERRED TO UPSTATE MEDICAL CENTER IN SYRACUSE BECAUSE OF MULTIPLE FRACTURES TO HER ARMS AND LEGS.
--

Cost of repairs to any one vehicle will be more than \$1000.
☐ Unknown/Unable to determine ☐ Yes ☐ No

Reference Marker	Coordinates (If available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☐ Town of
	Longitude/Easting	Road on which accident occurred (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) feet miles N S E W of (Milepost, Nearest intersecting Route Number or Street Name)

Accident Description/Officer's notes

ADVISED EMS UPON THERE ARRIVAL OF ALL INJURIES I HAD LEARNED ABOUT. DRIVER OF VEHICLE TWO WAS ISSUED A UTT FOR FAILURE TO KEEP RIGHT. ALL PERSONS WERE TAKEN TO CAYUGA MEDICAL CENTER AT ITHACA. DRIVER OF VEHICLE TWO WAS TRANSFERRED TO UPSTATE MEDICAL CENTER IN SYRACUSE BECAUSE OF MULTIPLE FRACTURES TO HER ARMS AND LEGS.
--

Cost of repairs to any one vehicle will be more than \$1000.
☐ Unknown/Unable to determine ☐ Yes ☐ No


Reference Marker	Coordinates (If available)	Place Where Accident Occurred:
	Latitude/Northing:	County TOMPKINS ☐ City ☐ Village ☐ Town of
	Longitude/Easting	Road on which accident occurred (Route Number or Street Name)
		at 1) intersecting street (Route Number or Street Name)
		or 2) feet miles N S E W of (Milepost, Nearest intersecting Route Number or Street Name)

New York State Department of Motor Vehicles
POLICE ACCIDENT REPORT
 MV-104A (3/04)

Local Codes
 (b) (6)
 (b) (6)

☐ AMENDED REPORT

Accident Date			Day of Week	Military Time	No. of Vehicles	No. Injured	No. Killed	Not Investigated at Scene ☐	Left Scene ☐	Police Photos ☒ Yes ☐ No
Month	Day	Year						Accident Reconstructed ☐		
12	9	2009	Wednesday	09:27	2	3	0			



PEDESTRIAN/BICYCLIST/OTHER PEDESTRIAN LOCATION 1. Pedestrian/Bicyclist/Other Pedestrian at Intersection 2. Pedestrian/Bicyclist/Other Pedestrian Not at Intersection			PEDESTRIAN/BICYCLIST/OTHER PEDESTRIAN ACTION 1. Crossing, With Signal 2. Crossing, Against Signal 3. Crossing, No Signal, Marked Crosswalk 4. Crossing, No Signal or Crosswalk 5. Riding/Walking/Skating Along Highway With Traffic 6. Riding/Walking/Skating Along Highway Against Traffic 7. Emerging from In Front of/Behind Parked Vehicle 8. Going to/From Stopped School Bus 9. Getting On/Off Vehicle Other Than School Bus 10. Working in Roadway 11. Playing in Roadway 12. Other Actions in Roadway* 13. Not in Roadway (Indicate)*			TRAFFIC CONTROL 1. None 2. Traffic Signal 3. Stop Sign 4. Flashing Light 5. Yield Sign 6. Officer/Guard 7. No Passing Zone 8. RR Crossing Sign 9. RR Crossing Flashing Light 10. RR Crossing Gates 11. Stopped School Bus-Red Lights Flashing 12. Construction Work Area 13. Maintenance Work Area 14. Utility Work Area 15. Police/Fire Emergency 16. School Zone 20. Other*			LIGHT CONDITIONS 1. Daylight 2. Dawn 3. Dusk 4. Dark-Road Lighted 5. Dark-Road Unlighted			ROADWAY CHARACTER 1. Straight and Level 2. Straight and Grade 3. Straight at Hillcrest 4. Curve and Level 5. Curve and Grade 6. Curve at Hillcrest			ROADWAY SURFACE CONDITION 1. Dry 2. Wet 3. Muddy 4. Snow/Ice 5. Slush 6. Flooded 0. Other*			WEATHER 1. Clear 2. Cloudy 3. Rain 4. Snow 5. Sleet/Hail/Freezing Rain 6. Fog/Smog/Smoke 0. Other*			WHICH VEHICLE OCCUPIED 1. Vehicle No. 1 A. All-Terrain Vehicle (ATV) O. Other* 2. Vehicle No. 2 B. Bicyclist P. Pedestrian I. In-Line Skater S. Snowmobiler			POSITION IN/VON VEHICLE 1. Driver 2-7. Passengers 8. Riding/Hanging on Outside			SAFETY EQUIPMENT USED 1. None 2. Lap Belt 3. Harness 4. Lap Belt/Harness 5. Child Restraint Only 6. Helmet (Motorcycle Only) 7. Air Bag Deployed 8. Air Bag Deployed/Lap Belt 9. Air Bag Deployed/Harness A. Air Bag Deployed/Lap Belt/Harness B. Air Bag Deployed/Child Restraint 0. Other*			EJECTION FROM VEHICLE 1. Not Ejected 2. Partially Ejected 3. Ejected			AGE SEX M/F			INJURED TAKEN 17 BY TO 18		
New York State Department of Motor Vehicles POLICE ACCIDENT REPORT MV-104A (7/01) *EXPLAIN IN ACCIDENT DESCRIPTION If a question DOES NOT APPLY, enter a dash (-). If an answer is UNKNOWN, enter an "X".												APPARENT CONTRIBUTING FACTORS Human 2. Alcohol Involvement 3. Backing Unsafely 4. Driver Inattention/Distracted* 5. Driver Inexperience* 6. Drugs (Illegal) 7. Failure to Yield Right-of-Way 27. Failure to Keep Right 21. Fatigued/Drowsy 8. Fell Asleep 9. Following Too Closely 10. Illness 11. Lost Consciousness 12. Passenger Distraction 13. Passing or Lane Usage Improper 14. Pedestrian/Bicyclist/Other Pedestrian Error/Confusion 15. Physical Disability 16. Prescription Medication 17. Traffic Control Disregarded 18. Turning Improperly 19. Unsafe Speed 20. Unsafe Lane Changing 22. Cell Phone (hand-held) 23. Cell Phone (hands-free) 24. Other Electronic Device* 25. Outside Car Distraction* 26. Reaction to Other Uninvolved Vehicle 28. Aggressive Driving/Road Rage			Vehicular 41. Accelerator Defective 42. Brakes Defective 43. Headlights Defective 44. Other Lighting Defects 45. Oversized Vehicle 46. Steering Failure 47. Tire Failure/Inadequate 48. Tow Hitch Defective 49. Windshield Inadequate 50. Driverless/Runaway Vehicle 60. Other Vehicular* Environmental 61. Animal's Action 62. Glare 63. Lane Marking Improper/Inadequate 64. Obstruction/Debris 65. Pavement Defective 66. Pavement Slippery 67. Shoulders Defective/Improper 68. Traffic Control Device Improper/Non-Working 69. View Obstructed/Limited			DIRECTION OF VEHICLE: 			PRE-ACCIDENT VEHICLE ACTION 1. Going Straight Ahead 2. Making Right Turn 16. Making Right Turn on Red 3. Making Left Turn 17. Making Left Turn on Red 4. Making U Turn 5. Starting from Parking 6. Starting in Traffic 7. Slowing or Stopping 8. Stopped in Traffic 9. Entering Parked Position 10. Parked 11. Avoiding Object in Roadway 12. Changing Lanes 13. Passing 14. Merging 15. Backing 18. Police Pursuit 20. Other*			LOCATION OF FIRST EVENT 1. On Roadway 2. Off Roadway			TYPE OF ACCIDENT - COLLISION WITH 1. Other Motor Vehicle 6. In-Line Skater 2. Pedestrian 7. Deer 3. Bicyclist 8. Other Pedestrian 4. Animal 10. Other Object (Not Fixed) 5. Railroad Train			COLLISION WITH FIXED OBJECT 11. Light Support/Utility Pole 12. Guide Rail-Not At End 25. Guide Rail-End 13. Crash Cushion 14. Sign Post 15. Tree 16. Building/Wall 17. Curbing 18. Fence 19. Bridge Structure 20. Culvert/Head Wall 21. Median-Not At End 26. Median-End 27. Barrier 22. Snow Embankment 23. Earth Embankment/Rock Cut/Ditch 24. Fire Hydrant 30. Other Fixed Object* NO COLLISION 31. Overturned 32. Fire/Explosion 33. Submersion 34. Ran Off Roadway Only 40. Other			COVER SHEET N					

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Paul Olle
Claims Administrator

March 8, 2010

(b) (6)

SYRACUSE, NY **(b) (6)**

RE: Claimant: **(b) (6)**
Our File No.: 683052
Your File No.: **(b) (6)**
Our Client: General Motors LLC
Date/Event: 12/9/2009
Vehicle: 2006 Chevrolet Cobalt
VIN: 1G1AK55F667 **(b) (6)**

Dear **(b) (6)**:

This will confirm that we have completed our review of your claim regarding a 2006 Chevrolet Cobalt owned by Progressive Insurance. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Paul Olle
Claims Administrator

CDR File Information

User Entered VIN	1G1AK55F667
User	r.h.schottler
Case Number	683052
EDR Data Imaging Date	Friday, January 29 2010
Crash Date	Wednesday, December 9 2009
Filename	1G1AK55F667.ACM.CDR
Saved on	Friday, January 29 2010 at 01:21:17 PM
Collected with CDR version	Crash Data Retrieval Tool 3.3
Reported with CDR version	Crash Data Retrieval Tool 3.3
EDR Device Type	airbag control module
Event(s) recovered	Deployment Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC recommends that the latest production release of Crash Data Retrieval software be utilized when viewing, printing or exporting any retrieved data from within the CDR program. This ensures that the retrieved data has been translated using the most recent information including but not limited to that which was provided by the manufacturers of the vehicles supported in this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event 1. A locked Non-Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data

-Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.

-The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.

-If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.

-The ignition cycle counter relies upon the transitions through OFF ->RUN->CRANK power-modifying messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.

-Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

-Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.

-The Belt Switch Circuit is wired directly to the SDM.

Multiple Event Data

Associated Events Not Recorded	0
An Event(s) Preceded the Recorded Event(s)	No
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	No
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	No

System Status At AE

Vehicle Identification Number	**1AK55F*6*
Low Tire Pressure Warning Lamp (If Equipped)	Invalid
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Third Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	36
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	Yes	Yes
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	57	58	53	64	58
Engine Speed (RPM)	2048	2048	3648	4608	4544
Percent Throttle	35	45	100	30	48
Accelerator Pedal Position (percent)	0	0	0	0	0
Antilock Brake System Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Lateral Acceleration (feet/s ²)(If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Deployment

Ignition Cycles At Investigation	9053
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	3112
Ignition Cycles At Event	9051
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Automatic Passenger SIR Suppression System Validity Status at AE	Valid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Suppressed
Automatic Passenger SIR Suppression System Validity Status at First Deployment Command	Valid
Automatic Passenger SIR Suppression System Status at First Deployment Command	Air Bag Suppressed
Driver 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	20
Driver 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	36
Passenger 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	Suppressed
Passenger 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met (msec)	Suppressed
Time Between Events (sec)	-.36
Driver First Stage Deployment Loop Commanded	Yes
Driver Second Stage Deployment Loop Commanded	Yes
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	Yes
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	Yes
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Driver 2nd Stage Deployment Loop Commanded for Disposal	No
Passenger 2nd Stage Deployment Loop Commanded for Disposal	No
Crash Record Locked	Yes
Vehicle Event Data (Pre-Crash) Associated With This Event	Yes
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes




Time (milliseconds)	-70	-60	-50	-40	-30	-20	-10	0	10	20	30	40	50	60	70
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	-1.36	-2.71	-6.10	-10.85	-15.59	-19.66	-23.05	-25.76	-26.44	-26.44	-26.44
Time (milliseconds)	80	90	100	110	120	130	140	150	160	170	180	190	200	210	220
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-26.44	-27.11	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00




Time (milliseconds)	-70	-60	-50	-40	-30	-20	-10	0	10	20	30	40	50	60	70
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	-2.03	-4.07	-9.49	-12.88	-14.91	-15.59	-16.27	-16.95	-16.27	-16.95
Time (milliseconds)	80	90	100	110	120	130	140	150	160	170	180	190	200	210	220
SDM Lateral Axis Recorded Velocity Change (MPH)	-16.27	-16.27	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

System Status At Non-Deployment

Ignition Cycles At Investigation	9053
SIR Warning Lamp Status	ON
SIR Warning Lamp ON/OFF Time (seconds)	0
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	0
Ignition Cycles At Event	9051
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Invalid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	B0052
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	10.87
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	150
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	Yes
Vehicle Event Data (Pre-Crash) Associated With This Event	No
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-0.68	-1.36	-3.39	-4.07	-5.42	-6.78	-7.46	-8.13	-8.81	-9.49	-10.17	-10.17	-10.17	-10.17	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 68 00 00 00 00 00 00
$02 C0 00 00 00 00 00 00
$03 02 00 00 00 00 00 00
$04 02 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 20 4A 00 00 19 90 11
$07 10 81 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 02 43 43 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 3C 01 05 0F 00 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 00 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F A2 00 00 00 00 00 00
$10 47 31 41 4B 35 35 46
$11 36 36 37 36 31 35 32
$12 32 30 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 07 07 02 02 00 00 00
$18 07 07 00 00 00 00 00
$19 07 07 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 4F 00 00 5F 00 01 00
$1F 33 C1 00 00 00 23 00
$20 48 00 00 00 00 00 00
$21 FF FF 00 00 50 00 00
$22 00 8A 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 80 00 E2 00 02 00 00
$2F 00 FE 23 5D 02 00 00
$30 9D 00 00 00 00 00 00
$31 00 00 00 00 00 00 00
$32 00 00 C0 00 00 00 00
$33 7A 4C FE 73 5A 00 00
$34 47 48 39 20 20 00 00
$35 5E 67 56 5E 5C 00 00
$36 00 00 00 00 00 00 00
$37 00 00 00 03 04 00 E2
$38 54 00 00 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
$3D 31 41 4B 35 35 46 00
```



```

$3E 36 61 52 20 00 00 00
$3F 00 00 90 00 00 00 00
$40 80 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 80 00 00 00 00 00 00
$43 FE 23 5B 00 00 00 00
$44 80 52 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 FF 00 FE 00 FB 00
$48 00 FA 00 F8 FF F6 00
$49 FF F5 FF F4 FF F3 00
$4A FF F2 FF F1 FF F1 00
$4B FF F1 FF F1 00 00 00
$4C 00 00 00 00 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 D0 00 00 00 00 00 00
$52 80 00 00 00 00 00 00
$53 0F 01 01 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 A0 A5 00 00 00 00 00
$68 D0 10 00 00 00 00 00
$69 00 FF F0 0C 28 00 00
$6A FE 23 5B 00 00 00 00
$6B 00 00 00 00 00 00 00
$6C 00 00 00 00 00 00 00
$6D 00 00 00 00 00 00 00
$6E 00 00 00 00 00 00 00
$6F 00 00 00 FE FD FC 00
$70 FA F7 F2 F0 ED E9 00
$71 EA E3 E9 DE E8 DA 00
$72 E7 D9 E8 D9 E7 D9 00
$73 E8 D9 E8 D8 00 00 00
$74 00 00 00 00 00 00 00
$75 00 00 00 00 00 00 00
$76 00 00 00 00 00 00 00
$77 00 00 00 00 00 00 00
$78 D0 00 00 00 00 00 00
$79 00 00 00 00 00 00 00
$7A 00 00 00 00 00 00 00
$7B 0A 12 00 00 00 00 F7

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 35 31 30 39 33 30 39 4B 4B
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 05 31 37 34 31 38 53 33
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 33 19 2A B4 E6 87 91 9A
$22 90 11
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA

```

\$26 32 41 FA FA FA FA FA
\$40 00 00
\$41 3F 00 00 02 00 1A
\$42 F0 C4
\$43 00 00 8E 80
\$44 C6 00 00 FC C0 C0
\$45 07 01 07 01 05 01
\$46 FF 1A 1A 64 64
\$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
\$48 18 08 08
\$B0 58
\$B1 FD FE 00
\$B2 FF FF FF FF FF
\$B4 41 53 39 30 31 31 32 31 30 37 48 55 20 20 20 20
\$B7 50 AA 04 0F 03
\$B8 41 57 68 09 19
\$C1 30 46 30 33
\$CA 30 46 30 33
\$CB 01 5A D1 33
\$CC 01 5A D1 33
\$D1 00 00
\$DB 00 00
\$DC 00 00

Comments

just this investigator
in lot of royal chevrolet cortland,ny
hooked up to d.l.c.
using cars battery
mileage 59707
air bag light remains on no flashing

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.