


EWR D&I ANNOTATION



FAN-000001L103001DP619-2938

Artemis # : 000001L103001DP619**Record Created Date :** 04/22/2011**Printed Date :** 04/25/2011**Description :**

DI11-005. SEQ ID 619. 2010 Q3. WE RECEIVED A CALL LOG FOR A 2007 SATURN ION. THE DRIVER WAS HEADED TOWARDS AN INTERSECTION OF A HWY AROUND 5MPH. SHE DIDNT SEE ANOTHER VEHICLE COMING TOWARDS HER AND WAS HIT ON THE DRIVERS SIDE. THERE IS DAMAGE TO THE FRONT DRIVERS SIDE AND THE CUSTOMER SAYS THE WHOLE FRONT END IS GONE. THERE WERE THREE OCCUPANTS OF THE VEHICLE AND THERE WERE MINOR INJURIES. THE ALLEGED SPEED OF THE TRUCK WAS 55-60MPH WHEN IT HIT THE ION. THE CUSTOMER IS CONCERNED THAT NONE OF THE FRONT AIRBAGS DEPLOYED. NON-DEPLOYMENT OF 2007 IONS: VOQ-5. FR-1. PURSUIT-0. RECALL-0. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

February 15, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DII11-005

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 7, 8, 19, 20, 21, 23, 24, 50, 51, 68, 73, 83, 94, 113, 124, 136, 138, 147, 170, 172, 175, 177, 181, 183, 187, 191, 195, 197, 205, 225, 227, 274, 321, 323, 324, 327, 329, 369, 374, 375, 376, 377, 378, 379, 401, 418, 419, 437, 454, 455, 461, 468, 473, 474, 481, 483, 484, 487, 504, 511, 541, 560, 565, 570, 618, 619, 633	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly

identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CRF 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **March 18, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name and last name clearly distinguishable.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

March 17, 2011

MAR 18 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-005

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated February 15, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2010.

GM's response is comprised of 68 disks for the incidents that are the subject of DI11-005.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 7 316869715-696125 and 2010 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 7 316869715-696125_00_**Request and Responses**. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-005
7 316869715-696125
2010 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

7 316869715-696125_01_001- is the first document responsive to Inquiry no.1.

7 316869715-696125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(67 Vehicles from the Light Vehicle Template)			
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)		TYPE
7	5GALRBED2AJ		NISM
8	5GALRAEDXAJ		NISM
19	1G4HD572X7U		NISM
20	1G4HD57257U		NISM
21	1G4HR57Y77U		NISM
23	1G4HA5EM8AU		NISM
24	1G4HC5EM3AU		NISM
50	1G6DE5EG6A0		NISM
51	1G6DE5EY7B0		NISM
68	3GYFNFY9AS		NISM
73	3GNEC12097G		LIT
83	KL1TD66638B		NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
94	2G1FB1EV5A9	NISM
113	1G1AK15F567	NISM
124	1G1AK55F267	NISM
136	1G1AK15F967	NISM
138	1G1AL55F767	NISM
147	1G1AL15F277	PAR
170	1G1AL18F087	NISM
172	1G1AL58F887	NISM
175	1G1AK18F087	NISM
177	1G1AK18F987	NISM
181	1G1AK18H197	PAR
183	1G1AS18H397	NISM
187	1G1AT58H697	NISM
191	1G1AS58H297	NISM
195	1G1AB5F59A7	NISM
197	1G1AB5F57A7	NISM
205	1GTJTCDE1A8	NISM
225	2CNALDEW3A6	PAR
227	2CNALBEC0B6	NISM
274	2G1WA5EN4A1	NISM
321	1G1ZC5E05AF	NISM
323	1G1ZD5E7XAF	NISM
324	1G1ZA5E08AF	NISM
327	1G1ZE5EB4AF	NISM
329	1G1ZC5EU2BF	NISM
369	1GCEC290X9Z	RMR
374	1GCEK290X9Z	NISM
375	3GCRKSE31AG	NISM
376	3GCRKSE39AG	NISM
377	3GCXKTE29AG	NISM
378	1GCSKREA0AZ	NISM
379	1GCSKSEA2AZ	NISM
401	1GNUKKE32AR	NISM
418	1GNFK13017R1	NISM
419	1GNFC13J97R	NISM
437	1GNDS13S052	LIT
454	1GNLRFEDXAS	PAR
455	1GNLVGED3AS	NISM
461	1GNDV33178D	LIT
468	1GNDV23E45D	NISM
473	1GKEV23738J	NISM
474	1GKEV23798J	NISM
481	1GKDS13SX52	NISM
483	1GKDT13S652	NISM
484	1GKDS13S652	NISM
487	1GKET63M672	NISM
504	1GTPKVE02AZ	PAR
511	1GKEC13T75R	LIT
541	1G2AL15F677	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
560	1G2ZH36N874 [REDACTED]	NISM
565	1G2ZM177984 [REDACTED]	NISM
570	1G2ZG57N494 [REDACTED]	NISM
618	1G8AJ55F47Z [REDACTED]	NISM
619	1G8AN15F17Z [REDACTED]	NISM
633	3GSCL33P58S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 68 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

982.2(b)(1)
FOR COURT USE ONLY

ATTORNEY OR PARTY WITHOUT ATTORNEY (PLEASE PRINT the name and address)
ERIC D. PARIS, ESQ., S/B# 147836
LAW OFFICES OF ERIC D. PARIS & ASSOCIATES
281 S. THOMAS STREET
SUITE 403
POMONA, CALIFORNIA 91766
TELEPHONE NO. 909-469-5127 FAX NO. 909-469-5126
ATTORNEY FOR: PLAINTIFF'S

REPORT NAME OF COURT, JUDICIAL DISTRICT AND BRANCH COURT, IF ANY
SUPERIOR COURT FOR THE STATE OF CALIFORNIA
INDIO COURT

CASE NAME: CARDONA V. CHEVROLET

CIVIL CASE COVER SHEET
☐ Limited ☒ Unlimited

Complex Case Designation
☐ Counter ☐ Joinder
Filed with first appearance by defendant
(Cal. Rules of Court, rule 181.1)

PLEASE COMPLETE ALL FIVE (5) SECTIONS BELOW

1. Check one box below for the case type that best describes this case.
☒ Auto Tort (22)
☐ Other PIP/DWD (Personal Injury-Property Damage/Wrongful Death) Tort
☐ Asbestos (24)
☐ Product Liability (24)
☐ Medical malpractice (46)
☐ Other PIP/DWD (23)
☐ Non-PIP/DWD (Other) Tort
☐ Business tortious business practice (37)
☐ Civil rights (e.g., discrimination, false arrest) (40)
☐ Defamation (e.g., slander, libel) (13)
☐ Fraud (16)
☐ Intellectual property (15)
☐ Professional negligence (e.g., legal malpractice) (25)
☐ Other non-PIP/DWD tort (36)
☐ Employment
☐ Wrongful termination (36)
☐ Other employment (15)
☐ Contract
☐ Breach of contract/warranty (26)
☐ Collateral (e.g., money owed, other legal accounts) (22)
☐ Insurance coverage (16)
☐ Other contract (37)
☐ Real Property
☐ Endowed domestic/tenure condemnation (14)
☐ Wrongful eviction (23)
☐ Other real property (e.g., quiet title) (26)
☐ Unlawful Detainer
☐ Commercial (21)
☐ Prudential (32)
☐ Drugs (38)
☐ Judicial Review
☐ Asset forfeiture (20)
☐ Petition re: arbitration award (11)
☐ Writ of mandate (22)
☐ Other judicial review (38)
☐ Provisionally Complex Civil Litigation (Cal. Rules of Court, rules 1800-1812)
☐ Arbitral/Trade regulation (23)
☐ Construction defect (10)
☐ Claims involving marine law (42)

2. This case ☒ is ☐ is not complex under rule 1800 of the California Rules requiring exceptional judicial management.
a. ☒ Large number of separately represented parties. d. ☒ Large number of
b. ☐ Extensive motion practice raising difficult or novel issues that will be time consuming to resolve. e. ☐ Coordination an
c. ☐ Substantial amount of documentary evidence. f. ☐ Substantial post
3. Type of remedies sought (check all that apply):
a. ☒ monetary b. ☐ nonmonetary, declaratory or injunctive relief c. ☐
4. Number of causes of action (specify): FIVE
5. This case ☐ is ☒ is not a class action suit.
Date: JULY 3, 2003
ERIC D. PARIS, ESQ., S/B# 147836
(PLEASE PRINT NAME)

NOTICE
• Plaintiff must file this cover sheet with the first paper filed in the action or proceeding (ex-
under the Probate, Family, or Welfare and Institutions Code). (Cal. Rules of Court, rule
• File this cover sheet in addition to any cover sheet required by local court rule.
• If this case is complex under rule 1800 at seq. of the California Rules of Court, you must
• Other parties to the action or proceeding.
• Unless this is a complex case, this cover sheet shall be used for statistical purposes only.

Form Adopted by Monterey Unit
Adopted County of California
982.2(b)(1) Rev. January 1, 2006

CIVIL CASE COVER SHEET

Next Image
Previous Image
Next page Ctrl+PgDn
Previous page Ctrl+PgUp
Full screen image Ctrl+F11
Slide show F10
Fit Scale to fit F5
1:2 Scale 50% F6
1:1 Scale 100% F7
2:1 Scale 200% F8
Rotate left Ctrl+Alt+L
Rotate right Ctrl+Alt+R
Rotate by 180°
Copy to clipboard
Copy file to... Ctrl+C
Move file to... Ctrl+X
Rename file... F2
Delete file... Del
PDF Image Information...
Preferences... Ctrl+R

Step 7: Next File
(Image)

Step 7: Next Page

Step 8: Scale
Image

Step 7: Image Properties

DI11-005
619 316870109 – 696955
2007 SATURN ION

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Detail

SR No.	71-858674703	Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initiate PAR- Collision
Address		City	Chinquapin	Involved Dir		Safety	Yes
State	NC ZipCd	Con Acct		Source	Phone	Updated	8/12/2010 02:49:14 PM
Serial #/VIN	1G8AN15F17Z	Model Year	2007	Priority	Medium License #	Owner	MARQUEMO
Make	Saturn	Warr. Start	02/21/2007	Status	Open	Opened	8/12/2010 01:11:33 PM
Model	ION 2	Mileage	35000	Sub-Status	Dissatisfied	Closed	
Abstract	Collision - Injuries - Restraints - (SIR) - Driver Front						
Customer Description	***This is a BRC PAR Case. Please do not assume. Forward any inquiries to Monica at ext.21072 ***						

Pre-PAR

Owner	8/11/2010 11:30:00 AM	Y	1	2	Asphalt	Dry	N/A	Unknown
Driver Last Name		Driver First Name		52		none		
Insurance Agent	Justin	Insurance Agent First Name		(800) 531-8722	USAA Insurance Company			
Incident Loc	Intersection of HWAY 111 FOUNTAINTOWN, NC 28521			Incident Desc	Cust sts: Her granddaughter was driving at the time when she was going into an intersection - she didn't see the truck coming towards her and the tp truck struck the front driver side - cust sts: her concern is upon impact none of the frontal airbags deployed such as the driver front end			
Component	Restraints - (SIR) - Driver Front			Damage Desc	Frontal driver side damages - whole front end is gone			
Vehicle Loc	Insurance comp has the vehicle - unknown where the veh is located			Add'l Info	Cust sts: she doesn't know personal info for the passenger such as DOB - address or number. Cust sts she was not given a claim number.			
Emgcy Svc Names	State Highway Patrol			Maint Loc	Jiffy Lube			

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	none
Vehicle Speed	5	Weather Condition	Dry	Prop Owner	N/A	Property Type	N/A	
Last Service Date	7/22/2010	Loc Last Service		Property Location	N/A	Prop Est Repair Cost		
Veh Est Repair Cost	\$0.00	Spec Equip Installer	none	Prop Damage Description	N/A			
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	Frontal driver side damages - whole front end is gone			Explain Other	File forwarded to ESIS			

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	Seatbelt
Injury Description			Medical Role	Treatment Location	Treated By	
stiff neck and sore shoulder -			unknown	EMS checked driver out at the scene of the collision	Unknown	
Street Address			City	State	Zip Code	
			Chinquapin	NC		
Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Front Passenger	Seatbelt
Injury Description			Medical Role	Treatment Location	Treated By	
- Chest is bruised on shoulder and Knee has a large lump from hitting the dashboard			unknown	EMS checked driver out at the scene of the collision	Unknown	
Street Address			City	State	Zip Code	

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 02:49:45 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS
Contact Last Name	Contact First Name	Account	BAC Code				
Comments							
- stiff neck and sore shoulder - checked out by EMS at the scene							
- Chest is bruised on shoulder and Knee has a large lump from hitting the dashboard - checked out by EMS at the scene							
Joe G/PA/ATX							
Confidential Comments							

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 02:26:18 PM	MARQUEM	MARQUEMO	Scheduled Follow-up		Scheduled Alarm		Follow up with ESIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments
THIS IS NOT A SCHEDULED CALL (SOCC). PLEASE DO NOT ADVISE THE CUSTOMER OF THIS SCHEDULED ACTIVITY. FORWARD ANY QUESTIONS TO OCRS.

Check file to see if it has been picked up by ESIS. If so, close file.

Monica/BRCPAR/ATX

x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 02:25:24 PM	MARQUEM	GARCIAJR	Notify CRM		Done	8/12/2010 02:49:42 PM	Assign to ESIS

Contact Last Name	Contact First Name	Account	BAC Code

Comments
Injuries - Medical Attention Required

Both driver and passenger sustained injuries where they were checked out on scene by EMS.

Monica/BRCPAR/ATX

x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:27:37 PM	MARQUEM	MARQUEMO	Ownership Changed		Done	8/12/2010 01:27:37 PM	Service Request Ownership has changed FROM: REYRA TO: MARQUEMO

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:26:52 PM	MARQUEM O	MARQUEMO	Ownership Changed	Ownership Escalated to BRC	Done	8/12/2010 01:26:52 PM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:18:41 PM	MARQUEM O	MARQUEMO	BRC PAR	Initial Contact- AVM	Done	8/12/2010 01:30:11 PM	Called:

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Due to the brand - Initial contact to the FFOM is not required

Monica/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:18:32 PM	MARQUEM O	MARQUEMO	BRC PAR	Initial Contact- Dealer	Done	8/12/2010 02:25:18 PM	Called:

Contact Last Name	Contact First Name	Account	BAC Code

Comments

No need to call Dir. Vehicle beyond warranty and has not been to dealer in two years. No contact made.

Monica/BRCPAR/ATX
X21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:18:21 PM	MARQUEM	MARQUEMO	BRC PAR	Initial Contact- Phone	Done	8/12/2010 02:25:21 PM	Spoke with [REDACTED]

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments

Cust sts: Her granddaughter was driving at the time when she was going into an intersection - she didn't see the truck coming towards her and the tp truck struck the front driver side - cust sts: her concern is upon impact none of the frontal airbags deployed such as the driver front and passenger front airbags. Cust sts: The police dept did arrive but cust has not received a report til Monday. Cust sts her granddaughter and passenger were checked out by EMS on the scene. Cust sts: She doesn't know any personal info for the passenger - unknown of DOB or address or number. Cust sts she did make a claim with the insurance company - cust sts she doesn't have a claim number yet. Cust sts the insurance comp took the veh - unknown where the veh is currently located. Cust sts the damages to the veh is Frontal driver side damages - whole front end is gone. The injuries that were sustained were from the seatbelts.

Cust sts: to find out why the frontal airbags didn't deploy

CRS adv: Due to the injuries where medical attention was sought this file will need to be forwarded to ESIS for further handling - advised cust if she gets a police report to hold onto it - along with address where veh is incase ESIS needs that info. Provided number and ext if needed - advised ESIS will be incontact within 7-10 business days.

Monica/BRCPAR/ATX
x21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:18:15 PM	MARQUEM	MARQUEMO	BRC PAR	Acknowledgement	Done	8/12/2010 02:25:15 PM	Spoke with [REDACTED]

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments

See Initial Contact

Monica/BRCPAR/ATX
x21072

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:18:08 PM	MARQUEM	MARQUEMO	Research		Done	8/12/2010 02:25:13 PM	VIN scan

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS Performed VIN Scan:

GMVIS and Global Warranty: No recalls existed to be active on vehicle in GMVIS or Global Warranty

NO Closed Recalls Found:

VIN: Found Additional Files

ST-1-26243107 - Address update/warranty inquiry/brake issue

SVC History: No Service History Related to Allegation in GMVIS or Global Warranty

Monica/BRC PAR/ATX
X21072

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:18:00 PM	MARQUEM	MARQUEMO	BRC PAR	Case Assigned	Done	8/12/2010 02:25:10 PM	File assigned to Monica @ ext.21072

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
8/12/2010 01:12:23 PM	REYRA	REYRA	Inbound Call Customer	Complaint or Escalation	Done	8/12/2010 01:14:06 PM	PAR - airbags did not deploy
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Cust Sits and sks:
-truck hit the front part of the veh, the airbags did not deploy
-55-60mph speed of the truck when it hit the veh
-no injuries, just bruises
-Yesterday, 11:30am Intersection HWAY 111 FOUNTAINTOWN, NC 28521
-police report filed, number not with the cust
-insurance, USAA Insurance

Source: CAC PAR Procedures d_108767
Ray/CAC T1/MAN/Level 0 Empowered
1-866-790-5600 ext. 13059

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front
C48	SIR - Did Not Deploy	Restraints - (SIR) - Passenger Front



Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary



This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

For this

View V

Vehicle Information

VIN 1G8AN15F17Z

Model: ZAN37-2007 COUPE QUAD ION.2 - AUTOMATIC

Service Contract No Branded Title No Warranty Block No

PDI Status Yes

Order Type T - DEALER STOCK

Field Actions 0 Open

View V

View V

Comp

View V

Transa

Detail

View V

Inform

Required Field Actions

Open field actions are highlighted

Vehicle has no current record of required field actions.

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Refer to Help page for details. For OnStar contact 888.ON.STAR1 (888.667.8271) and for XM Radio contact 877.GET.XMST (877.438.9677).

OnStar Equipped Y

OnStar Status Active

XM Equipped N

XM Radio ID:

XM Status NA

OnStar Vehicle Diagnostics Y

DMN Enabled: N

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Saturn 36/36K Bumper to Bumper	07/29/2010	02/21/2007	380 MI	02/21/2010	36,380 MI
	Saturn 72/100K Corrosion	07/29/2010	02/21/2007	380 MI	02/21/2013	100,380 MI
	Saturn 60/100K Powertrain	07/29/2010	02/21/2007	380 MI	02/21/2012	100,380 MI
	Saturn 96/80M Emission select components	07/29/2010	02/21/2007	380 MI	02/21/2015	80,380 MI
	Special Coverage 10187	07/29/2010	02/21/2007	380 MI	02/21/2017	100,380 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History

[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
06/09/2007	0187305	ZSET—Service Event		M5010 -	10,661 MI
05/23/2006	0171701	ZPDI—Pre-Delivery Inspection		Z7000 -	1 MI
05/23/2006	0171701	ZSET—Service Event		M6015 -	1 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.

**Warranty**

Mr. GMVIS 2

August 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

**INTERFACE WITH
CUSTOMER****View Vehicle Build**

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available)

For this

• View V

Vehicle Information

VIN 1G8AN15F17Z

Model: ZAN37-2007 COUPE QUAD ION.2 - AUTOMATIC

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: T - DEALER STOCK

Field Actions [Q](#), [Open](#)[REQUEST ANOTHER VIN](#)

• View V

• View V

• Comp

• View V

• Transa
Detail• View V
Inform**Vehicle Build**

Model: ZAN37-2007 COUPE QUAD ION.2 - AUTOMATIC

Order Number: GGE708

Gross Vehicle Weight: 0

Build Date: 05/10/2006

Build Plant: Z-

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only.
Should there be any questions about the vehicle's original build or RPO information please refer to the original
vehicle invoice or window sticker

13L - BRIGHT SILVER METALLIC

19E - BLACK CLOTH

28U -

6AA - SUSPENSION

8AA - SUSPENSION

A31 - POWER WINDOWS

AK5 - DR & PASS SEAT RESTRAINT SYSTEM

AU0 - REMOTE KEYLESS ENTRY W/ALARM

BBC - BODY COLOR APPLIQUES

DG7 - PWR. REMOTE EXTERIOR MIRRORS

FE9 - FEDERAL EMISSIONS

HAA - PREFERRED PACKAGE INCLUDES: * POWER WINDOWS * REMOTE
KEYLESS ENTRY W/ALARM * PWR. REMOTE EXTERIOR MIRRORS *
CRUISE CONTROL * DRIVER SEAT MANUAL HEIGHT ADJ * AM/FM
STEREO, CD PLAYER, MP3 PLAYER (REPLACES STD/OPT PKG RADIO)

J41 - POWER BRAKE SYSTEM

K62 - 105 AMP GENERATOR

MN5 - 4 SPEED AUTO TRANS

NK5 - STANDARD STEERING WHEEL

13U - SILVER NICKEL

19I - BLACK

51L -

7AA - SUSPENSION

9AA - SUSPENSION

AG4 - DRIVER SEAT MANUAL
HEIGHT ADJ.

AR9 - DLXE FRT BKT SEAT

B37 - FLOOR MATS FRONT &
REARC60 - A/C W/DUST & POLLEN
FILTERFE1 - SOFT RIDE
SUSPENSION SYSTEM

FY1 - RATIO - 3.63

IPE - TRIM INTERIOR DESIGN

K34 - CRUISE CONTROL

L61 - 2.2L 4CYL DOHC 16V
145 HP ENG. W/DUAL
BALANCE SHAFTS

MX0 - MERCHANDISED
TRANS AUTO PROVIS

NT7 - EMISSION SYSTEM
FEDERAL

P2W - WHEEL COVER, FLUSH SPORT

QTU - P195/60R15 TOURING TIRES

R6P - SPECIAL PAINT

R9N - LEATHER APPOINTMENTS

T43 - DECKLID SPOILER

UE1 - ONSTAR SERVICE: INCLUDES 1 YEAR SAFE AND SOUND PLAN

US6 - FIXED ANTENNA, PAINTED, RADIO

V73 - VEHICLE STATEMENT USA/CANADA

PG1 - 15" STYLED WHEEL
COVERS

R6H - SDS CHARGE

R7Y - COMMUNICATIONS
PLUS

RF7 - MERCHANDISED PKG
SATURN

U79 - 4 COAXIAL SPEAKERS

UH8 - CLUSTER INST, COOL
TEMP, TRIP ODOM, TACH

US8 - AM/FM STEREO W/CD &
MP3

VK3 - LICENSE PLATE FRONT
FRT

Added Option Codes

-BA -

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors

**Warranty**

Mr. GMVIS 2

August 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

**INTERFACE WITH
CUSTOMER****View Vehicle Component Summary**

②

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build.

For this:

View V

Vehicle Information

VIN 1G8AN15F17Z

Model: ZAN37-2007 COUPE QUAD ION.2 - AUTOMATIC

Service Contract No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: T - DEALER STOCK

Field Actions [Q Open](#)[REQUEST ANOTHER VIN](#)

View V

View V

Compc

View V

Transa

Detail

View V

Inform

Vehicle Component

Component Code 10-ENGINE ASSEMBLY

Source Plant: S-

Date Scanned: 05/10/2006

Traceability: 604270990

Part / Number Broadcast: AXD

Time Scanned: 15:31:00

Scan Station:

Component Code 61-TRANSMISSION

Source Plant J-HYDRAMATIC WINDSOR, ONTARIO

Date Scanned: 05/10/2006

Traceability: 02NR

Part / Number Broadcast: 7EHJ

Time Scanned: 15:31:00

Scan Station:

Component Code 86-ELECTRONIC CONTROL MODULE (ECM)

Source Plant M-DELCO ELECTRONICS MILWAUKEE,
WISCONSIN

Date Scanned: 05/10/2006

Traceability: 06123FQ8C

Part / Number Broadcast:
YPDF

Time Scanned: 15:31:00

Scan
Station:

Component Code 87-BODY CONTROL MODULE

Source Plant 6-

Date Scanned: 05/10/2006

Traceability: 533016116

Part / Number Broadcast: 8901

Time Scanned: 15:31:00

Scan Station:

Component Code AB-IR-MODULE ASM-INFLATOR

Source Plant I-INLAND

Date Scanned: 05/10/2006

Traceability: H081D2533

Part / Number Broadcast: 2525

Time Scanned: 07:44:00

Scan Station:

Component Code AL-IR-MODULE ASM-I/P

Source Plant I-INLAND

Date Scanned: 05/09/2006

Traceability: 301124087

Part / Number Broadcast: 1596

Time Scanned: 17:02:00

Scan Station:

Component Code AS-SENSING DIAGNOSTIC MODULE

Source Plant K-DELCO ELECTRONICS KOKOMO,IN

Date Scanned: 05/10/2006

Traceability: 261214TQ7

Part / Number Broadcast: 0731

Time Scanned: 15:31:00

Scan Station:

Component Code BK-INTERNATIONAL TRANS. CONTROL
MODULE

Source Plant K-

Date Scanned: 05/10/2006

Traceability: 061230270

Part / Number Broadcast:
YMAR

Time Scanned: 15:31:00

Scan
Station:

Component Code: DU---

Traceability: 65030102

Source Plant: 2-

Part / Number Broadcast: 9677

Date Scanned: 05/09/2006

Time Scanned: 17:02:00

Scan Station:

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.

**Warranty**

Mr. GMVIS 2

August 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER**View Vehicle Transaction History Detail**

This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

For this

View V

Vehicle Information

VIN 1G8AN15F17Z

Model: ZAN37-2007 COUPE QUAD ION.2 - AUTOMATIC

Service Contract No

Branded Title No

Warranty Block No

PDI Status: Yes

Order Type: T - DEALER STOCK

Field Actions [Q_Open](#)

REDUCE CLAIMS VIN

View V

View V

Comp

View V

Transa

Detail

View V

Informu

Job Card Date: 06/09/2007

Job Card Number: 0187305

Repair Service Agent: 121887

Odometer Reading: 10,661 MI

SATURN OF NORTH HOUSTON
17805 NORTH FREEWAY
HOUSTON TX 77090-4907
2815692200

Authorization Code:

Process Date
11/20/2007Transaction Type
ZSET---Service Event

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line # 1

Transaction Adjustment:

Cause Code: -

Labour Op M5010-

Causal Part Number

[See other Parts and/or Net Items](#)

Line Total: USD 0.00

Job Card Date: 05/23/2006

Job Card Number: 0171701

Repair Service Agent: 121887

Odometer Reading: 1 MI

SATURN OF NORTH HOUSTON
17805 NORTH FREEWAY
HOUSTON TX 77090-4907
2815692200

Authorization Code:

Process Date
11/20/2007Transaction Type
ZPDI---Pre-Delivery Inspection

Transaction Expense Category

Customer Complaint Code
0000-Converted Claim

Job Card Line # 2

Transaction Adjustment:

Cause Code: -

Labour Op Z7000-

Causal Part Number

-See other Parts and/or Net Items

Line Total: USD 92.75

Job Card Date: 05/23/2006

Job Card Number: 0171701

Repair Service Agent: 121887

Odometer Reading: 1 MI

SATURN OF NORTH HOUSTON

Authorization Code:

17805 NORTH FREEWAY

HOUSTON TX 77090-4907

2815692200

Process Date:

11/20/2007

Transaction Type:

ZSET—Service Event

Transaction Expense Category:

Customer Complaint Code:

0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment:

Cause Code: *

Labour Op M6015-

Causal Part Number

Line Total: USD 0.00

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors.

**Warranty**

Mr. GMVIS 2

August 13, 2010

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER**View Vehicle Delivery Information**

This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

For this

View V

Vehicle Information

VIN 1G8AN15F17Z

Model: ZAN37-2007 COUPE QUAD ION.2 - AUTOMATIC

Service Contract No

Branded Title: No

Warranty Block: No

PDI Status: Yes

Order Type: T - DEALER STOCK

Field Actions [0 Open](#)

PREVIOUS SCREEN

View V

View V

Compt

View V

Transa

Detail

View V

Inform:

Invoice Information

Invoicing Service Agent 121887

Invoice Date: 02/21/2007

SATURN OF NORTH HOUSTON

17805 NORTH FREEWAY

HOUSTON TX 77090-4907 2815692200

Ship to Information

Invoicing Service Agent 121887

Ship to Date: N/A

SATURN OF NORTH HOUSTON

17805 NORTH FREEWAY

HOUSTON TX 77090-4907 2815692200

Delivery Information

Delivery Service Agent 121887

Delivery Date: 02/21/2007

SATURN OF NORTH HOUSTON

Delivery Type:

17805 NORTH FREEWAY

Delivery Odometer: 380

HOUSTON TX 77090-4907 2815692200

In Service Information

Invoicing Service Agent 2210731

In Service Date: N/A

In Service Type: 0000

In Service Odometer: 0

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors.