


EWR D&I ANNOTATION



FAN-000001L103001DP147-6941

Artemis # : 000001L103001DP147

Record Created Date :

Printed Date : 03/29/2011

Description :

DI11-005. SEQ ID 147. 2010 Q3. WE RECEIVED A CALL LOG FOR A 2007 CHEVY COBALT. THE CUSTOMER IS ALLEGING THAT THE SEAT BELT HOLDER STICKS OUT TOO FAR CAUSING INJURIES. SHE WAS PUTTING AN ITEM IN THE FRONT PASSENGER SEAT WHEN HER SON WHO WAS SITTING IN THE REAR PASSENGER SEAT PRESSED THE SEAT FORWARD LEVER. THE SEAT WENT FORWARD AND THE CUSTOMER WAS HIT WITH THE SEAT BELT HOLDER IN THE HEAD. THE CUSTOMER SUFFERED MINOR INJURIES. THERE IS NOT A COMMON HISTORY OF COMPLAINTS FOR THE 2007 COBALT. GM HAS OPTED TO NOT RESPOND. *RM

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE.
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

February 15, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-005

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 3rd quarter of 2010. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 7, 8, 19, 20, 21, 23, 24, 50, 51, 68, 73, 83, 94, 113, 124, 136, 138, 147, 170, 172, 175, 177, 181, 183, 187, 191, 195, 197, 205, 225, 227, 274, 321, 323, 324, 327, 329, 369, 374, 375, 376, 377, 378, 379, 401, 418, 419, 437, 454, 455, 461, 468, 473, 474, 481, 483, 484, 487, 504, 511, 541, 560, 565, 570, 618, 619, 633	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly

identified in accordance with 5 U.S.C. § 512.6. If you submit a request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CRF 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **March 18, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly legible.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

March 17, 2011

MAR 18 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-005

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated February 15, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 3rd quarter of 2010.

GM's response is comprised of 68 disks for the incidents that are the subject of DI11-005.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 7 316869715-696125 and 2010 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 7 316869715-696125_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-005
7 316869715-696125
2010 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**



Response: See attached document.

2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

7 316869715-696125_01_001- is the first document responsive to Inquiry no.1.

7 316869715-696125_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI10-107, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(67 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
7	5GALRBED2AJ [REDACTED]	NISM
8	5GALRAEDXAJ [REDACTED]	NISM
19	1G4HD572X7U [REDACTED]	NISM
20	1G4HD57257U [REDACTED]	NISM
21	1G4HR57Y77U [REDACTED]	NISM
23	1G4HA5EM8AU [REDACTED]	NISM
24	1G4HC5EM3AU [REDACTED]	NISM
50	1G6DE5EG6A0 [REDACTED]	NISM
51	1G6DE5EY7B0 [REDACTED]	NISM
68	3GYFNFY9AS [REDACTED]	NISM
73	3GNEC12097G [REDACTED]	LIT
83	KL1TD66638B [REDACTED]	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
94	2G1FB1EV5A9	NISM
113	1G1AK15F567	NISM
124	1G1AK55F267	NISM
136	1G1AK15F967	NISM
138	1G1AL55F767	NISM
147	1G1AL15F277	PAR
170	1G1AL18F087	NISM
172	1G1AL58F887	NISM
175	1G1AK18F087	NISM
177	1G1AK18F987	NISM
181	1G1AK18H197	PAR
183	1G1AS18H397	NISM
187	1G1AT58H697	NISM
191	1G1AS58H297	NISM
195	1G1AB5F59A7	NISM
197	1G1AB5F57A7	NISM
205	1GTJTCDE1A8	NISM
225	2CNALDEW3A6	PAR
227	2CNALBEC0B6	NISM
274	2G1WA5EN4A1	NISM
321	1G1ZC5E05AF	NISM
323	1G1ZD5E7XAF	NISM
324	1G1ZA5E08AF	NISM
327	1G1ZE5EB4AF	NISM
329	1G1ZC5EU2BF	NISM
369	1GCEC290X9Z	RMR
374	1GCEK290X9Z	NISM
375	3GCRKSE31AG	NISM
376	3GCRKSE39AG	NISM
377	3GCXKTE29AG	NISM
378	1GCSKREA0AZ	NISM
379	1GCSKSEA2AZ	NISM
401	1GNUKKE32AR	NISM
418	1GNFK13017R	NISM
419	1GNFC13J97R	NISM
437	1GNDS13S052	LIT
454	1GNLRFEDXAS	PAR
455	1GNLVGED3AS	NISM
461	1GNDV33178D	LIT
468	1GNDV23E45D	NISM
473	1GKEV23738J	NISM
474	1GKEV23798J	NISM
481	1GKDS13SX52	NISM
483	1GKDT13S652	NISM
484	1GKDS13S652	NISM
487	1GKET63M672	NISM
504	1GTPKVE02AZ	PAR
511	1GKEC13T75R	LIT
541	1G2AL15F677	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
560	1G2ZH36N874 [REDACTED]	NISM
565	1G2ZM177984 [REDACTED]	NISM
570	1G2ZG57N494 [REDACTED]	NISM
618	1G8AJ55F47Z [REDACTED]	NISM
619	1G8AN15F17Z [REDACTED]	NISM
633	3GSCL33P58S [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 68 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer


1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



5. Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
7. Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



DI11-005
147 318804879-71- 875666041
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: GM opts not to respond.

Service Request Activity

SR No.		Ref No.		Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site		GW SubType		Bus. Unit	BRC
Last Name		First Name		Approval	Not Initiated	Area	PAR
Daytime #		Evening #		UCC	Trim - Headrest / Recliner / Seat	Sub-Area	Initiate PAR- Injury
Address		City	Fair Lawn	Involved Dir		Safety	Yes
State	NJ	Postal Cd	4810	Source	Email	Updated	10/1/2010 04:47:54 PM
Serial #/VIN	1G1AL15F277	Model Year	2007	Priority	Medium	License #	
Make	Chevrolet	Warr. Start	05/15/2007	Status	Closed	Owner	
Model	Cobalt	Mileage	23,000	Sub-Status	Dissatisfied	Opened	9/30/2010 10:55:47 PM
Abstract	Trim - Headrest / Redliner / Seat back (Fit)						
Customer Description	This is a BRC PAR File. Please do not Assume. DO NOT ADVISE. Forward all inquiries to Renea @ ext 21071						
						Closed	10/1/2010 04:47:51 PM

GMPP Details

GMPP Term	GMPP Mileage	GMPP Retail Cost
-----------	--------------	------------------

Component Coverage

Component Coverage	Expiration Mileage	Expiration Date
--------------------	--------------------	-----------------

Certificate Details

Certificate Number	Amount	Expiration Date
--------------------	--------	-----------------

Pre-Authorization Basics

Service Dealer	BAC Code	Div. Dealer Code	Repair Order #
----------------	----------	------------------	----------------

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:47:51 PM	RJOHNS36	RJOHNS36	SR Closed - Dissatisfied		Done	10/1/2010 04:47:51 PM	Service Request has been Closed
Contact Last Name	Contact First Name	Account				BAC Code	Dissatisfied.
Comments							

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:47:21 PM	RJOHNS36	RJOHNS36	SR Opened		Done	10/1/2010 04:47:21 PM	SR in Status of Closed has been Re-Opened by RJOHNS36
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:47:07 PM	RJOHNS36	RJOHNS36	SR Closed - Dissatisfied		Done	10/1/2010 04:47:07 PM	Service Request has been Closed Dissatisfied.
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:46:42 PM	RJOHNS36	RJOHNS36	BRC PAR	Close	Done	10/1/2010 04:47:00 PM	Close
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

see business case

Renea Soto/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:46:08 PM	RJOHNS36	RJOHNS36	BRC PAR	Business Case	Done	10/1/2010 04:46:38 PM	PAR Case Assessment
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Cust alleging the seat belt holder sticks out causing injuries when her son pressed the passenger seat forward release lever. Cust was informed this is the design of the vehicle

Renea Soto/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:40:22 PM	RJOHNS36	RJOHNS36	Research		Done	10/1/2010 04:45:32 PM	Research VIN
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Open/Closed Recalls

Product Safety Recall N100023 10023 LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR
03/18/2010 Open

No Previous Related Claim History

No Branded Title

No Warranty Block

Customer/ VIN Scan: No Previous Cases

Renea Soto/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:32:34 PM	RJOHNS36	RJOHNS36	BRC PAR	Initial Contact- AVM	Done	10/1/2010 04:40:12 PM	Called FFOM
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

FFOM/RCCDVM cell phone number is for BRC use only

FFOM Name:

Node/Mailbox:

This is Renea calling from the GM Product Allegation Dept to make you aware of a file that was received in your area.

The request number is:

The Customer's name is:

The dealer involved is: none

Located in: none

The vehicle is a: 2007 Chevrolet Cobalt

With current mileage: 23000

The last 8 digits of the VIN# are: 77

This involves: Cust alleging the seat belt holder sticks out causing injuries when her son pressed the passenger seat forward release lever.

Cust was informed this is the design of the vehicle and the file will be closed.

This message is for informational purposes only. However if you do have any questions please feel free to give me a call. My phone number is 866-790-5700 ext 21071.

Renea Soto/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:32:08 PM	RJOHNS36	RJOHNS36	BRC PAR	Initial Contact- Dealer	Done	10/1/2010 04:32:32 PM	No Initial Contact required. Vehicle has not been to dealer in two years
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

No Initial Contact required. Vehicle has not been to dealer in two years

Renea Soto/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:31:00 PM	RJOHNS36	RJOHNS36	Other		Done	10/1/2010 04:31:46 PM	additional info to cust initial
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

cust sts she will request the seat belt holder piece to be removed when she get the vehicle's recall performed.

Renea Soto/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 04:18:59 PM	RJOHNS36	RJOHNS36	Ownership Changed	Ownership Escalated to BRC	Done	10/1/2010 04:18:59 PM	Ownership Escalated to BRC
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 03:43:00 PM	RJOHNS36	RJOHNS36	BRC PAR	Initial Contact- Phone	Done	10/1/2010 04:30:41 PM	called in
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Crs verified cust contact info.

cust sts the incident occurred on 9/29/10. Cust states she has a 2 door coupe. Cust sts the seat belt was out of the seat belt holder by the headrest. Cust sts while she was placing her son's lunch box into the passenger front, her son got into the back of the passenger side, and hit the front passenger seat release lever causing the front passenger seat to fly forward and the seat belt piece to hit her in the face. Cust sts the seat belt holder piece sticks out.

CRS advised customer of required verbiage as stated in d_1075834

Cust requested to start the GM review process.

Crs gathered prePAR and PAR detail screens.

Crs advised the seat belt holder location is the design of the vehicle. Crs advised cust if she does received medical treatment to give me a call.

Crs advised cust of the nearest dealership to complete the recall on vehicle. Crs offered to transfer cust to dealership but cust declined.

Crs provided my contact information and the case number.

Crs closing file.

Renea Soto/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 03:39:25 PM	RJOHNS36	RJOHNS36	BRC PAR	Acknowledgement	Done	10/1/2010 03:40:02 PM	called in
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

see initial

Renea Soto/PAR/ATX

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 03:26:19 PM	RJOHNS36	RJOHNS36	BRC PAR	Case Assigned	Done	10/1/2010 03:39:23 PM	File assigned to Renea Soto @ ext 21071
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

received

Renea Soto/PAR/ATX

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 03:26:16 PM	RJOHNS36	RJOHNS36	Ownership Changed		Done	10/1/2010 03:26:16 PM	Service Request Ownership has changed FROM: BUENAVKA TO: RJOHNS36
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
10/1/2010 02:57:08 PM	BUENAVKA	BUENAVKA	Outbound Call Customer	Made Contact	Done	10/1/2010 03:14:39 PM	
Contact Last Name		Contact First Name		Account		BAC Code	
Comments							

Cust:

>theres a bar that sticks out
 >when you take the seatbelt out
 >seat belt is in the way
 >seat move forward very quicky -
 >my 3 year old started to climb in
 >umust have stepped on the seat release
 >and head was in the car
 >seat release was very fast and it flung forward
 >part of face all swollen and soar
 >headache for a couple of days
 >its very dangerous
 >its not the first time that the arm sticks out
 >and its really hard plastic

CRS:

>sorry to hear about that
 >will forward concern ot another dept for their review
 >put cust on hold and transfer to PAR

Karren/MAN/CACT1/AuthLv1

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub Type	Status	Completed	Description
9/30/2010 11:04:44 PM	BUENAVKA	BUENAVKA	Scheduled Outbound Call Cust	Initial Attempt	Done	10/1/2010 02:57:07 PM	

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

10/1/2010
funnel cust

Karren/MAN/CACT1/AuthLv1

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/30/2010 11:03:52 PM	BUENAVKA	BUENAVKA	Email - Outbound		Done	9/30/2010 11:04:37 PM	Chevrolet Customer Assistance Center
Contact Last Name	Contact First Name	Account	BAC Code				

Service Request: 71-875666041
Customer Relationship Specialist: Karren

Dear [REDACTED]

Thank you for contacting the Chevrolet Customer Assistance Center. This is in relation to the recent email that you have sent to us regarding the concern on 2007 Chevrolet Cobalt.

On behalf of General Motors and Chevrolet, we apologize for any inconvenience this matter has caused you.

Due to the nature of your concern, it is necessary to continue this communication through telephone. We will schedule a call for you tomorrow, October 1, 2010, between the hours of 2:00 PM and 4:00 PM, Eastern Time, to follow up on your concern. If this is not a good time to contact you, please do not hesitate to call me at 1-866-7905600, extension 12952. I am in the office Monday through Friday 1:00 PM to 9:00PM, Eastern Time and would be happy to assist you.

If you need assistance in the future, you may reply to this email or call us at 1-800-222-1020 Customer Relationship Specialists are available Mondays through Saturdays from 8:00 a.m. to 9:00 p.m. Eastern Time.

Again, thank you for contacting Chevrolet.

Sincerely,

The Chevrolet Consumer Support Team

[THREAD ID:1-EH4VW6]

-----Original Message-----

From: [REDACTED]
Sent: 9/30/2010 09:19:04 AM
To: cac@chevrolet.com
Subject: Chevrolet Owner Concern

Name: [REDACTED]
Email Address: [REDACTED]
Address: [REDACTED]

Service Request Activity

Activities

Created	Created By	Assigned To	Activity Type	Activity SubType	Status	Completed	Description
9/30/2010 09:19:31 AM		BUENAVKA	Email - Inbound		Done	9/30/2010 11:04:34 PM	Chevrolet Owner Concern
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Name:

Email Address:

Address:

Fair Lawn, NJ

Day Phone: ()-- ex

Evening Phone:

Comments: I own a 2007 2 door Chevy Cobolt. On the front seat is an arm that holds the seatbelt that comes from the back for the front passenger. Well when you put the seat forward the seat belt gets in the way of the person trying to get into the back seat, so I take it out before I put the seat up for the person to go into the back seats. However doing this makes the seat move forward very fast and that arm sticks out is dangerous when this happens especially if someone hits the seat forward button when another person is putting something in the front seat. My grandson hit the seat forward button when I was putting my purse on the front seat and the seat flung forward very fast and hit me in the side of the face hitting my jaw and cheek bone. I was getting ready to put him in the back seat where his car seat is, but had to put my purse in before I put him in and that's when he hit the seat forward button. If I had turned my head I am sure the arm would have taken out my eye, as it is I'm not so sure my jaw or cheek bone is not broken. Perhaps some sort of remodeling of this option needs to be done.

Vehicle Concern Info:

Nature of Concern: other

Model: Cobalt Coupe

Year: 2007

VIN Number:

Mileage:

Allow Phone Contact: yes

Best Time for Phone Contact: after 4pm

Deal...

UCC Codes

UCC Code	UCC Symptom	UCC Description
C15	Fit	Trim - Headrest / Recliner / Seat back