


EWR D&I ANNOTATION



000001L111001DP125-3825

Artemis # : 000001L111001DP125**Record Created Date :** 08/16/2011**Printed Date :** 08/16/2011

Description : DI11-072 SEQUENCE ID 12S: A SERVICE REQUEST DETAIL LOG FOR GENERAL MOTORS LLC MAKES THE ALLEGATION THAT A 2007 CHEVROLET COBALT IS POTENTIALLY DANGEROUS DUE TO AN AIR BAG NONDEPLOYMENT. THE LOG STATES THAT THE COBALT WAS INVOLVED IN AN ACCIDENT WHEREBY THE VEHICLE WAS APPROACHING A FLASHING YELLOW LIGHT INTERSECTION AND ANOTHER VEHICLE FAILED TO STOP DESPITE HAVING A FLASHING RED LIGHT. THE DRIVER OF THE COBALT SWERVED TO AVOID HITTING THE OTHER VEHICLE AND RAN INTO A POLE AS A RESULT. NO PICTURES OF THE DAMAGE WERE PROVIDED AND NO DESCRIPTION OF WHERE THE COBALT WAS HIT IS MENTIONED. THE SPEED THE VEHICLE WAS TRAVELING AND/OR SPEED OF IMPACT WAS NOT PROVIDED. NO INJURIES WERE MENTIONED IN THE SEQUENCE DOCUMENTATION. NO POLICE REPORTS WERE INCLUDED WITH THE SEQUENCE DOCUMENTATION. FROM A SEARCH NO RECALLS OR PURSUITS WERE FOUND RELATING THIS VEHICLE TO THE ALLEGED SAFETY DEFECT. FROM A VOQ SEARCH, 11 REPORTS WERE FOUND CLAIMING AIR BAG NON DEPLOYMENT OF VARYING SPEEDS AND INCIDENT SPECIFICS. FROM A SEARCH, 21 FIELD REPORTS WERE FOUND WHICH STATED 'NONDEPLOYMENT' IN THE SUMMARY OF THE REPORT. 7 TSBS WERE FOUND FOR THE AIRBAG COMPONENT WHICH ALL MENTION SIR/PASSENGER PRESENCE LIGHTS BEING ILLUMINATED.

*NO



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

June 22, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-072

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 1st quarter of 2011. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents
For Reporting Category: L
For the following Sequence IDs: 6, 12, 23, 40, 42, 44, 46, 47, 60, 61, 64, 73, 81, 82, 87, 89, 91, 115, 121, 125, 129, 131, 139, 143, 144, 145, 154, 157, 167, 170, 171, 172, 188, 189, 214, 217, 218, 221, 231, 236, 240, 243, 244, 245, 246, 270, 276, 277, 279, 280, 281, 292, 302, 304, 312, 314, 322, 323, 324, 336, 409, 410, 412, 434, 465, 473

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **July 22, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is fluid and cursive, with the first name "Christina" and last name "Morgan" clearly legible.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

July 22, 2011

JUL 22 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., S.E.
Washington, DC 20590

NVS-217kb
DI11-072

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated June 22, 2011 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 1st quarter of 2011.

GM's response is comprised of 66 disks for the incidents that are the subject of DI11-072.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 6 333829231-724510 and 2009 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 6 333829231-724510_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-072
6 333829231-724510
2009 BUICK ENCLAVE

Request for Information:

1. **Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.**

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

6 333829231-724510_01_001- is the first document responsive to Inquiry no.1.

6 333829231-724510_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI11-072, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(66 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
6	5GAEV23D59J	NISM
12	1G4GE5ED8BF	NISM
23	1G4HJ5EM0BU	NISM
40	1G6DS57V290	NISM
42	1G6DU57V090	NISM
44	1G6DE5EG3A0	NISM
46	1G6DP1ED3B0	PAR
47	1G6DS1ED5B0	NISM
60	1GYEE437390	PAR
61	3GYFNCEY2AS	NISM
64	3GYFNBEXBS	NISM
73	3GNFK12357G	NISM
81	KL1TD66698B	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
82	KL1TD66628B	NISM
87	KL1TG5DEXAB	NISM
89	2G1FJ1EJ0A9	NISM
91	2G1FA1ED6B9	NISM
115	1G1AL55F077	NISM
121	1G1AL15F977	NISM
125	1G1AM15B477	NISM
129	1G1AK18F587	NISM
131	1G1AK18F087	NISM
139	1G1AS18H297	NISM
143	1G1AT58H397	NISM
144	1G1AD1F57A7	NISM
145	1G1AF5F59A7	NISM
154	1G1YY24U555	NISM
157	1G1YY26E185	NISM
167	2CNALBEW2A6	NISM
170	2CNALBEC2B6	NISM
171	2CNFLNEC9B6	NISM
172	2CNALDEC2B6	NISM
188	3GNBABDV7AS	NISM
189	3GNBAADB0AS	NISM
214	2G1WT57N291	NISM
217	2G1WB5EK8A1	NISM
218	2G1WB5EK2A1	NISM
221	2G1WA5EK7A1	NISM
231	1G1ZS58N97F	NISM
236	1G1ZF57588F	NISM
240	1G1ZB5EB5A4	LIT
243	1G1ZD5EB6AF	NISM
244	1G1ZB5E17BF	NISM
245	1G1ZA5E1XBF	NISM
246	1G1ZB5E11BF	NISM
270	3GCEC13C28G	LIT
276	3GCEC23089G	NISM
277	1GCSCSE08AZ	NISM
279	1GCRKSE37BZ	NISM
280	1GCRCSE00BZ	NISM
281	UNKNOWN	NISM
292	1GC1KXC89BF	NISM
302	1GNFC16J47J	Rumor
304	3GNFC16087G	PAR
312	1GNFC13047R	PAR
314	1GNFC13J78R	NISM
322	1GNSCAE06BR	NISM
323	1GNSKDFJ9BR	Rumor
324	1GNSKCE0XBR	NISM
336	1GNDT13S052	NISM
409	2CTFLEEW0A6	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
410	2CTALSEC6B6 [REDACTED]	NISM
412	2CTALSEC2B6 [REDACTED]	NISM
434	KL2TD66E39B6 [REDACTED]	NISM
465	1G2ZG57B6942 [REDACTED]	NISM
473	2G2WP552781 [REDACTED]	NISM

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.


Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides
Director, Product Investigations
and Safety Regulations

Enclosures: 66 Disks
Attachment A


Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPegger" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down arrow key on your keyboard to browse through the images.



8. If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

[illegible]

Step 7: Next File (Image)

Step 7: Next Page

Step 8: Scale Image

Step 7: Image Properties

DI11-072
125 333828814 - 723664
2007 CHEVROLET COBALT

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: None.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No. (b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account	Silo	GW SubType		Bus, Unit	BRC
Last Name	First Name	Approval	Not Initiated	Area	PAR
Daytime #	Evening #	UCC	Restraints - (SIR) - Driver Front	Sub-Area	Initial PAR- Collision
Address	City Pittsburgh	Involved Dir	Century III Chevrolet, Inc.	Safety	Yes
State PA ZipCd	Con Acct	Source	Phone	Updated	1/14/2011 10:20:18 AM
Serial #/VIN 1G1AM15B477	Model Year 2007	Priority	Medium License #	Owner	SANCHERJ
Make Chevrolet	Warr. Start 04/25/2007	Status	Open	Opened	1/12/2011 08:45:35 AM
Model Cobalt	Mileage 32000	Sub-Status	Dissatisfied	Closed	
Abstract	Esis - Airbag did not Deploy				
Customer Description	IF CUST CALLS IN, PLS TRANSFER TO PAR				

Pre-PAR

PAR Notifier	Incident Date/Time	Injures	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	1/8/2011 01:50:08 AM	Y	1	1	Asphalt	Dry	na	5158
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		5'10		none				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
Lehamamm	Ed	(412) 357-2906	Erie Insurance					
Incident Loc	West Liberty Ave Pittsburg PA				Incident Desc	he was driving thru a blinking light and car that was supposed to stop ran the light and my son swirled and hit pole head on and the airbags didnt deploy		
Component	airbags				Damage Desc	front end damage		
Vehicle Loc	towed to mccorm				Add'l Info			
Emgcy Svc Names	Pittsburg Police Department				Maint Loc	na		

PAR Detail

Collision	Y	Non Collision	Property Damage	Y	Thermal Evt	N	Spec Equip	na
Vehicle Speed	35	Weather Condition	clear	Prop Owner	state	Property Type	pole and street sign	
Last Service Date		Loc Last Service		Property Location	pittsburg pa	Prop Est Repair Cost	\$0.00	
Veh Est Repair Cost	\$0.00	Spec Equip Installer	na	Prop Damage Description	unknown	Inspection Date/Time		
Primary Veh Use	Personal	Inspection Type	Restraint System SIR/Seat Belt	Inspected By	Inspection Not Performed			
Veh Damage Description	front end damage	Explain Other	sent to esis					

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
			Occupant of Owner's Vehicle		Driver	none
Injury Description			Medical Rpt#	Treatment Location		Treated By
ankle, right knee injury lacerations on face chest and back na				UPMC Mercy		Er Doctor
injury head injury whiplash						
Street Address			City	State	Zip Code	
			Pittsburgh	PA		

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/17/2011 02:47:44 PM	GARCIAJR	ESISBQU	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

- ankle, right knee injury lacerations on face chest and back injury head injury whiplash - went to UPMC Mercy Hospital

Joe G/PARIATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/14/2011 10:20:16 AM	SANCHERI	SANCHERI	Ownership Changed	Ownership Escalated to BRC	Done	1/14/2011 10:20:16 AM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/14/2011 10:19:20 AM	SANCHERI	GARCIAJR	Notify CRM		Done	1/17/2011 02:59:23 PM	esls - Injury

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Injuries

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/14/2011 10:17:24 AM	SANCHERJ	SANCHERJ	Inbound Call Customer	Complex Request	Done	1/14/2011 10:18:18 AM	

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

verified customer information and allegation

provided esis statement

cust sts i want to proceed

crs sts what happen

cust sts he was driving thru a blinking light and car that was supposed to stop ran the light and my son swerved and hit pole head on and the airbags didnt deploy he was injured and taken to the hospital

crs sts ok ma'am what i will be doing is getting this over to our central claims department and they will be in contact with you within 7-10 business days

cust sts ok thank

rla sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/13/2011 04:08:27 PM	SANCHERJ	SANCHERJ	Scheduled Follow-up		Scheduled Alarm		/u esis pick up

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/13/2011 04:07:55 PM	SANCHERJ	BRCPARLQ	Submit for Approval	Letter (Non Goodwill)	Done	1/14/2011 08:44:43 AM	10 day letter

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

1/12-1/13

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/13/2011 04:06:23 PM	SANCHERJ	SANCHERJ	Correspondence		Done	1/13/2011 04:06:23 PM	Created:BRCPAR_PA0005, SR#71-907345580

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/13/2011 04:03:23 PM	SANCHERJ	SANCHERJ	Correspondence		Done	1/13/2011 04:03:23 PM	Created:BRCPAR_PA0005, SR#71-907345580

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/13/2011 04:01:15 PM	SANCHERJ	SANCHERJ	Outbound Call Customer	Left Message	Done	1/13/2011 04:02:34 PM	

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

crs left a message for customer to call in regarding cobalt 866-790-5600 x 31227

rita sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/13/2011 09:37:30 AM	STEWARDE	SANCHERJ	Scheduled Outbound Call Cust	Final Attempt	Done	1/13/2011 04:00:58 PM	Called @

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Continue to INI

Debbie Stewart/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/13/2011 09:35:50 AM	STEWARDE	STEWARDE	Outbound Call Customer	Left Message	Done	1/13/2011 09:37:25 AM	Called [REDACTED]

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments

left message with contact info and SR#

Debbie Stewart/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 04:23:59 PM	SANCHERI	SANCHERI	Scheduled Follow-up		Done	1/13/2011 09:40:42 AM	Initial

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:49:47 PM	MERCADTO	SANCHERI	Ownership Changed		Done	1/12/2011 01:49:47 PM	Service Request Ownership has changed FROM: Omaysh TO: SANCHERI

Contact Last Name	Contact First Name	Account	BAC Code
[REDACTED]	[REDACTED]	[REDACTED]	[REDACTED]

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:49:39 PM	MERCADITO	SANCHERI	BRC PAR	Initial Contact- AVM	Done	1/12/2011 04:23:39 PM	called Salvador Christine 914055 8047

Contact Last Name	Contact First Name	Account	BAC Code

Comments

This is Rita Sanchez calling from gm par dept.

Customer:

Service Request:71907345580

Vehicle Information:2007 chevy cobalt

Last 8 of the VIN: 7

Involved Dealership:Century III Chevrolet

Nature of allegation: non deployment

CRS adv if you have any additional information pertaining to customer or vehicle please contact me at 1-866-780-5600 X 31227 If not then this is an FYI to let you know what is going on in your district.

Rita Sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:49:36 PM	MERCADITO	SANCHERI	BRC PAR	Initial Contact- Dealer	Done	1/12/2011 04:20:19 PM	called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Spoke with: Service Manager - tom

CRS adv: Calling on regards to an claim that was called in by an cust by the names of . They have an 2007 chevy cobalt -. Calling to make dir aware of allegation and checking to see what dir knows of allegation non deployment

Dir als: no history and yes you can have that inspected with a 3rd party Inspector here if needed

CRS Adv: ok thanks

Rita Sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:49:32 PM	MERCADITO	SANCHERI	BRC PAR	Initial Contact- 10 Day Letter	Done	1/13/2011 04:03:08 PM	called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

called 1/12 thru 1/13

rita sanchez/ATX/PAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:48:28 PM	MERCADTO	SANCHER	BRC PAR	Acknowledgement	Done	1/12/2011 04:14:53 PM	called

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS adv: This message is for [REDACTED]. This is Rita Sanchez calling from gm par dept in regards to the 2007 chevrolet cobalt. Advised to call CRS back at 868-790-5600 x 31227
Rita Sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:49:19 PM	MERCADTO	SANCHER	Notify CRM		Done	1/12/2011 04:12:46 PM	File assigned

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:49:14 PM	MERCADTO	SANCHER	Research		Done	1/12/2011 04:12:41 PM	Research 1G1AM15B47[REDACTED]

Contact Last Name	Contact First Name	Account	BAC Code

Comments

CRS Performed VIN Scan
GMVIS: - Found No Open Recalls Product Safety Recall N100023 10023 LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR 03/18/2010 Closed

VIN: - Found No Duplicate File

SVC History: No Service History Related to Allegation

Rita Sanchez/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:48:58 PM	MERCADTO	SANCHERJ	BRC PAR	Case Assigned	Done	1/12/2011 04:11:20 PM	File assigned to Rita Sanchez @ ext 31227

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:48:52 PM	MERCADTO	OMAYSH	SR Opened		Done	1/12/2011 01:48:52 PM	SR in Status of Closed has been Re-Opened by MERCADTO

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:48:50 PM	MERCADTO	OMAYSH	SR Closed - Dissatisfied		Done	1/12/2011 01:48:50 PM	Service Request has been Closed Dissatisfied.

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:48:45 PM	CABRERPA	MERCADTO	Notify CRM		Done	1/12/2011 01:48:45 PM	assigning activity to PARQUE Received and assigned in PAR Toner/BRC PAR/ATX

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 01:22:42 PM	CABRERPA	CABRERPA	Outbound Call Customer	Made Contact	Done	1/12/2011 01:26:44 PM	update customer
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

crs stc: this is peejay from Chevrolet and you spoke with Sheila earlier. She was trying to connect you to PAR but the line was disconnected. I will connect you to that department now.

cust: I spoke with someone from that department already and they said they'll call me back.

crs: I see, so you just need to wait for their call then

cust: okay, thank you

Peejay/T1/CAC/MNULM0

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 12:39:06 PM	BOULDIAN	BOULDIAN	Inbound Call Customer	Complex Request	Done	1/12/2011 12:40:09 PM	***Assisting Only***

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

transfer from Chelly of Marketing

Reason for call:

- > complain about the previous agent disconnecting the call
- > was able to provide all info necessary, when the agent is to transfer the call the line got disconnected
- > feels really upset

Details Needed:

> [REDACTED]

- > 1g1am15b477 [REDACTED]
- > 32000 miles

- > 2007 Cobalt SS
- > Airbag did not deploy

CRS sts:

- > apologize for the inconvenience
- > was able to pull up the file
- > case is to be transferred to PAR for further review
- > provided ssn#

Cust sts:

- > will be leaving to the hospital, son got hurt
- > will it be OK if PAR calls me after an hour and a half?

CRS sts:

- > Par dept will get in contact with cust soon

Tremaine Bouldin/CAC/ATX/T1A/VL0

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 09:12:07 AM	OMAYSH	OMAYSH	Scheduled Outbound Call	Follow-up Attempt	Done	1/12/2011 12:14:02 PM	CALL CUSTOMER

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

1/12/11

11AM-1PM

Call: [REDACTED]

Phone #: [REDACTED]

AP:

Transfer to PAR

Sheila/CAC T1/MAN/Level 0 Empowered

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 09:10:59 AM	PAGLINE1	OMAYSH	Notify CRM	Customer Called	Done	1/12/2011 09:51:59 AM	Informing of contact with the cust

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 09:07:18 AM	OMAYSH	OMAYSH	Outbound Call Customer	Left Message	Done	1/12/2011 09:52:04 AM	Call Customer
Contact First Name	Contact First Name	Account	BAC Code				

Comments

CRS-
-Left a message on the voicemail
-SR # 71-907345580
-You can call us back at your most convenient time

Shella/CAC T1/MAN/Level 0

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 09:01:31 AM	PAGLINEL	PAGLINEL	Inbound Call Customer	Complex Request	Done	1/12/2011 09:10:42 AM	***Assisting Only***
Contact Last Name	Contact First Name	...	Account	BAC Code			

Comments

transfer from Chelly of Marketing

Reason for call:

- > complain about the previous agent disconnecting the call
- > was able to provide all info necessary, when the agent is to transfer the call the line got disconnected
- > feels really upset

Details/Needs

> [REDACTED]

> [REDACTED]

> 1p1am15b477 [REDACTED]

> 32000 miles

> 2007 Cobalt SS

> Airbag did not deploy

CRS sts:

- > apologize for the inconvenience
- > was able to pull up the file
- > case is to be transferred to PAR for further review
- > provided sr#

Cust sts:

- > will be leaving to the hospital, son got hurt
- > will it be OK if PAR calls me after an hour and a half?

CRS sts:

- > will go ahead and notify ccrs of the call and advise that she be transferred after an hour

Elaine/CAC T1/MAN/Level 0

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
1/12/2011 08:47:27 AM	OMAYSH	OMAYSH	Inbound Call Customer	Complex Request	Done	1/12/2011 09:03:17 AM	Product ALLEGATION
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Customer states:

- I HAVE A COBALT SS 2007
- It was towed on Saturday
- airbag didn't deploy
- stitches in his head, bruising...
- dealership is century free
- Phone #: [REDACTED]

Customer seeks:

- I just want to know why the airbag didn't deploy

CRS advised:

- we need to forward this to Product Allegation Request

Sheila/CAC T1/MAN/Level 0 Empowered

Confidential Comments

UCC Information

UCC Code	Symptom	Description
C46	SIR - Did Not Deploy	Restraints - (SIR) - Driver Front

Global Warranty

Mr. GMVIS 2 Logout
 January 18, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMERView Vehicle Summary ?

This screen allows GMVIS users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title Information and OnStar and XM Radio information (if applicable)

Vehicle Information

VIN 1G1AM15B477

Model 1AM37-2007 COBALT SS COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: [Open](#)

For this vehicle:

[View Vehicle Summary](#)[Service](#)[Contract](#)[Branded Title](#)[Warranty Block](#)[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History](#)[Detail](#)[View Vehicle Delivery](#)[Information](#)

Required Field Actions

Open field actions are
highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N100023	10023	LOSS OF POWER STEERING ASSIST - REPLACE ELECTRIC POWER STEERING MOTOR	03/18/2010	Closed

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Refer to Help page for details. For OnStar contact 888.ON.STAR1 (888.687.6271) and for XM Radio contact 877.GET.XMST (877.438.9677).

OnStar Equipped: N

OnStar Status: NA

XM Equipped: Y

XM Radio ID: GH39R0MZ

XM Status: Inactive

OnStar Vehicle Diagnostics: N

DMN Enabled: N

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Emission Select Component Ltd Wty	02/21/2010	04/25/2007	8 MI	04/25/2015	80,008 MI
	Powertrain Limited Warranty	02/21/2010	04/25/2007	8 MI	04/25/2012	100,008 MI

Bumper to Bumper Limited Warranty	02/21/2010	04/25/2007	8 MI	04/25/2010	36,008 MI
Corrosion Limited Warranty	02/21/2010	04/25/2007	8 MI	04/25/2013	100,008 MI

Service Contract

Vehicle has no current record of service contracts.

Transaction History

[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
09/23/2010	214727	ZFAT—Field Action Recall		V2220 - 10023 - Replace Power Steering Assist Motor (including Test Drive)	30,179 MI
02/26/2010	204475	ZREG—Regular Vehicle Transaction		E2147 - Stabilizer Shaft Link Replacement - Both Sides	24,911 MI
01/03/2008	170860	ZREG—Regular Vehicle Transaction		H0122 - Front Brake Rotor Refinishing	7,161 MI
10/23/2007	167730	ZREG—Regular Vehicle Transaction		R4490 - Remote Control Door Lock Transmitter Replacement	5,452 MI
10/10/2007	167040	ZREG—Regular Vehicle Transaction		H0132 - Rear Brake Rotor Refinishing	5,216 MI
01/29/2007	A85623	ZPDI—Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

[Global Warranty Management](#) [Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

Global Warranty

Mr. GMVIS 2
January 18, 2011

[Logout](#)

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMERView Vehicle Build ?

This screen allows GMVIS users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN 1G1AM15B477 [REDACTED] Model 1AM37-2007 COBALT SS COUPE
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [0 Open](#) [REDACTED]

Vehicle Build

Model: 1AM37-2007 COBALT SS COUPE Order Number: KRTH8Q
 Gross Vehicle Weight: 1,757 Build Date: 01/29/2007
 Build Plant: 7-

For this vehicle:

- [View Vehicle Summary](#)
 - Service Contract
 - Branded Title
 - Warranty Block
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Option Codes

*GMVIS is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

19C - EBONY 1SS - 1SS BASE SS PACKAGE 41U - BLACK 7AC - FRONT SPRING 9AD - REAR SPRING ALD - SENSOR INDICATOR INFLATABLE RESTRAINT, FRT PASS/CHILD PRESENCE DETECTOR AR9 - DELUXE FRONT BUCKET SEAT AU3 - POWER DOOR LOCKS W/REMOTE KEYLESS ENTRY CF5 - POWER SUNROOF DG7 - BODY COLOR POWER MIRRORS FE9 - 50-STATE EMISSIONS IPC - INTERIOR TRIM DESIGN K84 - 115 AMP GENERATOR LOD - ASSEMBLY PLANT - LORDSTOWN, OHIO MX0 - TRANSMISSION, 4 SPD AUTOMATIC NT7 - FEDERAL EMISSION TIER 2 PFE - 17 X 7 ALUMINUM WHEEL R8K - ONSTAR R9F - PROCESSING CODE R9X - XM TRACKING CODE SLM - STOCK ORDERS U2K - XM SATELLITE RADIO-SERVICE FEE EXTRA 1ST 3 MONTHS INCL US8 - AM/FM STEREO, CD PLAYER & MP3 PLAYER VT7 - OWNERS MANUAL ENGLISH	19I - EBONY 1SZ - OPTION PACKAGE DISCOUNT 6AC - SUSPENSION COMPONENT 8AD - REAR SPRING AK5 - DRIVER & RIGHT FRONT PASSENGER AIR BAGS AP3 - REMOTE VEHICLE START AT6 - RESTRAINT PROVISIONS CHILD, RR SEAT, RR FACING C67 - ELECT. FRONT AIR CONDITIONER DC4 - INTERIOR REARVIEW MIRROR W/DUAL READING LAMPS FE3 - SPORT SUSPENSION FX2 - TRANS/AXLE 3.91 RATIO JL9 - 4-WHEEL DISC ANTI-LOCK BRAKE SYSTEM LE5 - 2.4L 4 CYL DOHC HIGH OUTPUT GAS ENGINE W/VVT MN5 - 4 SPEED AUTO TRANSMISSION N34 - 3 SPOKE LEATHER STEERING WHEEL NW7 - TRACTION CONTROL CBU - P205/50R17 BLACKWALL TIRES R6P - PREMIUM PAINT R9N - HEATED LEATHER APPOINTED FRONT BUCKET SEATS RE8 - UPGRADE ORNAMENTATION T43 - REAR SPOILER UQ3 - AUDIO SYSTEM, HIGH PERFORMANCE WITH 7 PIONEER SPEAKERS V73 - STATEMENT OF VEHICLE CERT.- U.S./CANADA
---	--

Added Option Codes

Vehicle has no current record of SAIO codes.

[Global Warranty Management Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved

 Global Warranty	Mr. GMVIS 2	Logout
January 18, 2011		

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMERView Vehicle Component Summary ?

This screen allows GMVIS users to view the information on various major components added to the VIN selected during vehicle build

Vehicle Information

VIN 1G1AM15B477 XXXXXXXXXX Model: 1AM37-2007 COBALT SS COUPE
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [Open](#) XXXXXXXXXX

For this vehicle:

- [View Vehicle Summary](#)
 - Service
 - Contract
 - Branded Title
 - Warranty Block
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY	Traceability: 701020033
Source Plant: S-	Part / Number Broadcast: AXF
Date Scanned: 01/27/2007	Time Scanned: 10:46:00 Scan Station: 04
Component Code: 61-TRANSMISSION	Traceability: 1WZJ
Source Plant: J-HYDRAMATIC WINDSOR, ONTARIO	Part / Number Broadcast: 7ELJ
Date Scanned: 01/27/2007	Time Scanned: 10:48:00 Scan Station: 04
Component Code: 74-ELECTRON BRAKE & TRACTION CTRL MOD ASM	Traceability: 0127G4087
Source Plant: P-	Part / Number Broadcast: 6488
Date Scanned: 01/27/2007	Time Scanned: 11:50:00 Scan Station: 04
Component Code: 88-ELECTRONIC CONTROL MODULE (ECM)	Traceability: 07012UE3Z
Source Plant: M-DELCO ELECTRONICS MILWAUKEE, WISCONSIN	Part / Number Broadcast: YNUN
Date Scanned: 01/27/2007	Time Scanned: 14:56:00 Scan Station: 08
Component Code: 87-BODY CONTROL MODULE	Traceability: A70170131
Source Plant: R-	Part / Number Broadcast: 6911
Date Scanned: 01/27/2007	Time Scanned: 14:56:00 Scan Station: 04
Component Code: AB-IR-MODULE ASM-INFLATOR	Traceability: 280191177
Source Plant: M-MORTON-THIOKOL	Part / Number Broadcast: 6196
Date Scanned: 01/27/2007	Time Scanned: 11:32:00 Scan Station: 04
Component Code: AL-IR-MODULE ASM-I/P	Traceability: G022E2336
Source Plant: I-INLAND	Part / Number Broadcast: 5692
Date Scanned: 01/27/2007	Time Scanned: 02:09:00 Scan Station: 04
Component Code: BK-INTERNATIONAL TRANS. CONTROL MODULE	Traceability: 070191138
Source Plant: K-	Part / Number Broadcast: YHRL
Date Scanned: 01/27/2007	Time Scanned: 14:56:00 Scan Station: 04
Component Code: CB-SEQ NUM (FLEX) BODY ASM	Traceability: 1600248
Source Plant: -	Part / Number Broadcast: 1ZZ
Date Scanned: 01/25/2007	Time Scanned: 06:34:00 Scan Station:

Service Agent Installed Component

Vehicle has no current record of vehicle component.

[Global Warranty Management Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.



Mr. GMVIS 2

[Logout](#)

January 18, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail



This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN 1G1AM15B477 [REDACTED] Model: 1AM37-2007 COBALT SS COUPE
 Service Contract No [REDACTED] Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [0 Open](#) [REDACTED]

For this vehicle:

[View Vehicle Summary](#)

→ Service
 → Contract

→ Branded Title
 → Warranty Block

[View Vehicle Build](#)

→ [View Vehicle
 Component Summary](#)

→ [View Vehicle
 Transaction History
 Detail](#)

→ [View Vehicle Delivery
 Information](#)

Job Card Date: 09/23/2010

Job Card Number: 214727

Repair Service Agent: 113496
 CENTURY III CHEVROLET, INC.
 2430 LEBANON CHURCH RD
 WEST MIFFLIN PA 15122-2555
 4124669210

Odometer Reading: 30,179 MI
 Authorization Code:

Process Date
 09/24/2010

Transaction Type:
 ZFAT---Field Action Recall
 Transaction Expense Category:
 Field Action Recall
 Customer Complaint Code:
 -

Job Card Line #: 1 Transaction Adjustment: Cause Code: -
 Labour Op V2220-10923 - Replace Power Steering Assist Motor (including Test Drive)
 Causal Part Number
 → [See other Parts and/or Net Items](#)

Line Total: USD 130.80

Job Card Date: 02/26/2010

Job Card Number: 204475

Repair Service Agent: 113496
 CENTURY III CHEVROLET, INC.
 2430 LEBANON CHURCH RD
 WEST MIFFLIN PA 15122-2555
 4124669210

Odometer Reading: 24,911 MI
 Authorization Code:

Process Date:
 03/01/2010

Transaction Type:
 ZREG---Regular Vehicle Transaction
 Transaction Expense
 Category
 Warranty

Customer Complaint Code
 0126-Drivability - Noise

Job Card Line #: 1 Transaction Adjustment: Cause Code: 6051-Module/Component -
 Worn/Stripped
 Labour Op E2147-Stabilizer Shaft Link Replacement - Both Sides

Causal Part Number 000000000020784888-LINKASM-FRTSTABSHF
 → [See other Parts and/or Net Items](#)

Line Total: USD 95.77

Job Card Date: 01/03/2008 Job Card Number: 170860
Repair Service Agent: 113496 Odometer Reading: 7,161 MI
CENTURY III CHEVROLET, INC. Authorization Code: B
2430 LEBANON CHURCH RD
WEST MIFFLIN PA 15122-2555
4124689210

Process Date:
01/03/2008
Transaction Type:
ZREG—Regular Vehicle Transaction
Transaction Expense Category:
Customer Complaint Code:
0000-Converted Claim
Job Card Line #: 1 Transaction Adjustment Cause Code: 0000-Converted Claims
Labour Op H0122-Front Brake Rotor Refinishing
Causal Part Number

Line Total: USD 131.76

Job Card Date: 10/23/2007 Job Card Number: 167730
Repair Service Agent: 113496 Odometer Reading: 5,452 MI
CENTURY III CHEVROLET, INC. Authorization Code:
2430 LEBANON CHURCH RD
WEST MIFFLIN PA 15122-2555
4124689210

Process Date:
10/26/2007
Transaction Type:
ZREG—Regular Vehicle Transaction
Transaction Expense Category:
Customer Complaint Code:
0000-Converted Claim
Job Card Line #: 1 Transaction Adjustment Cause Code: 0000-Converted Claims
Labour Op R4490-Remote Control Door Lock Transmitter Replacement
Causal Part Number
--See other Parts and/or Net Items

Line Total: USD 113.91

Job Card Date: 10/10/2007 Job Card Number: 167040
Repair Service Agent: 113496 Odometer Reading: 5,216 MI
CENTURY III CHEVROLET, INC. Authorization Code:
2430 LEBANON CHURCH RD
WEST MIFFLIN PA 15122-2555
4124689210

Process Date:
10/16/2007
Transaction Type:
ZREG—Regular Vehicle Transaction
Transaction Expense Category:
Customer Complaint Code:
0000-Converted Claim
Job Card Line #: 1 Transaction Adjustment Cause Code: 0000-Converted Claims
Labour Op H0132-Rear Brake Rotor Refinishing
Causal Part Number

Line Total: USD 142.04

Job Card Date: 01/29/2007
Repair Service Agent: 113496
CENTURY III CHEVROLET, INC.
2430 LEBANON CHURCH RD
WEST MIFFLIN PA 15122-2555
4124689210

Job Card Number: A89623

Odometer Reading: 0 MI
Authorization Code:

Process Date:
02/02/2007

Transaction Type:
ZPDI—Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1

Transaction Adjustment

Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

Line Total: USD 92.33

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.



Mr. GMVIS 2

[Logout](#)

January 18, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information



This screen allows GMVIS users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN 1G1AM15B477

Model: 1AM37-2007 COBALT SS COUPE

Service Contract: No

Branded Title: No

Warranty Block: No

PDI Status: No

Order Type: 70 - RETAIL - STOCK

Field Actions: [Open](#)

Invoice Information

Invoicing Service Agent: 113496
CENTURY III CHEVROLET, INC.
2430 LEBANON CHURCH RD
WEST MIFFLIN PA 15122-2555 4124669210

Invoice Date: 01/29/2007

Ship to Information

Invoicing Service Agent: 113496
CENTURY III CHEVROLET, INC.
2430 LEBANON CHURCH RD
WEST MIFFLIN PA 15122-2555 4124669210

Ship to Date: N/A

Delivery Information

Delivery Service Agent: 113496
CENTURY III CHEVROLET, INC.
2430 LEBANON CHURCH RD
WEST MIFFLIN PA 15122-2555 4124669210

Delivery Date: 04/25/2007
Delivery Type: 010—INDIVIDUAL
Delivery Odometer: 8

In Service Information

Invoicing Service Agent:

In Service Date: N/A
In Service Type: 0000
In Service Odometer: 0

For this vehicle:

[View Vehicle Summary](#)[Service Contract](#)[Branded Title](#)[Warranty Block](#)[View Vehicle Build](#)[View Vehicle](#)[Component Summary](#)[View Vehicle](#)[Transaction History Detail](#)[View Vehicle Delivery Information](#)

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

5

ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Joshua Preister
Claims Administrator

March 16, 2011

[REDACTED]
PITTSBURGH, PA [REDACTED]

RE: Claimant: [REDACTED]
 Our File No.: [REDACTED]
 Our Client: General Motors LLC
 Date/Event: 01/09/2011
 Vehicle: 2007 Chevrolet Cobalt
 VIN: 1G1AM15B477 [REDACTED]

Dear Mr. [REDACTED]

This will confirm that we have completed our review of your claim regarding your 2007 Chevrolet Cobalt. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Joshua Preister
Claims Administrator

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G1AM15B477 [REDACTED]
User	James Tisdale
Case Number	[REDACTED]
EDR Data Imaging Date	03/03/2011
Crash Date	02/02/2011
Filename	723644-[REDACTED]-1G1AM15B477 [REDACTED].ACM.CDRX
Saved on	Thursday, March 3 2011 at 13:56:42
Collected with CDR version	Crash Data Retrieval Tool 3.5
Reported with CDR version	Crash Data Retrieval Tool 3.5
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

Comments

Salvage Direct, Adamsburg, PA
DLC
No Key
No Lamp - No Key
Mileage 32,570
James Tisdale, ESIS/GM Field investigator

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM.

The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record up to 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip
- Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.
- Pre-Crash data is recorded asynchronously.
- Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:
 - the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
 - no data is received from the module sending the pre-crash data
 - no module is present to send the pre-crash data
- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMEps_r002

Multiple Event Data

Associated Events Not Recorded	1
An Event(s) Preceded the Recorded Event(s)	Yes
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	No
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	Yes

System Status At AE

Vehicle Identification Number	**1AM15B*7*
Low Tire Pressure Warning Lamp (If Equipped)	OFF
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Fourth Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	No
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	15
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	No	No
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	56	57	55	43	31
Engine Speed (RPM)	2496	2560	2048	1472	896
Percent Throttle	36	36	20	18	16
Accelerator Pedal Position (percent)	22	23	0	0	0
Antilock Brake System Active (If Equipped)	No	No	No	Yes	Yes
Lateral Acceleration (feet/s ²) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	0	0	0	0	0
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	7054
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	7053
Ignition Cycles At Event	7054
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	UNBUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Valid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	27.99
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	160
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Vehicle Event Data (Pre-Crash) Associated With This Event	No
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	-0.68	-0.68	-1.36	-2.71	-4.74	-8.13	-11.52	-17.62	-22.36	-25.75
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	-27.79	-27.79	-27.11	-26.43	-25.75	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	0.00	-0.68	-0.68	-1.36	-1.36	-2.03	-3.39	-3.39
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	-3.39	-2.71	-2.71	-2.71	-3.39	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 08 00 00 00 00 00 00
$02 30 00 00 00 00 00 00
$03 00 00 00 00 00 00 00
$04 00 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 0A 00 03 0A 00 00
$07 00 20 00 00 00 00 00
$08 00 00 00 00 00 00 00
$09 00 00 00 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 05 0F 00 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 40 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F 00 00 00 00 00 00 00
$10 00 00 00 00 00 00 00
$11 00 00 00 00 00 00 00
$12 00 00 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 00 00 00 00 00 00 00
$18 00 00 00 00 00 00 00
$19 00 00 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 02 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 00 00 00 00 00 00 00
$1F 28 00 00 00 00 00 00
$20 40 00 00 00 00 00 00
$21 00 00 00 00 F0 00 00
$22 00 A0 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 1B 8D 00 00
$2F 00 FE 1B 8E 00 00 00
$30 9D 00 00 00 00 00 00
$31 00 00 00 3B 39 00 00
$32 00 00 00 00 00 00 00
$33 29 2F 32 5C 5B 00 00
$34 0E 17 20 28 27 00 00
$35 32 46 59 5B 5A 00 00
$36 00 00 00 00 00 00 00
$37 C0 00 00 04 04 00 20
$38 3D 00 40 00 03 C0 00
$39 00 00 00 00 00 80 00
```

```

$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
$3D 31 41 4D 31 35 42 00
$3E 37 26 96 23 00 00 00
$3F 89 00 90 00 00 00 00
$40 00 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 1B 8D 00 00
$43 FE 1B 8E 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 00 00 FF 00 FF 00 00
$48 FF 00 FF 00 FF FF 00
$49 FF FF 00 FE FF FC 00
$4A FF F9 FE F4 FE EF 00
$4B FD E6 FB DF FB DA 00
$4C FB D7 FC D7 FC D8 00
$4D FC D9 FB DA 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 50 00 00 00 00 00 00
$52 00 00 00 00 00 00 00
$53 10 06 AA 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 32 39 35 31 52 36 33 32 37 33 47 38 50 56
$0E 01 5A 4B 31
$0F 41 4A 01 02 03 04 52 45 41 32 30 32 33 30 30 30
$10 01 02 03 04
$13 42 52 30 31 33 34 56 31 07 30 31 30 45 34 47 51

```

```
$14 01 5A 74 02
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 37 35 E1 72 6A 74 91 9A
$22 39 15
$23 31 41 FA FA FA FA FA
$24 31 41 FA FA FA FA FA
$25 32 41 FA FA FA FA FA
$26 32 41 FA FA FA FA FA
$40 00 00
$41 3F 00 00 02 00 1A
$42 D0 C4
$43 00 00 8E 80
$44 C6 00 00 FC C0 C0
$45 07 01 07 01 05 01
$46 FF 1B 1B 64 28
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 33 39 31 35 32 32 34 46 59 45 20 20 20 20
$B7 50 AA 04 0F 07
$B8 43 48 70 02 09
$C1 30 46 30 37
$CA 30 46 30 37
$CB 01 89 6E 6B
$CC 01 89 6E 6B
$D1 00 00
$DB 00 00
$DC 00 00
```

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.