


EWR D&I ANNOTATION



FAN-000001L112001DP499-7668

Artemis # : 000001L112001DP499**Record Created Date :** 01/24/2012**Printed Date :** 02/29/2012**Description :**

DI11-096 SEQUENCE ID 499. 2006 PONTIAC SOLSTICE. A GM SERVICE REQUEST DETAIL REPORT CONTAINS A CONTACT LOG REGARDING A SINGLE VEHICLE CRASH INVOLVING A 2006 PONTIAC SOLSTICE. THE CUSTOMER COMPLAINT LISTS THE PROBLEM BEING WITH THE REAR AXLE. THE CONSUMER STATES THAT WHILE DRIVING APPROXIMATELY 40 MPH THE REAR END "KICKED OUT" CAUSING THE CAR TO SPIN. THE CAR STRUCK A CURB AND SPUN AGAIN AND CAME TO REST ON A GRASSY MEDIAN. THE DRIVER WAS BELTED AND WENT TO THE HOSPITAL FOR NON-SPECIFIED HEAD AND BACK INJURIES. THE CAR SUSTAINED NO BODY DAMAGE BUT WAS TOTALED DUE TO UNDERCARRIAGE, FRAME, AND SUSPENSION DAMAGE. THE PROVIDED POLICE REPORT STATES THAT THE CONDITIONS WERE RAINY AT THE TIME OF THE CRASH. THE CONSUMER PURCHASED THE VEHICLE THREE WEEKS PRIOR AND WANTS TO CHECK FOR RECALLS ON THE VEHICLE. THE REPORT STATES THAT THERE ARE NO OPEN RECALLS; RECALL 07V589000 (N070204) IS REPORTED AS BEING CLOSED. THERE ARE SEVERAL VOQS REGARDING PROBLEMS WITH THE REAR DIFFERENTIAL. SOME OF THESE VOQS ALLEGE THIS PROBLEM CAUSED A LOSS OF CONTROL. *RC

Print

Close



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

September 28, 2011

Ms. Carmen Benavides
General Motors Corp.
Mail Code 480-210-2V1
30001 Van Dyke
Warren, MI 48090

NVS-217kb
DI11-096

Dear Ms. Benavides:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors Corp. (GM) in its light early warning report from 2nd quarter of 2011. We are writing to request additional information about the following incidents:

Selected Death and Injury Incidents	
For Reporting Category: L	
For the following Sequence IDs: 7, 23, 57, 79, 81, 83, 96, 99, 100, 101, 108, 109, 110, 146, 152, 155, 176, 183, 184, 185, 186, 187, 190, 192, 201, 204, 206, 208, 209, 226, 228, 257, 258, 259, 260, 261, 302, 303, 351, 372, 406, 410, 438, 449, 450, 451, 453, 475, 477, 499	

Unless otherwise stated in the text, the following definitions apply to these information requests:

Incident: each incident identified in the above table.

Claim and Notice: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

Vehicle: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.



Equipment: the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

Defect: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

Document: “Document(s)” is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM’s custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM’s response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
2. Provide a copy of the Police Accident Report.
3. At your option, provide GM’s assessment of the circumstances that led to the incident including GM’s analysis of the claim and/or notice regarding allegations of a defect.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590. GM is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted. Please remember that the words “CONFIDENTIAL BUSINESS INFORMATION” must appear at the top of each page containing information claimed to be confidential, and the information must be clearly identified in accordance with 5 U.S.C. § 512.6. If you submit a

request for confidentiality for all or part of your response to this letter, that is in an electronic format (e.g., CD-ROM), your request and associated submission must conform to the new requirements in NHTSA's Confidential Business Information Rule regarding submissions in electronic formats (49CFR 512.(c)). See Federal Register, volume 72, page 59434 (October 19, 2007).

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by **October 28, 2011**. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

A handwritten signature in black ink that reads "Christina Morgan". The script is cursive and fluid, with the first name "Christina" and last name "Morgan" clearly legible.

Christina Morgan, Chief
Early Warning Division
Office of Defects Investigation
Enforcement



GENERAL MOTORS LLC
Global Interior and Safety Center

October 28, 2011

OCT 28 2011

Ms. Christina Morgan, Chief
Early Warning Division, NVS-217
Office of Defects Investigation
National Highway Traffic Safety Administration
1200 New Jersey Ave., SE
Washington, DC 20590

NVS-217kb
DI11-096
Partial Response

Dear Ms. Morgan:

This is General Motors' (GM) partial response to your inquiry dated September 28, 2011, regarding certain death and injury incidents reported by GM in its light vehicle early warning report from the 2nd quarter of 2011.

GM's response is comprised of 48 disks for the incidents that are the subject of DI11-096.

Attachment "A" includes instructions for navigating the disk. Each disk, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 7 342947291-728355 and 2011 BUICK ENCLAVE. When the disk is launched, this identification number appears again along with all of the documents on the disk (including photographs and videos, if applicable) listed under "Filename". The first document listed under Filename is an index with the Request and Responses, e.g., identified as 7 342947291-728355_00_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the Inquiry and Response in the index
for the disk are as follows:

DI11-096
7 342947291-728355
2011 BUICK ENCLAVE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.



2. Provide a copy of the Police Accident Report.

Response: See attached documents and photographs.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

7 342947291-728355_01_001- is the first document responsive to Inquiry no.1.

7 342947291-728355_02_001- is the first document responsive to Inquiry no. 2.

Your inquiries and our corresponding replies are as follows:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See attached document.

The table below lists the incident that is the subject of DI11-096, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR) or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim". PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice". Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further.

(48 Vehicles from the Light Vehicle Template)		
SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
7	5GAKRBED5BJ	NISM
23	1G4HE5EM3AU	NISM
57	1G6DE5EYXB0	NISM
79	3GYFNDEY0AS	NISM
81	3GYFNDEY7BS	NISM
83	3GYFNBEY6BS	NISM
96	KL1TD56EX9B	NISM
99	KL1TD5DE3BB	NISM
100	KL1TD5DE2BB	NISM
101	KL1TD6DE0BB	NISM
108	2G1FC1ED8B9	NISM
109	2G1FC1ED9B9	NISM
110	2G1FK1EJ3B9	NISM

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
146*	UNKNOWN	LIT
152	1G1AL58F587	NISM
155*	UNKNOWN	LIT
176	1GCESCF91B8	NISM
183	1G1PH5S91B7	NISM
184	1G1PF5S95B7	NISM
185	1G1PC5SH0B7	NISM
186	1G1PG5S97B7	NISM
187	1G1PF5S96B7	NISM
190	1G1PC5SH4B7	NISM
192	2CNDL73F856	NISM
201	2CNDL737586	NISM
204	2CNALBEW0A6	NISM
206	2CNFLEEC3B6	NISM
208	2GNALBEC0B1	NISM
209	2GNALFEC3B1	NISM
226	3GNBACFU5BS	NISM
228	3GNBABFW7BS	NISM
257	2G1WB5EKXB1	NISM
258	2G1WA5EKXB1	NISM
259	2G1WB5EK4B1	NISM
260	UNKNOWN	NISM
261	2G1WG5EK8B1	NISM
302	1G1ZB5E17BF	NISM
303	1G1ZC5EU3BF	LIT
351	1GC4K1C81BF	NISM
372	1GNFC13087R	NISM
406	1GNKVGED7BJ	NISM
410	1G1RD6E48BU	NISM
438	2GTEK13V871	NISM
449	2CTALMEC6B6	NISM
450	2CTALMEC2B6	NISM
451	2CTALUEC2B6	NISM
453	2CTALMEC0B6	NISM
475	1G2ZG57B584	NISM
477	1G2ZH57N094	NISM
499	1G2MB33B36Y	NISM

* Sequence ID numbers 146 and 155 are not included in this partial response and will be sent at a later date as soon as the documents have been translated.

2. Provide a copy of the Police Accident Report.

Response: If available, see attached document(s) and photograph(s) on the enclosed disk(s).

- 3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.**

Response: GM opts not to respond.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs and evaluations by attorneys (and by consultants, claims analysts, investigators and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

Sincerely,




M. Carmen Benavides, Director
Product Investigations and Safety Regulations

Enclosures: 48 Disks
Attachment A

Attachment A

Instructions for using Disk Viewer

1. Insert the disk into the disk ROM drive; the disk will open automatically.
2. Click the "Run JPepper" button on the pop up window.



3. The program will launch in the browsing mode, which is shown in the image below.
4. You can use the down-arrow key on your keyboard to browse through the images.

Step 5: Select Page Icon

Step 5: Previous Page Icon (Ctrl +PgUp)

Step 5: Next Page Icon (Ctrl + PgDn)

Step 8: Scale Image Icons (F6, F7, & F8)

Step 4: Image List

**1997 CHEVROLET VENTURE
335 62588861-466779**

Request for Information:

1. Provide a copy of the claim or notice that notified General Motors of the incident, including any amendments and supplements thereto, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.
 Response: See Attached Documents
2. Provide a copy of all documents received from the claimant(s) or the claimant's representative that identify and/or support or purport to support any allegation of a defect in the vehicle, regardless of whether the General Motors disputes the assertions therein.
 Response: See Attached Documents
3. Provide a copy of all investigative documents prepared by any local, state or Federal governmental agency or personnel related to the incident, including but not limited to police accident report(s).
 Response: See Attached Documents
4. Provide a copy of all diagrams and drawings that relate to the incident, including post-incident reconstruction.
 Response: See #3
5. Provide a copy of all documents, photographs or videos that relate to the incident, or the vehicles involved in the incident, excluding materials related to the progression, cure, or rehabilitation of any injury.
 Response: See Attached Photographs and Attached Documents

- Each image file may contain multiple pages. In the browsing mode use **Next Page Icon (Ctrl + PgDn)**, **Select Page Icon** or **Previous Page Icon (Ctrl + PgUp)** to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages.)
- By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use **Ctrl + PgDn** or **Ctrl + PgUp** to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next Page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use **F5**, **F6**, **F7** and **F8** to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.

ATTORNEY OF PARTY MUST SIGN AND PRINT NAME AND ADDRESS OF OFFICE ERIC D. PARIS, ESQ., 5/85 167926 LAW OFFICES OF ERIC D. PARIS & ASSOCIATES 231 S. THOMAS STREET SUITE 402 POMONA, CALIFORNIA 91766 Telephone No: 909-469-5127 FAX: 909-469-5126 Attorney for Plaintiff		8-72 (Rev. 11-81) FOR COURT USE ONLY
SUPERIOR COURT FOR THE STATE OF CALIFORNIA INDIO COUNTY		
CASE NAME: CARDONA V. CHEVROLET		
CIVIL CASE COVER SHEET ☐ Unfiled ☒ (3) Unfiled	Check Case Designation: ☐ Civil ☐ Juvenile Filed with last appearance by defendant (C.C. Rules of Court, rule 181)	CASE NUMBER: ASSIGNED JUDGE:
Please complete all five (5) items below		
1. Check one (1) below for the case type that best describes this case: A. Civil ☒ A.1 (2) Other Person's Personal Injury/Property Damages/Contract Breach Tort ☐ A.2 (4) Plaintiff's Injury ☐ A.3 (4) Plaintiff's Injury ☐ A.4 (4) Plaintiff's Injury ☐ A.5 (4) Plaintiff's Injury ☐ A.6 (4) Plaintiff's Injury ☐ A.7 (4) Plaintiff's Injury ☐ A.8 (4) Plaintiff's Injury ☐ A.9 (4) Plaintiff's Injury ☐ A.10 (4) Plaintiff's Injury ☐ A.11 (4) Plaintiff's Injury ☐ A.12 (4) Plaintiff's Injury ☐ A.13 (4) Plaintiff's Injury ☐ A.14 (4) Plaintiff's Injury ☐ A.15 (4) Plaintiff's Injury ☐ A.16 (4) Plaintiff's Injury ☐ A.17 (4) Plaintiff's Injury ☐ A.18 (4) Plaintiff's Injury ☐ A.19 (4) Plaintiff's Injury ☐ A.20 (4) Plaintiff's Injury ☐ A.21 (4) Plaintiff's Injury ☐ A.22 (4) Plaintiff's Injury ☐ A.23 (4) Plaintiff's Injury ☐ A.24 (4) Plaintiff's Injury ☐ A.25 (4) Plaintiff's Injury ☐ A.26 (4) Plaintiff's Injury ☐ A.27 (4) Plaintiff's Injury ☐ A.28 (4) Plaintiff's Injury ☐ A.29 (4) Plaintiff's Injury ☐ A.30 (4) Plaintiff's Injury ☐ A.31 (4) Plaintiff's Injury ☐ A.32 (4) Plaintiff's Injury ☐ A.33 (4) Plaintiff's Injury ☐ A.34 (4) Plaintiff's Injury ☐ A.35 (4) Plaintiff's Injury ☐ A.36 (4) Plaintiff's Injury ☐ A.37 (4) Plaintiff's Injury ☐ A.38 (4) Plaintiff's Injury ☐ A.39 (4) Plaintiff's Injury ☐ A.40 (4) Plaintiff's Injury ☐ A.41 (4) Plaintiff's Injury ☐ A.42 (4) Plaintiff's Injury ☐ A.43 (4) Plaintiff's Injury ☐ A.44 (4) Plaintiff's Injury ☐ A.45 (4) Plaintiff's Injury ☐ A.46 (4) Plaintiff's Injury ☐ A.47 (4) Plaintiff's Injury ☐ A.48 (4) Plaintiff's Injury ☐ A.49 (4) Plaintiff's Injury ☐ A.50 (4) Plaintiff's Injury ☐ A.51 (4) Plaintiff's Injury ☐ A.52 (4) Plaintiff's Injury ☐ A.53 (4) Plaintiff's Injury ☐ A.54 (4) Plaintiff's Injury ☐ A.55 (4) Plaintiff's Injury ☐ A.56 (4) Plaintiff's Injury ☐ A.57 (4) Plaintiff's Injury ☐ A.58 (4) Plaintiff's Injury ☐ A.59 (4) Plaintiff's Injury ☐ A.60 (4) Plaintiff's Injury ☐ A.61 (4) Plaintiff's Injury ☐ A.62 (4) Plaintiff's Injury ☐ A.63 (4) Plaintiff's Injury ☐ A.64 (4) Plaintiff's Injury ☐ A.65 (4) Plaintiff's Injury ☐ A.66 (4) Plaintiff's Injury ☐ A.67 (4) Plaintiff's Injury ☐ A.68 (4) Plaintiff's Injury ☐ A.69 (4) Plaintiff's Injury ☐ A.70 (4) Plaintiff's Injury ☐ A.71 (4) Plaintiff's Injury ☐ A.72 (4) Plaintiff's Injury ☐ A.73 (4) Plaintiff's Injury ☐ A.74 (4) Plaintiff's Injury ☐ A.75 (4) Plaintiff's Injury ☐ A.76 (4) Plaintiff's Injury ☐ A.77 (4) Plaintiff's Injury ☐ A.78 (4) Plaintiff's Injury ☐ A.79 (4) Plaintiff's Injury ☐ A.80 (4) Plaintiff's Injury ☐ A.81 (4) Plaintiff's Injury ☐ A.82 (4) Plaintiff's Injury ☐ A.83 (4) Plaintiff's Injury ☐ A.84 (4) Plaintiff's Injury ☐ A.85 (4) Plaintiff's Injury ☐ A.86 (4) Plaintiff's Injury ☐ A.87 (4) Plaintiff's Injury ☐ A.88 (4) Plaintiff's Injury ☐ A.89 (4) Plaintiff's Injury ☐ A.90 (4) Plaintiff's Injury ☐ A.91 (4) Plaintiff's Injury ☐ A.92 (4) Plaintiff's Injury ☐ A.93 (4) Plaintiff's Injury ☐ A.94 (4) Plaintiff's Injury ☐ A.95 (4) Plaintiff's Injury ☐ A.96 (4) Plaintiff's Injury ☐ A.97 (4) Plaintiff's Injury ☐ A.98 (4) Plaintiff's Injury ☐ A.99 (4) Plaintiff's Injury ☐ A.100 (4) Plaintiff's Injury ☐ A.101 (4) Plaintiff's Injury ☐ A.102 (4) Plaintiff's Injury ☐ A.103 (4) Plaintiff's Injury ☐ A.104 (4) Plaintiff's Injury ☐ A.105 (4) Plaintiff's Injury ☐ A.106 (4) Plaintiff's Injury ☐ A.107 (4) Plaintiff's Injury ☐ A.108 (4) Plaintiff's Injury ☐ A.109 (4) Plaintiff's Injury ☐ A.110 (4) Plaintiff's Injury ☐ A.111 (4) Plaintiff's Injury ☐ A.112 (4) Plaintiff's Injury ☐ A.113 (4) Plaintiff's Injury ☐ A.114 (4) Plaintiff's Injury ☐ A.115 (4) Plaintiff's Injury ☐ A.116 (4) Plaintiff's Injury ☐ A.117 (4) Plaintiff's Injury ☐ A.118 (4) Plaintiff's Injury ☐ A.119 (4) Plaintiff's Injury ☐ A.120 (4) Plaintiff's Injury ☐ A.121 (4) Plaintiff's Injury ☐ A.122 (4) Plaintiff's Injury ☐ A.123 (4) Plaintiff's Injury ☐ A.124 (4) Plaintiff's Injury ☐ A.125 (4) Plaintiff's Injury ☐ A.126 (4) Plaintiff's Injury ☐ A.127 (4) Plaintiff's Injury ☐ A.128 (4) Plaintiff's Injury ☐ A.129 (4) Plaintiff's Injury ☐ A.130 (4) Plaintiff's Injury ☐ A.131 (4) Plaintiff's Injury ☐ A.132 (4) Plaintiff's Injury ☐ A.133 (4) Plaintiff's Injury ☐ A.134 (4) Plaintiff's Injury ☐ A.135 (4) Plaintiff's Injury ☐ A.136 (4) Plaintiff's Injury ☐ A.137 (4) Plaintiff's Injury ☐ A.138 (4) Plaintiff's Injury ☐ A.139 (4) Plaintiff's Injury ☐ A.140 (4) Plaintiff's Injury ☐ A.141 (4) Plaintiff's Injury ☐ A.142 (4) Plaintiff's Injury ☐ A.143 (4) Plaintiff's Injury ☐ A.144 (4) Plaintiff's Injury ☐ A.145 (4) Plaintiff's Injury ☐ A.146 (4) Plaintiff's Injury ☐ A.147 (4) Plaintiff's Injury ☐ A.148 (4) Plaintiff's Injury ☐ A.149 (4) Plaintiff's Injury ☐ A.150 (4) Plaintiff's Injury ☐ A.151 (4) Plaintiff's Injury ☐ A.152 (4) Plaintiff's Injury ☐ A.153 (		

Step 7: Next File (Image)

Step 7: Next Page

Step 8: Scale Image

Step 7: Image Properties

DI11-096
499 342947977-730167
2006 PONTIAC SOLSTICE

Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Documents.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: See Attached Document. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Service Request Detail

SR No.	(b) (6)	Ref No.	Goodwill	No Goodwill Offered	BRC Type	PAR
Account		Site	GW SubType		Bus. Unit	BRC
Last Name		First Name	Approval	Not Initiated	Area	PAR
Daytime #		Evening #	UCC	Axle - Complete Rear End Assembly	Sub-Area	Initiate PAR- Injury
Address		City	Involved Dir		Safety	Yes
State	NJ	ZipCd	Source	Phone	Updated	6/24/2011 03:13:22 PM
Serial #/VIN	1G2MB33B36Y	Model Year	2006	Priority	Medium	License # PONTIAC
Make	Pontiac	Warr. Start	12/17/2005	Status	Open	Opened
Model	Solstice	Mileage	13425	Sub-Status	Dissatisfied	Closed
Abstract	Rear axle kicked in and caused accident on veh					
Customer Description	***This is a BRC PAR Case. Please do not assume. Forward any inquiries to Rita Sanchez at ext.31227 ***					

Pre-PAR

PAR Notifier	Incident Date/Time	Injuries	# Other Veh	# People in Veh	Road Surface	Road Cond.	Fire Report#	Police Report#
Owner	6/17/2011 06:00:46 PM	Y	0	1	Asphalt	Wet	na	unk
Driver Last Name	Driver First Name	Height	DOB	Disabilities				
		54		na				
Insurance Agent Last Name	Insurance Agent First Name	Phone #	Insurance Agency					
unk	unk	(800) 691-4312	Geico					
Incident Loc	route 80 in paterson New Jersey	Incident Desc	I was driving and the rear of the vehicle kicked out and spun when i was going 40 mph and i hit a curb and then the vehicle spun again and I landed on a grass median.					
Component	rear axle	Damage Desc	no body damage simple under carriage damage					
Vehicle Loc	body shop in wyckoff new jersey	Addl Info	n/a					
Emgcy Svc Names	New Jersey State Police	Maint Loc	na					

PAR Detail

Collision	Y	Non Collision	Property Damage	N	Thermal Evt	N	Spec Equip	na
Vehicle Speed	40	Weather Condition	rained previously	Prop Owner	na	Property Type	na	
Last Service Date		Loc Last Service		Property Location	na	Prop Est Repair Cost	\$0.00	
Veh Est Repair Cost	\$0.00	Spec Equip Installer	na	Prop Damage Description	na	Inspected By	Inspection Not Performed	Inspection Date/Time
Primary Veh Use	Personal	Inspection Type	Axle, Wheels and Tires Sys	Inspected By	Inspection Not Performed	Inspection Date/Time		
Veh Damage Description	under carriage damage	Explain Other	sent to esis					

Service Request Detail

PAR Injuries

Last Name	First Name	DOB	Location	Phone #	Seating Pos	Restraint Type
		07/01/82	Occupant of Owner's Vehicle		Driver	seatbelt
Injury Description		Medical Rpt#		Treatment Location		Treated By
head and back injury		na		saint joes hospital		Er Doctor
Street Address		City	State	Zip Code		
		Riverdale	NJ			

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/24/2011 03:17:46 PM	GARCIAJR	GARCIAJR	Escalation	ESIS - Injuries	In Progress		Injuries - ESIS
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

head and back injury - went to saint joes hospital

Joe G/PAR/ATX

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/24/2011 03:13:33 PM	GARCIAJR	ESISBIQU	Escalation	ESIS - Property Damage	Done	6/24/2011 03:17:37 PM	Property damage - ESIS
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 01:05:32 PM	SANCHERI	SANCHERI	BRC PAR	Business Case	Done	6/23/2011 01:06:10 PM	
Contact Last Name	Contact First Name		Account		BAC Code		

Comments

axel concern - injury

rita sanchez/ATXPAR

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 01:02:45 PM	SANCHERI	SANCHERI	Scheduled Follow-up	Scheduled Alarm			fu esls pick up

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 01:02:28 PM	SANCHERI	GARCIAJR	Notify CRM		Done	6/24/2011 03:13:27 PM	esls - injury

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:56:36 AM	SANCHERI	SANCHERI	Ownership Changed	Ownership Escalated to BRC	Done	6/23/2011 11:56:36 AM	Ownership Escalated to BRC

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:53:27 AM	SANCHERI	SANCHERI	Ownership Changed		Done	6/23/2011 11:53:27 AM	Service Request Ownership has changed FROM: TROGOJO TO: SANCHERI

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:21:29 AM	SANCHERI	SANCHERI	BRC PAR	Initial Contact- AVM	Done	6/23/2011 01:02:25 PM	callTom Schen 732-282-3504

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

This is Rita Sanchez calling from gm par dept.

Customer: 71-960466648

Service Request:

Vehicle information: 2009 Pontiac

Last 8 of the VIN: 6Y

Involved Dealership: none

Nature of allegation: axle concern

CRS adv if you have any additional information pertaining to customer or vehicle please contact me at 1-888-790-5600 X 31227 If not then this is an FYI to let you know what is going on in your district.

Rita Sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:21:25 AM	SANCHERI	SANCHERI	BRC PAR	Initial Contact- Dealer	Done	6/23/2011 11:55:29 AM	call

Contact Last Name	Contact First Name	Account	BAC Code
-------------------	--------------------	---------	----------

Comments

No need to call Dir. Vehicle beyond warranty and has not been to dealer in two years.

Rita Sanchez/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:21:03 AM	SANCHERI	SANCHERI	BRC PAR	Initial Contact- Phone	Done	6/23/2011 11:52:20 AM	call
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

verified information and allegation

provided esis information

crs sts i will proceed

crs sts what happen

cust sts i was driving and the rear of the vehicle kicked out and spun when i was going 40 mph and i hit a curb and then the vehicle spun again and i landed on a grass median.
i was injured and went to the hospital

crs sts ok what i will do is get this over to our central claims department and they will contact up with you within 7-10 business days

cust sts ok

rita sanchez/ATX/PAR

Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:20:50 AM	SANCHERI	SANCHERI	Research		Done	6/23/2011 12:59:14 PM	vin 1G2MB33B35Y
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

CRS Performed VIN Scan

GMVIS:Found No Open Recalls Product Safety Recall N070204 07204 DRIVE AXLE PINION SEAL LEAK - REPLACE SEAL 01/31/2008 Closed

VIN: -- Found No Duplicate File

SVC History: No Service History Related to Allegation

Rita Sanchez/PAR/ATX

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:19:24 AM	SANCHER	SANCHER	BRC PAR	Acknowledgement	Done	6/23/2011 11:43:40 AM	call
Contact Last Name	Contact First Name	Account	BAC Code				

Comments
see initial

rita sanchez/ATX/PAR
Confidential Comments

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:15:46 AM	SANCHER	SANCHER	BRC PAR	Case Assigned	Done	6/23/2011 11:21:59 AM	File assigned to Rita Sanchez @ ext 31227
Contact Last Name	Contact First Name	Account	BAC Code				

Comments

Confidential Comments

Service Request Detail

Activities

Created	Created By	Assigned To	Activity Type	Activity Sub-Type	Status	Completed	Description
6/23/2011 11:11:27 AM	TROGOJO	TROGOJO	Inbound Call Customer	Complex Request	Done	6/23/2011 11:11:44 AM	Complaint Veh

Contact Last Name	Contact First Name	Account	BAC Code

Comments

Cust States:

- have pontiac solstice
- would like to check for recalls
- got into an accident because rear end kicked out and veh spun
- cust lost control on veh and caused an accident
- veh was totalled but suspension frame and everything underneath veh was damage
- this is a total loss considering veh just purchased 3 weeks ago

*Customer Name

*VIN 1g2mb33b36y

*Mileage 13425

*BNTC

*BTTG

*Address ct nj

Cust Seeks:

- Complaint veh

CRS Adv:

- informed cust that veh not included under any open recalls
- gave SR number
- will forward case to Par

Joseph/Mla/CAC T1/ Lvl 1

Confidential Comments

UCC Information

UCC Code	Symptom	Description
G24	Broken	Axle - Complete Rear End Assembly



June 27, 2011

Logout

Global Warranty Management: Main > Interface With Customer > View Vehicle Summary

INTERFACE WITH
CUSTOMER

View Vehicle Summary

This screen allows IVH users to view the Summary of Vehicle Information, Field Actions, Service Information, Applicable Warranties, Transaction History, Service Contract(s) if applicable, Warranty Block, Branded Title information and OnStar and XM Radio information (if applicable).

For this vehicle:

→ [View Vehicle Summary](#)

- Service Contract
- Branded Title
- Warranty Block

→ [View Vehicle Build](#)→ [View Vehicle Component Summary](#)→ [View Vehicle](#)→ [Transaction History Detail](#)→ [View Vehicle Delivery Information](#)

Vehicle Information

VIN: 1G2MB33B36Y Model: 2MB67-2006 SOLSTICE 2 DR. CONVERTIBLE
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 60 - RETAIL - SOLD
 Field Actions: [0 Open](#)

13 OUT OF 4000000 MINS

Required Field Actions

Open field actions are
highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N070204	07204	DRIVE AXLE PINION SEAL LEAK - REPLACE SEAL	01/31/2008	Closed

Branded Title

*The VIN information contained herein and information derived therefrom is the proprietary property of The Polk Company and is to be used only for the purpose of warranty verification and shall not be used for any other purpose whatsoever.

Vehicle has no current record of branded titles.

Warranty Block

Vehicle has no current record of warranty block.

Service Information

Vehicle has no current record of outstanding service information.

OnStar and XM Satellite Radio Information

Vehicle has no current record of OnStar / XM Radio Information.

Applicable Warranties

Valid warranties are highlighted

Valid	Description	Warranty Add Date	Start Date	Effective Odometer	End Date	End Odometer
	Bumper to Bumper Limited Warranty	06/02/2011	12/22/2005	14 MI	12/22/2008	36,014 MI
	Special Coverage 08300	06/02/2011	12/22/2005	14 MI	12/22/2015	120,014 MI
	Certified Used Powertrain Limited Wty	06/02/2011	12/22/2005	14 MI	12/22/2010	100,014 MI
	Certified Used Limited Warranty	06/02/2011	05/30/2009	4,789 MI	05/30/2010	16,799 MI
	Emission Select	06/02/2011	12/22/2005	14 MI	12/22/2013	80,014 MI

<http://gmvis2.gotd.gm.com/gmvis2/showVehicleHistorySummary.do?vin=1G2MB33B36...> 6/27/2011

Component Ltd Wty					
Corrosion Limited	06/02/2011	12/22/2005	14 MI	12/22/2011	100,014 MI
Warranty					

Service Contract

Vehicle has no current record of service contracts.

Transaction History

[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
06/18/2008	203293	ZREG---Regular Vehicle Transaction		R4490 - Remote Control Door Lock Transmitter Replacement	4,674 MI
02/20/2008	200851	ZFAT---Field Action Recall		V1777 - 07204 - Replace Rear Differential Seal Only	4,650 MI
06/12/2007	195576	ZREG---Regular Vehicle Transaction		F2023 - Seal, Pinion Shaft Oil - Rear Differential - Replace	4,337 MI
10/11/2006	190192	ZREG---Regular Vehicle Transaction		B5490 - Rear Compartment Lid Latch Striker Replacement	3,277 MI
11/17/2005	A05608	ZPDI---Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.



June 27, 2011

[Logout](#)

Global Warranty Management: Main > Interface With Customer > View Vehicle Build

INTERFACE WITH
CUSTOMER

View Vehicle Build



This screen allows IVH users to view the initial build information on the selected VIN including option codes with descriptions (where available).

Vehicle Information

VIN: 1G2MB33B36Y [REDACTED] Model: 2MB67-2006 SOLSTICE 2 DR. CONVERTIBLE
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 60 - RETAIL - SOLD
 Field Actions: [0 - Open](#) [1 - Closed](#) [2 - Other VIN](#)

For this vehicle:

→ [View Vehicle Summary](#)

- Service Contract
- Branded Title
- Warranty Block

→ [View Vehicle Build](#)→ [View Vehicle Component Summary](#)→ [View Vehicle](#)→ [Transaction History Detail](#)→ [View Vehicle Delivery Information](#)

Vehicle Build

Model: 2MB67-2006 SOLSTICE 2 DR. CONVERTIBLE Order Number: JCRQF2
 Gross Vehicle Weight: 1,491 Build Date: 11/17/2005
 Build Plant: Y-

Option Codes

*IVH is not the definitive source of GM Vehicle RPO information and is intended for service reference only. Should there be any questions about the vehicle's original build or RPO information please refer to the original vehicle invoice or window sticker.

192 - EBONY	19I - TRIM, EBONY
19T - CONVERTIBLE TOP	1SA - OPTION GROUP - 1SA
1SZ - OPTION PACKAGE DISCOUNT	50U - PURE (WHITE)
A31 - POWER WINDOWS	A50 - FRONT SEAT, BUCKET
AU0 - REMOTE KEYLESS ENTRY	AU3 - POWER DOOR LOCKS
B32 - CARPETED FRONT FLOORMATS	C60 - AIR CONDITIONING
D48 - OUTSIDE MIRROR	E2C - ORDER TO DELIVERY - EXPEDITE
FE2 - SUSPENSION SYSTEM, HANDLING	FE9 - 50-STATE EMISSIONS
G80 - LTD SLIP REAR DIFFERENTIAL	GW1 - 3.91 REAR AXLE RATIO
IP2 - TRIM INTERIOR DESIGN	JL9 - 4-WHEEL ANTILOCK BRAKES
K34 - CRUISE CONTROL	KG7 - GENERATOR 125 AMP
LE5 - ECOTEC 2.4L DOHC ALUM ENGINE	MA5 - MANUAL TRANSMISSION
MM5 - TRANSMISSION, 5-SPEED MANUAL	N34 - LEATHER STEERING WHEEL
NT9 - FED EMIS SYS, TIER 2 PHASE-OUT	PCQ - PREMIUM PACKAGE *LEATHER SEATING SURFACES *LEATHER WRAPPED STEERING WHEEL *REDUNDANT RADIO CONTROLS
QF8 - 18" POLISHED ALUMINUM WHEELS (REPLACES STD/OPT WHEELS)	QFX - P245/45R18-96V BW TIRE
R6P - PREMIUM PAINT	R9N - LEATHER SEAT TRIM
R9U - GM ACCESS - AUTOBOOK IDENTIFIER	R9Z - POMS EXPEDITE-SOLD ORDERS/TSE
SLL - SALES SOLD ORDERS	T96 - LAMPS, FOG
U68 - DRIVER INFORMATION CENTER	UK3 - STEERING WHEEL WRADIO CONTROLS
UQ3 - MONSOON PREMIUM AUDIO SYSTEM	US6 - FIXED ANTENNA
US8 - AM/FM RADIO W/CD & MP3 PLAYER (REPLACES STD/OPT RADIO)	V73 - VEHICLE CERTIFICATION U.S.
VK3 - LICENSE PLATE BRACKET, FRONT	VY7 - KNOB-SHIFTER LEVER, LEATHER
WIL - WILMINGTON PLANT	ZQ2 - POWER PACKAGE *POWER DOOR LOCKS *REMOTE KEYLESS ENTRY *POWER WINDOWS *OUTSIDE REARVIEW PWR MIRRORS
ZQ3 - CONVENIENCE PACKAGE *CRUISE CONTROL *DRIVER INFORMATION CENTER *STEERING WHEEL MOUNTED CRUISE & DRIVER INFO. CENTER CONTROLS *INTEGRATED FRONT FOG LAMPS	

[http://gmvis2.gotd.gm.com/gmvis2/showVehicleBuild.do?VIN=1G2MB33B36Y\[REDACTED\]&...](http://gmvis2.gotd.gm.com/gmvis2/showVehicleBuild.do?VIN=1G2MB33B36Y[REDACTED]&...) 6/27/2011

Added Option Codes

~AR - SPECIAL COVERAGE APPLIED

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.



June 27, 2011

Logout

Global Warranty Management: Main > Interface With Customer > View Vehicle Component Summary

INTERFACE WITH
CUSTOMER

View Vehicle Component Summary

This screen allows IVH users to view the information on various major components added to the VIN selected during vehicle build.

Vehicle Information

VIN: 1G2MB33B36Y [REDACTED] Model: 2MB67-2006 SOLSTICE 2 DR. CONVERTIBLE
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 60 - RETAIL - SOLD
 Field Actions: [Open](#)

[REDACTED]

For this vehicle:

→ [View Vehicle Summary](#)

- Service Contract
- Branded Title
- Warranty Block

→ [View Vehicle Build](#)→ [View Vehicle Component Summary](#)→ [View Vehicle Transaction History Detail](#)→ [View Vehicle Delivery Information](#)

Vehicle Component

Component Code: 10-ENGINE ASSEMBLY	Traceability: 510310224
Source Plant: S-	Part / Number Broadcast: TAJ
Date Scanned: 11/17/2005	Time Scanned: 01:12:00 Scan Station: 03
Component Code: 50-INSTRUMENT CLUSTER	Traceability: 052880003
Source Plant: A-	Part / Number Broadcast: 5581
Date Scanned: 11/17/2005	Time Scanned: 21:43:00 Scan Station: 13
Component Code: 61-TRANSMISSION	Traceability: 050830035
Source Plant: 8-	Part / Number Broadcast: GCBY
Date Scanned: 11/17/2005	Time Scanned: 01:12:00 Scan Station: 04
Component Code: 86-ELECTRONIC CONTROL MODULE (ECM)	Traceability: 053076BD4
Source Plant: M-DELCO ELECTRONICS MILWAUKEE, WISCONSIN	Part / Number Broadcast: YMXB
Date Scanned: 11/17/2005	Time Scanned: 21:43:00 Scan Station: 01
Component Code: 87-BODY CONTROL MODULE	Traceability: A53020308
Source Plant: R-	Part / Number Broadcast: 8782
Date Scanned: 11/17/2005	Time Scanned: 21:43:00 Scan Station: 10
Component Code: 92-BRAKE PRESSURE MODULATOR VALVE ASSEMBLY	Traceability: U5F27A27
Source Plant: P-	Part / Number Broadcast: 5365
Date Scanned: 11/17/2005	Time Scanned: 21:43:00 Scan Station: 14
Component Code: AB-IR-MODULE ASM-INFLATOR	Traceability: 311550037
Source Plant: Z-BREED, MEXICO	Part / Number Broadcast: 4060
Date Scanned: 11/17/2005	Time Scanned: 12:07:00 Scan Station: 02
Component Code: AH-IR-SENSOR ASM-LEFT	Traceability: 520810C28
Source Plant: R-SIEMENS	Part / Number Broadcast: 5200
Date Scanned: 11/17/2005	Time Scanned: 21:43:00 Scan Station: 12
Component Code: AJ-IR-SENSOR ASM-RIGHT	Traceability: 525220E22
Source Plant: R-SIEMENS	Part / Number Broadcast: 5200
Date Scanned: 11/17/2005	Time Scanned: 21:43:00 Scan Station: 11
Component Code: AL-IR-MODULE ASM-I/P	Traceability: G312C2530
Source Plant: I-INLAND	Part / Number Broadcast: 4989
Date Scanned: 11/17/2005	Time Scanned: 08:25:00 Scan Station: 06
Component Code: AS-SENSING DIAGNOSTIC MODULE	Traceability: 1082B

http://gmvis2.gotd.gm.com/gmvis2/showVehicleComponent.do?VIN=1G2MB33B36Y [REDACTED]

6/27/2011

Source Plant: 2-	Part / Number Broadcast: 8918
Date Scanned: 11/17/2005	Time Scanned: 21:43:00 Scan Station: 05
Component Code: CB-SEQ NUM (FLEX) BODY ASM	Traceability: 0590172
Source Plant: -	Part / Number Broadcast: 1CC
Date Scanned: 11/08/2005	Time Scanned: 02:31:00 Scan Station:
Component Code: CC-SEQ NUM (FLEX) BODY ASM	Traceability: 161008373
Source Plant: -	Part / Number Broadcast: BSSN
Date Scanned: 11/12/2005	Time Scanned: N/A Scan Station: 08
Component Code: CF-SEQ NUM (FLEX) PAINT PROCESS	Traceability: 0006752
Source Plant: -	Part / Number Broadcast: 1BB
Date Scanned: 11/16/2005	Time Scanned: 13:15:00 Scan Station:
Component Code: CG-SEQ NUM (FLEX) PAINT PROCESS	Traceability: 161008373
Source Plant: -	Part / Number Broadcast: BSSN
Date Scanned: 11/15/2005	Time Scanned: 10:30:00 Scan Station: 09
Component Code: CP-SEQ NUM (FLEX) GEN ASM	Traceability: 1006701
Source Plant: -	Part / Number Broadcast: 1AZ
Date Scanned: 11/16/2005	Time Scanned: 16:47:00 Scan Station:
Component Code: CZ-SEQ NUM (FLEX) GEN ASM	Traceability: 161008373
Source Plant: -	Part / Number Broadcast: BSSN
Date Scanned: 11/17/2005	Time Scanned: 22:25:00 Scan Station: 07

Service Agent Installed Component

Vehicle has no current record of vehicle component.

Global Warranty Management Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.


[Logout](#)

June 27, 2011

Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail

③

This screen allows IVH users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN: 1G2MB33B36Y [REDACTED] Model: 2MB67-2006 SOLSTICE 2 DR. CONVERTIBLE
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
 Order Type: 60 - RETAIL - SOLD
 Field Actions: [0 Open](#)

[REDACTED]

For this vehicle:

- [View Vehicle Summary](#)
 - Service Contract
 - Branded Title
 - Warranty Block
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

Job Card Date: 06/18/2008

Job Card Number: 203293

Repair Service Agent: 162337
 CLEMONS, INC
 2909 S CENTER
 MARSHALLTOWN IA 50158-4711
 6417525491

Odometer Reading: 4,674 MI
 Authorization Code:

Process Date:
 06/20/2008

Transaction Type:
 ZREG---Regular Vehicle Transaction
 Transaction Expense Category:

Customer Complaint Code:
 0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment: Cause Code: 0000-Converted Claims
 Labour Op R4490-Remote Control Door Lock Transmitter Replacement
 Causal Part Number

Job Card Date: 02/20/2008

Job Card Number: 200851

Repair Service Agent: 162337
 CLEMONS, INC
 2909 S CENTER
 MARSHALLTOWN IA 50158-4711
 6417525491

Odometer Reading: 4,650 MI
 Authorization Code:

Process Date:
 02/26/2008

Transaction Type:
 ZFAT---Field Action Recall
 Transaction Expense Category:

Customer Complaint Code:
 0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment: Cause Code: 0000-Converted Claims
 Labour Op V1777-07204 - Replace Rear Differential Seal Only
 Causal Part Number

→ See other Parts and/or Net Items

Job Card Date: 06/12/2007

Job Card Number: 195576

Repair Service Agent: 162337
 CLEMONS, INC

Odometer Reading: 4,337 MI
 Authorization Code:

2909 S CENTER
MARSHALLTOWN IA 50158-4711
6417525491

Process Date:
06/22/2007

Transaction Type:
ZREG---Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment: Cause Code: 0000-Converted Claims

Labour Op F2023-Seal, Pinion Shaft Oil - Rear Differential - Replace

Causal Part Number

→See other Parts and/or Nel Items

Job Card Date: 10/11/2006

Job Card Number: 190192

Repair Service Agent: 162337

Odometer Reading: 3,277 MI

CLEMONS, INC

Authorization Code:

2909 S CENTER

MARSHALLTOWN IA 50158-4711

6417525491

Process Date:
10/17/2006

Transaction Type:
ZREG---Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment: Cause Code: 0000-Converted Claims

Labour Op B5490-Rear Compartment Lid Latch Striker Replacement

Causal Part Number

Job Card Date: 11/17/2005

Job Card Number: A05608

Repair Service Agent: 162337

Odometer Reading: 0 MI

CLEMONS, INC

Authorization Code:

2909 S CENTER

MARSHALLTOWN IA 50158-4711

6417525491

Process Date:
11/22/2005

Transaction Type:
ZPDI---Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:
0000-Converted Claim

Job Card Line #: 1 Transaction Adjustment: Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

Global Warranty Management: Site Map

Privacy Policy | Terms of Use

© 2005 General Motors. All rights reserved.

<http://gmvis2.gotd.gm.com/gmvis2/showClaimHistoryDetail.do?VIN=1G2MB33B36Y>

6/27/2011

TA000117388



June 27, 2011

[Logout](#)

Global Warranty Management: Main > Interface With Customer > View Vehicle Delivery Information

INTERFACE WITH
CUSTOMER

View Vehicle Delivery Information

②

This screen allows IVH users to view the available information for the selected VIN delivered to the Service Agent and the ultimate customer. Not all sections will be populated for all VINs.

Vehicle Information

VIN: 1G2MB33B36Y [REDACTED] Model: 2MB67-2006 SOLSTICE 2 DR. CONVERTIBLE
Service Contract: No Branded Title: No Warranty Block: No PDI Status: No
Order Type: 60 - RETAIL - SOLD
Field Actions: [0 Open](#) [REQUEST APPROVAL VIN](#)

Invoice Information

Invoicing Service Agent: 162337 Invoice Date: 11/17/2005
CLEMONS, INC
2909 S CENTER
MARSHALLTOWN IA 50158-4711 6417525491

Ship to Information

Invoicing Service Agent: 162337 Ship to Date: N/A
CLEMONS, INC
2909 S CENTER
MARSHALLTOWN IA 50158-4711 6417525491

Delivery Information

Delivery Service Agent: 162337 Delivery Date: 12/22/2005
CLEMONS, INC Delivery Type: 010--INDIVIDUAL
2909 S CENTER Delivery Odometer: 14
MARSHALLTOWN IA 50158-4711 6417525491

In Service Information

Invoicing Service Agent: In Service Date: N/A
In Service Type: 0000
In Service Odometer: 0

For this vehicle:

→ [View Vehicle Summary](#)
→ Service
→ Contract
→ Branded Title
→ Warranty Block

→ [View Vehicle Build](#)
→ [View Vehicle](#)
→ [Component Summary](#)
→ [View Vehicle](#)
→ [Transaction History](#)
→ [Detail](#)
→ [View Vehicle Delivery](#)
→ [Information](#)

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.

96	Page <u>1</u> of <u>1</u>	Fatal ☐	New Jersey Police Crash Investigation Report		Reportable ☒	Non-Reportable ☐	Change Report ☐
97	1 Police Dept of <u>STATE POLICE</u>	Code <u>02</u>	10 Crash Occurred On: <u>I-80</u>	11 Speed Limit <u>W 55</u>	12 Route No. <u>80</u>	13 Milepost <u>58</u>	18 Speed Limit <u>51</u>
98	2 Station/Precinct <u>TOTOWA - SUB</u>		14 ☐ At Intersection with	15 ☐ Foot	16 ☐ Miles	17 Cross Road Name	19 ☐ To: ☐ From:
99	3 Date of Crash <u>06/17/11</u>	5 Day of Week <u>Th</u>	6 Time (use 2400 hrs) <u>1753</u>	7 Municipality Code <u>1608</u>	8 Total Killed <u>0</u>	9 Total Injured <u>1</u>	21 Latitude <u>40.90495</u>
100	23 Veh No <u>1</u>	24 ☐ Parked ☐ Ped ☐ Pedalcyclist ☐ Resp to Emergency ☐ Hit & Run	25 Ins Code <u>148</u>	53 Veh No	54 Policy No.	55 Ins Code	22 Longitude <u>70.54921</u>
101	26 Driver's First Name <u>[REDACTED]</u>	29 Sex <u>01</u>	56 Driver's First Name <u>[REDACTED]</u>	59 Sex <u>01</u>			
102	27 Number and Street <u>[REDACTED]</u>	30 Eyes <u>05</u>	57 Number and Street <u>[REDACTED]</u>	60 Eyes <u>[REDACTED]</u>			
103	28 City <u>RIVERDALE</u>	31 State <u>NJ</u>	32 Drivers License No <u>[REDACTED]</u>	33 DOB <u>[REDACTED]</u>	34 Expires <u>07/11</u>		
104	35 Owner's First Name <u>[REDACTED]</u>	36 Number and Street <u>[REDACTED]</u>	37 City <u>[REDACTED]</u>	38 State <u>[REDACTED]</u>	39 Zip <u>[REDACTED]</u>		
105	38 Make <u>PONT</u>	39 Model <u>SOLSTICE</u>	40 Color <u>WHT</u>	41 Year <u>06</u>	42 Plate No. <u>[REDACTED]</u>	43 State <u>NJ</u>	44 VIN <u>1G2MB33B36Y</u>
106	45 Expires <u>01/12</u>	46 Vehicle Removed To ☐ Driven ☐ Left at Scene ☒ Towed ☐ Impound ☐ Disabled	47 Authority ☐ Owner ☐ Driver ☐ Police	74 VIN <u>[REDACTED]</u>	75 Expires <u>[REDACTED]</u>		
107	48 Alcohol/Drug Test Given: ☒ No ☐ Yes ☐ Refused	49 Hazardous Material On Board ☐ Spill ☐ Name or Placard No. <u>[REDACTED]</u>	50 Carrier No. ☐ USDOT ☐ Other	51 Commercial Vehicle Weight ☐ ≤ 10,000 lbs ☐ 10,001 - 26,000 lbs ☐ ≥ 26,001 lbs	52 Carrier name <u>[REDACTED]</u>		
108	134 Crash Diagram (NOT TO SCALE)			78 Alcohol/Drug Test Given: ☐ No ☐ Yes ☐ Refused			
109				79 Hazardous Material On Board ☐ Spill ☐ Name or Placard No. <u>[REDACTED]</u>			
110	135 Crash Description			80 Carrier No. ☐ USDOT ☐ Other			
111	DRIVER #1 STATED IN EFFECT: I WAS DRIVING AND THE CAR JUST SHOT OUT ON ME. INVEST REVEALED: V#1 WAS TRAVELING I-80 WB IN THE CENTER LANE, IN RAINY CONDITIONS. D#1 FAILED TO MAINTAIN DIRECTIONAL CONTROL OF HER VEHICLE AND LEFT THE TRAVEL PORTION OF THE ROADWAY. ONCE OFF THE ROADWAY V#1 STUCK THE CONCRETE CURB AND CAME TO FULL REST IN THE GRASS MEDIAN. THE DRIVER COMPLAINED OF HEAD PAIN. PATERSON EMS RESPONDED AND TRANSPORT SAME TO ST JOE'S HOSPITAL IN PATERSON FOR TREATMENT.						
112	136 Damage To Other Property						
113	137 Charge ☐ Multiple Charges	138 Summons No.	139 Charge ☐ Multiple Charges	140 Summons No.			
114	141 Officer's Signature <u>[Signature]</u>	142 Badge No. <u>6192</u>	143 Reviewed By <u>SB</u>	144 Case Status ☐ Pending ☒ Complete			
115	Names & Addresses of Occupants - If Deceased, Date & Time of Death						
116	83	84	85	86	87	88	89
117	A	1	1	01	04	F	01
	B						
	C						
	D						
	E						



ESIS/GM Central Claims Unit
P.O. Box 300
Mail Code 482 C19 B61
Detroit, MI 48265-3000

800.888.0164 *tel*
313.665.0911 *fax*

Dawn McGuin
Claims Administrator

August 11, 2011

[REDACTED]
Riverdale, NJ [REDACTED]

RE: Claimant: [REDACTED]
Our File No.: [REDACTED]
Our Client: General Motors LLC
Date/Event: June 17, 2011
Vehicle: 2006 Pontiac Solstice
VIN: 1G2MB33B36Y [REDACTED]

Dear Ms. [REDACTED]

This will confirm that we have completed our review of your claim regarding your 2006 Pontiac Solstice. At this time, based on all documentation received and reviewed, ESIS, on behalf of General Motors LLC, will not be in a position to honor your request for damages. If you have any additional evidence that supports your claim of a product defect, please forward it to my attention for further review.

Please find enclosed a copy of the air bag data retrieved from the above referenced vehicle.

Also, you have an obligation and responsibility to ensure that the subject vehicle and its related components are maintained and preserved in their immediate post-incident condition for as long as you intend to pursue a claim and/or cause of action.

Sincerely,

Dawn McGuin

Dawn McGuin
Claims Administrator

Enclosure

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

CDR File Information

User Entered VIN	1G2MB33B36Y [REDACTED]
User	John Keher
Case Number	
EDR Data Imaging Date	07/13/2011
Crash Date	06/17/2011
Filename	1G2MB33B36Y [REDACTED] ACM DERISI.CDRX
Saved on	Wednesday, July 13 2011 at 10:59:05
Collected with CDR version	Crash Data Retrieval Tool 3.8
Reported with CDR version	Crash Data Retrieval Tool 3.8
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

Comments

Downloaded through the DLC
Air bag lamp flashed and went out upon keyed power up
Air bags have not deployed
Vehicle has not been repaired
Odometer 13425
Downloaded at IAA in Carteret, N.J.
Power supplied via battery booster box.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non Deployment Event cannot be overwritten or cleared by the SDM. The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record up to 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes

- wheel lockup and wheel slip
- Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.
- Pre-Crash data is recorded asynchronously.
- Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:
 - the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
 - no data is received from the module sending the pre-crash data
 - no module is present to send the pre-crash data
- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except:
The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 15 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMEps_r002

Multiple Event Data

Associated Events Not Recorded	0
An Event(s) Preceded the Recorded Event(s)	No
An Event(s) was in Between the Recorded Event(s)	No
An Event(s) Followed the Recorded Event(s)	No
The Event(s) Not Recorded was a Deployment Event(s)	No
The Event(s) Not Recorded was a Non-Deployment Event(s)	No

System Status At AE

Vehicle Identification Number	**2MB33B*6*
Low Tire Pressure Warning Lamp (If Equipped)	OFF
Vehicle Power Mode Status	Run
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Active
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Invalid
Transmission Selector Position (If Equipped)	Invalid
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Soon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	Invalid
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	No	No
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No


Pre-Crash Data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	Invalid	Invalid	Invalid	Invalid	Invalid
Engine Speed (RPM)	2368	2624	2496	1984	960
Percent Throttle	27	58	16	13	11
Brake Switch Circuit State	OFF	OFF	OFF	ON	OFF
Accelerator Pedal Position (percent)	11	41	0	0	0
Antilock Brake System Active (If Equipped)	No	No	No	Yes	Yes
Lateral Acceleration (feet/s²) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid


Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Yaw Rate (degrees per second) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Vehicle Dynamics Control Active (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid

System Status At Non-Deployment

Ignition Cycles At Investigation	3235
SIR Warning Lamp Status	OFF
SIR Warning Lamp ON/OFF Time (seconds)	655200
Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	1925
Ignition Cycles At Event	3218
Ignition Cycles Since DTCs Were Last Cleared	254
Driver's Belt Switch Circuit Status	BUCKLED
Passenger's Belt Switch Circuit Status	UNBUCKLED
Automatic Passenger SIR Suppression System Validity Status at AE	Valid
Automatic Passenger SIR Suppression System Status at AE	Air Bag Suppressed
Diagnostic Trouble Codes at Event, fault number: 1	N/A
Diagnostic Trouble Codes at Event, fault number: 2	N/A
Diagnostic Trouble Codes at Event, fault number: 3	N/A
Diagnostic Trouble Codes at Event, fault number: 4	N/A
Diagnostic Trouble Codes at Event, fault number: 5	N/A
Diagnostic Trouble Codes at Event, fault number: 6	N/A
Maximum SDM Recorded Velocity Change (MPH)	10.93
Algorithm Enable to Maximum SDM Recorded Velocity Change (msec)	70
Driver First Stage Deployment Loop Commanded	No
Driver Second Stage Deployment Loop Commanded	No
Driver Side Deployment Loop Commanded	No
Driver Pretensioner Deployment Loop Commanded	No
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Driver Knee Deployment Loop Commanded	No
Passenger First Stage Deployment Loop Commanded	No
Passenger Second Stage Deployment Loop Commanded	No
Passenger Side Deployment Loop Commanded	No
Passenger Pretensioner Deployment Loop Commanded	No
Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No
Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No
Passenger Knee Deployment Loop Commanded	No
Driver Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Left Pretensioner Deployment Loop Commanded	No
Third Row Left Roof Rail/Head Curtain Loop Commanded	No
Passenger Anchor Pretensioner Deployment Loop Commanded (If Equipped)	No
Second Row Right Pretensioner Deployment Loop Commanded	No
Third Row Right Roof Rail/Head Curtain Loop Commanded	No
Second Row Center Pretensioner Deployment Loop Commanded	No
Crash Record Locked	No
Multiple Event Data/Vehicle Event Data (Pre-Crash) Associated With This Event	Yes
Deployment Event Recorded in the Non-Deployment Record	No
Event Recording Complete	Yes



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	-0.68	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Longitudinal Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00



Time (milliseconds)	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150
SDM Lateral Axis Recorded Velocity Change (MPH)	0.68	2.71	5.42	6.10	8.81	9.49	10.84	10.84	10.84	10.84	10.17	10.17	0.00	0.00	0.00
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
SDM Lateral Axis Recorded Velocity Change (MPH)	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00

Hexadecimal Data

Data that the vehicle manufacturer has specified for data retrieval is shown in the hexadecimal data section of the CDR report. The hexadecimal data section of the CDR report may contain data that is not translated by the CDR program. The control module contains additional data that is not retrievable by the CDR system.

```
$01 00 00 00 00 45 00 00
$02 20 00 00 00 00 00 00
$03 02 00 00 00 00 00 00
$04 02 00 00 00 00 00 00
$05 00 00 00 00 00 00 00
$06 00 4A 00 00 19 89 18
$07 04 69 00 00 00 00 00
$08 00 FF 00 00 00 00 00
$09 03 FF 7E 00 00 00 00
$0A 00 00 00 00 00 00 00
$0B 00 00 01 0F 01 00 00
$0C 00 00 00 00 00 00 00
$0D 00 00 00 00 00 00 00
$0E 00 00 00 00 00 00 00
$0F 92 00 00 00 00 00 00
$10 47 32 4D 42 33 33 42
$11 33 36 59 31 30 35 36
$12 30 38 00 00 00 00 00
$13 00 00 00 00 00 00 00
$14 00 00 00 00 00 00 00
$15 00 00 00 00 00 00 00
$16 03 06 0C 16 34 00 00
$17 03 03 02 02 00 00 00
$18 03 03 00 00 00 00 00
$19 07 07 00 00 00 00 00
$1B 3F 00 00 67 00 7A 00
$1C 3F 00 00 06 00 1A 00
$1D 00 00 00 00 00 00 00
$1E 4F 4F 00 4F 00 01 00
$1F 33 C0 00 00 00 00 00
$20 40 00 00 00 00 00 00
$21 FF FF 00 00 50 00 00
$22 00 91 00 00 00 00 00
$24 00 00 00 00 00 00 00
$25 00 00 00 00 00 00 00
$26 00 00 00 00 00 00 00
$27 FF 00 FF 00 00 00 00
$2A 00 00 00 00 00 00 00
$2B 00 00 00 00 00 00 00
$2D 00 00 00 00 00 00 00
$2E 00 FF F0 07 97 00 00
$2F 00 FE 0C A3 11 00 00
$30 9D 00 00 00 00 00 00
$31 00 00 00 69 1C 00 00
$32 40 00 00 00 00 00 00
$33 1C 22 29 93 46 00 00
$34 0F 1F 27 29 25 00 00
$35 22 40 4E 53 4A 80 00
$36 00 00 00 00 00 80 00
$37 C0 00 00 09 0A 00 78
$38 7E 80 40 00 03 C0 00
$39 00 00 00 00 00 80 00
$3A 00 00 00 00 00 80 00
$3B 03 06 0C 00 00 00 00
$3C 00 00 00 00 00 00 C0
```

```

$3D 32 4D 42 33 33 42 00
$3E 36 10 56 08 00 00 00
$3F 00 00 90 00 00 00 00
$40 20 A5 00 00 00 00 00
$41 00 00 00 00 00 00 00
$42 00 FF F0 07 85 00 00
$43 FE 0C 92 00 00 00 00
$44 00 00 00 00 00 00 00
$45 00 00 00 00 00 00 00
$46 00 00 00 00 00 00 00
$47 01 00 04 00 08 00 00
$48 09 FF 0D FF 0E FF 00
$49 10 FF 10 FF 10 FF 00
$4A 10 FF 0F FF 0F FF 00
$4B 00 00 00 00 00 00 00
$4C 00 00 00 00 00 00 00
$4D 00 00 00 00 00 00 00
$4E 00 00 00 00 00 00 00
$4F 00 00 00 00 00 00 00
$50 00 00 00 00 00 00 00
$51 D0 00 00 00 00 00 00
$52 00 00 00 00 00 00 00
$53 07 01 04 00 00 00 00
$54 00 00 00 00 00 00 00
$55 00 00 00 00 00 00 00
$67 00 00 00 00 00 00 00
$68 F8 F8 90 C0 00 00 00
$69 80 FF FF FF FF 00 00
$6A FF FF FF 00 00 00 00
$6B FF FF FF FF FF FF 00
$6C FF FF FF FF FF FF 00
$6D FF FF FF FF FF FF 00
$6E FF FF FF FF FF FF 00
$6F FF FF FF FF FF FF 00
$70 FF FF FF FF FF FF 00
$71 FF FF FF FF FF FF 00
$72 FF FF FF FF FF FF 00
$73 FF FF FF FF FF FF 00
$74 FF FF FF FF FF FF 00
$75 FF FF FF FF FF FF 00
$76 FF FF FF FF FF FF 00
$77 FF FF FF FF FF FF 00
$78 F0 00 00 F0 00 00 00
$79 81 FF FF FF 00 00 00
$7A 82 FF FF 00 00 00 00
$7B FF FF FF FF FF FF 00

```

```

$01 41 55 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$02 01 02 03 04
$03 41 54 01 02 03 04 52 53 41 32 03 09 01 AA AA 01
$04 01 02 03 04
$05 42 55 FF FF FF FF FF FF FF FF FF FF FF FF FF
$06 FF FF FF FF
$07 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$08 FF FF FF FF
$0D 41 48 35 32 30 30 52 35 32 30 38 31 30 43 32 38
$0E 00 E9 14 C0
$0F 41 4A 35 32 30 30 52 35 32 35 32 32 30 45 32 32
$10 00 E9 14 C0
$13 42 52 35 33 30 30 38 33 35 32 31 30 31 50 36 59
$14 00 9D DB 54
$17 42 54 FF FF FF FF FF FF FF FF FF FF FF FF FF
$18 FF FF FF FF
$21 32 16 B8 0B 2C 38 91 9A
$22 89 18

```

```
$23 FA 4D FA FA FA FA FA
$24 FA 4D FA FA FA FA FA
$25 FA 4D FA FA FA FA FA
$26 FA 4D FA FA FA FA FA
$40 00 00
$41 3F 00 00 06 00 1A
$42 D0 E4
$43 00 00 BE 80
$44 C2 0C 00 FC C0 C0
$45 07 01 07 01 05 01
$46 28 14 14 64 64
$47 0A 64 06 04 04 05 0A 06 04 0A 00 00 FA 00 00 FF 04 64
$48 18 08 08
$B0 58
$B1 FD FE 00
$B2 FF FF FF FF FF
$B4 41 53 38 39 31 38 32 31 30 38 32 42 20 20 20 20
$B7 50 AA 01 0F 02
$B8 45 4D 69 01 31
$C1 30 46 30 32
$CA 30 46 30 32
$CB 00 F1 AE C6
$CC 00 F1 AE C6
$D1 00 00
$DB 00 00
$DC 00 00
```

Disclaimer of Liability

The users of the CDR product and reviewers of the CDR reports and exported data shall ensure that data and information supplied is applicable to the vehicle, vehicle's system(s) and the vehicle ECU. Robert Bosch LLC and all its directors, officers, employees and members shall not be liable for damages arising out of or related to incorrect, incomplete or misinterpreted software and/or data. Robert Bosch LLC expressly excludes all liability for incidental, consequential, special or punitive damages arising from or related to the CDR data, CDR software or use thereof.



CDR File Information

User Entered VIN	1G2MB33B36Y
User	John Keher
Case Number	
EDR Data Imaging Date	07/13/2011
Crash Date	06/17/2011
Filename	1G2MB33B36Y.ACM.DERISI.CDRX
Saved on	Wednesday, July 13 2011 at 10:59:05
Collected with CDR version	Crash Data Retrieval Tool 3.8
Reported with CDR version	Crash Data Retrieval Tool 3.8
EDR Device Type	airbag control module
Event(s) recovered	Non-Deployment

IMPORTANT NOTICE: Robert Bosch LLC and the manufacturers whose vehicles are accessible using the CDR System urge end users to use the latest production release of the Crash Data Retrieval system software when viewing, printing or exporting any retrieved data from within the CDR program. Using the latest version of the CDR software is the best way to ensure that retrieved data has been translated using the most current information provided by the manufacturers of the vehicles supported by this product.

Data Limitations

Recorded Crash Events:

There are two types of recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event records data but does not deploy the air bag(s). The minimum SDM Recorded Vehicle Velocity Change, that is needed to record a Non-Deployment Event, is five MPH. A Non-Deployment Event may contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle velocity change. This event will be cleared by the SDM, after approximately 250 ignition cycles. This event can be overwritten by a second Deployment Event, referred to as Deployment Event #2, if the Non-Deployment Event is not locked. The data in the Non-Deployment Event file will be locked, if the Non-Deployment Event occurred within five seconds of a Deployment Event. A locked Non-Deployment Event cannot be overwritten or cleared by the SDM. The second type of SDM recorded crash event is the Deployment Event. It also may contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events. If a second Deployment Event occurs any time after the Deployment Event, the Deployment Event #2 will overwrite any non-locked Non-Deployment Event. Deployment Events cannot be overwritten or cleared by the SDM. Once the SDM has deployed an air bag, the SDM must be replaced.

Data:

-SDM Recorded Vehicle Velocity Change reflects the change in velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. For Deployment Events, the SDM will record up to 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM can record up to the first 300 milliseconds of data after algorithm enable. Velocity Change data is displayed in SAE sign convention.

-The CDR tool displays time from Algorithm Enable (AE) to time of deployment command in a deployment event and AE to time of maximum SDM recorded vehicle velocity change in a non-deployment event. Time from AE begins when the first air bag system enable threshold is met and ends when deployment command criteria is met or at maximum SDM recorded vehicle velocity change. Air bag systems such as frontal, side, or rollover, may be a source of an enable. The time represented in a CDR report can be that of the enable of one air bag system to the deployment time of another air bag system.

-Maximum Recorded Vehicle Velocity Change is the maximum square root value of the sum of the squares for the vehicle's combined "X" and "Y" axis change in velocity.

-Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.

-SDM Recorded Vehicle Speed accuracy can be affected by various factors, including but not limited to the following:

- significant changes in the tire's rolling radius
- final drive axle ratio changes
- wheel lockup and wheel slip

-Brake Switch Circuit Status indicates the open/closed state of the brake switch circuit.

-Pre-Crash data is recorded asynchronously.

-Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if:

1G2MB33B36Y



- the SDM receives a message with an "invalid" flag from the module sending the pre-crash data
- no data is received from the module sending the pre-crash data
- no module is present to send the pre-crash data
- Driver's and Passenger's Belt Switch Circuit Status indicates the status of the seat belt switch circuit, except: The Passenger Belt Switch Circuit Status for 2005 vehicles is available only on the Cadillac STS. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes Recaro brand seats (RPO ALV), always reports a default value of "Buckled," because there is no passenger belt switch with the Recaro seat option.
- The Time Between Non-Deployment to Deployment Events is displayed in seconds. If the time between the two events is greater than five seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- If power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-modding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the ignition counter.
- Steering Wheel Angle data is displayed as a positive value when the steering wheel is turned to the right and a negative value when the steering wheel is turned to the left, except for Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7). For Cadillac STS model vehicles with StabiliTrak 3.0 systems (RPO JL7), when the steering wheel is turned to the right, a negative value will be displayed and when the steering wheel is turned to the left, a positive value will be displayed. The Steering Wheel Angle data is reported in 16 degree increments.

Data Source:

All SDM recorded data is measured, calculated, and stored internally, except for the following:

- Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
- The Belt Switch Circuit is wired directly to the SDM.

01016_SDMeps_r002



Ignition Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$2F Bytes 3-4	\$0CA3	Ignition Cycles at Investigation	3235	cycles



Vehicle Status Data (Pre-Crash)

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID Pack \$31 Byte 1	\$00	Accelerator Pedal Position (-1 sec)	0	% full throttle
DPID Pack \$31 Byte 2	\$00	Accelerator Pedal Position (-2 sec)	0	% full throttle
DPID Pack \$31 Byte 3	\$00	Accelerator Pedal Position (-3 sec)	0	% full throttle
DPID Pack \$31 Byte 4	\$69	Accelerator Pedal Position (-4 sec)	41	% full throttle
DPID Pack \$31 Byte 5	\$1C	Accelerator Pedal Position (-5 sec)	11	% full throttle
DPID \$31 Byte 6 bit 7	\$00	Accelerator Pedal Position Validity Status	Valid	
DPID \$32 Byte 1 bit 7	\$40	Brake Switch Circuit State (-1 sec)	OFF	
DPID \$32 Byte 1 bit 6	\$40	Brake Switch Circuit State (-2 sec)	ON	
DPID \$32 Byte 1 bit 5	\$40	Brake Switch Circuit State (-3 sec)	OFF	
DPID \$32 Byte 1 bit 4	\$40	Brake Switch Circuit State (-4 sec)	OFF	
DPID \$32 Byte 1 bit 3	\$40	Brake Switch Circuit State (-5 sec)	OFF	
DPID \$32 Byte 2 bit 7	\$00	Brake Switch Circuit State Validity Status	Valid	
DPID \$32 Byte 3 bit 7	\$00	Cruise Control Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 6	\$00	Cruise Control Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 5	\$00	Cruise Control Resume Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 4	\$00	Cruise Control Resume Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 3	\$00	Cruise Control Set Switch Active (-1 sec) If Equipped	No	
DPID \$32 Byte 3 bit 2	\$00	Cruise Control Set Switch Active (-2 sec) If Equipped	No	
DPID \$32 Byte 3 bit 1	\$00	Reduced Engine Power Mode (-1sec)	OFF	
DPID \$32 Byte 3 bit 0	\$00	Reduced Engine Power Mode (-2sec)	OFF	
DPID \$32 Byte 4 bit 7	\$00	Cruise Control Active Validity Status If Equipped	Valid	
DPID \$33 Byte 1	\$1C	Throttle Position (-1 sec)	11	% full throttle
DPID \$33 Byte 2	\$22	Throttle Position (-2 sec)	13	% full throttle
DPID \$33 Byte 3	\$29	Throttle Position (-3 sec)	16	% full throttle
DPID \$33 Byte 4	\$93	Throttle Position (-4 sec)	58	% full throttle
DPID \$33 Byte 5	\$46	Throttle Position (-5 sec)	27	% full throttle
DPID \$33 Byte 6 bit 7	\$00	Throttle Position Validity Status	Valid	



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$34 Byte 1	\$0F	Engine Speed (-1 sec)	960	RPM
DPID \$34 Byte 2	\$1F	Engine Speed (-2 sec)	1984	RPM
DPID \$34 Byte 3	\$27	Engine Speed (-3 sec)	2496	RPM
DPID \$34 Byte 4	\$29	Engine Speed (-4 sec)	2624	RPM
DPID \$34 Byte 5	\$25	Engine Speed (-5 sec)	2368	RPM
DPID \$34 Byte 6 bit 7	\$00	Engine Speed Validity Status	Valid	
DPID \$35 Byte 1	\$22	Vehicle Speed (-1 sec)	21	MPH
DPID \$35 Byte 2	\$40	Vehicle Speed (-2 sec)	40	MPH
DPID \$35 Byte 3	\$4E	Vehicle Speed (-3 sec)	48	MPH
DPID \$35 Byte 4	\$53	Vehicle Speed (-4 sec)	52	MPH
DPID \$35 Byte 5	\$4A	Vehicle Speed (-5 sec)	46	MPH
DPID \$35 Byte 6 bit 7	\$80	Vehicle Speed Validity Status	Invalid	
DPID \$36 Byte 1	\$00	Steering Wheel Angle (-1 sec) If Equipped	0	degrees
DPID \$36 Byte 2	\$00	Steering Wheel Angle (-2 sec) If Equipped	0	degrees
DPID \$36 Byte 3	\$00	Steering Wheel Angle (-3 sec) If Equipped	0	degrees
DPID \$36 Byte 4	\$00	Steering Wheel Angle (-4 sec) If Equipped	0	degrees
DPID \$36 Byte 5	\$00	Steering Wheel Angle (-5 sec) If Equipped	0	degrees
DPID \$36 Byte 6 bit 7	\$80	Steering Wheel Angle Validity Status If Equipped	Invalid	
DPID \$37 Byte 1 bit 7	\$C0	Antilock Brake System Active (-1 sec) If Equipped	Yes	
DPID \$37 Byte 1 bit 6	\$C0	Antilock Brake System Active (-2 sec) If Equipped	Yes	
DPID \$37 Byte 1 bit 5	\$C0	Antilock Brake System Active (-3 sec) If Equipped	No	
DPID \$37 Byte 1 bit 4	\$C0	Antilock Brake System Active (-4 sec) If Equipped	No	
DPID \$37 Byte 1 bit 3	\$C0	Antilock Brake System Active (-5 sec) If Equipped	No	
DPID \$37 Byte 2 bit 7	\$00	Traction Control System Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 7	\$00	Vehicle Dynamics Control Active (-1 sec) If Equipped	No	
DPID \$37 Byte 3 bit 6	\$00	Vehicle Dynamics Control Active (-2 sec) If Equipped	No	
DPID \$37 Byte 3 bit 5	\$00	Vehicle Dynamics Control Active (-3 sec) If Equipped	No	
DPID \$37 Byte 3 bit 4	\$00	Vehicle Dynamics Control Active (-4 sec) If Equipped	No	
DPID \$37 Byte 3 bit 3	\$00	Vehicle Dynamics Control Active (-5 sec) If Equipped	No	
DPID \$37 Byte 4 bits 3-0	\$09	Transmission Range (-1 sec) If Equipped	Neutral	
DPID \$37 Byte 5 bits 3-0	\$0A	Transmission Selector Position (-1 sec) If Equipped	Park	
DPID \$37 Byte 6 bit 7	\$00	Service Engine Soon (Non-Emission Related) Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 6	\$00	Service Vehicle Soon Lamp (1 sec)	OFF	
DPID \$37 Byte 6 bit 3	\$00	Brake System Warning Lamp If Equipped	OFF	
DPID \$37 Byte 6 bit 1	\$00	Low Tire Pressure Warning Lamp If Equipped	OFF	
DPID \$37 Byte 7 bit 7	\$78	Antilock Brake System Active Validity Status If Equipped	Valid	
DPID \$37 Byte 7 bit 6	\$78	Traction Control System Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 5	\$78	Vehicle Dynamics Control Active Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 4	\$78	Transmission Range Validity Status If Equipped	Invalid	
DPID \$37 Byte 7 bit 3	\$78	Transmission Selector Position Validity Status If Equipped	Invalid	

1G2MB33B38Y

Page 5 of 13

Printed on: Wednesday, July 13 2011 at 11:00:23

TA000117406



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$37 Byte 7 bit 2	\$78	Service Engine Soon (Non-Emission Related) / Service Vehicle Soon Lamp Validity Status	Valid	
DPID \$37 Byte 7 bit 1	\$78	Low Tire Pressure Warning Lamp Validity Status If Equipped	Valid	
DPID \$38 Byte 1	\$7E	Outside Air Temperature (-1 sec) If Equipped	73	
DPID \$38 Byte 2 bit 7	\$80	Outside Air Temperature Validity Status (-1 sec) If Equipped	Invalid	
DPID \$38 Byte 5 bits 7-6	\$03	Left Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 5-4	\$03	Right Front Door Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 3-2	\$03	Rear Door(s) Status (-1 sec) If Equipped	Closed	
DPID \$38 Byte 5 bits 1-0	\$03	Left Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 6 bits 7-6	\$C0	Right Rear Door Status (-1 sec) If Equipped	Unused	
DPID \$38 Byte 7 bit 7	\$00	Left Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 6	\$00	Right Front Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 5	\$00	Rear Door(s) Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 4	\$00	Left Rear Door Validity Status If Equipped	Valid	
DPID \$38 Byte 7 bit 3	\$00	Right Rear Door Validity Status If Equipped	Valid	
DPID \$39 Byte 1	\$00	Lateral Acceleration (-1 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 2	\$00	Lateral Acceleration (-2 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 3	\$00	Lateral Acceleration (-3 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 4	\$00	Lateral Acceleration (-4 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 5	\$00	Lateral Acceleration (-5 sec) If Equipped	0.00	feet/sec ²
DPID \$39 Byte 6 bit 7	\$80	Lateral Acceleration Validity Status If Equipped	Invalid	
DPID \$3A Byte 1	\$00	Yaw Rate (-1 sec) If Equipped	0	
DPID \$3A Byte 2	\$00	Yaw Rate (-2 sec) If Equipped	0	
DPID \$3A Byte 3	\$00	Yaw Rate (-3 sec) If Equipped	0	
DPID \$3A Byte 4	\$00	Yaw Rate (-4 sec) If Equipped	0	
DPID \$3A Byte 5	\$00	Yaw Rate (-5 sec) If Equipped	0	
DPID \$3A Byte 6 bit 7	\$80	Yaw Rate Validity Status If Equipped	Invalid	



VIN Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3D Byte 1	\$32	Vehicle Identification Number (VIN) Digit 3	2	
DPID \$3D Byte 2	\$4D	Vehicle Identification Number (VIN) Digit 4	M	
DPID \$3D Byte 3	\$42	Vehicle Identification Number (VIN) Digit 5	B	
DPID \$3D Byte 4	\$33	Vehicle Identification Number (VIN) Digit 6	3	
DPID \$3D Byte 5	\$33	Vehicle Identification Number (VIN) Digit 7	3	
DPID \$3D Byte 6	\$42	Vehicle Identification Number (VIN) Digit 8	3	
DPID \$3E Byte 1	\$36	Vehicle Identification Number (VIN) Digit 10		
DPID \$3E Byte 2 bits 7-4	\$10	Vehicle Identification Number (VIN) Digit 12		
DPID \$3E Byte 2 bits 3-0	\$10	Vehicle Identification Number (VIN) Digit 13		
DPID \$3E Byte 3 bits 7-4	\$56	Vehicle Identification Number (VIN) Digit 14		
DPID \$3E Byte 3 bits 3-0	\$56	Vehicle Identification Number (VIN) Digit 15		
DPID \$3E Byte 4 bits 7-4	\$08	Vehicle Identification Number (VIN) Digit 16		
DPID \$3E Byte 4 bits 3-0	\$08	Vehicle Identification Number (VIN) Digit 17		

Multiple Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 1 bit 7	\$00	An Event(s) Preceded the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 6	\$00	An Event(s) was in Between the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 5	\$00	An Event(s) Followed the Recorded Event(s)	No	
DPID \$3F Byte 1 bit 4	\$00	The Event(s) Not Recorded was a Deployment Event(s)	No	
DPID \$3F Byte 1 bit 3	\$00	The Event(s) Not Recorded was a Non-Deployment Event(s)	No	
DPID \$3F Byte 1 bits 2-0	\$00	Associated Events Not Recorded	0	

Power Mode Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$3F Byte 3 bits 7-6	\$90	Vehicle Power Mode Status	Run	
DPID \$3F Byte 3 bit 5	\$90	Remote Start Status If Equipped	Inactive	
DPID \$3F Byte 3 bit 4	\$90	Run/Crank Ignition Switch Logic Level	Active	



Non-Deployment Or Deployment #2 Event Data

Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$40 Byte 1 bit 7	\$20	Crash Record Locked	No	
DPID \$40 Byte 1 bit 6	\$20	Deployment Event Recorded in the Non-Deployment Record	No	
DPID \$40 Byte 1 bit 5	\$20	Multiple Event Data/Vehicle Event Data (Pre-Crash) Associated With This Event	Yes	
DPID \$40 Byte 2	\$A5	Event Recording Complete	Yes	
DPID \$41 Byte 1 bit 7	\$00	Driver 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 6	\$00	Driver 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 5	\$00	Driver Side Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 4	\$00	Driver Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 1 bit 3	\$00	Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 2	\$00	Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 1 bit 1	\$00	Driver Knee Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 7	\$00	Passenger 1st Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 6	\$00	Passenger 2nd Stage Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 5	\$00	Passenger Side Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 4	\$00	Passenger Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 2 bit 3	\$00	Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 2	\$00	Passenger (Initiator 2) Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 2 bit 1	\$00	Passenger Knee Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 7	\$00	Driver Anchor Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 6	\$00	Second Row Left Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 5	\$00	Third Row Left Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 4	\$00	Second Row Right Side Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 3	\$00	Second Row Right Pretensioner Deployment Loop Commanded	No	
DPID \$41 Byte 3 bit 2	\$00	Third Row Right Roof Rail/Head Curtain Loop Commanded	No	
DPID \$41 Byte 3 bit 1	\$00	Center Rear Pretensioner Deployment Loop Commanded	No	
DPID \$42 Byte 1 bit 7	\$00	SIR Warning Lamp Status	OFF	
DPID \$42 Bytes 2-3	\$FFF0	SIR Warning Lamp ON/OFF Time Continuously	655200	seconds
DPID \$42 Bytes 4-5	\$0785	Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously	1925	cycles
DPID \$43 Byte 1	\$FE	Ignition Cycles Since DTCs Were Last Cleared	254	cycles
DPID \$43 Bytes 2-3	\$0C92	Ignition Cycles at Event	3218	cycles
DPID \$44 Bytes 1-2	\$0000	DTC number for fault #1	N/A	
DPID \$44 Byte 3	\$00	DTC fault type for fault #1	\$00	
DPID \$44 Bytes 4-5	\$0000	DTC number for fault #2	N/A	
DPID \$44 Byte 6	\$00	DTC fault type for fault #2	\$00	
DPID \$45 Bytes 1-2	\$0000	DTC number for fault #3	N/A	



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$45 Byte 3	\$00	DTC fault type for fault #3	\$00	
DPID \$45 Bytes 4-5	\$0000	DTC number for fault #4	N/A	
DPID \$45 Byte 6	\$00	DTC fault type for fault #4	\$00	
DPID \$46 Bytes 1-2	\$0000	DTC number for fault #5	N/A	
DPID \$46 Byte 3	\$00	DTC fault type for fault #5	\$00	
DPID \$46 Bytes 4-5	\$0000	DTC number for fault #6	N/A	
DPID \$46 Byte 6	\$00	DTC fault type for fault #6	\$00	
DPID \$47 Byte 1	\$01	SDM Recorded Vehicle Velocity Change for Axis #1 (10 ms after event enable or 70 ms before deployment)	0.68	MPH
DPID \$47 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (10 ms after event enable or 70 ms before deployment)	0.00	MPH
DPID \$47 Byte 3	\$04	SDM Recorded Vehicle Velocity Change for Axis #1 (20 ms after event enable or 60 ms before deployment)	2.71	MPH
DPID \$47 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (20 ms after event enable or 60 ms before deployment)	0.00	MPH
DPID \$47 Byte 5	\$08	SDM Recorded Vehicle Velocity Change for Axis #1 (30 ms after event enable or 50 ms before deployment)	5.42	MPH
DPID \$47 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (30 ms after event enable or 50 ms before deployment)	0.00	MPH
DPID \$48 Byte 1	\$09	SDM Recorded Vehicle Velocity Change for Axis #1 (40 ms after event enable or 40 ms before deployment)	6.10	MPH
DPID \$48 Byte 2	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (40 ms after event enable or 40 ms before deployment)	-0.68	MPH
DPID \$48 Byte 3	\$0D	SDM Recorded Vehicle Velocity Change for Axis #1 (50 ms after event enable or 30 ms before deployment)	8.81	MPH
DPID \$48 Byte 4	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (50 ms after event enable or 30 ms before deployment)	-0.68	MPH
DPID \$48 Byte 5	\$0E	SDM Recorded Vehicle Velocity Change for Axis #1 (60 ms after event enable or 20 ms before deployment)	9.49	MPH
DPID \$48 Byte 6	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (60 ms after event enable or 20 ms before deployment)	-0.68	MPH
DPID \$49 Byte 1	\$10	SDM Recorded Vehicle Velocity Change for Axis #1 (70 ms after event enable or 10 ms before deployment)	10.84	MPH
DPID \$49 Byte 2	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (70 ms after event enable or 10 ms before deployment)	-0.68	MPH
DPID \$49 Byte 3	\$10	SDM Recorded Vehicle Velocity Change for Axis #1 (80 ms after event enable or at deployment)	10.84	MPH
DPID \$49 Byte 4	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (80 ms after event enable or at deployment)	-0.68	MPH



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$49 Byte 5	\$10	SDM Recorded Vehicle Velocity Change for Axis #1 (90 ms after event enable or 10 ms after deployment)	10.84	MPH
DPID \$49 Byte 6	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (90 ms after event enable or 10 ms after deployment)	-0.68	MPH
DPID \$4A Byte 1	\$10	SDM Recorded Vehicle Velocity Change for Axis #1 (100 ms after event enable or 20 ms after deployment)	10.84	MPH
DPID \$4A Byte 2	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (100 ms after event enable or 20 ms after deployment)	-0.68	MPH
DPID \$4A Byte 3	\$0F	SDM Recorded Vehicle Velocity Change for Axis #1 (110 ms after event enable or 30 ms after deployment)	10.17	MPH
DPID \$4A Byte 4	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (110 ms after event enable or 30 ms after deployment)	-0.68	MPH
DPID \$4A Byte 5	\$0F	SDM Recorded Vehicle Velocity Change for Axis #1 (120 ms after event enable or 40 ms after deployment)	10.17	MPH
DPID \$4A Byte 6	\$FF	SDM Recorded Vehicle Velocity Change for Axis #2 (120 ms after event enable or 40 ms after deployment)	-0.68	MPH
DPID \$4B Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (130 ms after event enable or 50 ms after deployment)	0.00	MPH
DPID \$4B Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (130 ms after event enable or 50 ms after deployment)	0.00	MPH
DPID \$4B Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (140 ms after event enable or 60 ms after deployment)	0.00	MPH
DPID \$4B Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (140 ms after event enable or 60 ms after deployment)	0.00	MPH
DPID \$4B Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4B Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (150 ms after event enable or 70 ms after deployment)	0.00	MPH
DPID \$4C Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (160 ms after event enable or 80 ms after deployment)	0.00	MPH
DPID \$4C Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (170 ms after event enable or 90 ms after deployment)	0.00	MPH
DPID \$4C Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (170 ms after event enable or 90 ms after deployment)	0.00	MPH
DPID \$4C Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (180 ms after event enable or 100 ms after deployment)	0.00	MPH
DPID \$4C Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (180 ms after event enable or 100 ms after deployment)	0.00	MPH



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$4D Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (190 ms after event enable or 110 ms after deployment)	0.00	MPH
DPID \$4D Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (190 ms after event enable or 110 ms after deployment)	0.00	MPH
DPID \$4D Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (200 ms after event enable or 120 ms after deployment)	0.00	MPH
DPID \$4D Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4D Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (210 ms after event enable or 130 ms after deployment)	0.00	MPH
DPID \$4E Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (220 ms after event enable or 140 ms after deployment)	0.00	MPH
DPID \$4E Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (230 ms after event enable or 150 ms after deployment)	0.00	MPH
DPID \$4E Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4E Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (240 ms after event enable or 160 ms after deployment)	0.00	MPH
DPID \$4F Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (250 ms after event enable or 170 ms after deployment)	0.00	MPH
DPID \$4F Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (260 ms after event enable or 180 ms after deployment)	0.00	MPH
DPID \$4F Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (270 ms after event enable or 190 ms after deployment)	0.00	MPH
DPID \$4F Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (270 ms after event enable or 190 ms after deployment)	0.00	MPH
DPID \$50 Byte 1	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (280 ms after event enable or 200 ms after deployment)	0.00	MPH
DPID \$50 Byte 2	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (280 ms after event enable or 200 ms after deployment)	0.00	MPH



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$50 Byte 3	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (290 ms after event enable or 210 ms after deployment)	0.00	MPH
DPID \$50 Byte 4	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (290 ms after event enable or 210 ms after deployment)	0.00	MPH
DPID \$50 Byte 5	\$00	SDM Recorded Vehicle Velocity Change for Axis #1 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$50 Byte 6	\$00	SDM Recorded Vehicle Velocity Change for Axis #2 (300 ms after event enable or 220 ms after deployment)	0.00	MPH
DPID \$51 Byte 1 bit 7	\$D0	Driver Belt Switch Circuit Status	BUCKLED	
DPID \$51 Byte 1 bit 6	\$D0	Driver Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 5	\$D0	Passenger Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 4	\$D0	Passenger Belt Switch Circuit Status Monitored	Yes	
DPID \$51 Byte 1 bit 3	\$D0	Front Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 1 bit 2	\$D0	Front Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 7	\$00	Second Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 6	\$00	Second Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 5	\$00	Second Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 4	\$00	Second Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 2 bit 3	\$00	Second Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 2 bit 2	\$00	Second Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 7	\$00	Third Row Left Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 6	\$00	Third Row Left Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 5	\$00	Third Row Center Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 4	\$00	Third Row Center Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 3 bit 3	\$00	Third Row Right Belt Switch Circuit Status	UNBUCKLED	
DPID \$51 Byte 3 bit 2	\$00	Third Row Right Belt Switch Circuit Status Monitored	No	
DPID \$51 Byte 4 bit 7	\$00	Driver Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 6	\$00	Driver Seat Position Status Monitored	No	
DPID \$51 Byte 4 bit 5	\$00	Passenger Seat Position Status	Rearward	
DPID \$51 Byte 4 bit 4	\$00	Passenger Seat Position Status Monitored	No	
DPID \$52 Byte 1 bit 7	\$00	Automatic Passenger SIR Suppression System Validity Status	Valid	
DPID \$52 Byte 1 bit 0	\$00	Automatic Passenger SIR Suppression System Status	Air Bag Suppressed	
DPID \$52 Bytes 2-3	\$0000	SDM Synchronization Counter	0	
DPID \$52 Byte 4 bits 7-6	\$00	Rollover Sensor Message Status	No Rollover Event	
DPID \$52 Byte 4 bit 5	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Side Impact Event	No	
DPID \$52 Byte 4 bit 4	\$00	Side Air Bag(s) Were First Commanded to Deploy Due to Rollover Event	No	



Data Location	Data Value (Hex)	Parameter Descriptor	Translated Value	Units
DPID \$52 Byte 4 bits 3-0	\$00	Rollover Sensor Status	Last message received contained errors	
DPID \$53 Byte 1	\$07	Time From Algorithm Enable to Maximum SDM Recorded Vehicle Velocity Change	70	msec
DPID \$53 Bytes 2-3	\$0104	Maximum SDM Recorded Vehicle Velocity Change	10.93	MPH
DPID \$54 Byte 1 bit 7	\$00	Automatic Passenger SIR Suppression System Validity Status / Passenger SIR Suppression Switch Circuit Validity Status	Valid	
DPID \$54 Byte 1 bit 1	\$00	Automatic Passenger SIR Suppression System Status / Passenger SIR Suppression Switch Circuit Status	Air Bag Suppressed	
DPID \$54 Byte 2	\$00	Rollover Sensor - Time Between Successive Side Deploys	0	msec
DPID \$54 Byte 3	\$00	Rollover Sensor - Time From Rollover Enable to Deploy	0	msec
DPID \$55 Byte 1	\$00	Driver 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 2	\$00	Driver 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 3	\$00	Passenger 1st Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 4	\$00	Passenger 2nd Stage Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 5	\$00	Driver Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec
DPID \$55 Byte 6	\$00	Passenger Side or Roof Rail/Head Curtain Time From Algorithm Enable to Deployment Command Criteria Met	0	msec