Resources:

- 1) Three wire quarter-bridge circuit configuration and conversion of output voltage to strain : National instruments on Strain gauge configuration types: http://www.ni.com/white-paper/4172/en/
- 2) Conversion of output voltage to directional strains, 2 principal strains, 2 principal stresses, shear strain and shear stress:

 Vishay Micromeasurements databooks on Stress analysis with Strain gauges:

 http://www.vishaypg.com/micro-measurements/databooks/
- 3) HBM strain gauge catalog http://www.hbm.com/en/menu/products/strain-gages-accessories/strain-gauge-catalog/
- 4) Processing reference pages and tutorials: www.processing.org