DrawerSideRight



l enend

- CUT laver (red): Panel outline
- DRILL laver (blue). Holes to be drilled
- DIMENSION layer (grey): Panel and hole dimensions
- ANNOTATION layer (black) Hole dimensions (dediameter hedentholds)
- bor side-drilled holes, Z-coordinate is included (e.g., d10 h20 z9.5
- Side-drilled holes are also marked with a blue cross on the DRILL layerr

Hole Schedule