

- CUT layer (red). Panel outline

DRILL layer (blue) Holes to be drillected

DIMENSION layer (green) Panel and hole dimensions

ANNOTATION layer (magenta) Hole dimensions (dediameter hadepth)

Side drilled holes are also marked with a blue cross on the DRUL layer