

ASIAN SKY  
GROUP

2005  
BOMBARDIER  
GLOBAL 5000  
SN: 9149



## AIRCRAFT

MANUFACTURING YEAR	2005
SERIAL NUMBER	9149
TOTAL HOURS	4,928 Since New
TOTAL CYCLES	2,363 Since New
ASKING PRICE	\$9,500,000



TEL: +852 9199 7751  
E-MAIL: sales@asianskygroup.com

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---

## AIRCRAFT HIGHLIGHTS

- Completing 240M Inspection
  - 14 Passenger Configuration
  - 5,000 Hours since new
  - Engine Enrolled on RRCC Enhanced
  - APU Enrolled on JSSI
  - Airframe Enrolled on Bombardier Smart Parts Plus
  - CAMP Maintenance Tracking Program
  - Enhanced Vision System & HUD
  - Batch 3 Upgrade, ADS-B Out, FANS-1/A (CPDLC), WAAS / LPV & TCAS 7.1
  - No Damage History
  - San Marino Registered
  - Private Flights Only
  - Interior Refurbished 2016, New carpet 2024
  - Exterior Paint 2016
- 



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---

## ENGINES & APU

### Engines enrolled on RRCC enhanced

- Engine 1
  - ◊ Model: BR710A2-20
  - ◊ Serial Number: 12411
  - ◊ Total Hours: 4,977 Since New
  - ◊ Total Cycles: 2,343 Since New
- Engine 2
  - ◊ Model: BR710A2-20
  - ◊ Serial Number: 12412
  - ◊ Total Hours: 4,982 Since New
  - ◊ Total Cycles: 2,363 Since New
- APU
  - ◊ Model: Honeywell RE220 (GX)
  - ◊ Serial Number: P-249
  - ◊ Program: JSSI
  - ◊ Total Hours: 6,045 Since New

---

## AVIONICS

- Honeywell Primus 2000XP Avionics Package
- Dual Honeywell RNZ-850 ADF
- Honeywell Primus 2000XP IFCS Autopilot
- Triple Honeywell RCZ-833K w/8.33 kHz spacing Communication Radios
- Honeywell SSCVR w/datalink upgrade CVR
- Dual Honeywell DM-850 DME
- Honeywell DU-870 6-tube (color) EFIS
- Honeywell SSFDR FDR
- Honeywell WU-880 Radar
- Honeywell Primus 2000XP IFCS Flight Director
- Dual Honeywell XS-852A TDR
- Dual Honeywell NZ-2000 FMS
- Dual Honeywell FMS-2000 w/LPV GPS
- Dual Collins HF-9031 w/Avtech CSD-714 SELCAL Hi Frequency
- Triple Honeywell LASEREF III IRS
- Dual Honeywell RNZ-851 w/FM immunity Navigation Radios
- Collins ALT-4000 Radar Altimeter
- Collins SAT-2100 ICG Aerocom 3000 Iridium SATCOM
- Honeywell LSZ-860 Stormscope
- Honeywell Mark V EGPWS w/windshear TAWS
- Honeywell TCAS-2000 w/change 7.1 TCAS
- Dual Honeywell RCZ-833M Mode S w/ enhanced surveillance Transponder
- Honeywell Primus 880 Weather Radar



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---

## STANDARD EQUIPMENT

- Inertial Reference System
  - Flight Data Recorder
  - Weather Radar
  - SATCOM
  - Cockpit Voice Recorder
  - Emergency Locator Transmitter
  - Terrain Awareness & Warning System
  - RVSM
  - Traffic Collision Avoidance System
  - Dual Flight Management System
  - 8.33 channel spacing
- 

## ADDITIONAL EQUIPMENT

- Performance Mod: Fuel Tank Mod in 2018 to increase MTOW to 92,500 lbs
  - Cockpit: Batch 3.3 upgrades, dual multi-function displays, dual EICAS, dual regime autothrottle systems, integrated electric standby instrument (IESI), triple Honeywell AZ-950 micro air data computers, quad Ametek DA-810 data acquisition units, Teledyne datalink system (ACARS), Artex 406 MHz ELT w/nav interface, quick access recorder, CAIMS, Thales enhanced vision system & heads-up display, ADS-B Out, triple Honeywell IC-800 integrated avionics computers, FANS-1/A, WAAS/LPV (SBAS), ADLS datalink, Honeywell Primus II radio management units
  - Crew Accessories: Dual electronic flight bags, electronic pilot checklist (OBDS), Cockpit Printer
- 

## MAINTENANCE PROGRAM

- Airframe: Bombardier Smart Parts Plus
- Engine: Rolls Royce Corporate Care Enhanced
- APU: JSSI
- Tracking: CAMP



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751


Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---

## INTERIOR

- Refurbished in 2016
  - Configuration: Executive/14 passengers
  - Seating: Tan leather seating, four forward executive seats, mid-cabin 3-place berthable divan opposite dual executive club seats, aft 4-place conference group opposite dual executive club seats
  - Refreshment: Forward galley w/coffeemaker, chilled area & ice drawer, galley annex w/high-temperature oven & microwave
  - Cabinetry/Wood: High-gloss dark wood veneer, dual forward foldout tables, mid-cabin foldout table, aft foldout table
  - Entertainment: Airshow 400, dual 18.1-inch bulkhead monitors, four 10.4-inch plug-in monitors, dual DVD players, multi-disc CD changer
  - Accessories: 110-volt AC outlets
  - Lavatory: Forward crew lav & aft lav
- 



## EXTERIOR

- New Paint 2016, Air Livery UK
  - White w/ blue accent stripes
- 



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.

# 2005 BOMBARDIER GLOBAL 5000 SN: 9149

---



ASIAN SKY GROUP

[sales@asianskygroup.com](mailto:sales@asianskygroup.com)  
+852 9199 7751

Specifications are subject to verification by purchaser upon Inspection. Aircraft is subject to prior sale and/or removal from the market without prior notice.



# ASIAN SKY GROUP

Suite 1509, 15/F, 8 Queen's Road East, Wan Chai,  
Hong Kong

TEL: +852 9199 7751  
E-MAIL: sales@asianskygroup.com

[www.asianskygroup.com](http://www.asianskygroup.com)