A SCRAM is necessary	Control rods inserted a utoma tica lly	Control rods inserted manually	Decay heat removal systems	Sa fety Injection System	Manually adds cool sodium to the core	#	End State (Phase - PH1)
SCRAM_TODO	AUTO_RODS_FALL	MANU_RODS_FALL	AUTO_DHR	AUTO_SIS	MANU_PROVIDE_COOLANT		
		•	_			1	ОК
					 0	2	0 K
					—	3	CONTAINMENT
						4	CONTAINMENT
					 0	5	CONTAINMENT
				O	 0	6	CONTAINMENT
						7	CONTAINMENT
						8	CONTAINMENT
		•	•	•		9	CONTAINMENT
						10	CONTAINMENT