

P600 Matrix edition V2.5 - LFO and vibrato waveforms

LFO: "to tape" + 1 (1st press), data knob picks a pair, the LFO shape button picks the shape of the pair. Vibrato: "to tape" + 2, 5th press.
The same speed and amount for every shape; 1 second shown. Plotted from the output of the V2.5 firmware.


0 pulse




1 tri




2 rand (random steps)




3 sine




4 noise (random every tick)




5 saw




6 step8 (8 steps, saw speed)




7 revsaw




8 seq (16-step random melody, 16x slower)



9 step4 (4 steps, saw speed)



10 bit tri (8 steps)



11 bit sine (16 steps)

