



After receiving this proof, the client must carefully check all the details and then confirm OK to proceed.

Please scan and test any barcode/QR code before production.





After the proof is confirmed by the client, the supplier will no longer bear any liability.

date: 2026. 6. 17 Modifies: 1
name: HSX 1EDP9119 6. 17



White

3-01



After receiving this proof, the client must carefully check all the details and then confirm OK to proceed.

Please scan and test any barcode/QR code before production.





After the proof is confirmed by the client, the supplier will no longer bear any liability.

date: 2026. 6. 17 Modifies:1
name: HSX 1EDP9119 6. 17



White

3-02



After receiving this proof, the client must carefully check all the details and then confirm OK to proceed.

Please scan and test any barcode/QR code before production.

After the proof is confirmed by the client, the supplier will no longer bear any liability.

date: 2026. 6. 17 Modifies: 1
name: HSX 1EDP9119 6. 17



White

3-03