
## 7. Soil Moisture



```
void setup()
{
Serial.begin(9600);
pinMode(9,OUTPUT);
}
void loop()
{
int val = analogRead(A1);
 delay(250);
 int perc = (val/876.00)*100;
 if(perc>30){
  digitalWrite(9,HIGH);
 delay(1000);
 }
 else{
 digitalWrite(9,LOW);
 }
}
```