
6. Gas Sensor



```
void setup()
{
    Serial.begin(9600);
    pinMode(13,OUTPUT);
}
void loop()
{
    int sensor_val;
    sensor_val = analogRead(A5);
    Serial.println(ssensor_val);
    delay(500);
}
```