


IDE App

Integrated Development Environment

Version 4.6.0



Copyright

© Bosch Rexroth AG 2026

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAD-SYS (MiSc)/(PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.0	4
3.1	Resolved defects and modifications	4
3.1.1	Bug 1101540: The user cannot navigate from IDE text editing to the start page	4
3.1.2	Bug 1164018: The console log of the text-based coding is incorrect and also has a problem with autocomplete	4
4	Version 4.4.5	4
4.1	New functions	4
4.1.1	PBI 1115165: New button called "Soft Stop"	4
4.2	Resolved defects and modifications	5
4.2.1	Bug 1070023: "move to point" function does not consider jerk	5
4.2.2	Bug 1085178: 3D Viewer extension is not removeable	5
5	Service and support	6
6	Index	7

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025-11	IDE App Version 4.4.5
02	2026-03	IDE App Version 4.6.0

Further information

- See ➔ [IDE App, Application Manual](#)

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.0

3.1 Resolved defects and modifications

3.1.1 Bug 1101540: The user cannot navigate from IDE text editing to the start page

Description

The user can now navigate from the text-based programming in the IDE to the start page via the start page icon.

3.1.2 Bug 1164018: The console log of the text-based coding is incorrect and also has a problem with autocomplete

Description

The console output is now visible in all cases. The autocomplete suggestions have been corrected.


4 Version 4.4.5

4.1 New functions

4.1.1 PBI 1115165: New button called "Soft Stop"

Description

A new button called "Soft Stop" has been introduced in Visual Coding to stop the Script Manager without error generation.



4.2 Resolved defects and modifications

4.2.1 Bug 1070023: "move to point" function does not consider jerk Description

There was no option to add jerk parameter in the "move to point" block.

Bugfix

Jerk parameter can be added to "move to point" block.

4.2.2 Bug 1085178: 3D Viewer extension is not removeable

Description

3D Viewer extension once added could not be removed as there was no delete button available.

Bugfix

The delete button has been added to the 3D Viewer extension too and now it can be deleted.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: [↗ service.svc@boschrexroth.de](mailto:service.svc@boschrexroth.de)

Internet: [↗ http://www.boschrexroth.com](http://www.boschrexroth.com)

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

1, 2, 3 ...

"move to point" function does not consider jerk	5
3D Viewer extension is not removeable	5

A

About this documentation	4
--------------------------------	---

B

Bug 1070023	5
Bug 1085178	5
Bug 1101540	4
Bug 1164018	4

H

Helpdesk	6
Hotline	6

I

Important information	4
-----------------------------	---

N

New button called "Soft Stop"	4
New functions version 4.4.5	4

P

PBI 1115165	4
Product information	4

R

Resolved defects and modifications version 4.4.5	5
Resolved defects and modifications Version 4.6.0	4

S

Service hotline	6
Support	6

T

The console log of text-based coding is incorrect and also has a problem with autocomplete	4
The user cannot navigate from IDE text editing to the start page	4

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

