

Key Value Database App

Managing Data in the ctrlX OS Data Layer with Persistence

Version 4.6.3

Copyright

© Bosch Rexroth AG 2026

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAX (TaDo/PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.3	4
3.1	New functions	4
3.1.1	Feature 1132411: Improvements and bugfixes	4
3.2	Resolved defects and modifications	4
3.2.1	Bug 1148925: Memory leak when reading meta data from implicit (virtual) nodes	4
3.2.2	Bug 1191856: Vulnerability bugfix: GO-2020-0036 (CVE-2019-11254)	4
4	Version 4.4.0	4
4.1	Resolved defects and modifications	4
4.1.1	Bug 1035076: KVD-implicit nodes showed errors in the Data Layer web interface	4
5	Service and support	6
6	Index	7

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025-11	Key Value Database App Version 4.4.0
02	2026-03	Key Value Database App Version 4.6.3

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.3

3.1 New functions

3.1.1 Feature 1132411: Improvements and bugfixes

Description

The app contains improvements, security updates and minor corrections.

3.2 Resolved defects and modifications

3.2.1 Bug 1148925: Memory leak when reading meta data from implicit (virtual) nodes

Description

Increase in memory when reading meta information from implicit (virtual) nodes.

3.2.2 Bug 1191856: Vulnerability bugfix: GO-2020-0036 (CVE-2019-11254)

Description

Vulnerability bugfix GO-2020-0036 Excessive resource consumption when parsing YAML in gopkg.in/yaml.v2.

Further information: ➔ <https://pkg.go.dev/vuln/GO-2020-0036>

4 Version 4.4.0

4.1 Resolved defects and modifications

4.1.1 Bug 1035076: KVD-implicit nodes showed errors in the Data Layer web interface

Description

If the option "Show incomplete configuration from Data Layer node" is activated, an error "Error 404 Invalid Address" was displayed for implicitly configured nodes.

This bug fix adapts metadata of implicit nodes and their allowed operations to the use in the app:

- Corrects allowed operations of implicit nodes.
- Implicit root node changed to "Folder" type.
- Implicit branch nodes have been changed to the "Folder" type, but allow reading, writing and deleting (unchanged).
- Explicit nodes of type "Collection" and "Resource" allow writing.
- Explicit nodes of type "Folder" prohibit writing.



The yellow validation warnings, which are optionally displayed in the Data Layer web interface, can be ignored. The app uses a customized set of allowed operations that differs from the recommended set.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: ➔ service.svc@boschrexroth.de

Internet: ➔ <http://www.boschrexroth.com>

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

B

Bug 1148925 4

Bug 1191856 4

F

Feature 1132411 4

H

Helpdesk 6

Hotline 6

I

Important information 4

Improvements and bugfixes 4

M

Memory leak when reading meta data from
implicit (virtual) nodes 4

P

Product information 4

S

Service hotline 6

Support 6

V

Vulnerability bugfix: GO-2020-0036
(CVE-2019-11254) 4

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

