

OPC UA Client App

OPC UA Client for ctrlX OS

Version 4.6.0

Copyright

© Bosch Rexroth AG 2026-03

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAG-SW (MiNi/PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.0	4
3.1	New functions	4
3.1.1	Feature 1120334: OPC UA Client – New functionalities	4
3.2	Resolved defects and modifications	4
3.2.1	Bug 1120160: OPC UA Client – Subscription with a large number of MonitoredItems led to problems with certain OPC UA servers	4
3.2.2	Bug 1133347: OPC UA – License status was sporadically displayed incorrectly if the app startup was faulty	5
3.2.3	Bug 1137399: Incorrect ErrorID in case of invalid identifier type for UA_NodeGetInformation	5
3.2.4	Bug 1159217: OPC UA Client – Exception when operating the subscription	5
3.2.5	Bug 1163938: Creating subscriptions not possible after several network interruptions	5
3.2.6	Bug 1174085: OPC UA Client – Not all sessions were closed when shutting down the OPC UA Client App	5
3.2.7	Bug 1174296: Fatal exception when using Int32, enums and structures in subscriptions	5
3.2.8	Bug 1174299: Missing folder "Objects" for MonitoredItems which transfer errors	6
3.2.9	Bug 1182232: Data Layer Subscription does not return any data	6
3.2.10	Bug 1182763: OPC UA Client – When deleting a session, an exception could sporadically occur	6
4	Version 4.4.1	6
4.1	New functions	6
4.1.1	Feature 1003995: OPC UA Client – Support for core24 and ctrlX OS version 4.X	6
4.1.2	Feature 1004005: OPC UA Client – Update of the OPC UA Stack	6
4.1.3	Feature 1045456: OPC UA Client – Support for floating licenses	6
4.1.4	Feature 1054450: New functionality in the OPC UA Client App	6
4.2	Resolved defects and modifications	7
4.2.1	Bug 962373: OPC UA Client – Addressing OPC UA nodes with string node IDs ending with "/" does not work	7
4.2.2	Bug 1007205: OPC UA Client – Session was not terminated correctly in case of error	7
5	Service and support	8
6	Index	9

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025-11	OPC UA Client App Version 4.4.1
02	2026-03	OPC UA Client App Version 4.6.0

Further information

- Refer to ➔ [OPC UA Client App, Application Manual](#)

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.0

3.1 New functions

3.1.1 Feature 1120334: OPC UA Client – New functionalities

Description

The OPC UA Client contains the following new functionalities:

- Status and configuration of the memory in the web interface.
- Reading out and considering the server operation limit `MaxMonitoredItemsPerCall`.

3.2 Resolved defects and modifications

3.2.1 Bug 1120160: OPC UA Client – Subscription with a large number of MonitoredItems led to problems with certain OPC UA servers

Description

Creating a subscription on Data Layer nodes of the OPC UA client results in an unnecessarily high number of `CreateMonitoredItem` requests. The nodes were added to the subscription individually instead of in a collective request. This resulted in an overload on some OPC UA servers, which was indicated by various error codes (e.g. "BadResourceUnavailable").

Bug fix

It is now possible to bundle several `MonitoredItems` in a `CreateMonitoredItem` request. For this purpose, the `MonitoredItems` requests are collected for a configurable period of time and transmitted in a request.

The following steps have to be carried out to activate the function:

1. ➔ Create your client session (persistent).
2. ➔ Go to "Manage app data" (or similar) and click on "Save as archive".

3. In the archive, edit the: "*settings* → *opcuaclient* → *clients_configuration.conf*" file and set `clients/0/add_remove_monitored_item_delay = 100`
4. Load the changed configuration and restart the OPC UA Client App or ctrlX CORE.

3.2.2 Bug 1133347: OPC UA – License status was sporadically displayed incorrectly if the app startup was faulty

Description

The license status of the OPC UA app was sporadically displayed incorrectly if the start-up of the app was faulty. As a result, it was displayed that a license was missing, which was incorrect.

3.2.3 Bug 1137399: Incorrect ErrorID in case of invalid identifier type for UA_NodeGetInformation

Description

If an invalid identifier type (e.g. numeric instead of string) was used as identifier (e.g. `i=asdf`), the function `UA_NodeGetInformation` incorrectly returned `BadNotFound`.

Troubleshooting

The function now correctly returns `BadNodeIdInvalid` if there is an invalid combination of identifier type and identifier format.

3.2.4 Bug 1159217: OPC UA Client – Exception when operating the subscription

Description

Exceptions occurred in the OPC UA Client when operating subscription exceptions.

3.2.5 Bug 1163938: Creating subscriptions not possible after several network interruptions

Description

If several communication interruptions occurred within the network during an active subscription, it was sporadically not possible anymore to create new subscriptions. Subsequently, the existing subscription did not return any data anymore.

3.2.6 Bug 1174085: OPC UA Client – Not all sessions were closed when shutting down the OPC UA Client App

Description

When shutting down the OPC UA Client app, not all sessions were closed (via `SessionCloseRequest`) by the client. This resulted in open sessions on pages of the connected OPC UA Server.

3.2.7 Bug 1174296: Fatal exception when using Int32, enums and structures in subscriptions

Description

When using `Int32`, enums and structures in subscriptions, fatal exceptions could occur in server timeout scenarios.

3.2.8 Bug 1174299: Missing folder "Objects" for MonitoredItems which transfer errors

Description

When using several hundred nodes in a subscription, which return an error code, sporadically, the session did not return any data anymore.

3.2.9 Bug 1182232: Data Layer Subscription does not return any data

Description

If the server returns an incorrect code when the value of a subscription is changed for the first time `BadWaitingForInitialData` it resulted in the subscription not returning any data.

3.2.10 Bug 1182763: OPC UA Client – When deleting a session, an exception could sporadically occur

Description

When deleting a session, an exception sporadically occurred when trying to simultaneously establish a connection for the session. The exception resulted in an OPC UA Client app restart.

4 Version 4.4.1

4.1 New functions

4.1.1 Feature 1003995: OPC UA Client – Support for core24 and ctrlX OS version 4.X

Description

The OPC UA Client App is based on core24 and ctrlX OS version 4.X.

4.1.2 Feature 1004005: OPC UA Client – Update of the OPC UA Stack

Description

The OPC UA Client App contains the latest version of the OPC UA stack.

4.1.3 Feature 1045456: OPC UA Client – Support for floating licenses

Description

The OPC UA Client App now supports the following floating license:

- SWL-XC*-UAC-OPCUA*CLT*SD*-Y1F1

4.1.4 Feature 1054450: New functionality in the OPC UA Client App

Description

New functionality in the OPC UA Client App:

- The OPC UA Client now supports redundancy in cold failover mode.
This corresponds to the [↗ non-transparent redundancy](#) with failover mode [↗ cold](#), described in the OPC UA specification.
- Support for additional security policies:
 - [↗ ECC-nistP256](#)
 - [↗ ECC-nistP384](#)
- Health status display of the app.

4.2 Resolved defects and modifications

4.2.1 Bug 962373: OPC UA Client – Addressing OPC UA nodes with string node IDs ending with "/" does not work

Description

In the OPC UA Client App, addressing OPC UA nodes using string node IDs ending with a slash ("/") did not work.

As a result, the corresponding nodes could not be read, written or browsed. The cause of the error has been fixed.

4.2.2 Bug 1007205: OPC UA Client – Session was not terminated correctly in case of error

Description

In case of an error in a client session, the session was sporadically not closed correctly using CloseSessionRequest by the OPC UA Client app. Thus, the sessions could remain active on the OPC UA Server pages as long as the timeout was not yet active.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: ➔ service.svc@boschrexroth.de

Internet: ➔ <http://www.boschrexroth.com>

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

H

Helpdesk 8

Hotline 8

I

Important information 4

P

Product information 4

S

Service hotline 8

Support 8

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

