

OPC UA Server App

OPC UA Server for ctrlX OS

Version 4.6.0

Copyright

© Bosch Rexroth AG 2026-03

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAG-SW (MiNi/PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.0	4
3.1	New functions	4
3.1.1	Feature 1120333: OPC UA Server – New functionality	4
3.2	Resolved defects and modifications	4
3.2.1	Bug 1119296: The user roles are not set correctly	4
3.2.2	Bug 1143590: OPC UA Server: Fatal exception error when terminating an OPC UA session	4
3.2.3	Bug 1166711: High CPU load for MonitoredItems which are set to "Disable" mode	5
3.2.4	Bug 1178914: OPC UA Server – The shutdown of the OPC UA Server App was faulty	5
4	Version 4.4.1	5
4.1	New functions	5
4.1.1	Feature 1003996: OPC UA Server – Support of core24 and ctrlX OS Version 4.X	5
4.1.2	Feature 1004006: OPC UA Server – Update of the OPC UA Stack	5
4.1.3	Feature 1004008: OPC UA Server – Support for server redundancy in cold failover mode	5
4.1.4	Feature 1006577: OPC UA Server – New licenses available ...	5
4.1.5	Feature 1045455: OPC UA Server – Support for floating licenses	5
4.1.6	Feature 1054448: OPC UA Server – New functionalities	6
4.2	Resolved defects and modifications	6
4.2.1	Bug 1049875: OPC UA Apps – Selection in the navigation menu was lost	6
4.2.2	Bug 1079729: OPC UA Server – Subscription sampling interval may have been determined outside the configuration limits ..	6
4.2.3	Bug 1094637: OPC UA Server – Invalid endpoint configuration was possible	6
4.2.4	Bug 1094642: OPC UA Server – Configuration adjustments during app startup were not saved	6
4.2.5	Bug 1095291: OPC UA Server – Nodes under Data Layer address "opcuaserver/companion-model" are missing when using OPC UA Server authorizations	7
4.2.6	Bug 1104802: OPC UA Apps – Display of the "OPC UA" navigation menu in the web interface despite missing authorization .	7
4.2.7	Bug 1119335: The user roles are not set correctly	7
5	Service and support	8
6	Index	9

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025 - 11	OPC UA Server App Version 4.4.1
02	2026 - 3	OPC UA Server App Version 4.6.0

Further information

- Refer to ➔ [OPC UA Server App, Application Manual](#)

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.0

3.1 New functions

3.1.1 Feature 1120333: OPC UA Server – New functionality

Description

The OPC UA Server provides the following new functionality:

- Status and configuration of the memory in the web interface.

3.2 Resolved defects and modifications

3.2.1 Bug 1119296: The user roles are not set correctly

Description

The OPC UA user roles (CONFIGUREADMIN, SECURITYADMIN) are not set according to the Data Layer user area (SCOPE OPCUA_SERVER_MANAGE, SCOPE OPCUA_PUBSUB_MANAGE).

The cause of the error has been resolved.

3.2.2 Bug 1143590: OPC UA Server: Fatal exception error when terminating an OPC UA session

Description

In rare cases, a critical exception error could occur in the ctrlX OPC UA Server App when terminating an OPC UA session. This caused the app to crash and restart, potentially interrupting existing connections.

The cause of the error has been resolved.

3.2.3 Bug 1166711: High CPU load for MonitoredItems which are set to "Disable" mode

Description

If the MonitoredItems in a subscription are set to "Disable", they do not return any data anymore. Nevertheless, a high system load was generated by these MonitoredItems.

3.2.4 Bug 1178914: OPC UA Server – The shutdown of the OPC UA Server App was faulty

Description

When shutting down the OPC UA Server App, various errors could occur, e.g. service requests not fully answered or fatal exceptions in the OPC UA Server App.

4 Version 4.4.1

4.1 New functions

4.1.1 Feature 1003996: OPC UA Server – Support of core24 and ctrlX OS Version 4.X

Description

The OPC UA Server App is based on core24 and ctrlX OS version 4.X.

4.1.2 Feature 1004006: OPC UA Server – Update of the OPC UA Stack

Description

The latest version of the OPC UA stack is built into the OPC UA Server app.

4.1.3 Feature 1004008: OPC UA Server – Support for server redundancy in cold failover mode

Description

The OPC UA Server now supports server redundancy in cold failover mode. This corresponds to the ➔ [non-transparent redundancy](#) with failover mode ➔ [cold](#), described in the OPC UA specification.

4.1.4 Feature 1006577: OPC UA Server – New licenses available

Description

The following new licenses are available for the OPC UA Server:

- OPC UA Server Basic License: SWL-XCx-UAS-OPCUA*SRV*xxx-BANN
- OPC UA Server Advanced License: SWL-XCx-UAS-OPCUASERVER*xx-ADNN

4.1.5 Feature 1045455: OPC UA Server – Support for floating licenses

Description

The OPC UA Server supports the following floating licenses:

- R911430693 / SWL-XC*-UAS-OPCUA*SRV*SD*-Y1F1
- R911430692 / SWL-XC*-UAS-OPCUA*SRV*AD*-Y1F1

4.1.6 Feature 1054448: OPC UA Server – New functionalities

Description

The OPC UA Server contains the following new functionalities:

- In the web interface of the OPC UA Server, there is now an icon with a link to the certificate store. The icon shows whether there are any rejected certificates.
- Support for additional security policies:
 - ➔ [ECC-nistP256](#)
 - ➔ [ECC-nistP384](#)
- Use of DataLayer bulk requests for OPC UA Service Browse.
- Health status display of the app.

4.2 Resolved defects and modifications

4.2.1 Bug 1049875: OPC UA Apps – Selection in the navigation menu was lost

Description

If a page of an OPC UA app was selected in the web interface, for example OPC UA Server configuration, and if another tab was selected within the called page, for example "Information Model", the selection in the navigation menu, for example "OPC UA -> Server", was lost.

The cause of the error has been fixed.

4.2.2 Bug 1079729: OPC UA Server – Subscription sampling interval may have been determined outside the configuration limits

Description

The logic for determining the closest subscription sampling interval ignored the configuration limits of the ctrlX OPC UA Server.

The cause of the error has been fixed.

4.2.3 Bug 1094637: OPC UA Server – Invalid endpoint configuration was possible

Description

An invalid endpoint configuration could be created in the OPC UA Server if an invalid PolicyId was specified with 8 in the Data Layer method "add-user-token-config" (address: opcuaserver/endpoint-configuration/add-user-token-config). This prevented the OPC UA Server from starting upon the next restart.

4.2.4 Bug 1094642: OPC UA Server – Configuration adjustments during app startup were not saved

Description

In the ctrlX OPC UA Server app, configuration changes resulting from extensions after an app update, for example, may not have been saved.

The cause of the error has been fixed.

4.2.5 Bug 1095291: OPC UA Server – Nodes under Data Layer address "opcuaserver/companion-model" are missing when using OPC UA Server authorizations

Description

Even though the OPC UA Server authorizations “View” (Data Layer Scope: opcuaserver.view) and “Manage” (Data Layer Scope: opcuaserver.manage) were set for a user, not all nodes were displayed under the Data Layer address "opcuaserver/companion-model". Data Layer access to these nodes was therefore not possible for this user.

The cause of the error has been fixed.

4.2.6 Bug 1104802: OPC UA Apps – Display of the "OPC UA" navigation menu in the web interface despite missing authorization

Description

In the OPC UA apps, the "OPC UA" navigation menu was displayed in the ctrlX web interface even though the current user session did not have the required OPC UA authorizations.

The cause of the error has been fixed.

4.2.7 Bug 1119335: The user roles are not set correctly

Description

The OPC UA user roles (CONFIGUREADMIN, SECURITYADMIN) are not set according to the DataLayer user panel (SCOPE_OPCUA_SERVER_MANAGE, SCOPE_OPCUA_PUBSUB_MANAGE).

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: ➔ service.svc@boschrexroth.de

Internet: ➔ <http://www.boschrexroth.com>

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

B

Bug 1119296 4

Bug 1143590 4

H

Helpdesk 8

Hotline 8

I

Important information 4

O

OPC UA Server: Fatal exception error when
terminating an OPC UA session 4

P

Product information 4

S

Service hotline 8

Support 8

T

The user roles are not set correctly 4

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

