

PLC App

PLC Runtime Environment for ctrlX OS
Version 4.6.0

Copyright

© Bosch Rexroth AG 2026-03

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAG-SW (MiNi)

Table of contents

1	About this documentation	4
2	Product information	4
2.1	Product information	4
3	Version 4.6.0	4
3.1	New functions	4
3.1.1	Feature 1105726: Integration CODESYS V3.5 SP21 Patch 5 ..	4
3.2	Notes on use and known restrictions	4
3.2.1	Bug 991188: According to IEC Watchdog, diagnostic messages are cyclically entered in the PLC log	4
4	Version 4.4.0	4
4.1	New functions	4
4.1.1	Feature 1095704: Integration CODESYS V3.5 SP21	4
4.2	Notes on use and known restrictions	5
4.2.1	Bug 991188: According to IEC Watchdog, diagnostic messages are cyclically entered in the PLC log	5
5	Service and support	6
6	Index	7

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025 – 11	Release Notes for PLC App Version 4.4.0
02	2026 – 03	Release Notes for PLC App Version 4.6.0

2 Product information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.0

3.1 New functions

3.1.1 Feature 1105726: Integration CODESYS V3.5 SP21 Patch 5

Description

The software products ctrlX PLC Engineering (PLE-4.6.0) and ctrlX I/O Engineering (IOE-4.6.0), as well as the PLC App (PLC-4.6.0) are based on CODESYS version 3.5 SP21 Patch 5.

3.2 Notes on use and known restrictions

3.2.1 Bug 991188: According to IEC Watchdog, diagnostic messages are cyclically entered in the PLC log

Description

If a watchdog occurs in a PLC task, the following message is entered sporadically and cyclically in the PLC log:

getting the context... ERROR: address not mapped to object ERROR: SIGSEGV (address:0x1102561483800) in <Async_SrvService>

4 Version 4.4.0

4.1 New functions

4.1.1 Feature 1095704: Integration CODESYS V3.5 SP21

Description

The software products ctrlX PLC Engineering (PLE-4.4.0) and ctrlX I/O Engineering (IOE-4.4.0), as well as the PLC App (PLC-4.4.0) are based on CODESYS Version 3.5 SP21 Patch 3 (3.5.21.30).

4.2 Notes on use and known restrictions

4.2.1 Bug 991188: According to IEC Watchdog, diagnostic messages are cyclically entered in the PLC log

Description

If a watchdog occurs in a PLC task, the following message is entered sporadically and cyclically in the PLC log:

getting the context... ERROR: address not mapped to object ERROR: SIGSEGV (address:0x1102561483800) in <Async_SrvService>

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: ➔ service.svc@boschrexroth.de

Internet: ➔ <http://www.boschrexroth.com>

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

H

Helpdesk 6

Hotline 6

I

Important notes 4

P

Product information 4

S

Service hotline 6

Support 6

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

