

Service Indicator App

Service Indicator for ctrlX OS

Version 4.6.1

Copyright

© Bosch Rexroth AG 2026

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAX (TaDo)/(PiaSt)

Table of contents

1	About this documentation	4
2	Information	4
2.1	Product information	4
3	Version 4.6.1	4
3.1	New functions	4
3.1.1	Feature 1097040: Improved CCD devices handling	4
3.1.2	Feature 1109490: Improvements of the web interface and the user experience	4
3.1.3	Feature 1132139: Detailed view of drives and motors	4
3.1.4	Feature 1138813: User configurable region and contact information	4
3.2	Resolved defects and modifications	5
3.2.1	Bug 1155910: Unit mismatch in motor operating hours in exported excel file	5
4	Version 4.4.0	5
4.1	New functions	5
4.1.1	Feature 1004328: New Features	5
4.2	Resolved defects and modifications	5
4.2.1	Bug 1105158: Diagnosis column does not show the actual status of the drive	5
4.2.2	Bug 1105666: Summary indicator does not reflect the correct statuses of devices	5
5	Service and support	6
6	Index	7

1 About this documentation

Editions of this documentation

Edition	Release date	Notes
01	2025-11	Service Indicator App version 4.4.0
02	2026-03	Service Indicator App version 4.6.1

2 Information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.1

3.1 New functions

3.1.1 Feature 1097040: Improved CCD devices handling

Description

QR codes are now individually shown for CCD master and slave devices.

3.1.2 Feature 1109490: Improvements of the web interface and the user experience

Description

- QR code display is now in a scrollable window
- Error messages are now accurate based on DCA app status (not installed, deactivated)
- The number of subcomponents that have an issue (warning / error) is now displayed in the status bar message
- Minor improvements to remote devices dialog and export dialog
- Units for speed, torque/force are now accurately displayed based on axis configuration

3.1.3 Feature 1132139: Detailed view of drives and motors

Description

The "Axisname" item in each row can be clicked to open a pop-up dialog window, with more details about the drive and motor for that particular axis (type, firmware, serial number, etc.).

3.1.4 Feature 1138813: User configurable region and contact information

Description

The contact information displayed in the "Contact Us" section of the web interface can be changed for different world regions from the configure button in the drive overview (Canada, China, DE/AT/CH, India, Mexico, US, others).

3.2 Resolved defects and modifications

3.2.1 Bug 1155910: Unit mismatch in motor operating hours in exported excel file

Description

The unit of the motor operating hours in the exported excel file can sometimes be inaccurate.

Bugfix

The time unit (hours/seconds) is properly handled in the excel export function which fixes the mismatch of values.

4 Version 4.4.0

4.1 New functions

4.1.1 Feature 1004328: New Features

Description

- Drives connected in a CCD topology (CCD master + slaves) are now properly supported by the Service Indicator app.
- The export function web interface is simplified for ease of use.

4.2 Resolved defects and modifications

4.2.1 Bug 1105158: Diagnosis column does not show the actual status of the drive

Description

The diagnosis column in the web interface table sometimes does not change when an error on the drive is cleared. It shows that the drive is still in error state.

Bugfix

The caching mechanism is improved for faster updating of values on the web interface.

4.2.2 Bug 1105666: Summary indicator does not reflect the correct statuses of devices

Description

The summary indicator output sometimes does not reflect the correct statuses of all devices in the Service Indicator web interface table. E.g. sometimes the indicator shows "Yellow", and the message says "Probability of failure for one or more devices" while all the devices are green.

Bugfix

The caching mechanism is improved for faster updating of values on the web interface.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: [↗ service.svc@boschrexroth.de](mailto:service.svc@boschrexroth.de)

Internet: [↗ http://www.boschrexroth.com](http://www.boschrexroth.com)

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

B

Bug 1105158	5
Bug 1105666	5
Bug 1155910	5

D

Detailed view of drives and motors	4
Diagnosis column does not show the actual status of the drive	5

F

Feature 1004328	5
Feature 1097040	4
Feature 1109490	4
Feature 1132139	4
Feature 1138813	4

H

Helpdesk	6
Hotline	6

I

Improved CCD devices handling	4
Improvements of the web interface and the user experience	4
Information	4

N

New Features	5
New functions	4, 5

P

Product information	4
---------------------------	---

R

Resolved defects and modifications	5
--	---

S

Service hotline	6
Summary indicator does not reflect the correct statuses of devices	5
Support	6

U

Unit mismatch in motor operating hours in exported excel file	5
User configurable region and contact information	4

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

