

System Overview App

System Topology and System Information
Version 4.6.0

Copyright

© Bosch Rexroth AG 2026

All rights reserved, also regarding any disposal, exploitation, reproduction, editing, distribution, as well as in the event of applications for industrial property rights.

Disclaimer

The specified data only serves to describe the product. As our products are constantly being further developed, no statements concerning a certain condition or suitability for a certain application can be derived from our information. The information given does not release the user from the obligation of own judgment and verification. Please note that our products are subject to a natural process of wear and aging.

DC-AE/PAX (TaDo/PiaSt)

Table of contents

1	About this documentation	4
2	Important information	4
2.1	Product information	4
3	Version 4.6.0	4
3.1	New functions	4
3.1.1	Feature 1109476: Device replacement	4
3.1.2	Feature 1122227: Improvement of the user interface	4
3.2	Bugfixes and modifications	4
3.2.1	Bug 1017155: EtherCAT data request via SOE and COE	4
3.2.2	Bug 1039519: IndraDrive data is mostly not read	4
3.2.3	Bug 1132379: No warning for incomplete component data	5
3.2.4	Bug 1132386: Error in the details, reading out motor information of the XVR device	5
3.2.5	Bug 1173933: Dependency conflict with EtherCAT Master	5
3.2.6	Bug 1185711: EtherCAT devices are not displayed correctly	5
4	Version 4.4.0	5
4.1	New functions	5
4.1.1	Feature 994799: Complete data backup: Restoring	5
4.1.2	Feature 994800: Complete data backup: Backup	5
4.2	Bugfixes and modifications	6
4.2.1	Bug 1038016: Details are hidden if the list contains many lines	6
4.2.2	Bug 1081137: Serial number of the Safety-IO is not displayed	6
4.2.3	Bug 1131324: "Components" tab does not work anymore	6
5	Service and support	7
6	Index	9

1 About this documentation

Editions of this documentation

Edition	Release date	Note
01	2025-11	System Overview App Version 4.4.0
02	2026-03	System Overview App Version 4.6.0

Further information

- See ➔ [System Overview App, Application Manual](#)

2 Important information

2.1 Product information

For the latest information on our products, go to ➔ <https://www.boschrexroth.com>.

For current security advisories, please refer to ➔ <https://psirt.bosch.com/security-advisories/>

3 Version 4.6.0

3.1 New functions

3.1.1 Feature 1109476: Device replacement

Description

- The drive can be replaced by a new drive.
- A wizard controls the entire process.

3.1.2 Feature 1122227: Improvement of the user interface

Description

- Improvements in the "Backup" dialog
- Improvements in the "Firmware update" dialog

3.2 Bugfixes and modifications

3.2.1 Bug 1017155: EtherCAT data request via SOE and COE

Description

The test setup comprises over 200 EtherCAT Slave devices. When accessing the "Components" window, only a small amount of device data is displayed. Many of the data requested via COE and SOE are not answered. An internal server error occurs.

Troubleshooting

All data requests are processed.

3.2.2 Bug 1039519: IndraDrive data is mostly not read

Description

Only a small amount of IndraDrive data is displayed.

Troubleshooting

Further IndraDrive data is displayed.

3.2.3 Bug 1132379: No warning for incomplete component data

Description

No warning was displayed if the component data was downloaded before the "Components" window was fully loaded.

Troubleshooting

A warning is displayed.

3.2.4 Bug 1132386: Error in the details, reading out motor information of the XVR device

Description

Although the XVR (and XVE) devices have ctrlX DRIVE firmware, they do not have motors, as they are "only" power supply units.

Troubleshooting

Motor information for the XVR device is not read.

3.2.5 Bug 1173933: Dependency conflict with EtherCAT Master

Description

The dependency of the application on the EtherCAT Master is not correct.

Troubleshooting

The dependency on the EtherCAT app was removed.

3.2.6 Bug 1185711: EtherCAT devices are not displayed correctly

Description

When the "Topology" window is opened, not all EtherCAT devices are displayed.

Troubleshooting

EtherCAT devices are displayed correctly.

4 Version 4.4.0

4.1 New functions

4.1.1 Feature 994799: Complete data backup: Restoring

Description

- Starts parallel restoring of the drive parameters
- Starts the restoring the ctrlX OS

4.1.2 Feature 994800: Complete data backup: Backup

Description

- Starts parallel saving of selected drives
- Starts the backup of ctrlX OS (with or without apps)

4.2 Bugfixes and modifications

4.2.1 Bug 1038016: Details are hidden if the list contains many lines

Description

If the device list is long enough, select a device in the lower area. The details are displayed, but are not yet visible. To see them, scroll up.

Troubleshooting

The details are always visible.

4.2.2 Bug 1081137: Serial number of the Safety-IO is not displayed

Description

The serial number of the Safety-IO is not displayed.

Troubleshooting

The serial number of the Safety-IO is displayed.

4.2.3 Bug 1131324: "Components" tab does not work anymore

Description

The "Components" tab does not longer work and remains empty.

Troubleshooting

All components are displayed.

5 Service and support

Our worldwide service network provides an optimized and efficient support. Our experts provide you with advice and assistance. You can contact us **24/7**.

Service Germany

Our technology-oriented Competence Center in Lohr, Germany, is responsible for all your service-related queries for electric drive and controls.

Contact the **Service Hotline** and **Service Helpdesk** under:

Phone: **+49 9352 40 5060**

Fax: **+49 9352 18 4941**

Email: [↗ service.svc@boschrexroth.de](mailto:service.svc@boschrexroth.de)

Internet: [↗ http://www.boschrexroth.com](http://www.boschrexroth.com)

Additional information on service, repair (e.g. delivery addresses) and training can be found on our internet sites.

Service worldwide

Outside Germany, please contact your local service office first. For hotline numbers, refer to the sales office addresses on the internet.

Preparing information

To be able to help you more quickly and efficiently, please have the following information ready:

- Detailed description of malfunction and circumstances
- Type plate specifications of the affected products, in particular type codes and serial numbers
- Your contact data (phone and fax number as well as your e-mail address)

6 Index

1, 2, 3 ...

"Components" tab does not work anymore . . 6

A

About this documentation 4

B

Bug 1017155 4

Bug 1038016 6

Bug 1039519 4

Bug 1081137 6

Bug 1131324 6

Bug 1132379 5

Bug 1132386 5

Bug 1173933 5

Bug 1185711 5

Bugfixes and modifications Version 3.6.1 . . 4, 6

C

Comprehensive data backup: Restore 5

D

Dependency conflict with EtherCAT Master . . 5

Details are hidden if the list contains many
lines 6

Device replacement 4

E

Error in the details, reading out motor
information of the XVR device 5

EtherCAT data request via SOE and COE . . . 4

EtherCAT devices are not displayed correctly . 5

F

Feature 994799 5

Feature 994800 5

Feature 1109476 4

Feature 1122227 4

H

Helpdesk 7

Holistic data backup: Archive 5

Hotline 7

I

Important information 4

Improvement of the user interface 4

IndraDrive data is mostly not read 4

N

New functions 3.6.0 4, 5

No warning for incomplete component data . . 5

P

Product information 4

S

Serial number of the Safety-IO is not displayed
. 6

Service hotline 7

Support 7

Bosch Rexroth AG
Bgm.-Dr.-Nebel-Str. 2
97816 Lohr a.Main
Germany
Tel. +49 9352 18 0
Fax +49 9352 18 8400
www.boschrexroth.com/electrics

