Browning Citori / Superposed Over/Under

Browning / Miroku Japan • Classic Boxlock Over/Under Double-Barrel Shotguns (12 & 20 Gauge)

Manufacturer:	Browning / Miroku Japan	**Category:**	Shotguns
Action Type:	Break-Action Over/Under Double-Barrel Shotgun	**Era / Service:**	Fine Sporting Benchmark (1973–Present)
Calibers:	12 Gauge, 20 Gauge, 28 Gauge, .410 Bore	**Covered Models:**	Citori 725, Citori CX / CXS, Superposed Classic (Belgium), Citori Hunter

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Inertia Block Trigger Block Tuning • Automatic Ejector Timing & Hammer Springs • Hinge Pin Wear Shimming (Off-Face Repair) • Top Lever Center Alignment Check • Locking Bolt Bite Hand-Stoning

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
LOCKING SYSTEM	Full-width transverse tapered locking bolt slides forward through receiver floor into underlugs (wears in, not out)
INERTIA TRIGGER	Recoil from first barrel shifts inertia block to disconnect first sear and connect second sear for second shot
TOP LEVER POSITION	Top lever must sit slightly to the RIGHT of center on fresh guns (sign of full locking bolt reserve)
HINGE PIN	Hardened replaceable cylindrical hinge pin; if action becomes loose, hinge pin is turned or replaced with oversize pin

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Second Barrel Fails to Fire on Light Loads (Inertia Trigger No-Reset) **First barrel fires normally, but pulling trigger second time feels dead; second hammer not tripped**	• Extremely light 7/8 oz low-recoil skeet loads fail to produce enough inertia to kick the inertia block rearward. • Dried grease gumming inertia block pivot.	**Immediate Action: Bump buttstock against knee to mechanically reset inertia block. Gunsmith Action: Remove buttstock. Clean trigger group. Lighten inertia block return spring slightly or convert to mechanical trigger conversion (as in Citori 725 FireLite trigger).**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Browning Citori Over/Under Disassembly & Action Tuning	MidwayUSA / Larry Potterfield	Teardown of the Browning Citori: removing buttstock, inspecting inertia block and hammer springs, and checking top lever lockup.