Browning Hi-Power / SA-35

FN Herstal / Browning / Springfield Armory • P-35 9mm Combat Pioneer & Springfield SA-35 (9x19mm Parabellum)

Manufacturer:	FN Herstal / Browning / Springfield Armory	**Category:**	Pistols
Action Type:	Single-Action Semi-Automatic (SAO)	**Era / Service:**	Historic Military & Duty (1935–Present)
Calibers:	9x19mm Parabellum, .40 S&W;	**Covered Models:**	FN Hi-Power Mk I / II / III, Browning Hi-Power Practical, Springfield Armory SA-35, Inglis Hi-Power

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Magazine Disconnect Safety Removal / Tuning • Trigger Pull Smoothing (drop from 8 lbs to 4.5 lbs) • Hammer Spur Bite Bobbing • Two-Piece Barrel Cam Inspection • Extractor Spring Replacement

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
OPERATING SYSTEM	Short recoil tilting barrel using fixed kidney-shaped cam lug (eliminating the swinging 1911 link)
MAGAZINE CAPACITY	Original 13-round double-stack staggered column magazine (pioneered by Dieudonné Saive)
MAGAZINE DISCONNECT	Plunger on rear of trigger shoe presses on front magazine wall; causes notoriously heavy gritty trigger pull
TRIGGER PULL STANDARD	7.5 to 9.0 lbs (with magazine disconnect) / 4.0 to 4.5 lbs (disconnect removed / polished)
BARREL CONSTRUCTION	Original two-piece brazed barrel assembly / modern forged one-piece barrel

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Excessively Heavy, Gritty, Creepy Trigger Pull Trigger pull exceeds 8 lbs with audible squeak and gritty drag throughout takeup	• Magazine disconnect safety shoe dragging directly across painted/blued steel front wall of magazine tube. • Dry or rusted disconnect plunger spring inside trigger body.	**Gunsmith Action: For competition/target use: Drift trigger pivot pin, remove trigger group, extract magazine disconnect plunger and spring (or install modern SA-35 parts which delete disconnect from factory). Polish trigger lever transfer bar.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Browning Hi-Power Complete Disassembly & Trigger Tuning	Mark Novak / Anvil Gunsmithing	Mark Novak inspects the Hi-Power trigger transfer bar, cleans the sear lever in the slide, addresses hammer bite, and improves the trigger pull.