ARMORER'S BENCH TECHNICAL MANUAL

CZ 75 / 75 B / SP-01 / Shadow 2

CZ (■eská Zbrojovka) • Classic Steel-Frame DA/SA Pistols (9x19mm NATO)

Manufacturer:	CZ (■eská Zbrojovka)	**Category:**	Pistols
Action Type:	Double-Action / Single-Action (DA/SA)	**Era / Service:**	Modern Combat & Competition Legend (1975–Present)
Calibers:	9x19mm Parabellum, .40 S&W;	**Covered Models:**	CZ 75 B, CZ 75 BD (Decocker), CZ 75 SP-01 Tactical, CZ Shadow 2, CZ 85 Combat, CZ 75 Compact

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Sear Cage Detail Assembly & Slave Pin Technique • Firing Pin Retaining Roll Pin Replacement • Trigger Return Spring Replacement • Disconnector Hand-Fitting • Slide Rail Lap

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
SLIDE TO FRAME FIT	Internal slide rails (slide rides INSIDE the frame rails like SIG P210) maximizing bearing surface and accuracy
LOCKING SYSTEM	Browning tilting barrel with two locking lugs machined into top of barrel interlocking into slide recesses
TRIGGER PULL WEIGHT	DA: 9.5 to 11 lbs / SA: 4.0 to 4.5 lbs (factory) / 2.0 to 2.5 lbs (Cajun Gun Works / Shadow 2)
FIRING PIN ROLL PIN	Transverse hollow roll pin in slide; prone to crushing during dry-fire, requires CGW hardened replacement pin
SEAR CAGE ASSEMBLY	Houses sear, sear spring, firing pin block lever, and ejector in self-contained modular cage

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Broken Firing Pin Retaining Roll Pin (Misfires / Binding) **Pistol exhibits light strikes; firing pin binds forward or refuses to rebound under finger pressure**	• Dry firing CZ 75 B models without O-ring or snap cap; firing pin shoulder batters the transverse roll pin until it crushes. • Deformed roll pin pinching the firing pin shaft.	**Gunsmith Action: Drive out damaged roll pin from right to left using 3mm roll pin punch. Remove firing pin and inspect waist notch. Install Cajun Gun Works tempered spring steel retaining pin. Always recommend snap caps for dry fire.**
Stoppage 2: Broken Trigger Return Spring (Trigger Flopping Back) **Trigger pulls, round fires, but trigger does not spring forward to reset; user must push trigger forward with finger**	• Factory wire trigger return spring fatigue fracture inside trigger shoe recess (typical after 5,000–8,000 cycles).	**Gunsmith Action: Drift out trigger pivot pin using slave pin. Replace broken spring with CGW reduced-power or heavy-duty wire spring. Use a short slave pin to capture the spring coils while inserting the factory trigger pin from the outside.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
CZ 75 Complete Detail Disassembly & Sear Cage Masterclass	Cajun Gun Works Bench	Step-by-step disassembly of the CZ 75 sear cage, using a slave pin to capture the sear springs, tuning the disconnector, and slide teardown.