Mossberg 500 & 590 / 590A1 Series

O.F. Mossberg & Sons • US Military Spec-D Pump Shotgun (12 Gauge & 20 Gauge)

Manufacturer:	O.F. Mossberg & Sons	**Category:**	Shotguns
Action Type:	Pump-Action Repeating Shotgun with Top Tang Safety	**Era / Service:**	Military & Tactical Benchmark (1960–Present)
Calibers:	12 Gauge (3" Chamber), 20 Gauge, .410 Bore	**Covered Models:**	Mossberg 500 Field, Mossberg 590 Tactical, Mossberg 590A1 (Heavy Barrel & Metal Trigger Group), Shockwave (14")

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Top Tang Safety Slide & Detent Ball Replacement • Dual Cartridge Stop & Interrupter Timing • Cleanout Magazine Tube Cap Service (590) • Metal Trigger Housing Upgrade • Elevator Assembly Alignment

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
TOP TANG SAFETY	Thumb-operated sliding safety switch located on top tang of receiver (completely ambidextrous and ergonomic)
DUAL EXTRACTORS	Twin symmetrical extractor claws on bolt (left and right) provide dual purchase on shell rim
CARTRIDGE STOPS	Cartridge stop and interrupter are loose floating stamped parts held in place by trigger housing (no staking required unlike Remington)
MIL SPEC QUALIFICATION	Mossberg 590A1 passed US Military Mil-S-3443G test (3,000 rounds of full-power 00-buck without a single malfunction)

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Double Shell Dump into Receiver (Two Shells Released at Once) Racking pump drops one shell onto elevator while second shell squirts beneath elevator into action	• Bent or fatigued cartridge interrupter on left inside receiver wall. • Trigger group pins walking out, allowing trigger housing to shift.	**Gunsmith Action: Drop trigger group. Inspect left-side cartridge interrupter. Measure bend angle against factory gauge. Bend front finger slightly inward to properly catch and hold the second round in magazine tube during pumping.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Mossberg 500 / 590 Complete Disassembly & Armorer Tuning	MidwayUSA / Larry Potterfield	Teardown of the Mossberg 500/590: removing bolt slide and dual extractors, replacing safety detent ball, and tuning the cartridge stop.