Springfield Armory Hellcat & XD Series

Springfield Armory / HS Produkt • Hellcat, Hellcat Pro, XD-M Elite & XD-S (9x19mm & .45 ACP)

Manufacturer:	Springfield Armory / HS Produkt	**Category:**	Pistols
Action Type:	Striker-Fired Micro-Compact & Duty	**Era / Service:**	Modern Duty & CCW (2002–Present)
Calibers:	9x19mm Parabellum, .45 ACP, 10mm Auto, .40 S&W;	**Covered Models:**	Hellcat Micro-Compact, Hellcat Pro, XD-M Elite 4.5", XD-S Mod.2, XD-9 Service

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Striker Retaining Roll Pin Replacement • Extractor Tension Tuning • Dual Captive Recoil Spring Service • Grip Safety Spring Reset (XD) • Optics Cut Screws Torque

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
OPERATING SYSTEM	Short recoil tilting barrel (Browning-Petter style locking)
STRIKER PIN SAFETY	Transverse steel roll pin through slide top retains striker and striker dampening spring
LOADED CHAMBER INDICATOR	Mechanical pivoting top lever visually and tactilely indicates loaded chamber
TRIGGER PULL WEIGHT	5.5 to 6.5 lbs (Hellcat Gen 2 flat trigger) / 5.0 to 5.5 lbs (XD-M Elite META trigger)
MAGAZINE CAPACITY	11+1 / 13+1 / 15+1 rounds in patented staggered micro-compact magazine body

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: Broken Striker Retaining Roll Pin (Dry Fire Failure) **Striker fails to capture; slide locks up or striker binds forward during cycling**	• Extensive dry fire without snap caps causing striker collar to batter the transverse roll pin in slide. • Split or sheared factory split roll pin.	**Gunsmith Action: Drive out broken roll pin fragments using 3/32" roll pin punch. Inspect striker lug. Replace with heavy-duty spiral coiled spring pin (Channellock/PRP heavy-duty replacement). Always advise customer to use snap caps during dry-fire practice.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Springfield Hellcat Complete Disassembly, Cleaning & Upgrades	Powder River Precision	Teardown of the Springfield Hellcat slide, extractor removal, sear spring installation, and trigger shoe upgrade.