ARMORER'S BENCH TECHNICAL MANUAL

Taurus G-Series & TX22 Pistols

Taurus USA • G2c, G3, G3c & TX22 Rimfire (9x19mm & .22 LR)

Manufacturer:	Taurus USA	**Category:**	Pistols
Action Type:	Striker-Fired Duty, CCW & Rimfire Target	**Era / Service:**	Modern Consumer Market (2015–Present)
Calibers:	9x19mm Parabellum, .22 LR	**Covered Models:**	Taurus G2c, Taurus G3, Taurus G3c, Taurus TX22, Taurus TX22 Competition

KEY ARMORER TASKS & BENCH OPERATIONS

Core Procedures: Restrike Trigger Linkage Check • TX22 Feed Ramp Polishing • Striker Spring Inspection • Slide Endcap Removal • Chamber Cleaning

CRITICAL ARMORER TOLERANCES & SPECIFICATIONS

SPECIFICATION / CLEARANCE	ARMORER TOLERANCE & BENCH SPECIFICATION
RESTRIKE CAPABILITY	Double-action restrike capability allows pulling trigger again without racking slide on dud primer
TRIGGER SYSTEM	Single-action restrike with flat face or curved trigger blade (approx 5.5 to 6.0 lbs)
TX22 CAPACITY	Proprietary 16-round rimfire polymer magazine with staggered feed lips
TX22 OPERATING	Straight blowback action with lightweight aluminum slide and buffer pad

IMMEDIATE ACTION & MALFUNCTION DIAGNOSTIC MATRIX

MALFUNCTION CONDITION	PROBABLE CAUSES	ARMORER BENCH REMEDY
Stoppage 1: TX22 Rimfire Failure to Feed (Nose-Up Jam) Cartridge tip catches on top edge of chamber mouth rather than smoothly feeding	• Wax and carbon buildup on stainless steel feed ramp. • Magazine follower binding inside magazine body due to rimfire fouling. • Rim rim-lock from improperly loaded .22 LR rounds.	**Gunsmith Action: Polish feed ramp with felt bob and polishing paste. Disassemble TX22 magazine, clean interior tube with dry silicone cloth (no oil to attract powder residue). Ensure top rim sits in front of the rim below it.**

CURATED BENCH VIDEO REFERENCES

PROCEDURE TITLE	INSTRUCTOR / CREATOR	TECHNICAL PROCEDURE SUMMARY
Taurus TX22 & G3 Series Takedown, Cleaning & Tuning	22plinkster / Gunsmith Corner	Teardown of the TX22 and G3 pistols: feed ramp polishing, magazine maintenance, and recoil spring inspection.