Dhaka University of Engineering & Technology (DUET), Gazipur

Department of Computer Science and Engineering (CSE)

<u>Course Title:</u> Microprocessor and Interfacing Sessional (CSE 3812)

Lab # 03

Understanding 8086 Condition Control using Assembly Language.

Tasks to do:

- 1. Write an assembly language program to display the entire IBM character set.
- 2. Suppose AX and BX contain signed numbers, Write an assembly language program to put the biggest number in CX.
- 3. Write an assembly language program to find biggest number among three numbers.
- 4. Write an assembly language program to find whether a given number is zero or not.
- 5. Write an assembly language program that inputs a single letter and shows the next 5 (five) letters in opposite case of input (Lower-case to Upper-case or vice-versa) in a row of a new line and also shows the previous 5 (five) letters in the next line in opposite case of input (Lower-case to Upper-case or vice-versa).

Sample Input / Output:

Input: c Input: Z
Output: DEFGH Output: abcde yxwvu