







OpenBuilds CONTROL v1.0.199

Control

Gbl Settings

Troubleshooting

Save to Firmware

Restart

Unlock

Refresh

Reset Settings

Reset WCOs

Reset EEPROM

Unlock Alarm

Stop Job

Gbl Settings

Firmware Reset Defaults

E-Stop

1

Load Default Settings

Populate Gbl parameters from machine-type defaults. You can customize values as needed below. Remember to click Save above to apply

Select Machine

Limit Switches Installed

2

Advanced Settings

Customise your Gbl settings below

\$32	Laser-mode enable	X Disable	
\$100	X-axis steps per millimeter	1024.000	steps/mm Calc Steps
\$101	Y-axis steps per millimeter	1024.000	steps/mm Calc Steps
\$102	Z-axis steps per millimeter	1024.000	steps/mm Calc Steps
\$110	X-axis maximum rate, mm/min	1600.000	mm/min
\$111	Y-axis maximum rate, mm/min	1600.000	mm/min
\$112	Z-axis maximum rate, mm/min	1600.000	mm/min
\$120	X-axis acceleration, mm/sec ²	30.000	mm/sec ²
\$121	Y-axis acceleration, mm/sec ²	30.000	mm/sec ²
\$122	Z-axis acceleration, mm/sec ²	20.000	mm/sec ²
\$130	X-axis maximum travel, millimeters	200.000	mm
\$131	Y-axis maximum travel, millimeters	200.000	mm

Port: Connected

Controller: Idle

Job Queue: 0

OpenBuilds CONTROL v1.0.199

Control

Gbl Settings

Troubleshooting

Save to Firmware

Restart

Unlock

Refresh

Reset Settings

Reset WCOs

Reset EEPROM

Unlock Alarm

Stop Job

Gbl Settings

Firmware Reset Defaults

E-Stop

1

Load Default Settings

Populate Gbl parameters from machine-type defaults. You can customize values as needed below. Remember to click Save above to apply

Select Machine

Limit Switches Installed

2

Advanced Settings

Customise your Gbl settings below

\$101	Y-axis steps per millimeter	1024.000	steps/mm Calc Steps
\$102	Z-axis steps per millimeter	1024.000	steps/mm Calc Steps
\$110	X-axis maximum rate, mm/min	1600.000	mm/min
\$111	Y-axis maximum rate, mm/min	1600.000	mm/min
\$112	Z-axis maximum rate, mm/min	1600.000	mm/min
\$120	X-axis acceleration, mm/sec ²	30.000	mm/sec ²
\$121	Y-axis acceleration, mm/sec ²	30.000	mm/sec ²
\$122	Z-axis acceleration, mm/sec ²	20.000	mm/sec ²
\$130	X-axis maximum travel, millimeters	200.000	mm
\$131	Y-axis maximum travel, millimeters	200.000	mm
\$132	Z-axis maximum travel, millimeters	200.000	mm

Port: Connected

Controller: Idle

Job Queue: 0