

HAZARD IDENTIFICATION, RISK ASSESSMENT& CONTROL REPORT

B TITLE:	Earthquake and Calamities - Mactan Cebu International Airport			HIRAC Ref. No.: CSC-2023-01 (Refer to SSQA Risk Registry Database)
Department:		Location:	Mactan Cebu International Airport T1 and T2	
Activity/Area being assessed:	Mactan Cebu International Airport T1 and T2			Assessor(s)/Team: SSQA
Date Created:	October 27, 2025	Date Reviewed:		

Type of Operation or Activity	Generic Hazard	Risks (Consequences of the Hazard)	Existing Defenses to Control Safety Risks	Safety Risk Index	Mitigating Actions to Further Reduce Safety Risks (a) Elimination (b) Substitution (c) Engineering control (d) Administrative (e) PPE	Residual Risk Index	Remarks	Target Date	Department Responsible
Passenger terminal operations	Earthquake	Structural collapse, panic, injury and stampede.	Emergency evacuation plan, posted evacuation routes, regular drills, PA system announcements		d) Reinforce earthquake drills and awareness sessions (c) Regular inspection of terminal structure and emergency exits (e) Proper PPE for responders		Ensure regular coordination with airport emergency committee		SSQA / Terminal Operations
Passenger terminal operations	Typhoon	Glass breakage, flying debris, power outage, flooding inside terminal	Typhoon contingency plan, standby generator, secured glass panels, pre-storm inspections		(c) Install storm shutters and secure signage (d) Reinforce weather monitoring and advance passenger advisories (e) PPE for ramp/terminal personnel		Ensure emergency kits and comms lines are functional		

HAZARD IDENTIFICATION, RISK ASSESSMENT & CONTROL REPORT

Type of Operation or Activity	Generic Hazard	Risks (Consequences of the Hazard)	Existing Defenses to Control Safety Risks	Safety Risk Index	Mitigating Actions to Further Reduce Safety Risks (a) Elimination (b) Substitution (c) Engineering control (d) Administrative (e) PPE	Residual Risk Index	Remarks	Target Date	Department Responsible
Passenger terminal operations	Fire	Smoke inhalation, burns, panic, and evacuation bottlenecks	Fire detection and suppression systems, trained fire marshals, regular fire drills	Medium	(c) Regular inspection of extinguishers and alarms (d) Conduct quarterly fire safety orientation (e) Ensure fire PPE readiness	Low	Conduct fire drill every quarter		Safety & Security / Terminal Operations
Passenger Terminal Operations	Volcanic Ash Fall	Respiratory irritation, reduced visibility, air quality deterioration	Coordination with airport authority, air filtration system, mask availability	Medium	(d) Implement "Shelter-in-Place" procedures (e) Issue N95 masks to all personnel (c) Regular maintenance of air filters	Low	Coordinate with MCIA and PAGASA for alerts		SSQA / Terminal Operations

HAZARD IDENTIFICATION, RISK ASSESSMENT & CONTROL REPORT

Type of Operation or Activity	Generic Hazard	Risks (Consequences of the Hazard)	Existing Defenses to Control Safety Risks	Safety Risk Index	Mitigating Actions to Further Reduce Safety Risks (a) Elimination (b) Substitution (c) Engineering control (d) Administrative (e) PPE	Residual Risk Index	Remarks	Target Date	Department Responsible
Aircraft Ground Handling	Earthquake	Equipment damage, falling GSE, personal injury	Emergency response plan, open ramp area with clear evacuation points	Medium	(c) Secure all GSE parking positions (d) Conduct ramp evacuation drill (e) Mandatory safety briefing for ramp crew	Low	Include earthquake response in ramp toolbox talks		Ramp Operations / GSE Maintenance
Aircraft Ground Handling	Typhoon	High wind gusts, FOD hazards, equipment overturn, flight delays	Ramp closure procedures, FOD walks, tie-downs for equipment	Medium	(c) Reinforce GSE anchoring system (d) Suspend operations beyond safe wind limits (e) Ensure proper PPE (rain gear, goggles)	Low	Maintain coordination with ATC and AOCC		Ramp Operations / GSE
Aircraft Ground Handling	Fire	GSE fire, fuel ignition, personal injury	Fire extinguishers in all GSE, trained operators, no-smoking enforcement	Medium	(c) Inspect GSE fuel lines (d) Regular fire drills and hot work permit compliance (e) Fire-resistant gloves and coveralls	Low	Continuous refresher training		GSE Maintenance / SSQA

HAZARD IDENTIFICATION, RISK ASSESSMENT & CONTROL REPORT

Type of Operation or Activity	Generic Hazard	Risks (Consequences of the Hazard)	Existing Defenses to Control Safety Risks	Safety Risk Index	Mitigating Actions to Further Reduce Safety Risks (a) Elimination (b) Substitution (c) Engineering control (d) Administrative (e) PPE	Residual Risk Index	Remarks	Target Date	Department Responsible
Aircraft Ground Handling	Volcanic Ash Fall	Reduced aircraft visibility, aircraft contamination, engine hazard	Coordination with airlines and ATC, ash monitoring updates	Medium	(d) Suspend ramp ops during heavy ash fall (c) Provide aircraft protective covers (e) PPE with respiratory masks and goggles	Low	Align with airport emergency ash protocol	Ongoing	Ramp Operations / SSQA

Prepared by: Kearck Adrian K. Aro S.H.E Specialist Approved by: Roy Philip Magsayo Vice President – Safety, Security and Quality Assurance Department	Acknowledged by: Melchor Rios GSE Manager Remarks:
Name and Signature	Name and Signature



HAZARD IDENTIFICATION, RISK ASSESSMENT& CONTROL REPORT