TEO GEOK YAN
A-162, Aurora Resort,
Jalan Aurora Utama, Aurora Sentral,
79100 Iskandar Puteri,
Johor.

E-mail: gyteo97@gmail.com
Tel: +65 8617 8812

M/s K.H. KOH, AZHAR & KOH
Advocates & Solicitors
Suite 25-03, Level 25, Menara Landmark,
No. 12, Jalan Ngee Heng,
80000 Johor Bahru, Johor.

12 October 2026

E-mail: khkohjoetan@yahoo.com; khkjoetan@gmail.com
Tel: 07-224 2323 Fax: 07-224 7262

Our Ref: STAKEHOLDER/NOTIS-2/2026/035

Dear Sirs,

RE: NOTICE TO STAKEHOLDER LAWYERS — RETENTION OF 5% STAKEHOLDER SUM

Developer	**:**	COUNTRY VIEW RESOURCES SDN BHD (200001021248 / 523855-A)
Purchaser	**:**	TEO GEOK YAN (NRIC: 970729-01-6582)
Project	**:**	Aurora Resort Villas, Phase 1, Aurora Sentral
Property	**:**	Double Storey Link Villa (Lot 247)
Address	**:**	A-162, Aurora Resort, Jalan Aurora Utama, Aurora Sentral, 79100 Iskandar Puteri, Johor
SPA	**:**	Schedule H, dated 21 December 2023 (Ref: 8428-23/eSPA/141223/247/01)

We refer to the above matter.

Pursuant to the Sale and Purchase Agreement, I have given the requisite written notices to the Developer to remedy the defects within the Defect Liability Period under Clause 30(1) of Schedule H, namely: (i) the Defect Inspection Reports submitted through the Developer's CVConnect application on 1 and 2 July 2025 (Defect 728811-2 and 228839-3); (ii) the First Notice (Ref: NOTIS-1/2026/035) dated 2 September 2026, delivered by AR Registered Post No. RW214680799MY and RECEIVED by the Developer on 23 September 2026; and (iii) the Second and Final Notice (Ref: NOTIS-2/2026/035) dated 12 October 2026, with a final deadline of 27 October 2026.

I wish to bring to your attention that a substantial number of defect rectification works

have not been completed by the Developer despite numerous written and verbal complaints and inspections, and/or the Developer has failed, neglected or refused to attend to them. Among others, the latest Re-Inspection on 27 August 2026 confirmed the defects remain unresolved, and all nine (9) further defect cases submitted through CVConnect on 28 August 2026 and 1 September 2026 remain in "Pending" status to date. A copy of the list of outstanding defects is attached herewith for your record, and an official repair quotation amounting to RM25,565.00 has been obtained.

I hereby give you notice, as Stakeholder under Clause 30(2) of Schedule H of the Sale and Purchase Agreement, NOT to release any portion of the five per cent (5%) stakeholder sum (retention sum) to the Developer until such time that I am satisfied with the remedial works and due written notice to that effect is given to you. In default of your professional role as Stakeholder, I will hold your firm personally responsible and will not hesitate to lodge an official complaint with the Bar Council of Malaysia.

Your cooperation is appreciated. Thank you.

Yours faithfully,

(TEO GEOK YAN)
NRIC: 970729-01-6582
E-mail: gyteo97@gmail.com
Tel: +65 8617 8812

cc:

COUNTRY VIEW RESOURCES SDN BHD (200001021248 / 523855-A) — No. 26-01, Level 26, Mail Box 261, Menara Landmark, No. 12, Jalan Ngee Heng, 80000 Johor Bahru, Johor.

Encl.:

1. List of outstanding defects (as per Second and Final Notice Ref: NOTIS-2/2026/035)
2. Copy of AR card No. RW214680799MY (proof of service of First Notice)