DFM analysis report_JLCDFM


File name: **collar-tracker-05h-final-40x32-dfm.zip**


Report generated at: **2026-10-25 22:13:20**


PCB layers: **6**

PCB size: **4x3.2cm**


Analyze project: ☑ **PCB DFM** ☐ **SMT DFM**








PCB DFM>Routing layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Sharp trace corner (Check for sharp corners in traces)	No	No	No	Danger: 0 Warning: 0 Good: 0
BGA pad (Check BGA pads on the board)	No	No	No	Danger: 0 Warning: 0 Good: 0
Via placed within a pad (Check if there is a via placed within a pad)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace to board edge (Detect traces too close to the board edge)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace spacing (Measure spacing between adjacent parallel traces)	0.2mm Good		collar-tracker-F_Cu.gtl collar-tracker-B_Cu.gbl	Danger: 0 Warning: 0 Good: 27
Unconnected trace end (Free-standing trace ends not connected to pads)	No	No	No	Danger: 0 Warning: 0 Good: 0
Trace width (Trace width information)	0.2mm Good		collar-tracker-F_Cu.gtl collar-tracker-B_Cu.gbl	Danger: 0 Warning: 0 Good: 100
Fiducial (Detect fiducial marks on the board)	No	No	No	Danger: 0 Warning: 0 Good: 0
Pad to board edge (Measure distance of pads from the board edge)	No	No	No	Danger: 0 Warning: 0 Good: 0
Pad spacing (Measure pad to pad spacing)	0.16mm Good		collar-tracker-F_Cu.gtl collar-tracker-B_Cu.gbl	Danger: 0 Warning: 0 Good: 100
Plated through-hole to trace clearance (Measure clearance of plated through-holes to traces)	No	No	No	Danger: 0 Warning: 0 Good: 0
Annular ring (Annular ring width of pads compared to holes)	0.2mm Good		collar-tracker-F_Cu.gtl collar-tracker-B_Cu.gbl	Danger: 0 Warning: 0 Good: 100
tht to smd (Detect clearance of vias to pads)	No	No	No	Danger: 0 Warning: 0 Good: 0
Via to pad (Detect clearance of vias to pads)	No	No	No	Danger: 0 Warning: 0 Good: 0

PCB DFM>Soldermask layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Soldermask bridge (Detect distance between parallel soldermask opening edges)	0.2mm Good		collar-tracker-B_Mask.gbs collar-tracker-F_Mask.gts	Danger: 0 Warning: 0 Good: 51
Solder mask opening exposing trace (Detect clearance of solder mask openings to nearby traces)	0.17mm Good		collar-tracker-B_Mask.gbs collar-tracker-F_Mask.gts	Danger: 0 Warning: 0 Good: 62
Soldermask opening with multiple segments (Check if solder mask openings are constructed from multiple geometric shapes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Negative soldermask expansion (Detect solder mask openings smaller than their corresponding pads)	No	No	No	Danger: 0 Warning: 0 Good: 0

PCB DFM>Silkscreen layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Silkscreen to pad (Detect clearance of silkscreen to pads)	No	No	No	Danger: 0 Warning: 0 Good: 0
Silkscreen to hole (Detect clearance of silkscreen to holes)	0mm Danger		collar-tracker-B_Silkscreen.gbo	Danger: 4 Warning: 2 Good: 2
Silkscreen line width (Check silkscreen line width)	0.2mm Good		collar-tracker-B_Silkscreen.gbo collar-tracker-F_Silkscreen.gto	Danger: 0 Warning: 0 Good: 9

PCB DFM>Drill layer analysis

Analyze project	Analysis results	PCB screenshot	Layer distribution	Statistics
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0
Missing plated through-hole (Detect top and bottom pads at the same location without plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0
Plated through-hole spacing (Measure spacing between plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Short slot detection (Detect slots shorter than twice their width)	No	No	No	Danger: 0 Warning: 0 Good: 0
Slot width check (Measure slot width)	No	No	No	Danger: 0 Warning: 0 Good: 0
Via to PTH spacing (Measure spacing of vias to plated through-holes)	No	No	No	Danger: 0 Warning: 0 Good: 0
Unconnected via (Detect isolated unconnected vias)	No	No	No	Danger: 0 Warning: 0 Good: 0