

ZETDC HRE ENG 03/022 NEW CONNECTION (NON - STANDARD JOB) PROCESS

	ACTIVITY	RISK BASED THINKING (ISO 9001:2015)		ENVIRONMENT (ISO 14001: 2015)		OCCUPATIONAL HEALTH AND SAFETY (ISO 45001:2018)	
		RISKS/ OPPORTUNITIES	CONTROLS	ASPECTS	IMPACTS	HAZARD	RISK
1	Client visit ZETDC			Vehicle & motor cycle emissions	pollution	Air bone diseases	Contacting Infectious diseases e.g. Covid 19
2	Filling application forms	Inputting wrong information	Clients to attaché supporting documents such as IDs & proof of residence.	Paper usage	Deforestation.	Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases
3	Checking & Filing inspection forms	Misplacing documents.	To double check before and after filing as well as creating a record on soft copy.			Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases
4	Inspection	Omission of error on wiring.	Proper training of artisans. Use of checklists.	Vehicle & motor cycle emissions	Pollution	Air bone diseases Violent customers Snakes & Insects in meter boxes.	Contacting Infectious diseases e.g. Covid 19 Assault Snakes & insects bites.
5	Rectifying wiring & paying for re- inspection.	System failure on payment	IT equipment to well maintained & have IT personnel on standby.	Electricity usage	Electricity costs.		
6	Capture client details and create p- reference number	System failure	IT equipment to well maintained & have IT personnel on standby.	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
7	Preparing quotation	System failure	IT equipment to well maintained & have IT personnel on standby	Electricity usage Paper usage	Electricity costs. Deforestation	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries

ZETDC HRE ENG 03/022 NEW CONNECTION (NON - STANDARD JOB) PROCESS

8	Approves quotation	System failure	IT equipment to well maintained & have IT personnel on standby	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
9	Print quotation and advise client	System failure Printer failure	IT equipment to well maintained & have IT personnel on standby Have alternative printer	Electricity usage Paper usage	Electricity costs. Deforestation	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
10	Receipting (Sub process)						
11	Assign and raise stores requisition	System failure	IT equipment to well maintained & have IT personnel on standby	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
12	Drawing materials from stores (Sub-process)						
13	Connection	Electrocution Fall from height Insect/snake bites	Use of PPE/C Safety procedures Tailgate discussions Proper housekeeping before connection.	Vehicle & motor cycle emissions traveling to premises	Pollution	Closely located live conductors & cables Air bone diseases Snakes & Insects in meter boxes.	Electrocution Contacting Infectious diseases e.g. Covid 19 Snakes & insects bites.
14	Commissioning	Commissioning wrong details System failure on payment	Double checking before capturing IT equipment to well maintained & have IT personnel on standby.	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
15	Client registration	Registering wrong details	Double checking before capturing	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries

ZETDC HRE ENG 03/022 NEW CONNECTION (NON - STANDARD JOB) PROCESS

		System failure on payment	IT equipment to well maintained & have IT personnel on standby.			Air bone diseases (walk-in customers)	Contacting Infectious diseases e.g. Covid 19
--	--	---------------------------	---	--	--	---------------------------------------	--