

ZETDC EASTERN REGION		
REVISION: 0	DOCUMENT TYPE: PROCEDURE TITLE: NON CONFORMITY, CORRECTIVE ACTION & PREVENTIVE ACTION	DOCUMENT NO: SHE 09
ISSUE DATE: 25/10/13 STATUS: CONTROLLED DOCUMENT	COMPILED BY: SAFETY & HEALTH OFFICER REVIEWED BY: CHIEF RISK OFFICER AUTHORISED BY: GENARAL MANAGER	SIGN: SIGN: SIGN:

1. PURPOSE

This procedure describes how non-conformities are identified, corrected and prevented.

2. SCOPE

This procedure applies to all non-conformities (actual or potential) which may be identified at ZETDC Eastern Region. The non-conformities may be related to the system, activities, products, or operations.

3. RESPONSIBILITIES

- 3.1 The CRO is responsible for ensuring implementation and maintenance of this procedure.
- 3.2 HOD(s) shall ensure that nonconformities (actual or potential) identified within areas of their jurisdiction are corrected.

4. DEFINITIONS

- 4.1 Non conformity – non fulfilment of a requirement
- 4.2 Corrective action – action to eliminate the cause of a detected non conformity
- 4.3 Preventive action – action to eliminate the cause of a potential non conformity

5. ACTIVITY DESCRIPTION

- 5.1 Anyone in the organisation can identify and report a non-conformity by way of raising a non conformity report form.
- 5.2 The non-conformity report form shall be submitted to the Supervisor who will in turn submit it to the CRO after corrective or preventive action has been logged on the form.
- 5.3 The respective Supervisor shall institute investigations to determine the cause of the non-conformities and put in place appropriate actions to address the non-conformity.
- 5.4 Results of the corrective and preventive action taken shall be recorded on the non-conformity report form.
- 5.5 A review shall be conducted to check effectiveness of the instituted corrective and preventive action.

- 5.6 The closing off of a non-conformity shall be done by the respective Supervisor and CRO after they are satisfied with the corrective and preventive action taken.
- 5.7 Anyone can identify potential non-conformities and fill in the potential nonconformity form.
- 5.8 The responsible Supervisor shall fill in the preventive action. The person identifying the nonformity in liason with the respective Supervisor/CRO shall assess the preventive action.
- 5.9 The Supervisor and CRO shall do closing out after they are satisfied that the preventive action has proved to be effective.

6. PERFORMANCE INDICATORS

Nonconformity reports

7. RECORDS

The following records shall be generated from implementation of this procedure.

Name of record:	Retention period:	Custodian / location:	Method of Disposal
Non Conformity report form	5 years	HOD & HSO Manager	Shredding
Potential nonconformity report form	5years	HSO	Shredding

8. REFERENCES

8.1 SAZS ISO 14001:2004 Clause 4.5.3

9. RELATED DOCUMENTS

SHE Policy Manual