

ZETDC HRE ENG 03/027 DISCONNECTION/RECONNECTION PROCESS

	ACTIVITY	RISK BASED THINKING (ISO 9001:2015)		ENVIRONMENT (ISO 14001: 2015)		OCCUPATIONAL HEALTH AND SAFETY (ISO 45001:2018)	
		RISKS/ OPPORTUNITIES	CONTROLS	ASPECTS	IMPACTS	HAZARD	RISK
1	Application for disconnection	wrong Address or Wrong details	Check and Verify details			Difficult client	Stress
2	Receipting (sub-process)						
3	Assign artisan for inspection	Communication breakdown	Assess state of mind and competency			Difficult employees	stress
4	Inspects and compiles BOQ	Capturing wrong details Failure to locate	Supervision and audits Contact client, refer to GIS	fuel usage	Fuel costs pollution	Contagious diseases	Contract Contagious disease e.g. covid 19
5	Prepares WOCI charges	Apportioning wrong costs	Supervision and audit			Computer glare Repetitive tasks	Eye strain Ergonomic strain
6	Assign Artisan to disconnect/re connect	Communication breakdown	Assess state of mind and competency			Difficult employees	stress
7	Disconnect/re connect	Failure to implement	Engage client, refer to supervisor.	paper usage fuel usage	Deforestation pollution	Difficult client	Stress
8	Advises client	Communication breakdown	Assess state of mind			Difficult client Contagious diseases	Stress Contract Contagious disease e.g. covid 19