

ZETDC HRE ENG 03/021 METER CHANGE PROCESS

	ACTIVITY	RISK BASED THINKING (ISO 9001:2015)		ENVIRONMENT (ISO 14001:2015)		OCCUPATIONAL HEALTH AND SAFETY (ISO 45001:2018)	
		RISKS/ OPPORTUNITIES	CONTROLS	ASPECTS	IMPACTS	HAZARD	RISK
1	Report fault	Wrong capture of details	Confirmation of details in OMS	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
2	Assign artisan	- Wrong assignment - Failure to understand task	Assess state of mind and competencies			Difficult employees	stress
3	Identify that meter is faulty and remove it	Wrong diagnosis	Refer to meter manuals			Closely located to live equipment	electrocution
4	Logs faulty meter details	Wrong capture of details	Confirmation of details	Paper usage	Deforestation.	Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases
5	Order new meter (sub-process)						
6	Assign artisan	- Wrong assignment - Failure to understand task	Assess state of mind and competencies			Difficult employees	stress
7	Install and commission (sub-process)						
8	Completing WOMI	Capturing wrong details	Verify all details	Paper usage	Deforestation.	Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases
9	Logs new meter details	Capturing wrong details	Verify all details	Paper usage	Deforestation.	Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases

ZETDC HRE ENG 03/021 METER CHANGE PROCESS

10	New meter enrolment	System challenges	Liaise with IT department	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
11	Close job	System challenges	Liaise with IT department	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries