

ZETDC HRE ENG 03/018 FAULTY TRANSFORMER CHANGE PROCESS

	ACTIVITY	RISK BASED THINKING (ISO 9001:2015)		ENVIRONMENT (ISO 14001:2015)		OCCUPATIONAL HEALTH AND SAFETY (ISO 45001:2018)	
		RISKS/ OPPORTUNITIES	CONTROLS	ASPECTS	IMPACTS	HAZARD	RISK
1	Report faulty transformer	Failure to articulate data	Collaborate with team members Seek second opinion			Difficult employees	stress
2	Create internal job for transformer replacement	Inputting wrong information	attach supporting documents	Paper usage	Deforestation.	Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases
3	Approve job	System challenges	Liaise with IT department	Paper usage	Deforestation.	Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases
4	Order new transformer (sub-process)						
5	Issue transformer	- Issuing wrong materials or quantities - System challenges	- Verify materials - Liaise with IT department	Electricity usage	Electricity costs.	Computer glare Repetitive tasks	Eye injuries Ergonomic injuries
6	Assign artisan	- Wrong assignment - Failure to understand task	Assess state of mind and competencies			Difficult employees	stress
7	Install and commission (sub-process)						
8	Completing documents	Capturing wrong details	Verify all details	Paper usage	Deforestation.	Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases

ZETDC HRE ENG 03/018 FAULTY TRANSFORMER CHANGE PROCESS

9	Check paperwork and close job	Overlook errors	Make checklist			Repetitive tasks Paper dust	Ergonomic injuries Respiratory diseases