




Notes:
1. Connector J1 is laid out in the same order as the host connector.
It is possible that a cable harvested from an OEM controller will not have the same pinout as this header, and will need to be repinned.

