



Heritage Site Assessment Report

1. General Information

2024-04-05
Assessor's Name: Bihh Ahh
Supervisor: Gogo Shii
Organization: Oves lan Toun
Monument Reference: GSHS00112
Monument Name: The Thrill
Ownership: No one

Date of Assessment:

2. Location Information

Governorate:
Beirut
District:
Ras Beirut
City/Village:
Beirut
Location:
Honik

3. Preliminary Conditions

Observed Structural Conditions: Stable

Exterior Walls Condition:

Roof Conditions:
Well Preserved

Major Architectural Failure:
No Failure

Location of Major Damage:
Foundation

Well Preserved

4. Evidence of Conflict or Damage

Evidence of Armed Conflict:

No

Fire or Smoke Damage:

No

Looting or Vandalism:

Nο

Conflict-Specific Damage Indicator:

No

5. Visible Damage

Significant Cultural/Religious Symbol Damage:

No

Visible Damage to Sculptures/Carvings:

No

Damage to Decorative Elements:

No

6. Environmental Concerns

Water Infiltration and Weather Exposure:

None Observed

Vegetation Overgrowth:

None observed

Secondary Hazards Present:

No

7. Documentation and Evidence

Satellite Imagery Observations:

Not Available

Eyewitness Report:

Voch

Testimonials:

Voch

7. Documentation and Evidence

Primary Display Photo:



8. Risk Assessment

Potential Hazards to Public and Site:

None observed

Urgent Stabilization Required:

Yes, within 1-2 weeks

Security Measures Needed:

Yes

Likelihood of Continued Damage:

Low

9. Historical or Cultural Significance

Historical or Cultural Significance:

Nobody Knows

Significance for Local Population:

Very much

Additional References:

Hima che hedo