

The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street, Canton, MA 02021
Phone: 617-624-5757 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

January 9, 2026

To: Shawn Jenkins, Commissioner, Department of Corrections (electronic copy)
Kiame Mahaniah, Secretary, Executive Office of Health and Human Services (electronic copy)
Clerk, Massachusetts House of Representatives (electronic copy)
Clerk, Massachusetts Senate (electronic copy)
Noe Bard, Environmental Health and Safety Officer (electronic copy)

Greetings,

Pursuant to 105 CMR 451.403, please find the inspection report for Worcester County Jail and House of Correction, the Plan of Correction (POC) from the facility and the POC acceptance letter from the Division of Environmental Health Regulations and Standards (EHRS).

Sincerely,

Cory J. Holmes
Senior Advisor, EHRS, BCEH

Cc: Robert Goldstein, MD, PhD, Commissioner, DPH (electronic copy)
Terrence Reidy, Secretary, Executive Office of Public Safety and Security (electronic copy)
Kris Jansen, Administrative Assistant, West Boylston Board of Health (electronic copy)
Brianna Arruda, Director, Policy Development and Compliance Unit (electronic copy)
Jason Rives, Superintendent, Worcester County Jail and House of Correction (electronic copy)



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
Bureau of Climate and Environmental Health
Division of Environmental Health Regulations and Standards
5 Randolph Street
Canton, MA 02021
617-624-6000 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

December 11, 2025

Jason Rives, Superintendent
Worcester County House of Corrections and Jail
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Facility Inspection – Worcester County House of Corrections and Jail, West Boylston

Dear Superintendent Rives:

The Massachusetts Department of Public Health (Department) Division of Environmental Health Regulations and Standards (EHRS) conducted an inspection of the Worcester County Jail and House of Correction on November 19 and 20, 2025, accompanied by Captain Eric Locke, Lieutenant Devon Walker, and Lieutenant Noe Bard in accordance with Department regulations 105 CMR 451.000: Minimum Health and Sanitation Standards and Inspection Procedures for Correctional Facilities.

The inspection identified 114 total deficiencies: 41 new deficiencies under the Required Standards (.100 and .200 series), 42 repeat deficiencies under the Required Standards, 20 new deficiencies under the Recommended Standards (.300 series), and 11 repeat deficiencies under the Recommended Standards.

Overview

Section 1 provides details of all deficiencies, including repeat deficiencies, found during the inspection. These are categorized by Required Standards, Recommended Standards, or additional applicable regulatory standards.

Section 2 provides information on areas that EHRS found to be compliant.

Section 3 documents the areas that EHRS did not inspect.

Section 4 provides information on submitting a Plan of Correction for the identified deficiencies.

Section 5 outlines observations and recommendations related to the inspection.

SECTION 1: Health and Safety Deficiencies

Main Building

Deficiencies under the Required Standards (.100 and .200 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Entrance	Male Staff Bathroom	105 CMR 451.123*	Maintenance: Rust on handwash sink fixture
----	----------	---------------------	------------------	--

Herman Building

Deficiencies under the Required Standards (.100 and .200 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Visiting Room	Male Bathroom	105 CMR 451.123*	Maintenance: Wall paint damaged above urinal
----	---------------	---------------	------------------	--

MAXI B

Deficiencies under the Required Standards (.100 and .200 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Upper Disciplinary Unit	105 CMR 451.117*	Toilet Fixtures: Toilet fixtures not easily cleanable, toilet rusted in cell #2	
2.	Upper Disciplinary Unit	105 CMR 451.123*	Maintenance: Handwash sink dirty in cell #2	

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	Upper Right Tier	105 CMR 451.353	Interior Maintenance: Wall paint damaged near toilet in cell # 336	
2.	Upper Right Tier	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 326	

Food Service

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Main Kitchen	Food Prep Area	105 CMR 451.200	Characteristics; Condition: Food not safe, unadulterated, and honestly presented (Pf), moldy buns observed. Standard found in 105 CMR 590; FC 3-101.11. ** Corrected On-Site **
2.	Main Kitchen	Dishwasher Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired, warewashing machine out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A).
3.	Main Kitchen	Freezer # 4	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gasket and door frame damaged. Standard found in 105 CMR 590; FC 4-501.11(A).

4.	Main Kitchen	Freezer # 4	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Food exposed to splash, dust, or other contamination, food stored beneath condensation where walls meet ceiling. Standard found in 105 CMR 590; FC 3-305.11(A)(2). ** Corrected On-Site **
5.	Main Kitchen	Bakery	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, rodent droppings observed behind oven. Standard found in 105 CMR 590; FC 6-501.12(A). ** Corrected On-Site **
6.	Main Kitchen	Inmate Serving Area	105 CMR 451.200*	Numbers and Capacities, Equipment: Insufficient hot holding equipment in number and capacity (Pf), inadequate number of operational hot holding equipment. Standard found in 105 CMR 590; FC 4-301.11.

Main Gymnasium

Deficiencies under the Required Standards (.100 and .200 series)

4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Inmate Toilets & Showers	105 CMR 451.123*	Maintenance: Wall paint damaged
2.	Staff Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty
3.	Staff Bathroom	105 CMR 451.123*	Maintenance: Door stuck and difficult to open
4.	Staff Bathroom	105 CMR 451.123*	Maintenance: Wall damaged behind toilet

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	Basketball Court	105 CMR 451.353	Interior Maintenance: Wall paint damaged
----	------------------	-----------------	--

Chapel

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Chapel	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged
----	--------	------------------	---

Central Control

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	Central Control	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
----	-----------------	-----------------	---

Mini 5

Deficiencies under the Required Standards (.100 and .200 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1. Bathroom (1)	105 CMR 451.123*	Maintenance: Caulking moldy in shower # 1
-----------------	------------------	---

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1. Control Booth	105 CMR 451.353*	Interior Maintenance: Floor paint damaged
------------------	------------------	---

MAXI C

Deficiencies under the Required Standards (.100 and .200 series)

7 repeat deficiencies (indicated by an *) were found during the inspection:

1. Upper Tier	Showers	105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower # 1, 2, and 3
2. Upper Tier	Showers	105 CMR 451.123*	Maintenance: Wall paint damaged in shower # 1, 2, and 3
3. Lower Tier	Showers	105 CMR 451.123*	Maintenance: Ceiling paint damaged outside of showers

Captain/Lieutenant's Office Area

Deficiencies under the Required Standards (.100 and .200 series)

2 repeat deficiencies (indicated by an *) were found during the inspection:

1. Bathrooms (2)	105 CMR 451.123*	Maintenance: Wall damaged under handwash sink in Bathroom # 1
2. Break Area	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets dirty

Deignan Building

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 4 repeat deficiencies (indicated by an *) were found during the inspection:

1. Control Booth Bathroom		105 CMR 451.123*	Maintenance: Floor paint damaged
2. Common Area		105 CMR 451.141*	Screens: Screens missing
3. Upper West	Showers	105 CMR 451.123	Maintenance: Ceiling vent dusty in showers # 1 and 2
4. Lower West	Bathroom	105 CMR 451.123*	Maintenance: Baseboard paint peeling
5. Upper East	Slop Sink Room	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, backflow preventer missing

Modular Administration

Deficiencies under the Required Standards (.100 and .200 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123*	Maintenance: Floor damaged in locker room area
----	---------------------------	-----------------------------	------------------	--

Deficiencies under the Recommended Standards (.300 series)

1 repeat deficiency (indicated by an *) was found during the inspection:

1.	Exterior		105 CMR 451.350*	Structural Maintenance: Exterior wall damaged
----	----------	--	------------------	---

Modular Gym

Deficiencies under the Required Standards (.100 and .200 series)

4 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Modular Gym	Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Floor tile missing
2.	Modular Gym	Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Ceiling vent cover missing
3.	Modular Gym	Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Wall damaged behind toilet
4.	Modular Gym	Gym	105 CMR 451.141*	Screens: Several screens damaged

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency and 3 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Modular Gym	Gym	105 CMR 451.353*	Interior Maintenance: Wall paint damaged
2.	Modular Gym	Gym	105 CMR 451.360*	Protective Measures: Bird nest observed in window
3.	Modular Gym	Gym	105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight
4.	Modular Gym	Gym	105 CMR 451.353	Interior Maintenance: Padding damaged on exercise equipment

MIU

Deficiencies under the Required Standards (.100 and .200 series)

3 new deficiencies were found during the inspection:

1.	Receiving	Medical Intake # 108	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature recorded at 98°F at handwash sink
2.	Receiving	Breakroom	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
3.	Receiving	Bathrooms # 126 and 127	105 CMR 451.123*	Maintenance: Ceiling vent dusty in bathroom # 126

Medical Entrance

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1.	Left Wing	Waiting Area 2 # 158	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 72°F at handwash sink
2.	2nd Floor	Showers	105 CMR 451.123*	Maintenance: Floor dirty in shower #3
3.	2nd Floor	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower #2
4.	2nd Floor	Showers	105 CMR 451.130*	Hot Water: Shower water temperature recorded at 71°F in shower # 1

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies were found during the inspection:

1.	Right Wing	Entrance/Main Desk Area	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
2.	Right Wing	Exam 3 # 160	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty

H Building

Deficiencies under the Recommended Standards (.300 series)

1 new deficiency was found during the inspection:

1.	H Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
----	------------	---------------	-----------------	---

I Building

Deficiencies under the Required Standards (.100 and .200 series)

2 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	I Building	Control Booth	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty
2.	I Building	Control Bathroom	105 CMR 451.117	Toilet Fixtures: Toilet dirty
3.	I Building	Cells	105 CMR 451.141*	Screens: Screen damaged in cell # 171

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies were found during the inspection:

1.	I Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged
2.	I Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty
3.	I Building	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 187
4.	I Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 200 and 216
5.	I Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 208

J Building

Deficiencies under the Required Standards (.100 and .200 series)

8 new deficiencies were found during the inspection:

1.	J Building	Showers	105 CMR 451.123	Maintenance: Lower push button non-operational in handicapped shower
2.	J Building	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 8 leaking
3.	J Building	Showers	105 CMR 451.123	Maintenance: Wall rusted at entry of shower # 4
4.	J Building	Showers	105 CMR 451.123	Maintenance: Mold where floor and wall meet in shower # 8
5.	J Building	Showers	105 CMR 451.123	Maintenance: Drain flies observed in shower # 8
6.	J Building	Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling of shower # 5, 7, and 9

Deficiencies under the Recommended Standards (.300 series)

6 new deficiencies and 1 repeat deficiency (indicated by an *) were found during the inspection:

1.	J Building	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 264
2.	J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 259 and 261
3.	J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 254, 261, and 279
4.	J Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 251

L Building

Deficiencies under the Required Standards (.100 and .200 series)

21 new deficiencies were found during the inspection:

1.	L Building	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1, 3, 4, 6, 7, 8, and 9
2.	L Building	Showers	105 CMR 451.123	Maintenance: Floors dirty in shower # 1, 2, 3, 4, 6, 7, and 8
3.	L Building	Showers	105 CMR 451.123	Maintenance: Mold where floor and wall meet in shower # 2, 3, 4, 5, 6, 7, and 8

Deficiencies under the Recommended Standards (.300 series)

2 new deficiencies and 2 repeat deficiencies (indicated by an *) were found during the inspection:

1.	L Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling damaged outside cell # 386
2.	L Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent dirty in cell # 374
3.	L Building	Cells	105 CMR 451.353*	Interior Maintenance: Wall damaged under window in cell # 395
4.	L Building	Cells	105 CMR 451.353*	Interior Maintenance: Screen dirty in cell # 343

Warehouse

Deficiencies under the Required Standards (.100 and .200 series)

3 repeat deficiencies (indicated by an *) were found during the inspection:

1. Staff Gym	Female Bathroom/Locker Room	105 CMR 451.123*	Maintenance: Wall paint damaged
2. Staff Gym	Female Bathroom/Locker Room	105 CMR 451.123*	Maintenance: Floor tiles not secure by toilet
3. Warehouse	Dry Storage Closet	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged. Standard found in 105 CMR 590; FC 6-501.11.

Annex

Deficiencies under the Required Standards (.100 and .200 series)

6 repeat deficiencies (indicated by an *) were found during the inspection:

1. Toilet/Handwash Sink Units	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, toilet # 1, 2, 4, 9, 11, and handicapped toilet out-of-order
-------------------------------	------------------	--

SECTION 2: Areas Found to be in Compliance

EHRS inspected 250 additional areas of the facility which were found to be in compliance.

Section 3: Areas EHRS did not inspect

EHRS did not inspect 8 areas of the facility because they were either in use, locked, or under construction.

1. A2 Block	Showers (Upstairs)	Unable to Inspect – In Use
2. A2 Block	Showers (Downstairs)	Unable to Inspect – In Use
3. Maintenance Corridor	Inmate Bathroom	Unable to Inspect – In Use
4. Modular Visiting Area		Unable to Inspect – Under Construction
5. VOC		Unable to Inspect – Under Construction
6. Work Release		Unable to Inspect – Closed
7. Tower		Unable to Inspect – Closed

SECTION 4: Plan of Correction

This facility does not comply with the Department's regulations cited above. In accordance with 105 CMR 451.404, please submit a plan of correction within 10 working days of receipt of this notice which includes:

1. Specific corrective steps to be taken
2. A timetable for the corrective actions for larger projects
3. The date by which correction will be achieved
4. Any interim measures being implemented to ensure the health and safety of incarcerated individuals and facility staff
5. The plan should be signed by the Superintendent or Administrator and submitted to my attention, at the address listed above.

SECTION 5: Observations and Recommendations

1. The inmate population was 688 at the time of inspection.
2. The EHRS recommends the facility continue with cleaning ceiling vents, wall vents, and fans on a regular schedule, (e.g., quarterly or during filter changes) throughout the facility (offices and common areas) to remove dust and debris. Particular attention should be paid to the MIU, which has a protective mesh covering over the vents that traps dust and mold spores.
3. To ensure time/temperature control for safety food is served at 135°F or above the EHRS recommends that kitchen staff obtain additional hot holding units for the serving line.

To review the specific regulatory requirements please visit our website at www.mass.gov/dph/dcs and click on "Correctional Facilities" [105 CMR 451.000](#) available in both PDF and RTF formats. For more specific information about the food standards, you can download the merged food code, which can be found [here](#).

An inspection may also include observations of other conditions which could constitute a threat to the health or safety of inmates or employees, including but not limited to the standards set forth by the Department as follows, and report on such pursuant to 451.402(B). You can use these links below to review these standards:

- [105 CMR 205.000](#): Minimum Standards Governing Medical Records and Conduct of Physical Examinations in Correctional Facilities
- [105 CMR 480.000](#): Minimum requirements for the Management of Medical or Biological Waste
- [105 CMR 500.000](#): Good Manufacturing Practices for Food

This inspection report is true and accurate to the best of my knowledge.

Sincerely,



Cory J. Holmes
Senior Advisor, EHRS, BCEH



Commonwealth of Massachusetts

OFFICE OF THE SHERIFF

COUNTY OF WORCESTER
JAIL AND HOUSE OF CORRECTION
5 PAUL X. TIVNAN DRIVE
WEST BOYLSTON, MASSACHUSETTS 01583
TELEPHONE: 508 854-1800

LEWIS G. EVANGELIDIS
SHERIFF

FAX: 508 856-0465
TTY: 508 854-1888

December 16, 2025

Cory J. Holmes
Senior Advisor for Indoor Air Quality Inspections, Audits, Outreach and Training
Division of Environmental Health Regulations and Standards
Massachusetts Department of Public Health
Bureau of Climate and Environmental Health
Donovan Health Building, 5 Randolph St.
Canton, MA 02021


Re: Plan of Correction – Worcester County House of Corrections and Jail

Dear Mr. Holmes:

Pursuant to the Department of Public Health (DPH) Regulations 105 CMR 451.000 – Minimum Health and Sanitations Standards and Inspection Procedures for Correctional Facilities, attached please find a corrected response to the inspection conducted on November 19 & 20, 2025.

If you require additional information, please feel free to contact me.

Sincerely,



Jason Rives
Superintendent

cc: AS Jason Butland
Capt. Eric Locke
Lt. Devon Walker
Anna Laukaitis – Compliance Analyst

Area	Room	Code	Description	Plan of Action	Deadline Date	Responsible Staff
1. Entrance	Male Staff Bathroom	105 CMR 451.123*	Maintenance: Rust on handwash sink fixture	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Visiting Room	Male Bathroom	105 CMR 451.123*	Maintenance: Wall paint damaged above urinal	Damaged paint to be scraped and repainted	4/1/2026	Hubacz
1. Upper Disciplinary Unit	Cell #2	105 CMR 451.117*	Toilet Fixtures: Toilet fixtures not easily cleanable, toilet rusted in cell #2	Maintenance to inspect and repair	2/6/2026	Hubacz
2. Upper Disciplinary Unit	Cell #2	105 CMR 451.123*	Maintenance: Handwash sink dirty in cell #2	Sink cleaned		
1. Maxi B	Cell #336	105 CMR 451.353	Interior Maintenance: Wall paint damaged near toilet in cell # 336	Damaged paint to be scraped and repainted	4/1/2026	Mara
2. Maxi B	Cell #326	105 CMR 451.353*	Interior Maintenance: Wall paint damaged in cell # 326	Damaged paint to be scraped and repainted	4/1/2026	Mara
1. Main Kitchen	Food Prep Area	105 CMR 451.200	Characteristics; Condition: Food not safe, unadulterated, and honestly presented (Pf), moldy buns observed. Standard found in 105 CMR 590; FC 3-101.11. ** Corrected On-Site **			
2. Main Kitchen	Dishwasher Area	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Non-functional equipment not repaired, warewashing machine out-of-order. Standard found in 105 CMR 590; FC 6-501.114(A).	Awaiting repair - disposable trays to be used	4/1/2026	Stone
3. Main Kitchen	Freezer # 4	105 CMR 451.200*	Maintenance and Operation, Equipment: Equipment not maintained in a state of good repair, gasket and door frame damaged. Standard found in 105 CMR 590; FC 4-501.11(A).	Equipment Ordered - awaiting repair	4/1/2026	Stone
4. Main Kitchen	Freezer # 4	105 CMR 451.200	Preventing Contamination from the Premises; Food Storage: Food exposed to splash, dust, or other contamination, food stored beneath condensation where walls meet ceiling. Standard found in 105 CMR 590; FC 3-305.11(A)(2).			
			** Corrected On-Site **			
5. Main Kitchen	Bakery	105 CMR 451.200	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not cleaned as often as necessary, rodent droppings observed behind oven. Standard found in			

			105 CMR 590; FC 6-501.12(A). ** Corrected On-Site **			
6. Main Kitchen	Inmate Serving Area	105 CMR 451.200*	Numbers and Capacities, Equipment: Insufficient hot holding equipment in number and capacity (Pf), inadequate number of operational hot holding equipment. Standard found in 105 CMR 590; FC 4-301.11.	New hot holding equipment to be ordered	4/1/2026	Stone
1. Main Gym	Inmate Toilets & Showers	105 CMR 451.123*	Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	4/1/2026	Hubacz
2. Main Gym	Staff Bathroom	105 CMR 451.123*	Maintenance: Ceiling vent dusty	Vent to be cleaned	1/9/2026	Hubacz
3. Main Gym	Staff Bathroom	105 CMR 451.123*	Maintenance: Door stuck and difficult to open	Maintenance to inspect and repair	2/6/2026	Hubacz
4. Main Gym	Staff Bathroom	105 CMR 451.123*	Maintenance: Wall damaged behind toilet	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Main Gym	Basketball Court	105 CMR 451.353	Interior Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	4/1/2026	Hubacz
1. Chapel	Back Office	105 CMR 451.353*	Interior Maintenance: Ceiling tiles water damaged	Tiles to be replaced	2/6/2026	Hubacz
1. Central Control		105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged	Tiles to be replaced	2/6/2026	Hubacz
1. Mini 5	Bathroom (1)	105 CMR 451.123*	Maintenance: Caulking moldy in shower # 1	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Mini 5	Control Booth	105 CMR 451.353*	Interior Maintenance: Floor paint damaged	Damaged paint to be scraped and repainted	4/1/2026	Head
1. Maxi C	Showers (Upper)	105 CMR 451.123*	Maintenance: Floor epoxy damaged in shower # 1, 2, and 3	Maintenance to inspect and repair	2/6/2026	Hubacz
2. Maxi C	Showers (Upper)	105 CMR 451.123*	Maintenance: Wall paint damaged in shower # 1, 2, and 3	Damaged paint to be scraped and repainted	4/1/2026	Head
3. Maxi C	Showers (Lower)	105 CMR 451.123*	Maintenance: Ceiling paint damaged outside of showers	Damaged paint to be scraped and repainted	4/1/2026	Head
1. Capt./Lt. Office	Bathrooms (2)	105 CMR 451.123*	Maintenance: Wall damaged under handwash sink in Bathroom # 1	Maintenance to inspect and repair	2/6/2026	Hubacz
2. Capt./Lt. Office	Break Area	105 CMR 451.200*	Food Storage, Preparation and Service: Food storage not in compliance with 105 CMR 590.000, refrigerator gaskets dirty	Gaskets Cleaned		
1. Deignan	Control Booth Bathroom	105 CMR 451.123*	Maintenance: Floor paint damaged	Damaged paint to be scraped and repainted	4/1/2026	Head
2. Deignan	Common Area	105 CMR 451.141*	Screens: Screens missing	Maintenance to inspect and repair	2/6/2026	Hubacz
3. Deignan	Showers (Upper West)	105 CMR 451.123	Maintenance: Ceiling vent dusty in showers # 1 and 2	Vents to be cleaned	1/9/2026	Hubacz
4. Deignan	Bathroom (Lower West)	105 CMR 451.123*	Maintenance: Baseboard paint peeling	Damaged paint to be scraped and repainted	4/1/2026	Head

5. Deignan	Slop Sink Room (Upper East)	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, backflow preventer missing	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Special Services Corridor	Male Locker Room & Bathroom	105 CMR 451.123*	Maintenance: Floor damaged in locker room area	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Mods Admin	Exterior	105 CMR 451.350*	Structural Maintenance: Exterior wall damaged	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Modular Gym	Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Floor tile missing	Missing tile to be replaced	4/1/2026	Hubacz
2. Modular Gym	Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Ceiling vent cover missing	Vent cover to be replaced	1/9/2026	Hubacz
3. Modular Gym	Inmate Bathroom # 104	105 CMR 451.123*	Maintenance: Wall damaged behind toilet	Maintenance to inspect and repair	2/6/2026	Hubacz
4. Modular Gym	Gym	105 CMR 451.141*	Screens: Several screens damaged	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Modular Gym	Gym	105 CMR 451.353*	Interior Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	4/1/2026	Hubacz
2. Modular Gym	Gym	105 CMR 451.360*	Protective Measures: Bird nest observed in window	Bird nest to be removed	1/9/2026	Hubacz
3. Modular Gym	Gym	105 CMR 451.350*	Structural Maintenance: Exterior door not rodent and weathertight	Maintenance to inspect and repair	2/6/2026	Hubacz
4. Modular Gym	Gym	105 CMR 451.353	Interior Maintenance: Padding damaged on exercise equipment	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Receiving	Medical Intake # 108	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature recorded at 98°F at handwash sink	Maintenance to inspect and repair	2/6/2026	Hubacz
2. Receiving	Breakroom	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with 105 CMR 590.000, interior of microwave oven dirty	Microwave Cleaned		
3. Receiving	Bathrooms # 126 and 127	105 CMR 451.123*	Maintenance: Ceiling vent dusty in bathroom # 126	Vent to be cleaned	1/9/2026	Hubacz
1. Left Wing	Waiting Area 2 # 158	105 CMR 451.126	Hot Water for Bathing and Hygiene: Hot water temperature 72°F at handwash sink	Maintenance to inspect and repair	2/6/2026	Hubacz
2. 2nd Floor	Showers	105 CMR 451.123*	Maintenance: Floor dirty in shower #3	Shower Cleaned		
3. 2nd Floor	Showers	105 CMR 451.123	Maintenance: Floor dirty in shower #2	Shower Cleaned		
4. 2nd Floor	Showers	105 CMR 451.130*	Hot Water: Shower water temperature recorded at 71°F in shower # 1	Maintenance to inspect and repair	2/6/2026	Hubacz
1. Right Wing	Entrance/Main Desk Area	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent to be cleaned	1/9/2026	Hubacz
2. Right Wing	Exam 3 # 160	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent to be cleaned	1/9/2026	Hubacz

1. H Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged	Tiles to be replaced	4/1/2026	Hubacz
1. I Building	Control Booth	105 CMR 451.200	Food Storage, Preparation and Service: Food preparation not in compliance with	Microwave Cleaned		
			105 CMR 590.000, interior of microwave oven dirty			
2. I Building	Control Bathroom	105 CMR 451.117	Toilet Fixtures: Toilet dirty	Toilet Cleaned		
3. I Building	Cells	105 CMR 451.141*	Screens: Screen damaged in cell # 171	Maintenance to inspect and repair	2/6/2026	Hubacz
1. I Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling tiles water damaged	Tiles to be replaced	4/1/2026	Hubacz
2. I Building	Control Booth	105 CMR 451.353	Interior Maintenance: Ceiling vent dusty	Vent to be cleaned	1/9/2026	Hubacz
3. I Building	Cells	105 CMR 451.353	Interior Maintenance: Floor paint damaged in cell # 187	Damaged paint to be scraped and repainted	4/1/2026	Foley
4. I Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 200 and 216	Damaged paint to be scraped and repainted	4/1/2026	Foley
5. I Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 208	Obstruction Removed		
1. J Building	Showers	105 CMR 451.123	Maintenance: Lower push button non-operational in handicapped shower	Maintenance to inspect and repair	2/6/2026	Hubacz
2. J Building	Showers	105 CMR 451.130	Plumbing: Plumbing not maintained in good repair, shower # 8 leaking	Maintenance to inspect and repair	2/6/2026	Hubacz
3. J Building	Showers	105 CMR 451.123	Maintenance: Wall rusted at entry of shower # 4	Maintenance to inspect and repair	2/6/2026	Hubacz
4. J Building	Showers	105 CMR 451.123	Maintenance: Mold where floor and wall meet in shower # 8	Shower Cleaned		
5. J Building	Showers	105 CMR 451.123	Maintenance: Drain flies observed in shower # 8	Shower to be treated	1/9/2026	Hubacz
6. J Building	Showers	105 CMR 451.123	Maintenance: Dead drain flies observed on ceiling of shower # 5, 7, and 9	Showers Cleaned		
1. J Building	Cells	105 CMR 451.353*	Interior Maintenance: Wall vent blocked in cell # 264	Obstruction Removed		
2. J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent blocked in cell # 259 and 261	Obstructions Removed		
3. J Building	Cells	105 CMR 451.353	Interior Maintenance: Wall paint damaged in cell # 254, 261, and 279	Damaged paint to be scraped and repainted	4/1/2026	Foley
4. J Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling paint damaged in cell # 251	Damaged paint to be scraped and repainted	4/1/2026	Foley
1. L Building	Showers	105 CMR 451.123	Maintenance: Walls dirty in shower # 1, 3, 4, 6, 7, 8, and 9	Showers Cleaned		
2. L Building	Showers	105 CMR 451.123	Maintenance: Floors dirty in shower # 1, 2, 3, 4, 6, 7, and 8	Showers Cleaned		

3. L Building	Showers	105 CMR 451.123	Maintenance: Mold where floor and wall meet in shower # 2, 3, 4, 5, 6, 7, and 8	Showers Cleaned		
1. L Building	Cells	105 CMR 451.353	Interior Maintenance: Ceiling damaged outside cell # 386	Maintenance to inspect and repair	2/6/2026	Hubacz
2. L Building	Cells	105 CMR 451.353	Interior Maintenance: Wall vent dirty in cell # 374	Vent to be cleaned	1/9/2026	Hubacz
3. L Building	Cells	105 CMR 451.353*	Interior Maintenance: Wall damaged under window in cell # 395	Maintenance to inspect and repair	2/6/2026	Hubacz
4. L Building	Cells	105 CMR 451.353*	Interior Maintenance: Screen dirty in cell # 343	Screen to be cleaned	1/9/2026	Hubacz
1. Staff Gym	Female Bathroom/Locker Room	105 CMR 451.123*	Maintenance: Wall paint damaged	Damaged paint to be scraped and repainted	4/1/2026	Hubacz
2. Staff Gym	Female Bathroom/Locker Room	105 CMR 451.123*	Maintenance: Floor tiles not secure by toilet	Maintenance to inspect and repair	2/6/2026	Hubacz
3. Warehouse	Dry Storage Closet	105 CMR 451.200*	Maintenance and Operation; Premises, Structure, Attachments, and Fixtures - Methods: Facility not in good repair, ceiling damaged. Standard found in	Maintenance to inspect and repair	2/6/2026	Hubacz
			105 CMR 590; FC 6-501.11.			
1. Annex	Toilet/Handwash Sink Units	105 CMR 451.130*	Plumbing: Plumbing not maintained in good repair, toilet # 1, 2, 4, 9, 11, and handicapped toilet out-of-order	Maintenance to inspect and repair	2/6/2026	Hubacz



The Commonwealth of Massachusetts
Executive Office of Health and Human Services
Department of Public Health
5 Randolph Street
Canton, MA 02021
781-828-7700 | mass.gov/dph

Maura T. Healey
Governor

Kimberley Driscoll
Lieutenant Governor

Kiame Mahaniah, MD, MBA
Secretary

Robert Goldstein, MD, PhD
Commissioner

December 29, 2025

Jason Rives, Superintendent
Worcester County Jail and House of Correction
5 Paul X. Tivnan Drive
West Boylston, MA 01583 (electronic copy)

Re: Plan of Correction – Worcester County Jail and House of Correction, West Boylston

Dear Superintendent Rives:

The Massachusetts Department of Public Health, Division of Environmental Health Regulations and Standards (EHRS) has received your Plan of Correction dated December 16, 2025. After review, the EHRS finds the plan addresses all the deficiencies noted.

Thank you for your prompt attention to this matter, should you have any questions please contact me at the address listed above.

Sincerely,

A handwritten signature in blue ink, appearing to read "C. J. Holmes".

Cory J. Holmes
Senior Advisor, EHRS, BCEH

cc: Noe Bard, Environmental Health and Safety Officer (electronic copy)
Captain Eric Locke, Policy, Procedure, Accreditation and Compliance (electronic copy)
Lieutenant Devon Walker, Policy, Procedure, Accreditation and Compliance (electronic copy)
Sheriff Lewis G. Evangelidis, Worcester County (electronic copy)