



Machinery Fault Diagnosis

A basic guide to understanding vibration analysis for machinery diagnosis.



Preface




This is a basic guide to understand vibration analysis for machinery diagnosis. In practice, many variables must be taken into account. PRUFTECHNIK Condition Monitoring and/or LUDECA are not responsible for any incorrect assumptions based on this information.

[©] Copyright 2011 by PRÜFTECHNIK AG. ISO 9001:2008 certified. No copying or reproduction of this information, in any form whatsoever, may be undertaken without express written permission of PRÜFTECHNIK AG or LUDECA Inc.


Unbalance






Unbalance is the condition when the geometric centerline of a rotation axis doesn't coincide with the mass centerline.

$$F_{unbalance} = m d \omega^2$$







A pure unbalance will generate a signal at the rotation speed and predominantly in the radial direction.

Static Unbalance








Static unbalance is caused by an unbalance mass out of the gravity centerline.


The static unbalance is seen when the machine is not in operation, the rotor will turn so the unbalance mass is at the lowest position.

The static unbalance produces a vibration signal at 1X, radial predominant, and in phase signals at both ends of the rotor.

Pure Couple Unbalance








Pure couple unbalance is caused by two identical unbalance masses located at 180° in the transverse area of the shaft.

Pure couple unbalance may be statically balanced.

When rotating pure couple unbalance produces a vibration signal at 1X, radial predominant and in opposite phase signals in both ends of the shaft.


Dynamic Unbalance





Dynamic unbalance is static and couple unbalance at the same time.


In practice, dynamic unbalance is the most common form of unbalance found.



When rotating the dynamic unbalance produces a vibration signal at 1X, radial predominant and the phase will depend on the mass distribution along the axis.


Documentation of balancing






Overhung Rotors





A special case of dynamic unbalance can be found in overhung rotors.


The unbalance creates a bending moment on the shaft.




Dynamic unbalance in overhung rotors causes high 1X levels in radial and axial direction due to bending of the shaft. The axial bearing signals in phase may confirm this unbalance.

Unbalance location









The relative levels of 1X vibration are dependant upon the location of the unbalance mass.


Misalignment





Misalignment is the condition when the geometric centerline of two coupled shafts are not co-linear along the rotation axis of both shafts at operating condition.







A 1X and 2X vibration signal predominant in the axial direction is generally the indicator of a misalignment between two coupled shafts.

Angular Misalignment








Angular misalignment is seen when the shaft centerlines coincide at one point along the projected axis of both shafts.


The spectrum shows high axial vibration at 1X plus some 2X and 3X with 180° phase difference across the coupling in the axial direction.

These signals may be also visible in the radial direction at a lower amplitude and in phase.



Parallel Misalignment









The spectrum shows high radial vibration at 2X and a lower 1X with 180° phase difference across the coupling in the radial direction.


These signals may be also visible in the axial direction in a lower amplitude and 180° phase difference across the coupling in the axial direction.






Misalignment Diagnosis Tips






In practice, alignment measurements will show a combination of parallel and angular misalignment.



Diagnosis may show both a 2X and an increased 1X signal in the axial and radial readings.

The misalignment symptoms vary depending on the machine and the misalignment conditions.



The misalignment assumptions can be often distinguished from unbalance by:

- Different speeds testing
- Uncoupled motor testing

Temperature effects caused by thermal growth should also be taken into account when assuming misalignment is the cause of increased vibration.

Alignment Tolerance Table




		Alignment Tolerance inch [mils]	
Short "flexible" couplings	RPM	acceptable	excellent
Offset	900	6.0	3.0
	1200	4.0	2.5
	1800	3.0	2.0
	3600	1.5	1.0
Angularity (gap difference at coupling edge per 10" diameter)	900	10.0	7.0
	1200	8.0	5.0
	1800	5.0	3.0
	3600	3.0	2.0
Spacer shafts and membrane (disk) couplings Offset	900	2.0	1.2
	1200	1.5	0.9
(per inch spacer length)	1800	1.0	0.6
	3600	0.5	0.3
Angularity [mrad]	900	2.0 ^{[mr.}	1.2
	1200	1.5	0.9
	1800	1.0	0.6
	3600	0.5	0.3
Soft foot	any	2.0 mils	


The suggested alignment tolerances shown above are general values based upon experience and should not be exceeded. They are to be used only if existing in-house standards or the manufacturer of the machine or coupling prescribe no other values.

Shaft Bending







A shaft bending is produced either by an axial asymmetry of the shaft or by external forces on the shaft producing the deformation.



A bent shaft causes axial opposed forces on the bearings identified in the vibration spectrum as 1X in the axial vibration.









Rotating Looseness




Rotating looseness is caused by an excessive clearance between the rotor and the bearing


Rolling element bearing:





Journal bearing:







Structural Looseness



Structural looseness occurs when the machine is not correctly supported by, or well fastened to its base.



- Poor mounting
- Poor or cracked base
- Poor base support
- Warped base




Structural looseness may increase vibration amplitudes in any measurement direction. Increases in any vibration amplitudes may indicate structural looseness.

Measurements should be made on the bolts, feet and bases in order to see a change in the amplitude and phase. A change in amplitude and 180° phase difference will confirm this problem.

Resonance




Resonance is a condition caused when a forcing frequency coincides (or is close) to the natural frequency of the machine's structure. The result will be a high vibration.



Resonance



- Resonance can be confused with other common problems in machinery.
- Resonance requires some additional testing to be diagnosed.




Amplitude at rotation frequency fn by residual unbalance on rigid rotor.

Strong increase in amplitude of the rotation frequency fn at the point of resonance, step-up dependent on the excitation (unbalanced condition) and damping.

Resonance Diagnosing Tests



Run Up or Coast Down Test:




- Performed when the machine is turned on or turned off.
- Series of spectra at different RPM.
- Vibration signals tracking may reveal a resonance.


The use of tachometer is optional and the data collector must support this kind of tests.


Resonance Diagnosing Tests















Journal Bearings




Journal bearings provides a very low friction surface to support and guide a rotor through a cylinder that surrounds the shaft and is filled with a lubricant preventing metal to metal contact.



High vibration damping due to the oil film:

- High frequencies signals may not be transmitted.
- Displacement sensor and continuous monitoring recommended

Clearance problems (rotating mechanical looseness).



Oil whirl


- Oil-film stability problems.
- May cause 0.3-0.5X component in the spectrum.



1. Wear:

- Lifetime exceeded
- Bearing overload
- Incorrect assembly
- Manufacturing error
- Insufficient lubrication






The vibration spectrum has a higher noise level and bearing characteristic frequencies can be identified.

Increased level of shock pulses.




2. Race Damage:


Roller bearing geometry and damage frequencies:



- α Angle of contact
- D Arc diameter
- d Rolling element diameter
- **Z** Number of rolling elements
- n Shaft RPM



- 1 Outer race damage
- 2 Inner race damage
- 3 Rolling element damage
- 4 Cage damage



Ball pass frequency, inner race: BPFI = $\frac{Z \cdot n}{2 \cdot 60}$ (1+ $\frac{d}{D}$ cos α)

Ball spin frequency: $BSF = \frac{D \cdot n}{d \cdot 60} \left(1 - \left[\frac{d}{D} \cos \alpha \right]^2 \right)$

Fundamental train frequency: TFT = $\frac{n}{2.60}$ (1- $\frac{d}{D}$ cos α)

Example of rollover frequencies:

Ball bearing SKF 6211


RPM, n = 2998 rev/min


Dimensions	Rollover frequencies		
d =77.50 mm	BPFO = n / 60 · 4.0781 = 203.77 Hz		
D =14.29 mm	BPFI = n / 60 · 5.9220 = 295.90 Hz		
Z = 10	$2 \cdot f_w = n / 60 \cdot 5.2390 = 261,77 \text{ Hz}$		
α = 0	$f_K = n / 60 \cdot 0.4079 = 20.38 \text{ Hz}$		



Outer race damage:

(Ball passing frequency, outer range BPFO)







Outer race damage frequency BPFO as well as harmonics clearly visible

Inner race damage:

(Ball passing frequency, inner range BPFI)







Inner race damage frequency BPFI as well as numerous sidebands at intervals of 1X.



Rolling element damage: (Ball spin frequency BSF)







Rolling elements rollover frequency BSF with harmonics as well as sidebands in intervals of FTF

Cage damage:

(Fundamental train frequency FTF)






Cage rotation frequency FTF and harmonics visible



Lubrication Problems:


Lubricant contamination

- Race damage
- Defective sealing
- Contaminated lubricant used




Insufficient lubrication

- Insufficient lubricant
- Underrating



Over-greasing

- Maintenance error
- Defective grease regulator
- Grease nipple blocked






Incorrect mounting.

Bearing rings out of round, deformed.

- Incorrect installation
- Wrong bearing storage
- Shaft manufacturing error
- Bearing housing overtorqued.




Bearing forces on floating bearing.

- Incorrect installation
- Wrong housing calculation
- Manufacturing error in bearing housing


Cocked bearing.

Incorrect installation



Blade and Vanes






A blade or vane generates a signal frequency called blade pass frequency, f_{BP:}


$$f_{BP} = B_n \cdot N$$

B_n = # of blades or vanes N = rotor speed in rpm

Identify and trend f_{BP}.

An increase in it and/or its harmonics may be a symptom of a problem like blade-diffuser or volute air gap differences.





Example characteristic frequency:

3 struts in the intake; x=3.


9 blades; $B_n=9$.

 $f_{BP} \cdot x = N \cdot B_n \cdot x$

Characteristic frequency = $N \cdot 27$

Aerodynamics and Hydraulic Forces







There are two basic moving fluid problems diagnosed with vibration analysis:

- Turbulence
- Cavitation

Cavitation:




Turbulence:



Belt Drive Faults






Belt transmission a common drive system in industry consisting of:

- Driver Pulley
- Driven Pulley
- Belt

The dynamic relation is: $\emptyset_1 \omega_1 = \emptyset_2 \omega_2$



Belt frequency:


$$f_B = \frac{3,1416\omega_1\phi_1}{l}$$

l: belt length

Belt Drive Faults








The belt frequency $f_{\rm B}$ and first two (or even three) harmonics are visible in the spectrum.

2 f_B generally dominates the spectrum

Pulley Misalignment:




1X of diver or driven pulley visible and predominant in the axial reading.

Belt Drive Faults



Eccentric Pulleys:




The geometric center doesn't coincide with the rotating center of the pulley.

High 1X of the eccentric pulley visible in the spectrum, predominant in the radial direction.

Easy to confuse with unbalance, but:

- Measurement phase in vertical an horizontal directions may be 0° or 180°.
- The vibration may be higher in the direction of the belts.

Belt Resonance:





If the belt natural frequency coincides with either the driver or driven 1X, this frequency may be visible in the spectrum.




Spur Gear:

Driving gear







Worm Gear:



Planet Gear:




Bevel Gear:





Gear Meshing:




Gear mesh frequency f_z can be calculated:

$$F_z = z f_n$$

Where z is the number of teeth of the gear rotating at f_n .


Gear meshing is the contact pattern of the pinion and wheel teeth when transmitting power.

The red dotted line is the contact path where the meshing teeth will be in contact during the rotation.








Incorrect tooth meshing



Wear













Incorrect tooth shape






Tooth break-out










Eccentricity, bent shafts





"Ghost frequencies" or machine frequencies







Electromagnetic forces vibrations:

Twice line frequency vibration: 2 · fL

Bar meshing frequency: $f_{bar} = f_n \cdot n_{bar}$

Synchronous frequency: $f_{syn} = 2 \cdot f_L / p$


Slip Frequency: $f_{slip} = f_{syn} - f_n$

Pole pass frequency: f_n=p · f_{slin}

f_L: line frequency

n_{bar}: number of rotor bars


p: number of poles




- Stator eccentricity
- Eccentric rotor
- Rotor problems
- Loose connections



Stator Eccentricity:



- Loose iron
- Shorted stator laminations
- Soft foot



1X and 2X signals


 f_L without sidebands


Radial predominant

High resolution should be used when analyzing two poles machines.





Eccentric Rotor:






- Rotor offset
- Misalignment
- Poor base








Modulation of the vibration time signal with the slip frequency f_{slip} $T_{slip} \approx 2\text{-}5~\text{s}$




Rotor Problems:

1. Rotor thermal bow:



- Unbalanced rotor bar current
- Unbalance rotor conditions
- Observable after some operation time


2. Broken or cracked rotor bars:



- 1X and harmonics with sidebands at fp
- High resolution spectrum needed
- Possible beating signal




3. Loose rotor bar:



- f_{bar} and 2f_{bar} with 2f_L sidebands
- 2f_{bar} can be higher
- 1X and 2X can appear

Loose connections:



- 2f_L excessive signal with sidebands at 1/3 f_L
- Electrical phase problem
- Correction must be done immediately