HOKLAS ACCREDITATION APPLICATION OF VERTICALITY CHECK TEST

Item	Task	Successor	Duration	Responsible by
1	Procure equipment • PeeWee/Devishot	2, 4	3 months	Project manager
2	Calibrate equipment • PeeWee Inclination • PeeWee Direction	3	1 month	Project manager, quality manager
3	Verify equipment	8	1 month	Project manager, quality manager
4	Provide in-house training of technical operations to technicians	5, 6, 7	2 months	Project manager, technician
5	Prepare standard test procedures, test records, daily records, test order forms, worksheets based on ISO/IEC 17025:2017	8	1 month	Project manager, consultant
6	Review quality manual, quality procedure, and all quality documents	8	1 month	Quality manager, consultant
7	Provide training of laboratory management for AS based on ISO/IEC 17025:2017	8	1 month	Project manager
8	Perform test under on-going contract or gather test records of past contracts	9, 10	3 months	Project manager, quality manager
9	Provide training of technical operations to all technicians by accredited laboratory	11	2 months	Project manager, quality manager, technician
10	Perform interlaboratory test	11	2 months	Project manager, quality manager
11	Submit HOKLAS accreditation application	12, 13	1 month	Quality manager
12	Perform additional test for preparing advisory visit	14	3 months	Project manager, technician
13	Perform internal audit and mock AS interview	14	1 month	Project manager, quality manager, consultant
14	Perform HKAS advisory visit	15	1 month	All staff
15	Perform corrective actions and review documents	16	1 month	Quality manager
16	Receive accreditation			All staff

Updated: 4 November 2024