

Houston Police Department

Patrol Division — Traffic Services
1200 Travis Street, Houston, TX 77002

OFFICIAL TRAFFIC COLLISION REPORT

(713) 555-0144 | Emergency: 911

CASE NUMBER	HPD-26-02-14-5512	WEATHER	Dense Fog (visibility approx. 80 ft)
DATE OF INCIDENT	February 14, 2026	LIGHT CONDITIONS	Pre-dawn / Dark
TIME OF INCIDENT	06:18 hrs	ROADWAY SURFACE	Wet
LOCATION	I-10 Westbound, Mile Marker 766.2, Houston, TX 77002	TYPE OF COLLISION / VEHICLES	5-vehicle chain rear-end (fog-related pileup) / 5 vehicles

SECTION 1 — RESPONDING UNITS

Responding Agency	Houston Police Department
Investigating Officer	Officer Marcus T. Landry, Badge #7741
Officer Phone	(713) 555-0144 ext. 512
EMS Agency	Houston Fire Dept. — Medic 9 and Medic 22 (transported four occupants)
Tow Companies	Gulf Coast Recovery (V2, V3, V5); Houston Towing (V4)
Additional Units	Sgt. P. Nguyen #4412; HPD Traffic Div. Unit 7; TxDOT Incident Response

SECTION 2 — VEHICLES

#	Year / Make / Model	VIN	Plate	Damage
V1	2022 Toyota Tundra	5TFJA5DB2NX041801	TX-PJK-4418 (TX)	Rear bumper deformed; trailer hitch bent — minor
V2	2019 Honda Odyssey	5FNRL6H77KB131801	TX-BRX-8821 (TX)	Front and rear deformed — sandwiched; both airbags deployed; sliding door jammed
V3	2021 Ford F-250 XLT	1FT8W2BT7MEE48801	TX-CTW-3319 (TX)	Front bumper, grille, hood destroyed; airbag deployed; coolant leak
V4	2018 Chevrolet Cruze	1G1BE5SM4J7144801	TX-DLM-7723 (TX)	Total loss — crushed front and rear; roof intrusion; all airbags deployed
V5	2020 Freightliner M2 106 (box truck, CMV)	1FVHG5BY0LHJA4801	TX-CFT-881 (TX)	Front bumper destroyed; grille and radiator severely damaged; CMV out of service

SECTION 3 — DRIVERS / OPERATORS

Party	Name	DOB	License	Citation
Driver V1	Carlos R. Delgado	09/11/1979	TX-D44218301	None
Driver V2	Maria L. Rivera	04/22/1984	TX-R88234107	TX Transp. Code §545.062 — Following Too Close
Driver V3	Emeka J. Okonkwo	07/18/1978	TX-O77187220	TX Transp. Code §545.062 — Following Too Close
Driver V4	Patrick B. Walsh	12/03/1991	TX-W44219813	TX Transp. Code §545.062 — Following Too Close
Operator V5 (CMV)	Donald R. Pruitt	03/27/1969	TX-CDL-P88241307	TX Transp. Code §545.062 — Following Too Close; FMCSA 49 CFR §392.14 — CMV in Hazardous Conditions

SECTION 4 — PASSENGERS

Veh	Name	DOB	Injury	Transported
V2	Sofia M. Rivera	06/15/1986	Serious: airbag facial burns, rib contusion, cervical strain	Yes — HFD Medic 9, to Memorial Hermann Hospital (serious)
V2	Lucas A. Rivera	03/08/2014	Moderate: forehead laceration, airbag contact bruising	Yes — HFD Medic 9, to Memorial Hermann Hospital (stable)
V2	Isabella R. Rivera	11/22/2018	Minor: precautionary evaluation, child safety seat intact	Yes — HFD Medic 22, to Texas Childrens Hospital (precautionary)
V4	Theresa K. Walsh	08/04/1993	Critical: head trauma, loss of consciousness at scene, suspected TBI	Yes — HFD Medic 22, to Memorial Hermann Trauma Center (trauma activation)
V1	Antonio G. Delgado	01/29/1982	Minor: neck stiffness — declined transport, advised follow-up	No — evaluated on scene, declined
V5	None (CMV — solo operator)	—	Operator Pruitt — minor airbag abrasions, refused transport	No

SECTION 5 — WITNESSES

#	Name	Address	Phone	Statement
W1	Linda P. Fontenot	Following motorist, pulled to shoulder; contact recorded	(713) 555-0391	Yes — confirmed five-vehicle sequence; written statement
W2	Gary T. Marchetti	Overpass pedestrian, observed from above	(713) 555-0448	Yes — observed fog severity and vehicle cluster; written statement
W3	Yvonne K. Slater	Northbound motorist, parallel lane; contact recorded	(713) 555-0512	Yes — described fog as sudden and near-zero; verbal statement
W4	James R. Whitmore	7701 Katy Freeway frontage, Houston TX 77024	(713) 555-0617	Yes — observed CMV following too close prior to scene; written statement

SECTION 6 — PROPERTY DAMAGE (NON-VEHICLE)

	I-10 WB centerline barrier — minor scraping from V4 post-impact slide. TxDOT notified. Highway emergency lighting post bent at Mile Marker 766.3.
--	---

SECTION 7 — NARRATIVE

On Saturday February 14, 2026 at approximately 06:18 hrs, this officer and Sgt. P. Nguyen were dispatched to I-10 westbound at Mile Marker 766.2 in Houston on report of a multi-vehicle chain collision with multiple injuries. Dense fog was present at the time, with visibility estimated at approximately 80 feet by this officer upon arrival. The roadway surface was wet from overnight drizzle. The incident occurred during pre-dawn hours with no natural light. V1 (2022 Toyota Tundra, Delgado) was traveling westbound in the center lane at a reduced speed appropriate for the fog conditions. V1 slowed further as congestion built ahead and came to a near-stop. V2 (2019 Honda Odyssey, Rivera) was traveling directly behind V1 and failed to maintain adequate following distance, striking the rear of V1 at an estimated 35–40 mph. V2 came to rest partially blocking the center and right lanes. V3 (2021 Ford F-250, Okonkwo) was behind V2 and was unable to stop in time, striking the rear of V2 with significant force, pushing V2 forward into V1 for a second impact. V4 (2018 Chevrolet Cruze, Walsh) was approaching at a higher rate of speed and struck the rear of V3, ricocheted left, and came to rest perpendicular across the center and left lanes. V5 (2020 Freightliner M2 106 commercial box truck, Pruitt — CFT Freight LLC) was approaching at highway speed and struck the rear of V4 with severe force. The CMV's front end override of V4 caused catastrophic compression of that vehicle. Witness Linda Fontenot was following at approximately twelve car lengths behind V5 and was able to stop safely by applying brakes well in advance. She stated V5 appeared to be traveling at a speed inconsistent with the visible fog conditions and showed no brake lights until approximately two seconds before impact. Witness Gary Marchetti observed the sequence from the overpass and described the fog as "a wall" at the Mile Marker 766 area. Witness Yvonne Slater, traveling northbound on the parallel IH-10 reverseway, stated the fog was markedly worse in the westbound corridor due to the low-lying terrain near the bayou at that mile marker. Witness James Whitmore had been traveling westbound ahead of the collision sequence and reported observing V5 in his rearview mirror following V4 at an uncommonly close interval for at least one mile prior to the pileup. V4 passenger Theresa Walsh was found unresponsive with head trauma and was transported by HFD Medic 22 to Memorial Hermann Trauma Center under trauma activation. V2 passenger Sofia Rivera was transported to Memorial Hermann Hospital with rib contusion and facial burns in serious but stable condition. V2 passenger Lucas Rivera, age 12, was transported with facial laceration to Memorial Hermann in stable condition. V2 passenger Isabella Rivera, age 7, was transported to Texas Children's Hospital as a precaution; her child safety seat sustained structural deformation and was documented per NHTSA protocols. V1 passenger Antonio Delgado declined transport after EMS evaluation. CMV operator Pruitt sustained minor airbag abrasions and declined transport. V2, V3, and V5 were towed by Gulf Coast Recovery. V4 is a probable total loss and was towed by Houston Towing. V1 was driven from the scene. TxDOT Incident Response arrived at 06:51 hrs and placed dynamic message boards at Mile Markers 769 and 770 warning of the incident and fog. The TxDOT Houston district fog advisory log for the period 04:00–07:00 hrs has been requested. A commercial vehicle out-of-service order was issued to V5 pending mechanical inspection per FMCSA 49 CFR §396.9.

SECTION 9 — SUPPLEMENTAL INVESTIGATION NOTES

SUPPLEMENTAL — CMV INSPECTION AND FMCSA COMPLIANCE: V5 (Freightliner M2 106, CFT Freight LLC, USDOT #2841107) was placed out of service at the scene per FMCSA 49 CFR §396.9 following this collision. TxDOT Motor Carrier Division Inspector R. Salazar arrived at 07:44 hrs and conducted a Level I roadside inspection. Preliminary findings: (1) Front brake adjustment out of spec on left steer axle. (2) One rear cargo door latch inoperative. (3) Operator Pruitt's hours-of-service log was reviewed on scene; logs showed 9.5 hours of on-duty driving in the 24-hour period preceding the incident, within FMCSA limits. The full Level I inspection report (TxDMV Form MCS-63) is attached as Exhibit B. Operator Pruitt holds a valid Texas Class A CDL (TX-CDL-P88241307) with no prior violations per TXDPS CDL database check at 07:22 hrs. CFT Freight LLC safety rating per FMCSA SMS is "Conditional" with two prior out-of-service orders in the preceding 24 months. CHILD SAFETY SEAT DOCUMENTATION: Three child passengers were involved. Isabella Rivera (V2, age 7) was in a forward-facing harness seat that sustained structural deformation consistent with a moderate-to-severe crash. Per NHTSA and TX law, seat should be replaced. Lucas Rivera (V2, age 12) was using a booster seat — seat appeared intact but is recommended for replacement per post-crash protocol. V4 passenger Theresa Walsh is an adult; no child seat involved. Resource sheets provided to Rivera family. SIG-ALERT: HPD Traffic Division issued a Significant Traffic Incident Alert at 06:42 hrs for I-10 WB at Mile Marker 766. All westbound lanes were closed until 09:17 hrs. TxDOT coordinated diversion to Westheimer Road and Westpark Tollway.

SECTION 10 — CITATIONS / CHARGES SUMMARY

Party	Statute	Violation	Fine / Disposition
Driver V2 (Rivera)	TX TC §545.062	Following Too Close — fog/reduced visibility	Civil Penalty
Driver V3 (Okonkwo)	TX TC §545.062	Following Too Close — fog/reduced visibility	Civil Penalty
Driver V4 (Walsh)	TX TC §545.062	Following Too Close — fog/reduced visibility	Civil Penalty
Operator V5 (Pruitt)	TX TC §545.062	Following Too Close — CMV fog conditions	Civil Penalty
Operator V5 (Pruitt)	49 CFR §392.14	CMV operation in hazardous fog conditions	Federal — FMCSA

SECTION 8 — OFFICER SIGN-OFF

signed

Officer Marcus T. Landry, Badge #7741

Investigating Officer, Houston Police Department Traffic Services

February 14, 2026

Date