


LCD board: U2 measurement points

BOTTOM view, viewed directly from the component side. J1 is at upper left in the board overview.

Positions from supplied ODB data. Simplified drawing; not actual probe size.



Black lead: TP9 or TP10 (GND). Red lead: A or B. Use DC voltage mode.

Identify points with power OFF. Touch one end only; do not bridge both ends or adjacent parts.