ERT Analysis - Non-

- Process Images
- Results Table
- Help & Guide

Step 1: Upload Images

Select ERT Images:

Browse... 876_18vii24.jpg

Upload complete

1 files uploaded

Step 2: Colorbar Calibration +

Step 3: Define Boundary

Auto-Detect Boundary

Detects PiCUS blue boundary polygon automatically.

Or click points on image manually:

Clear Points | Finish Polygon

Ready: 176 points

Edge Erosion (pixels):

0 2 10

0 1 2 3 4 5 6 7 8 9 10

Step 4: Process

Process This Image

1 processed

Image Display - Click to add polygon points

876_18vii24.jpg



Statistics

Metric	Value
Mean	513.9
CV	0.451
Gini	0.256
CMA	0.464

Radial Profile