
drain_watcher v1
SNS+ chassis side. SNS-/GND battery side
BAT+ via 1A fuse. Bridge shunt to crank